

Peru

This report shows the 2017-2019 Work Plan entries for Peru. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Peru in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Canton, Dixfield, Hartford, Peru

Asset(s): Route 140, Route 2, Route 108

Description: 71302 - WP 17 Drainage Repairs

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32897	Maintenance	Corridor 1, Corridor 2, Corridor 4	\$12,000

Work Plan Year: 2017

Municipalities(s): Peru, Sumner

Asset(s): Greenwoods Road

Description: 71302 - WP 17 Ditching on Greenwoods Road

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 33428	Maintenance	Corridor 5	\$54,000

Work Plan Year: 2018/19

Municipalities(s): Peru

Asset(s): Greenwoods Road

Description: Large culvert (No.47190) located 0.19 of a mile north of Pulsifer Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021811.00	Large Culvert Rehabilitation	5	\$75,000

Local Road Assistance – Fiscal Year 2016

\$35,224

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 9.0 Bridge(s) Washed
- 0.8 Miles of Striping Applied
- 2.8 Shoulder Miles of Sweeping
- 34.3 Ton(s) of Cold Patch Applied
- 6.0 Emergency Event Responses
- 7,520.0 Linear Feet of Backhoe Ditching
- 9.0 Minor Sign(s) Installed or Maintained
- 32.0 Drainage Structures Cleaned
- 5.0 Trees Removed
- 276.0 Linear Feet of Shoulder Rebuilt
- 299.0 Linear Feet of Guardrail or Fence Maintained
- 6.5 Drainage Structures Repaired
- 128.0 Center Lane Mile(s) Patrolling and Inspecting