

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 5929	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 4.8 MI NE OF JCT RTE 4	YEAR BUILT: 1964	DECK CONDITION: 6 Satisfactory
BRDGNAME: REEDS MILL	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: REEDS MILL ROAD	STRUCTURE LENGTH IN FEET: 57	DATE OF INSPECTION: 8/14/2012
FEATURE UNDER: ORBETON STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 90.7
ROAD INV NO: 0000700327	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 26 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 3391	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 3.1 MI NE OF JCT RTE 4	YEAR BUILT: 1953	DECK CONDITION: 6 Satisfactory
BRDGNAME: WEBBER	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 4 Poor
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: REEDS MILL ROAD	STRUCTURE LENGTH IN FEET: 34	DATE OF INSPECTION: 4/17/2012
FEATURE UNDER: WHINSHIP (CONANT) ST	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 70.6
ROAD INV NO: 0000700327	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 14 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 3186	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: 50 FT N JCT RTE 4	YEAR BUILT: 1935	DECK CONDITION: 5 Fair
BRDGNAME: VILLAGE	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 4 Poor
FEATURE ON: REEDS MILL ROAD	STRUCTURE LENGTH IN FEET: 66	DATE OF INSPECTION: 4/17/2012
FEATURE UNDER: SANDY RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 57.3
ROAD INV NO: 0000700546	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 12 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 4 Poor
BRIDGE NO.: 2934	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 1.7 MI W OF PHILLIPS TL	YEAR BUILT: 1933	DECK CONDITION: 5 Fair
BRDGNAME: WEYMOUTH	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE 4	STRUCTURE LENGTH IN FEET: 49	DATE OF INSPECTION: 9/10/2012
FEATURE UNDER: SANDY RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 17.1
ROAD INV NO: 000000004X	POSTING TYPE: 0 None needed	
ROUTE NO: 00004		
ROAD WIDTH: 22 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 0422	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 0.9 NW RT 4	YEAR BUILT: 1979	DECK CONDITION: 5 Fair
BRDGNAME: HINCKLEY	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 4 Poor
FEATURE ON: BEECH RIDGE RD.	STRUCTURE LENGTH IN FEET: 40	DATE OF INSPECTION: 8/4/2011
FEATURE UNDER: SADDLEBACK STREAM	POSTING STATUS: 3 Posted	FEDERAL SUFFICIENCY RATING: 18.7
ROAD INV NO: 0000700575	POSTING TYPE: 1 Weight Limit	
ROUTE NO: 00000		
ROAD WIDTH: 12 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 0383	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 4 MI NW RTE 142	YEAR BUILT: 1996	DECK CONDITION: 6 Satisfactory
BRDGNAME: EAST MADRID	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 8 Very Good
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: EAST MADRID ROAD	STRUCTURE LENGTH IN FEET: 72	DATE OF INSPECTION: 8/3/2011
FEATURE UNDER: PERHAM STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 76.3
ROAD INV NO: 0000700323	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 14 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		