

## Structures in the Municipality of Mexico

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mexico"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="6325"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="CONNECTS RTE 17 TO 120"/>	<b>YEAR BUILT:</b> <input type="text" value="1974"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="HALE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="BLACK BRIDGE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="98"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/3/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="SWIFT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0001701066"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Mexico

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mexico"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="3877"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".4 MI S TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1970"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> MITCHELL	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="#17"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="17"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/2/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MITCHELL BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="85.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000017X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00017"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Mexico

### CONDITION RATINGS

<b>TOWN1:</b> Mexico	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 5 Fair
<b>BRIDGE NO.:</b> 3792	<b>BRIDGE REGION:</b> Western	<b>SUPERSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>LOCATION:</b> .2 MI EJCT US 2	<b>YEAR BUILT:</b> 1941	<b>DECK CONDITION:</b> 6 Satisfactory
<b>BRDGNAME:</b> ANDREW LANG	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 8 Very Good
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 6 Satisfactory
<b>FEATURE ON:</b> WHITMAN ST	<b>STRUCTURE LENGTH IN FEET:</b> 21	<b>DATE OF INSPECTION:</b> 10/17/2011
<b>FEATURE UNDER:</b> ABBOTT BROOK	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 66.1
<b>ROAD INV NO:</b> 0001702814	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 22 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		

## Structures in the Municipality of Mexico

### CONDITION RATINGS

<b>TOWN1:</b> Mexico	<b>TOWN2:</b> Dixfield	<b>SUBSTRUCTURE CONDITION:</b> 7 Good
<b>BRIDGE NO.:</b> 3326	<b>BRIDGE REGION:</b> Western	<b>SUPERSTRUCTURE CONDITION:</b> 8 Very Good
<b>LOCATION:</b> 0.4 MI W RT 142	<b>YEAR BUILT:</b> 2008	<b>DECK CONDITION:</b> 9 Excellent
<b>BRDGNAME:</b> THAD WHITE BRIDGE	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 7 Good
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 5 Truss	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 5 Fair
<b>FEATURE ON:</b> COBURN AVE	<b>STRUCTURE LENGTH IN FEET:</b> 95	<b>DATE OF INSPECTION:</b> 10/17/2011
<b>FEATURE UNDER:</b> WEBB RIVER	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 73.9
<b>ROAD INV NO:</b> 0001701524	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 14 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> LOW USE/REDUNDANT BRIDGE		

## Structures in the Municipality of Mexico

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mexico"/>	<b>TOWN2:</b> <input type="text" value="Dixfield"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2917"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>LOCATION:</b> <input type="text" value="DIXFIELD-MEXICO TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="2012"/>	<b>DECK CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>BRDGNAME:</b> <input type="text" value="WEBB RIVER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>FEATURE ON:</b> <input type="text" value="#2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="120"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="2/5/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="WEBB RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="66.9"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Peru

### CONDITION RATINGS

<b>TOWN1:</b> Peru	<b>TOWN2:</b> Mexico	<b>SUBSTRUCTURE CONDITION:</b> 5 Fair
<b>BRIDGE NO.:</b> 2019	<b>BRIDGE REGION:</b> Western	<b>SUPERSTRUCTURE CONDITION:</b> 4 Poor
<b>LOCATION:</b> 150 FT S'LY OF JCT US2	<b>YEAR BUILT:</b> 1930	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> ANDROSCOGGIN RIVER	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 6 Satisfactory
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 5 Truss	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 3	<b>APPROACH CONDITION:</b> 4 Poor
<b>FEATURE ON:</b> IN PERU = N. MAIN	<b>STRUCTURE LENGTH IN FEET:</b> 574	<b>DATE OF INSPECTION:</b> 8/9/2012
<b>FEATURE UNDER:</b> ANDROSCOGGIN RIVER	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 11.4
<b>ROAD INV NO:</b> 0001700416	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 22 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> BRIDGE ON STATE HIGHWAY		

## Structures in the Municipality of Rumford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Rumford"/>	<b>TOWN2:</b> <input type="text" value="Mexico"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3327"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="50 FT S of US 2"/>	<b>YEAR BUILT:</b> <input type="text" value="2000"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="VETERANS MEMORIAL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="RAILROAD STREET"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="426"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/28/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="ANDROSCOGGIN RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="81.4"/>
<b>ROAD INV NO:</b> <input type="text" value="0001702842"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="39"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Rumford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Rumford"/>	<b>TOWN2:</b> <input type="text" value="Mexico"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="2707"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI W JCT RTE 17"/>	<b>YEAR BUILT:</b> <input type="text" value="1952"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="RED"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="2 Girder - floor beam"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="US #2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="176"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="SWIFT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="43.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		