

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: Milo	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 3244	BRIDGE REGION: Eastern	SUPERSTRUCTURE CONDITION: 4 Poor
LOCATION: 1.2 MI NE OF JCT RTE 11	YEAR BUILT: 1936	DECK CONDITION: 5 Fair
BRDGNAME: PLEASANT RIVER	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 5 Truss	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 2	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: PLEASANT STREET	STRUCTURE LENGTH IN FEET: 309	DATE OF INSPECTION: 5/1/2012
FEATURE UNDER: PLEASANT RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 47.4
ROAD INV NO: 0002101244	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 22 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: <input type="text" value="Milo"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="2931"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="600 FT SW OF JCT RTE 11"/>	YEAR BUILT: <input type="text" value="1924"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="SECOND WEST OPENING"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="RTE 6&16"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="26"/>	DATE OF INSPECTION: <input type="text" value="6/27/2011"/>
FEATURE UNDER: <input type="text" value="SEBEC RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="69.2"/>
ROAD INV NO: <input type="text" value="000000006X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00006"/>		
ROAD WIDTH: <input type="text" value="30"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Milo"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="4"/> <input style="width: 60px;" type="text" value="Poor"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="2867"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="4"/> <input style="width: 60px;" type="text" value="Poor"/>
LOCATION: <input style="width: 130px;" type="text" value="0.3 MI NW OF S'LY JCT 11"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1926"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
BRDGNAME: <input style="width: 100px;" type="text" value="OLD TOLL"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="5"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
FEATURE ON: <input style="width: 100px;" type="text" value="ROUTES 6,11,&16"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="240"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="12/12/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="PISCATAQUIS RIVER"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 40px;" type="text" value="40"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000006X"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00006"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: Milo	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 2573	BRIDGE REGION: Eastern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 500' SW OF JCT RTE 11	YEAR BUILT: 1915	DECK CONDITION: 6 Satisfactory
BRDGNAME: MILO WEST OPENING	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 6 Arch	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: ROUTES 6 & 16	STRUCTURE LENGTH IN FEET: 70	DATE OF INSPECTION: 7/25/2012
FEATURE UNDER: SEBEC RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 47.8
ROAD INV NO: 000000006X	POSTING TYPE: 0 None needed	
ROUTE NO: 00006		
ROAD WIDTH: 30 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: <input type="text" value="Milo"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="2572"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="200' SW OF JCT RTE11"/>	YEAR BUILT: <input type="text" value="1915"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="EAST OPENING"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="6 Arch"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="ROUTE 16"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="70"/>	DATE OF INSPECTION: <input type="text" value="7/25/2012"/>
FEATURE UNDER: <input type="text" value="SEBEC RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="84.1"/>
ROAD INV NO: <input type="text" value="00000006X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00006"/>		
ROAD WIDTH: <input type="text" value="35"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: <input type="text" value="Milo"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="2124"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="750' SW OF JCT RTE 11"/>	YEAR BUILT: <input type="text" value="1931"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="CANAL"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="ROUTES 6 & 16"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="43"/>	DATE OF INSPECTION: <input type="text" value="7/25/2012"/>
FEATURE UNDER: <input type="text" value="SEBEC RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="53.8"/>
ROAD INV NO: <input type="text" value="000000006X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00006"/>		
ROAD WIDTH: <input type="text" value="30"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: <input type="text" value="Milo"/>	TOWN2: <input type="text" value="Sebec"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0965"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="2.0 MI W RIVERSIDE ON TL"/>	YEAR BUILT: <input type="text" value="1935"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="MEADOW"/>	SPAN MATERIAL: <input type="text" value="4 Stone"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="6 Arch"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="RIVER RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="10"/>	DATE OF INSPECTION: <input type="text" value="10/25/2012"/>
FEATURE UNDER: <input type="text" value="MEADOW BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="91.8"/>
ROAD INV NO: <input type="text" value="0002102071"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: Milo	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 0954	BRIDGE REGION: Eastern	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: .3 MI W RT 11	YEAR BUILT: 1935	DECK CONDITION: 5 Fair
BRDGNAME: ALDER BROOK	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: TW Desmond Road	STRUCTURE LENGTH IN FEET: 29	DATE OF INSPECTION: 7/19/2012
FEATURE UNDER: ALDER STREAM	POSTING STATUS: 3 Posted	FEDERAL SUFFICIENCY RATING: 35.2
ROAD INV NO: 0002101389	POSTING TYPE: 1 Weight Limit	
ROUTE NO: 00000		
ROAD WIDTH: 13 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Milo

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Milo"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0926"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
LOCATION: <input style="width: 130px;" type="text" value="1.2 MIE RTE 6&16"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1960"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
BRDGNAME: <input style="width: 100px;" type="text" value="STINKING BROOK"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="3 Slab"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
MAINTAINER: <input style="width: 80px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="4"/> <input style="width: 80px;" type="text" value="Poor"/>
FEATURE ON: <input style="width: 100px;" type="text" value="PADDY HILL RD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="12"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="10/25/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="STINKING BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="80.4"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0002100386"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE AID ROAD"/>		