

Structures in the Municipality of Rome

CONDITION RATINGS

TOWN1: Rome	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 8 Very Good
BRIDGE NO.: 6037	BRIDGE REGION: Mid-Coast	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 2.3 MI N TOWNLIN	YEAR BUILT: 1965	DECK CONDITION: 7 Good
BRDGNAME: BEAVER BROOK	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 7 Good
OWNER: 4 Municipal	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: WATSON POND RD	STRUCTURE LENGTH IN FEET: 38	DATE OF INSPECTION: 7/23/2012
FEATURE UNDER: BEAVER BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 92.3
ROAD INV NO: 0001102041	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 26 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Rome

CONDITION RATINGS

TOWN1: Rome	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5912	BRIDGE REGION: Mid-Coast	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 50' W OF BELGRADE TL	YEAR BUILT: 1985	DECK CONDITION: N Not Applicable
BRDGRNAME: NARROWS WEST	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 6 Satisfactory
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 2	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: CASTLE ISLAND RD	STRUCTURE LENGTH IN FEET: 34	DATE OF INSPECTION: 10/20/2011
FEATURE UNDER: LONG POND	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 99.3
ROAD INV NO: 0001102667	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Rome

CONDITION RATINGS

TOWN1: Rome	TOWN2: Smithfield	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5221	BRIDGE REGION: Mid-Coast	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 0.4 MI W OF ROUTES 8&137	YEAR BUILT: 2006	DECK CONDITION: N Not Applicable
BRDGNAME: UPPER	SPAN MATERIAL: 5 Aluminum	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 8 Very Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 8 Very Good
FEATURE ON: N PD / PINE TRE RD	STRUCTURE LENGTH IN FEET: 23	DATE OF INSPECTION: 4/5/2012
FEATURE UNDER: GREAT MEADOW STREA	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 100
ROAD INV NO: 0001100329	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Rome

CONDITION RATINGS

TOWN1: Rome	TOWN2: Smithfield	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 5071	BRIDGE REGION: Mid-Coast	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: 0.7 MI W OF ROUTES 8&137	YEAR BUILT: 1930	DECK CONDITION: 6 Satisfactory
BRDGNAME: MEADOW STREAM	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE 225	STRUCTURE LENGTH IN FEET: 28	DATE OF INSPECTION: 4/5/2012
FEATURE UNDER: GREAT MEADOW STREA	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 78.3
ROAD INV NO: 000000225X	POSTING TYPE: 0 None needed	
ROUTE NO: 00225		
ROAD WIDTH: 24 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		