

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 6169	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 1.3 MI N RTE 158 OP	YEAR BUILT: 1967	DECK CONDITION: N Not Applicable
BRDGNAME: I95 NB / MOLUS STREAM	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 7 Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 8 Very Good
FEATURE ON: I95 NORTHBOUND	STRUCTURE LENGTH IN FEET: 31	DATE OF INSPECTION: 5/1/2012
FEATURE UNDER: MOLUS STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 97.4
ROAD INV NO: 000000095X	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 6168	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: I-95 INTERCHANGE 264	YEAR BUILT: 1967	DECK CONDITION: 6 Satisfactory
BRDGNAME: I-95 NB / ROUTE 158	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: N Not Applicable
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: I-95 NORTHBOUND	STRUCTURE LENGTH IN FEET: 97	DATE OF INSPECTION: 8/23/2012
FEATURE UNDER: ROUTE 158	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 97
ROAD INV NO: 000000095X	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 39 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 6167	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 0.5 MI S OF OP RTE 158	YEAR BUILT: 1967	DECK CONDITION: 6 Satisfactory
BRDGNAME: I-95 NB/ BENEDICTA RD	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: N Not Applicable
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: I-95 NORTHBOUND	STRUCTURE LENGTH IN FEET: 176	DATE OF INSPECTION: 8/23/2012
FEATURE UNDER: BENEDICTA (AROOSTOO)	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 94.9
ROAD INV NO: 000000095X	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 39 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 3815	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 1.4 MI W JCT US 2	YEAR BUILT: 1921	DECK CONDITION: 6 Satisfactory
BRDGNAME: LOGAN	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 7 Rigid Frame	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 8 Very Good
FEATURE ON: 158	STRUCTURE LENGTH IN FEET: 20	DATE OF INSPECTION: 6/8/2011
FEATURE UNDER: LOGAN BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 59.9
ROAD INV NO: 000000158X	POSTING TYPE: 0 None needed	
ROUTE NO: 00158		
ROAD WIDTH: 30 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 2899	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 1.2 MI E I95	YEAR BUILT: 1949	DECK CONDITION: 6 Satisfactory
BRDGNAME: VILLAGE	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: ROUTE 158	STRUCTURE LENGTH IN FEET: 32	DATE OF INSPECTION: 10/31/2012
FEATURE UNDER: MOLUS STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 74
ROAD INV NO: 000000158X	POSTING TYPE: 0 None needed	
ROUTE NO: 00158		
ROAD WIDTH: 26 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 1407	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 0.5 MI S OF OP RTE 158	YEAR BUILT: 1967	DECK CONDITION: 6 Satisfactory
BRDGNAME: I95 SB / BENEDICTA RD	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: N Not Applicable
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: I-95 SOUTHBOUND	STRUCTURE LENGTH IN FEET: 176	DATE OF INSPECTION: 8/23/2012
FEATURE UNDER: BENEDICTA (AROOSTOO)	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 94.9
ROAD INV NO: 000000095S	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 39 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 1406	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: I-95 INTERCHANGE 264	YEAR BUILT: 1967	DECK CONDITION: 6 Satisfactory
BRDGNAME: I95 SB / ROUTE 158	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: N Not Applicable
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: I-95 SOUTHBOUND	STRUCTURE LENGTH IN FEET: 97	DATE OF INSPECTION: 8/23/2012
FEATURE UNDER: ROUTE 158	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 97
ROAD INV NO: 000000095S	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 39 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Sherman

CONDITION RATINGS

TOWN1: Sherman	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 1405	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 1.3 MI N OF RTE 158 OP	YEAR BUILT: 1978	DECK CONDITION: N Not Applicable
BRDGNAME: I95 SB / MOLUS STREAM	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 8 Very Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 8 Very Good
FEATURE ON: I95 SOUTHBOUND	STRUCTURE LENGTH IN FEET: 29	DATE OF INSPECTION: 5/1/2012
FEATURE UNDER: MOLUS STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 97.3
ROAD INV NO: 000000095S	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		