

Structures in the Municipality of Sweden

CONDITION RATINGS

TOWN1: Sweden	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 8 Very Good
BRIDGE NO.: 6105	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 1.6 MI W OF WATERFORD	YEAR BUILT: 1967	DECK CONDITION: 7 Good
BRDGNAME: BLACK POND BROOK	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 7 Rigid Frame	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: WATERFORD ROAD	STRUCTURE LENGTH IN FEET: 23	DATE OF INSPECTION: 7/20/2011
FEATURE UNDER: BLACK POND BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 97.8
ROAD INV NO: 0001700756	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 28 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Sweden

CONDITION RATINGS

TOWN1: Sweden	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 8 Very Good
BRIDGE NO.: 6104	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 1.5 MI W'LY OF WATERFORD	YEAR BUILT: 1967	DECK CONDITION: 7 Good
BRDGNAME: DUCK POND BROOK	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: WATERFORD ROAD	STRUCTURE LENGTH IN FEET: 25	DATE OF INSPECTION: 7/20/2011
FEATURE UNDER: DUCK POND BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 96.8
ROAD INV NO: 0001700756	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 28 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Sweden

CONDITION RATINGS

TOWN1: Sweden	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 0733	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 1 MI E RT 93	YEAR BUILT: 1981	DECK CONDITION: N Not Applicable
BRDGNAME: DEFT ROAD	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 4 Municipal	SPAN TYPE: 6 Arch	CULVERT CONDITION: 7 Good
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: DEFT ROAD	STRUCTURE LENGTH IN FEET: 17	DATE OF INSPECTION: 5/11/2011
FEATURE UNDER: DUCK POND BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 92.7
ROAD INV NO: 0001700780	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON TOWN WAY		

Structures in the Municipality of Sweden

CONDITION RATINGS

TOWN1: Sweden	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 0732	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 1.0 MI. E. RTE 93	YEAR BUILT: 1924	DECK CONDITION: 7 Good
BRDGNAME: STEARNS POND OUTLET	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 4 Poor
FEATURE ON: TRULL BROOK RD	STRUCTURE LENGTH IN FEET: 22	DATE OF INSPECTION: 5/11/2011
FEATURE UNDER: STEARNS POND OUTLET	POSTING STATUS: 3 Posted	FEDERAL SUFFICIENCY RATING: 51
ROAD INV NO: 0001700774	POSTING TYPE: 1 Weight Limit	
ROUTE NO: 00000		
ROAD WIDTH: 11 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON TOWN WAY		