

Structures in the Municipality of Vanceboro

CONDITION RATINGS

TOWN1: Vanceboro	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 8 Very Good
BRIDGE NO.: 2401	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: AT US-CANADA BORDER	YEAR BUILT: 1997	DECK CONDITION: 7 Good
BRDGNAME: INTERNATIONAL	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE 6	STRUCTURE LENGTH IN FEET: 125	DATE OF INSPECTION: 6/13/2011
FEATURE UNDER: SAINT CROIX RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 98.6
ROAD INV NO: 000000006X	POSTING TYPE: 0 None needed	
ROUTE NO: 00006		
ROAD WIDTH: 36 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		