## **Seawater Access System Photo Log**



Photo 1: Upland route looking east over the "horseback" roadway zone at the Eckrote property



**Photo 2:** Intertidal mud flats from the Eckrote property shore.



**Photo 3:** Example of a narrow sheet pile structure with struts to suit this type of work.



**Photo 4:** Example of a shoreline coffer cell and excavator on the mudflats.



**Photo 5:** Example of a spud barge with crane, clamshell suited for this work.