

Structures in the Municipality of Marion Twp

CONDITION RATINGS

| | | |
|--|-------------------------------------|---|
| TOWN1: Marion Twp | TOWN2: No town 2 | SUBSTRUCTURE CONDITION: N Not Applicable |
| BRIDGE NO.: 5223 | BRIDGE REGION: Eastern | SUPERSTRUCTURE CONDITION: N Not Applicable |
| LOCATION: 3 MILES W OF TOWN LINE | YEAR BUILT: 1991 | DECK CONDITION: N Not Applicable |
| BRDGNAME: CLIFFORD | SPAN MATERIAL: 1 Steel | CHANNEL CONDITION: 6 Satisfactory |
| OWNER: 1 State DOT | SPAN TYPE: 4 Culvert | CULVERT CONDITION: 6 Satisfactory |
| MAINTAINER: 1 State DOT | NUMBER OF MAIN SPANS: 2 | APPROACH CONDITION: 7 Good |
| FEATURE ON: ROUTE 86 | STRUCTURE LENGTH IN FEET: 13 | DATE OF INSPECTION: 4/13/2011 |
| FEATURE UNDER: CLIFFORD STREAM | POSTING STATUS: 1 Open | FEDERAL SUFFICIENCY RATING: 99.2 |
| ROAD INV NO: 000000086X | POSTING TYPE: 0 None needed | |
| ROUTE NO: 00086 | | |
| ROAD WIDTH: 0 FEET | FEDERAL BRIDGE INDICATOR: N | |
| CLASS: MINOR SPAN ON STATE AID ROAD | | |

Structures in the Municipality of Marion Twp

CONDITION RATINGS

| | | |
|--|------------------------------------|---|
| TOWN1: Marion Twp | TOWN2: No town 2 | SUBSTRUCTURE CONDITION: N Not Applicable |
| BRIDGE NO.: 3140 | BRIDGE REGION: Eastern | SUPERSTRUCTURE CONDITION: N Not Applicable |
| LOCATION: 1.9 MI E ROUTE 191 | YEAR BUILT: 1951 | DECK CONDITION: N Not Applicable |
| BRDGNAME: PATRICK BROOK | SPAN MATERIAL: 1 Steel | CHANNEL CONDITION: 2 Critical |
| OWNER: 1 State DOT | SPAN TYPE: 4 Culvert | CULVERT CONDITION: 8 Very Good |
| MAINTAINER: 1 State DOT | NUMBER OF MAIN SPANS: 1 | APPROACH CONDITION: 5 Fair |
| FEATURE ON: 86 SA 1 | STRUCTURE LENGTH IN FEET: 8 | DATE OF INSPECTION: 10/3/2012 |
| FEATURE UNDER: PATRICK LAKE OUTLET | POSTING STATUS: 1 Open | FEDERAL SUFFICIENCY RATING: 95.1 |
| ROAD INV NO: 000000086X | POSTING TYPE: 0 None needed | |
| ROUTE NO: 00086 | | |
| ROAD WIDTH: 0 FEET | FEDERAL BRIDGE INDICATOR: N | |
| CLASS: MINOR SPAN ON STATE AID ROAD | | |

Structures in the Municipality of Marion Twp

CONDITION RATINGS

| | | |
|--|-------------------------------------|---|
| TOWN1: Marion Twp | TOWN2: No town 2 | SUBSTRUCTURE CONDITION: N Not Applicable |
| BRIDGE NO.: 1164 | BRIDGE REGION: Eastern | SUPERSTRUCTURE CONDITION: N Not Applicable |
| LOCATION: 2.5 MI E RT 191 | YEAR BUILT: 2006 | DECK CONDITION: N Not Applicable |
| BRDGNAME: ROCKY BROOK | SPAN MATERIAL: 1 Steel | CHANNEL CONDITION: 7 Good |
| OWNER: 1 State DOT | SPAN TYPE: 4 Culvert | CULVERT CONDITION: 7 Good |
| MAINTAINER: 1 State DOT | NUMBER OF MAIN SPANS: 1 | APPROACH CONDITION: 7 Good |
| FEATURE ON: RTE 86 | STRUCTURE LENGTH IN FEET: 11 | DATE OF INSPECTION: 10/3/2012 |
| FEATURE UNDER: ROCKY BROOK | POSTING STATUS: 1 Open | FEDERAL SUFFICIENCY RATING: 99.2 |
| ROAD INV NO: 000000086X | POSTING TYPE: 0 None needed | |
| ROUTE NO: 00086 | | |
| ROAD WIDTH: 0 FEET | FEDERAL BRIDGE INDICATOR: N | |
| CLASS: MINOR SPAN ON STATE AID ROAD | | |