

Northeast

East

Southeast



Eaton house

Gerrish house

House on other side of Samoset Road

Smalley House

Dessication fractures in clay

Arcuate head of slide

Headwall scarp

Fallen debris among jumbled blocks

Shrubs, rotated backward

Tree rotated forward

Trees rotated backward

Owls Head

Bedrock outcrop at adjacent point

Transported upright trees

Scar from older slide (1995)

Edge of 1996 slide

turf

Block top

Face of block

Block top

Block (behind shrub)

Minor scarp on face of large block

Block top

Minor scarp

Ridge of pushed-up clay

Foot of slide. Rubby rocks in fluidized clay

Grooves, caused by turf sliding off

Top of large block with turf removed