REPORT ON PRELIMINARY ENVIRONMENTAL ASSESSMENT MONTREAL, MAINE & ATLANTIC RAIL LINE PROJECT PENOBSCOT AND AROOSTOOK COUNTIES, MAINE PIN 17643

by

Haley & Aldrich, Inc. Portland, Maine

for

Maine Department of Transportation Augusta, Maine

File No. 37156-000 10 June 2010



Haley & Aldrich, Inc. 75 Washington Avenue Suite 203 Portland, ME 04101-2617

> Tel: 207.482.4600 Fax: 207.775.7666 HaleyAldrich.com



10 June 2010 File No. 37156-000

Maine Department of Transportation 16 State House Station Augusta, Maine 04333-0016

Attention: Mr. Dwight Doughty, Jr., C.G.

Subject: Preliminary Environmental Assessment

Montreal, Maine & Atlantic Rail Line Project Penobscot and Aroostook Counties, Maine

PIN 17643

Ladies and Gentlemen:

This report summarizes the results of a preliminary environmental assessment (PEA) associated with the acquisition of a portion of the Montreal, Maine & Atlantic (MMA) Railroad located in northern Penobscot and Aroostook Counties, Maine. The portion of the MMA being considered for acquisition consists of the approximately 233-mile stretch of rail line right-of-way (ROW) comprised of the 151-mile main line, and four subdivisions totaling approximately 82 miles in length. The purpose of this PEA is to evaluate existing conditions related to the presence of petroleum products and hazardous material and to assist in identifying potential environmental liabilities within the ROW. We understand that the Maine Department of Transportation (Maine DOT) may acquire this rail line from the MMA Railway for the continuation of the use of the rail line for freight traffic.

The work completed for this PEA consisted of the following work scope items:

- review of readily available information on history and usage of the rail line that included reviewing valuation section maps provided by the Maine DOT;
- review of available (online) aerial photographs of the project area;
- review of available state and federal databases for known and potential areas of environmental concern in the rail line corridors;
- review of available Maine Department of Environmental Protection (Maine DEP) electronic files and records related to sites associated with the use of petroleum products and hazardous materials within the project vicinity.

This work was performed in accordance with our proposal to the Maine DOT dated 10 May 2010 authorized on 14 May 2010.

RAIL LINE LOCATIONS AND DESCRIPTIONS

The major section of the rail line ROW for the project is approximately 151 miles in length, extending in a generally northerly direction from Grindstone to Frenchville. The portion of the main line from Grindstone to Sherman Station is located in Penobscot County. North of Sherman Station the rail line enters Aroostook County. The majority of the main line, and all four subdivisions, are located in Aroostook County. Figure 1, Project Alignment, shows the extent of the locations of the main line and each of the four subdivisions.

The Houlton subdivision (Figure 2) begins in Oakfield and extends east to Houlton where it turns sharply toward the north and terminates after a short distance. The Presque Isle subdivision (Figure 3) begins at Squa Pan and extends east toward Presque Isle, where the rail line splits into a north-south junction. The southern rail line ROW at this junction constitutes the Fort Fairfield subdivision (Figure 4), which extends southeast from Presque Isle and turns in a northeasterly direction toward Easton. This line continues toward Fort Fairfield. However, the section between Easton and Fort Fairfield is not considered to be part of the rail line ROW associated with this PEA. The northern rail line at the junction in Presque Isle constitutes the Limestone subdivision (Figure 5), extending north toward Caribou. This subdivision continues northeast toward Limestone but the 15-mile segment from Caribou to Limestone is no longer in use and was not investigated as part of this assessment. A summary of the provided valuation maps identifying mile post designations and corresponding towns for the main line and each of the four subdivisions is included on Table I, Summary of Valuation Maps.

The main line segment is approximately 151 miles long and extends north from Grindstone to Frenchville. The location of the line is shown on Figure 1, Project Alignment. For discussion purposes, locations along the alignment are referred to by their milepost (MP) designation (see Table I).

The relevant portion of the line begins just south of Grindstone (MP 109) on the east side of the Penobscot River and extends in a northeasterly direction, mostly through undeveloped, heavily forested areas, and passes over numerous streams and rivers including the Penobscot and Mattawamkeag rivers. It passes through the towns or townships of Grindstone (MP 114), Stacyville (MP 125), Sherman (MP 129), Island Falls (MP 140), Dyer Brook (MP 147), and Oakfield (MP 149) where there is a large siding area utilized as a rail line switching yard. The Houlton subdivision begins on the Oakfield station grounds (MP H0.0) and extends in an easterly direction (see Figure 1).

The main line continues in a northwesterly direction through mostly undeveloped, wooded land. It passes through Smyrna Mills (MP 151) before entering an approximately 30-mile stretch of undeveloped, forested areas, traversing the west side of the Mattawamkeag River and the east side of St. Croix Lake and the St. Croix Stream. The main line continues north through the town of Masardis (MP 181) and Squa Pan (MP 185), where the Presque Isle subdivision begins (MP P0.0), branching towards the east (see Figure 1).

The main line continues in a northwesterly direction through Ashland (MP 181) and runs along the eastern edge of Portage Lake and through the town of Portage (MP 203). At this location the main line enters an undeveloped stretch, extending along the east side of Nadeau Lake. The line passes through the towns of Eagle Lake (MP 227) and Wallagrass (MP 232), continuing through Fort Kent and turning sharply east through Frenchville (MP 255). The relevant portion of the line



terminates a short distance north of Frenchville and approximately ½ mile south of Madawaska at MP 260 (see Figure 1).

■ The Houlton subdivision is approximately 17 miles long and extends in an easterly direction from Oakfield to Houlton. The location of this subdivision is shown on Figure 2, Houlton Subdivision. Locations along this subdivision alignment are referred to by their milepost (MP H) designation (see Table 1).

The Houlton subdivision begins in Oakfield (MP H0.0) and extends northeast, south of and parallel to Interstate 95. The subdivision rail line turns southeast just before Route 2 at MP H5.7, and heads in a southeasterly direction through farm land and wooded areas through the northern portion of New Limerick (MP H10.5). The rail line then extends northeast through more wooded areas and farmland before entering Houlton (MP 17) and terminating.

■ The Presque Isle subdivision is approximately 25 miles long and extends in an easterly direction from the main line at Squa Pan to Presque Isle. The location of the line is shown on Figure 3, Presque Isle Subdivision. Locations along this subdivision alignment are referred to by their milepost (MP P) designation (see Table 1).

The Presque Isle subdivision begins in Squa Pan (MP P0.0) and extends in an easterly direction through wooded areas around Squa Pan Lake. This subdivision then continues in a northeasterly direction through forest and farm land before passing through Mapleton (MP P18.0). This subdivision continues through mostly farm land and crosses Presque Isle Stream into Presque Isle (MP 25.0). At this location the track comes to a north-south junction, north toward Limestone, and south toward Fort Fairfield.

The relevant portion of the Fort Fairfield subdivision is approximately 10 miles long and extends southward from Presque Isle to Easton. The location of this subdivision is shown on Figure 4, Fort Fairfield Subdivision. Locations along this subdivision alignment are referred to by their milepost (MP F) designation (see Table 1).

The Fort Fairfield subdivision begins in Presque Isle (MP F1.0) and extends in a southerly direction, traversing primarily farm land. At the town of Phair (MP F5.1), the line branches to the east through more farm land and then turns northeast. The line passes through Easton (MP F9.2) and continues in an easterly direction for a short distance before reaching the end of the designated section of the Fort Fairfield subdivision at MP F10.0.

■ The relevant portion of the Limestone subdivision is approximately 15 miles and extends northward from Presque Isle to Caribou. The location of the line is shown on Figure 5, Limestone Subdivision. Locations along this subdivision alignment are referred to by their milepost (MP L) designation (see Table 1).

The Limestone subdivision begins in Presque Isle (MP L0.0) and extends north, parallel to the west bank of the Aroostook River. The line passes primarily through farm land and occasional wooded areas. The subdivision crosses Fort Street (MP L14.5) and enters Caribou. The line passes through Caribou and splits at MP L15. One line diverts northwest and, according to the valuation map for this section (V-2s/1, updated 1979), is no longer in use. The other line, which



Maine Department of Transportation 10 June 2010 Page 4

constitutes the northern portion of the Limestone subdivision and is also not in use, continues along the Aroostook River toward the town of Limestone.

Rail Line Sidings

Valuation section maps provided by Maine DOT identified numerous railroad siding areas included within the rail line ROW. Siding areas include locations along the rail line typically used for railroad operations and/or storage potentially related to petroleum products and hazardous materials. Typically these areas would be observed during a site reconnaissance. However, due to the extensive nature of the rail line and limited scope associated with this PEA, a reconnaissance of the numerous siding areas was not completed as part of the project work scope. In addition, information associated with the past use and current conditions of the sidings is limited due to the historical nature of the maps, most of which were composed between 1914 and 1916.

A list of sidings as they appear on the valuation maps, including their relative locations, is provided in Table I.

REGULATORY REVIEW - EDR DATABASE REPORTS

Haley & Aldrich used the electronic database service Environmental Data Resources, Inc. (EDR) to complete the environmental records review using Radius Map reports. The database search was used to identify properties that were listed in the referenced agency records located within the vicinity of the rail line ROW in nine selected locations: Sherman Station, Oakfield, Ashland, Portage, Fort Kent, New Limerick, Presque Isle, Easton and Caribou. The locations were chosen based on their likelihood of posing a potential environmental risk related to the use, storage, and release of petroleum products and hazardous materials on or near the rail line ROW. The resulting reports encompass some of the denser residential areas along the ROW as well as several large industrial and agricultural facilities. Table II contains a summary of the findings in the Radius Map reports dated 21, 24 and 26 May 2010.

Haley & Aldrich also searched the Orphan Site List provided in the EDR report for the rail line ROW and sites in the vicinity of the main line and subdivisions. Orphan sites are those that, due to incorrect or incomplete addresses, could not be mapped.

Due to the volume of the Radius Map reports it was not practical to include them with this document. The executive summary of each report, which includes a summary of the contents and a map indicating the location of sites within the search area, is included in Appendix A. The complete Radius Map reports will be retained in Haley & Aldrich files and will be provided upon request.

A summary of pertinent environmental listings identified in the vicinity of the rail line ROW is presented below. The potential risk for each of the listings is identified based on an assessment of the information included in the database report. The actual risk associated with the listings could be better assessed with the completion of a site reconnaissance to view existing conditions.



Main Line

Sherman Station

- There are three orphan sites associated with Sherman Lumber Company: a SPILLS site, reported in 1999, involving approximately 100 gallons of oil; a UST; and a LUST. The LUST, reported in 1997, leaked approximately 100 gallons of oil. It is catalogued in the Maine DEP database under spill report #I-189-1997. The LUST listing is associated with the one of the USTs, identified in the database as utilizing three tanks. All three tanks, totaling a volume of 15,000 gallons, were removed in 1997. Both spill sites were remediated by excavation activities and the contaminated material was reportedly disposed at an off-site location. All three of these sites were less than 1/8 of a mile from the track. Potential impacts to the rail line ROW could not be determined.
- One orphan site is associated with Wheelabrator-Sherman Energy, a company with a facility on Sherman Lumber Company Road. This facility is identified as an AST site with numerous tanks containing HCl, NaOH and oil. Due to the number of tanks, all apparently still active, and their contents, there is the potential that the storage and use of these ASTs may have resulted in past spills or releases to the ground surface.

Oakfield Yard – Oakfield

There are four orphan sites around the Oakfield area. Three AST sites and one LAST site are all associated with Daigle Oil, which is identified as being located on River Road. The rail line crosses River Road at one location but does not run adjacent to it for any length of time. There were no other reports of the use, storage, or release of petroleum products and hazardous materials identified in the database report associated with the Oakfield yard.

Ashland

- There are four orphan sites south of Ashland associated with the J Paul Levesque & Sons lumber company. The company is headquartered in Ashland and they have a plant/yard south of Ashland in Masardis. At this plant the database report identifies two AST sites and one SWF/LF site. Additionally the facility is registered with FINDS. Due to the facility's proximity to the railway ROW, there is potential for spills, leaks, or releases from the ASTs and the listed landfill facility to impact subsurface conditions beneath the rail line in this area.
- An orphan site listing in Masardis is associated with Fraser Paper, whose address is on Levesque Mill Road. The site is listed in the RCRA-SQG database, associated with the use and storage of small quantities of hazardous material.here are two listed orphan sites in Ashland, both associated with oil distribution facilities located on Station Street. One site, an AST, belongs to Daigle Oil Company. The other is a LAST site associated with Dead River Oil Company. The LAST site, identified as Maine DEP spill #I-173-1983, represents a release of 458 gallons of oil. However, it appears that the spill occurred far



enough from the ROW that it does not likely represent a significant environmental threat to subsurface conditions beneath the ROW.

There are seven orphan sites to the north of Ashland at a location called Nashville Plantation, which includes a large lumber yard and sawmill. These seven sites are split between the Ashland and Portage EDR Radius Map reports. One site, an AST, was formerly utilized by Great Northern Paper Company but is currently operated by Irving Forest Products. Irving has three sites listed at this facility (called Pinkham Sawmill): two RCRA-CESOG sites, with no violations listed, and one LAST, Maine DEP spill #I-198-2007. This spill report summarizes a release, involving approximately 20 gallons of oil, that was remediated by excavation activities. Additionally, there are three sites listed under Pinkham Lumber, which may be another reference to Great Northern's Pinkham Sawmill. There are two SPILLS sites listed. Maine DEP spill #I-133-1998 and #I-98-1998 both involved 50 gallons of oil and were removed by excavation. One LUST site (spill #I-132-1998) involved 66 gallons of oil and was remediated by excavation operations. Because this facility is immediately adjacent to the railroad in an isolated, undeveloped area and a river runs on the opposite side of the track, there is the potential that spills or releases associated with this facility may impact subsurface conditions beneath the rail line ROW.

■ Fort Kent

- The database report for Fort Kent identifies a SPILLS site associated with the Bangor & Aroostook Railroad at their yard on Dube St in Fort Kent. The spills, nos. I-49-2001 and I-241-1998, involved 5 gallons of oil each due to storm damage and overfill, respectively. Both spills were removed using sorbents.
- There is one orphan site in this listing, belonging to MMA. It is a SPILLS site, identified as Maine DEP spill I-74-2007, located on a crossing over State Route 161. The spill involved 10 gallons of oil as a result of a mechanical failure, and was remediated by excavation activities.

Houlton Subdivision

New Limerick

The Louisiana Pacific facility in New Limerick has four associated SPILLS sites and one associated LUST site. The database information indicates the release of various quantities of fuel oil at the facility, totaling approximately 475 gallons, between 2003 and the present. There is also one UST site and one AST site (most likely multiple tanks, combined into one entry) at the facility. The facility is a UIC site and is registered in the FINDS database. Because of the facility's proximity to the ROW and its association with spills involving, in addition to oil, hazardous chemicals such as phenol formaldehyde, there is the potential that releases from this facility may impact the rail line ROW.



Presque Isle Subdivision

Presque Isle

- There were three Brownfield sites located in proximity to the rail line ROW in Presque Isle. Haines Manufacturing Company, the Lavway Property, and Webber Oil are identified as the Brownfield sites listed in the database report located at 28, 36, and 42 Chapman Road, respectively. According to the EDR reports, each of these Brownfield sites still contains the qualifier: "remediation needed." This area was previously used as a rail line spur off the Bangor & Aroostook Railroad, and prior to that it was occupied by a chemical plan. Potential impacts to the rail line ROW associated with past uses of this area would require additional assessment including subsurface investigations.
- A LAST site (Maine DEP spill #I-171-1999) is listed in the database report as involving approximately 90 gallons of release from a tank registered to Jim Mosher at 17 South Street. The release was remediated with excavation activities. There is no registered AST listing accompanying this site, but it can be assumed that, because of its residential use, the tank is relatively small and is unlikely to pose a significant environmental risk.
- There is one UST site listed in the database report near the ROW. A 500-gallon tank was registered to Maurice's Barber Shop at 4A Blake Street. It was removed in 1994.
- There is an ALLSITES site associated with the Bangor & Aroostook Railroad engine house at 25 Dyer Street. The site has been designated by the Bureau of Remediation and Waste Management (BRWM) as needing no further action.

Fort Fairfield Subdivision

Easton

- Between orphan and listed sites there are approximately 58 SPILLS sites and LAST sites (please see Table 2 for a full list of each individual event), all registered at 333 Station Road to either J.M. Huber Corporation or Huber Engineered Woods (a subset of J.M. Huber). The volume of the released product totals approximately 5,200 gallons. All but approximately 310 gallons have been spilled between 2001 and the present. The Huber Engineered Woods facility is also listed as a RCRA-CESQG site, a SWF/LF and it is registered in the FINDS database. The J.M. Huber/Huber Engineered Woods facility in Easton straddles the ROW at MP 9.2. Therefore there is the potential that spills or releases may have impacted subsurface conditions beneath the ROW in this vicinity.
- There is one ALLSITES listing associated with Vahlsing Warehouse on Station Road.
 The database indicates that an investigation is still needed.
- The McCain Foods facility is listed in the NPDES database, associated with handling of liquid waste.

Limestone Subdivision



Caribou

- There are six sites listed in the database report that are registered to Caribou utilities facilities: two NPDES sites associated with the Caribou Utilities District; one UST site and one AST site associated with the Caribou Steam & Diesel Station; and one AST site, one UST site, and a FINDS listing associated with the Caribou Generating Station. Due to the locations of these listings it is unlikely that spills or releases from this facilities would impact the rail line ROW.
- There are two listed sites, a SPILLS site and a NPDES site, associated with the WPS New England Generation Company. The SPILLS site involved only 1 gallon of oil and did not likely impact the ROW.
- The database report identifies a LAST site (Maine DEP spill #I-45-1995) related to the release of approximately 82.5 gallons of oil from the L.B. Carter bulk plant located on River Road. The oil was removed using excavation operations.
- Maine Paper Company is a listed RCRA-NonGen site. This facility is also included in the FINDS database.
- A UST site identifies S.W. Cole Engineering as having had one UST in close proximity to the rail line. The 500 gallon tank was removed in 1990.

REGULATORY REVIEW - MAINE DEP DATABASE

Haley & Aldrich also used a database provided by the Maine Department of Environmental Protection (Maine DEP) which pinpoints locations of LASTs, LUSTs, ASTs, and USTs on Google Earth and provides links to their respective reports. This database search was used to cross-check information with the EDR reports and to gather spill and leak data from locations that did not warrant a full 1-mile radius report; i.e., very small settlements, lumber yards, or undeveloped areas (which constitute most of the ROW). Additionally this database was used to find sites that the EDR reports may have missed within their 1-mile radius searches. The data locations below were chosen based on their likelihood of posing a substantial environmental risk on or near the ROW. Please refer to Table III for more detailed summaries of individual spill events, and to Table IV for a list of tanks.

Main Line

- In 2006 there was an approximately 100 gallon spill in an undeveloped area in Grindstone (MP 113). The spill, #B-229-2006, was associated with a MMA Railroad wrecking crane which was leaking fuel. The leak went unnoticed until Grindstone and the extent of the release remains unknown. Therefore the spill was deemed unrecoverable and no action was taken to remediate it.
- An approximately 350 gallon spill associated with the B&A Railroad occurred in undeveloped woodland in T2 R9 WELS between Grindstone and Stacyville. The DEP spill report (#B-721-1999) refers to it as an accident and gives no further explanation. The spill was remediated by excavation activities.



- Two spills identified in the DEP database occurred in Oakfield in 1994 (#I-94-1994 and #I-75-1994). Both were associated with the B&A Railroad and occurred in the Oakfield rail yard area. I-94-1994 involved approximately 500 gallons of oil while I-75-1994 involved approximately 100 gallons. Both spills were remediated by excavation activities.
- Due to an AST accident, approximately 538 gallons were spilled on the property of Robinson's Market in Masardis near the ROW. The spill, summarized in report #I-6-1996, was remediated by excavation activities.
- Two spills were recorded in Ashland. The first listed spill, #I-44-1996, involved 50 gallons of oil from a leaking UST site associated with Antonio Levesque & Sons. The release was remediated using carbon filtration. The other spill, #I-73-1988, was associated with Great Northern Paper and involved 10 gallons of oil. It was remediated by excavation activities.
- There were three spills recorded in the Nashville Plantation area in addition to those referenced by EDR. Spill #I-73-2001 was associated with Irving Forest Products and involved 400 gallons of non-hazardous paint, which was burned. The remaining two spills (#I-88-1994 and #I-132-1998) were associated with UST sites occupied by Pinkham Lumber, and combined involved approximately 95 gallons of oil, 75 gallons of which were removed by excavation. No action was taken to remove the other 20 gallons.
- Due to pipe corrosion, a 30 gallon spill (#I-238-2004) occurred near the rail line ROW in Portage.
 The spill was associated with Maine Woods Company and was removed using sorbents.
- There was a 5 gallon spill (#I-58-1994) associated with the B&A Railroad in Wallagrass. Because of the size of the spill no treatment was required.
- Three listed spills occurred in Fort Kent along the ROW. Two of the listings (#I-67-1994 and #I-12-2008) were associated with Daigle Oil Company and, combined, involved the release of 300 gallons of oil. The other spill (#I-21-2001) was associated with Dead River Company and involved 10 gallons. All three spills were remediated by excavation activities.
- In this database there are a total of 12 registered USTs in the Fort Kent and Frenchville areas along the ROW. Together they total 126,000 gallons in capacity. Five are associated with gas stations, one with the Daigle Oil bulk plant, and one with the Maine DOT.

Houlton Subdivision

- There were two spill reports associated with the Louisiana Pacific facility in New Limerick in addition to those referenced in the EDR report. I-217-2004 involved a release of 1,100 gallons of Phenol Formaldehyde resin, cleaned by sorbents and burning. I-163-200 involved 25 gallons of oil and was cleaned by burning.
- There was one spill in Houlton, associated with Vernon and Gladys Spooner and involving 100 gallons of oil. It was cleaned by excavation



Presque Isle Subdivision

- There was a spill in Mapleton, associated with Neal Buck, involving a release of 200 gallons due to an AST failure. The spill (#I-31-2001) was cleaned using sorbents and excavation operations.
- Three recorded spills occurred in Presque Isle, totaling 170 gallons of product. These spills were associated with Richard Thompkins (spill #I-233-2003), McCain Foods (spill #I-168-2000), and Ferris Oil Company (spill #I-4-1995), and all three releases were remediated by excavation activities.

Fort Fairfield Subdivision

Four spills were listed in the DEP database in the vicinity of the rail line ROW in Easton in addition to those referenced by EDR. One listed spill (#I-151-2000) was associated with J.M. Huber, and involved 50 gallons of product released due to a ruptured hydraulic hose. That was cleaned using sorbents. Spill #I-238-1998 was associated with McCain Foods and involved the release of 841 gallons of ammonia into the atmosphere due to an equipment failure. The remaining two spills (#I-1-1995 and #I-90-1995) were associated with releases of fuel oil and, combined, totaled 1,000 gallons. In both release incidents excavation activities were used as the remediation method.

Limestone Subdivision

Four spills occurred on or near the rail line ROW in Caribou. One spill (#I-168-2005) was due to tank leakage and involved 300 gallons of released product. It was remediated by excavation activities. Another listed spill (#I-54-1994) involved 55 gallons of oil associated with Al Cyr. No method of remediation was used. The remaining listed spill involved the release of approximately 1,250 gallons of fuel oil and was associated with L.B. Carter Company. The cause of the release was unknown and it was reportedly remediated by excavation and pumps.

SUMMARY AND CONCLUSIONS

Haley & Aldrich performed a preliminary environmental assessment (PEA) associated with an approximately 233-mile stretch of rail line right-of-way (ROW) comprised of the 151-mile main line between Grindstone and Frenchville and four subdivisions: the 17-mile Houlton subdivision, extending from Oakfield to Houlton; the 25-mile Presque Isle subdivision, extending from Squa Pan to Presque Isle; a 10-mile segment of the Fort Fairfield subdivision, extending from Presque Isle to Easton; and a 15-mile segment of the Limestone subdivision, extending from Presque Isle to Caribou.

The purpose of the PEA was to preliminarily evaluate existing conditions related to the presence of petroleum products and hazardous material to assist in identifying potential environmental liabilities within the rail line ROW. The work completed for this PEA consisted of railway valuation maps, satellite imagery of the rail line and vicinity, and a review of environmental records and files associated with the use, storage, and release of oil and hazardous material. This work was performed by Haley & Aldrich in accordance with our proposal dated 10 May 2010.



Maine Department of Transportation 10 June 2010 Page 11

The project alignment consists of approximately 218 linear miles of active rail line ROW that includes numerous rail line siding areas. The alignment is currently used for freight rail related operations by the Montreal, Maine & Atlantic Railway. The majority of the alignment traverses undeveloped property consisting of fields and wooded areas, with the exception of the northern portion of the main line, which passes through Fort Kent, and areas of Presque Isle and Houlton, which are included in those respective rail line subdivisions.

Based on the available database listings and DEP Spill reports, numerous documented spill incidents, mostly petroleum product related to leaking AST and UST sites have occurred in the developed areas of the rail line ROW. In some cases and some areas, such as large industrial facilities, there is sufficient information to conclude that past spill events have likely impacted subsurface conditions as well as ground surface areas within or in the vicinity of the MMA rail line ROW. There are few locations along the alignment where the Maine DEP or U.S. EPA are currently requiring ongoing remediation due to the past storage, use or disposal of oil and hazardous materials.

In summary, based on the results of this preliminary assessment, there appear to be several potential environmental liabilities along the rail line ROW and associated siding areas. Because Haley & Aldrich did not complete a site reconnaissance to observe existing ground conditions and locations of reported spills and releases of petroleum products and hazardous materials in the vicinity of the rail line ROW, further assessment related to many of these site areas is warranted. Our conclusions are based on the results of the available data from EDR reports and the Maine DEP database listings. This site data, especially in the case of orphan sites listed in the EDR reports, have the potential to be misplaced or mislabeled. As such, Haley & Aldrich recommends additional investigations of several areas along the main line and the four subdivisions. Investigations would include an alignment reconnaissance in areas of reported spills and releases and suspect siding areas to observe existing ground surface conditions. In addition, subsurface investigations may be required in selected areas in order to assess whether identified contamination beneath the rail line ROW has the potential to migrate to adjacent properties.

LIMITATIONS

This report has been prepared for the exclusive use of the Maine DOT in accordance with our proposal to the Maine DOT, dated 10 May 2010, and our General Consultant Agreement #CT200708100000000386 and the Consultant General Conditions between Haley & Aldrich, Inc., and the Maine Department of Transportation. The conclusions provided by Haley & Aldrich, Inc. are based solely on the scope of services conducted and the sources of information used for this report. Any additional information that becomes available concerning the ROW investigated for this PEA should be made available to Haley & Aldrich, Inc., so that our conclusions may be revised and modified, if necessary.

This work has been undertaken in accordance with generally accepted geoenvironmental practices in effect at the time the services were provided. Use of the information or data contained herein by anyone other than the Maine DOT shall be at that party's sole risk.



Maine Department of Transportation 10 June 2010 Page 12

Thank you for the opportunity to perform these services for you. Please do not hesitate to contact us if you have any questions or comments.

Sincerely yours,

HALEY & ALDRICH, INC.

Andrew L. Collins

Environmental Technician

David A. Dearden Project Manager

Wayne A. Chadbourne, P.E.

Vice President

Enclosures:

Table I - Summary of Valuation Maps

Table II - EDR-Listed Sites on or near the Montreal, Maine & Atlantic Railroad Right of Way

Table III - DEP-Listed Spill Sites on or near the Montreal, Maine & Atlantic Railroad Right of Way

Table IV - DEP-Listed Tank Sites on or near the Montreal, Maine & Atlantic Railroad Right of Way

Figure 1 - Project Alignment

Figure 2 - Houlton Subdivision

Figure 3 - Presque Isle Subdivision

Figure 4 - Fort Fairfield Subdivision

Figure 5 - Limestone Subdivision

Appendix A - EDR Radius Map Report Executive Summaries

Appendix B - Maine DEP Spill Reports

G:\PROJECTS\37156 - MMA Railway\Report Documents\2010-0610-HAI-MEDOT_MM&A_Railroad_PEA_F.doc



TABLE I
SUMMARY OF VALUATION MAPS
MONTREAL, MAINE & ATLANTIC RAILWAY PROJECT
PIN 17643

Subdivision	V (map) #	Mile Posts	Line Segment	Adjacent Settlements	Sidings and Track Features
	2g/10	109-112	Brownville to Oakfield		
	2g/11	113-116	Brownville to Oakfield	(Grindstone)	Short siding at station area (MP 113.4)
	2g/12	117-120	Brownville to Oakfield		Long (c. 1 mi) siding at MP 119.5
	2g/13	121-124	Brownville to Oakfield	(Davidson)	Very short spur at MP 123
	2g/14	125-128	Brownville to Oakfield	Stacyville	Short siding at station area (MP 125)
	2g/15	129-132	Brownville to Oakfield	Sherman	Several short sidings and 1 short spur (to mill) at station area (MP 128.9, 129)
	2g/S.15	Station	Brownville to Oakfield	Sherman Station	See above
	2g/16	133-136	Brownville to Oakfield	(Crystal)	Short siding at station area (MP 134)
	2g/17	137-140	Brownville to Oakfield	(Belvedere)	2 short spurs at station area (MP 138.4)
	2g/18	140-142	Brownville to Oakfield	Island Falls	Several short sidings and 1 long spur (to tannery) at (MP 139.7)
	2g/5.18	Station	Brownville to Oakfield	Island Falls Station	See above
	2g/19	143-145	Brownville to Oakfield		
	2g/20	146-148	Brownville to Oakfield	Dyer Brook	Short siding at station area (MP 146.6)
	2K/ST1	149-150/H0	Brownville to Oakfield	Oakfield	Yard - 8 tracks at widest point; single line forks toward Houlton (MP 148.8)
	2K/SL1a	Station	Brownville to Oakfield	Oakfield Station	
	2m/1	149-152/H0	Ashland Junction to Sheridan	Oakfield; Ashland Jct.; Smyrna Mills	Short siding at Smyrna Mills (MP 150.7)
	2m/S.1	Station	Ashland Junction to Sheridan	Smyrna Mills Station	See above
	2m/2	152-156	Ashland Junction to Sheridan	(Dudley)	
Main Line	2m/3	156-160	Ashland Junction to Sheridan		A Comment of the second of the
	2m/4	160-164	Ashland Junction to Sheridan	(Weeksboro)	Short spur at station area (MP 160.6); long siding at MP 163.8
	2m/5	164-167	Ashland Junction to Sheridan	(Howe Brook)	Termination of siding from previous map
	2m/6	168-171	Ashland Junction to Sheridan	(St. Croix)	Short siding at station area (MP 167.9)
	2m/7	172-175	Ashland Junction to Sheridan		Short siding at MP 175.1
	2m/8	176-180	Ashland Junction to Sheridan		The first of the second of the
	2m/9	180-183	Ashland Junction to Sheridan	Masardis; (Stimson's)	Short siding at each station area (MP 181.1, 183)
	2m/10	184-187/P0	Ashland Junction to Sheridan	Squa Pan; (Hotham)	Several short sidings at (MP 184.9); single line forks toward Presque Isle
	2m/S.10	Station	Ashland Junction to Sheridan	Squa Pan Station	See above
	2m/11	188-191	Ashland Junction to Sheridan	(Trafton's)	Short siding at MP 188.5
	2m/12	192-193	Ashland Junction to Sheridan	Ashland	Several short sidings and 1 long siding at station area (MP 192.9)
	2m/S.12	Station	Ashland Junction to Sheridan	Ashland Station	See above
	2n/1	194-197	Sheridan to Fort Kent	Sheridan; (Wrightville); (Moody)	Spur (to mills) at Sheridan; two short sidings at Moody (MP 194.3)
	2n/2	198-201	Sheridan to Fort Kent	Skerry; Machias	Several short sidings at Skerry (MP 198.0)
	2n/3	201-205	Sheridan to Fort Kent	Portage	Large siding cluster at MP 202.1; several short sidings and 1 spur at (MP 203.5)
	2n/S.3	Station	Sheridan to Fort Kent	Portage Station	A Links Dispute payor provide a superpopular control of the payor of the superpopular
	2n/4	206-209	Sheridan to Fort Kent		
	2n/5	210-213	Sheridan to Fort Kent	Nixon	Short siding at Nixon (MP 212.1)
	2n/6 (N/A)	214-216	Sheridan to Fort Kent		

TABLE I (Continued) SUMMARY OF VALUATION MAPS

Subdivision	V (map) #	Mile Posts	Line Segment	Adjacent Settlements	Sidings and Track Features
	2n/7	217-221	Sheridan to Fort Kent	(St. Froid); Winterville	Short siding at Winterville (MP 220.1)
	2n/8	222-225	Sheridan to Fort Kent		
	2n/9	226-229	Sheridan to Fort Kent	Eagle Lake	
	2n/S.9	Station	Sheridan to Fort Kent	Eagle Lake Station	Short siding and short spur at station area (MP 226.7)
	2n/10	230-233	Sheridan to Fort Kent	Wallagrass	Spur (to mill) at MP 231; several short sidings at station area (MP 231.5)
	2n/11 (N/A)	234-237	Sheridan to Fort Kent		
	2n/12	238-241	Sheridan to Fort Kent	(Sutton)	
Main Line	2n/13	242-244	Sheridan to Fort Kent	(Bradbury); (Dunn)	Short spur at MP 242
	2n/14 (N/A)	245-246	Sheridan to Fort Kent		7.0272.00
	2u/11	247-249	Van Buren to Fort Kent		
	2u/10	250-252	Van Buren to Fort Kent	(Robbins)	
	2u/9	253-256	Van Buren to Fort Kent	(Cleveland); Frenchville; (St. Luce)	44 60 60 60 60 60 60
	2u/S.9a	Station	Van Buren to Fort Kent	Cleveland Station	Short siding at station area
	2u/S.9b	Station	Van Buren to Fort Kent	Frenchville Station; St. Luce Station	2 short sidings at Frenchville station area
	2u/8	257-260	Van Buren to Fort Kent	(Gilman)	
	2k/1	H0-H2/149-152	Oakfield to Caribou	Oakfield	
	2k/2	H3-H-6/152-155	Oakfield to Caribou	Ludlow	Short siding at station area
	2k/3	H7-H10/156-159	Oakfield to Caribou	New Limerick	Very short siding at station area
	2k/5.3	Station	Oakfield to Caribou	New Limerick Tannery Spur	Self-explanatory
Houlton	2k/4	11-H14/160-16	Oakfield to Caribou	Cary's Mills	Several short sidings and short spurs around station
Subdivision	2k/5	H15-H17	Oakfield to Caribou	Cary's Mills; (Horseback Pit); Houlton	
	2k/5.5a	Station	Oakfield to Caribou	Cary's Mills Station	The second of th
	2k/S.5b	Station	Oakfield to Caribou	Houlton Station	Several sidings and spurs around station and to roundhouse
	2k/S.5c	Station	Oakfield to Caribou	Ryan Farm	Siding at station area and spur (to ME Sugar Industries)
	2k/S.6	168-171	Oakfield to Caribou	(Hutchinson)	
	2p/1	P0-P3	Squa Pan to Stockholm		T
	2p/1 2p/2	P4-P7	Squa Pan to Stockholm		
	F-7.55	P8-P11	Squa Pan to Stockholm	Walker	
Denemun Iela	2p/3	P12-P15	Squa Pan to Stockholm		Short siding at station area
Presque Isle Subdivision	2p/4 2p/5	P16-P18/W0	Squa Pan to Stockholm	Chapman Mapleton	Short siding at station area Several short sidings and short spurs around station
PUDUIVISION	10.45			And the second s	See above
	2p/S.5	Station	Squa Pan to Stockholm	Mapleton Station	See above See above; short siding at Brannen
	2q/2	P18-P21	Presque Isle to Mapleton	Mapleton; Brannen	
	2q/1	P22-P25	Presque Isle to Mapleton	Presque Isle	Several short sidings and short spurs around station

Subdivision	V (map) #	Mile Posts	Line Segment	Adjacent Settlements	Sidings and Track Features
	2k/16	F1-F3	Oakfield to Caribou	(Deering); (Aroostook Farm)	Small spur at Aroostook Farm
400	2k/15	F4-F6	Oakfield to Caribou	Phair	Track forks toward Houlton - abandoned at that point
Fort Fairfield	2k/S.15	Station	Oakfield to Caribou	Phair Station	Short siding at station area; see above
Subdivision	2r/1	F6-F9	Phair to Fort Fairfield	Phair	
	2r/2	F8-F-12	Phair to Fort Fairfield	Easton; Fairmount	Short siding at Fairmount; several short sidings at Easton
	2r/S.2	Station	Phair to Fort Fairfield	Easton Station	See above

	2k/17	LO-L3	Oakfield to Caribou	Presque Isle; (Goodings)	Several short sidings and short spurs and bunker at Goodings
	2k/S.17	Station	Oakfield to Caribou	Saunders and Goodings stations	See above; short siding and short spur at Saunders
	2k/SL17a	Irrelevant	Oakfield to Caribou		
	2k/SL17b	Irrelevant	Oakfield to Caribou		Appropriate the second
Limertons	2k/18	L4-L7	Oakfield to Caribou	T .	Industrial siding at L6
Limestone	2k/19	L8-L11	Oakfield to Caribou	1	
Subdivision	2k/20	L12-L14	Oakfield to Caribou	(Snider); Caribou	Short spur at Snider
	2k/S.20a	Station	Oakfield to Caribou	Snider Station	See above
	2k/5.20b	Station	Oakfield to Caribou	Caribou Station	Yard - 5 tracks at widest point; several sidings and spurs
	2s/1	L15	Caribou to Van Buren		Siding after MP L15; track abandoned at markers 227.93-242.60
	2s/S.1	Station	Caribou to Van Buren		Small siding area

Notes

- 1. Valuation maps were provided by the Maine DOT between 11 May 2010 and 25 May 2010
- 2. All valuation maps were composed by Bangor & Aroostook Railroad between 30 June 1914 and 30 June 1916, with the following exceptions (see above for their subdivision affiliation:

2K/ST1 and 2K/SL1a were composed 30 November 1948 and 5 May 1941, respectively

2K/S.5a, 2K/S.5b, and 2K/S.5c were composed 15 March 1881, 24 January 1950, and 3 January 1966, respectively

2K/S.17 was composed 6 January 1961

2K/SL17a and 2K/SL17b were composed 16 October 1931 and 5 November 1931, respectively

2K/S.18 was composed 16 April 1946

2K/20 was composed 15 July, 1946

2K/S.20a and 2K/S.20b were composed 31 October 1945 and 6 June 1929, respectively

25/S.1 was composed 2 February 1968

3. Adjacent settlements, sidings and track feature information was determined using the valuation maps provided

Parentheses around a settlement name indicate an area that was not or is no longer incorporated

N/A - not available. Indicates valuation maps not provided by the Maine DOT

HALEY & ALDRICH, INC.

g:\projects\37156 - MMA Railway\Report Documents\Tables\2010-0610-HAI-MaineDOT valuation map summary T1.xls

TABLE II

EDR-LISTED SITES ON OR NEAR THE MONTREAL, MAINE & ATLANTIC RAILROAD RIGHT OF WAY

MONTREAL, MAINE & ATLANTIC RAILROAD PROJECT

PIN 17643

						SPILLS/LAST/LUST Information	
Subdivision	Location	Facility	Listed database	Date reported	Spill amount*	Remedial methods	Spill ID
	Sherman	Sherman Lumber Sherman Lumber Sherman Lumber	SPILLS LUST UST	2/15/1999 12/23/1997	100 gal 100 gal	Excavation/Pumps/Sorbents Excavation	I-14-1999 I-189-1997
	Station	Sherman Lumber Wheelabrator-Sherman Energy	FINDS AST	1			
	Oakfield	Daigle Oil Co	LAST AST AST AST	9/18/2000	50 gal	Excavation	I-101-2000
Main Line	Masardis	Fraser Paper J Paul Levesque & Sons	RCRA-SQG AST AST FINDS SWF/LF				
	Ashland	Daigle Oil Co Dead River Oil Co	AST LAST	10/27/1983	458 gal	Excavation	B-173-1983
	Nashville Plantation	Great Northern Paper (Pinkham Mill) Irving Forest Products (Pinkham Mill) Irving Forest Products (Pinkham Mill) Irving Forest Products (Pinkham Mill) Pinkham Lumber Pinkham Lumber Pinkham Lumber	AST RCRA-CESQG, FINDS LAST RCRA-CESQG, FINDS SPILLS SPILLS LUST	9/26/2007 6/16/1998 4/28/1998 6/16/1998	20 gal 50 gal 50 gal 66 gal	Sorbents/Vacuum Truck Excavation Excavation/Pumps/Sorbents Excavation	I-198-2007 I-133-1998 I-98-1998 I-132-1998
	Fort Kent	B&A Railroad B&A Railroad	SPILLS SPILLS	2/12/2001 11/13/1998	5 gal 5 gal	Sorbents Sorbents	I-49-2001 I-241-1998
Houlton Subdivision	New Limerick	Louisiana Pacific Louisiana Pacific Louisiana Pacific Louisiana Pacific Louisiana Pacific Louisiana Pacific Louisiana Pacific	SPILLS SPILLS SPILLS SPILLS LUST AST UST UIC	2/8/2005 4/4/2003 10/10/2004 9/28/2007 7/7/1994	250 gal PF 50 gal 50 gal 50 gal 50 gal 76 gal	Pump Sorbents Sorbents Sorbents Excavation	I-31-2005 I-96-2003 I-211-2004 I-209-2007 I-87-1994
Presque Isle Subdivision	Presque Isle	B&A Railroad Engine House H Smith Packaging Haines Manufacturing Co Jim Mosher Lavway Property Maurice's Barber Shop Webber Oil	ALLSITES FINDS Brownfields LAST Brownfields UST Brownfields	11/14/1999	90 gal	No further action Needs remediation Excavation Needs remediation Needs remediation	I-171-1999

					SP	ILLS/LAST/LUST Information	
Subdivision	Location	Facility	Listed database	Date reported	Spill amount*	Remedial methods	Spill ID
		Huber Engineered Wood	SPILLS	11/26/2007	100 gal	Sorbents	1-248-2007
		Huber Engineered Wood	SPILLS	11/9/2007	25 gal	Sorbents	1-253-2007
		Huber Engineered Wood	SPILLS	10/6/2007	20 gal	Sorbents	1-214-2007
		Huber Engineered Wood	SPILLS	9/10/2007	25 gal	Sorbents/Excavation	1-179-2007
	1.3	Huber Engineered Wood	SPILLS	7/27/2007	35 gal	Sorbents	I-148-2007
	1.14	Huber Engineered Wood	SPILLS	7/26/2007	20 gal	Sorbents	1-146-2007
		Huber Engineered Wood	SPILLS	7/12/2007	20 gal	Sorbents	1-137-2007
		Huber Engineered Wood	SPILLS	5/28/2007	20 gal	Sorbents	1-138-2007
		Huber Engineered Wood	SPILLS	3/2/2007	20 gal	Sorbents	1-51-2007
		Huber Engineered Wood	SPILLS	2/3/2005	20 gal	Sorbents	1-33-2005
		Huber Engineered Wood	AST	(3/8/5)(36	7-2-2	4213400	7.05 2.00
	1.04	Huber Engineered Wood	FINDS				
		J.M. Huber	SPILLS	4/27/2003	40 gal	Sorbents	1-109-2003
		J.M. Huber	SPILLS	4/10/2003	146 gal	Sorbents	1-99-2003
		J.M. Huber	SPILLS	1/15/2003	25 gal	Sorbents	1-19-2003
		J.M. Huber	SPILLS	5/4/1999	50 gal	Sorbents	1-89-1999
		J.M. Huber	SPILLS	5/30/1998	10 gal	Sorbents	1-114-1998
1		J.M. Huber	SPILLS	1/26/1998	10 gal	Sorbents	1-12-1998
		J.M. Huber	SPILLS	11/5/1997	10 gal	Sorbents	1-178-1997
		J.M. Huber	SPILLS	9/19/1997	80 gal	Sorbents	I-153-1997
		J.M. Huber	SPILLS	8/30/1997	30 gal	Sorbents	1-150-1997
		J.M. Huber	SPILLS	8/9/1997	10 gal	Excavation/Sorbents	1-121-1997
		J.M. Huber	SPILLS	2/20/1997	30 gal	Sorbents	20 4 Call 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
aston Subdivision	Easton	J.M. Huber	LAST	3/2/2005	40 gal	Sorbents	I-17-1997 I-44-2005
1011 300001113.011	Luston	J.M. Huber	LAST	8/22/2004	30 gal	Sorbents	1-164-2004
		J.M. Huber	LAST	7/2/2004	0.000	Sorbents	E.C. 94.1113130.
		J.M. Huber	LAST		100 gal		1-124-2004
			28974	6/20/2004	30 gal	Sorbents	1-114-2004
		J.M. Huber	LAST	5/5/2004	20 gal	Sorbents	1-101-2004
		J.M. Huber	LAST	3/21/2004	20 gal	Sorbents	1-56-2004
		J.M. Huber	LAST	11/16/2003	25 gal	Sorbents	1-222-2003
		J.M. Huber	LAST	10/21/2003	25 gal	Pumps	1-209-2003
		J.M. Huber	LAST	10/14/2003	150 gal	None reported	1-210-2003
		J.M. Huber	LAST	9/17/2003	75 gal	Sorbents	1-256-2003
		J.M. Huber	LAST	9/15/2003	30 gal	Sorbents	1-201-2003
		J.M. Huber	LAST	8/26/2003	20 gal	Sorbents	1-192-2003
		J.M. Huber	LAST	8/10/2003	500 gal BB	None reported	1-190-2003
		J.M. Huber	LAST	7/22/2003	75 gal	Sorbents	I-179-2003
		J.M. Huber	LAST	7/10/2003	600 gal BB	Pumps	I-148-2003
		J.M. Huber	LAST	6/21/2003	600 gal	Sorbents	I-125-2003
		J.M. Huber	LAST	5/2/2003	20 gal	Pumps	1-144-2003
21		J.M. Huber	LAST	5/1/2003	20 gal	Sorbents	I-141-2003
	Y.	J.M. Huber	LAST	5/1/2003	200 gal	Pumps	1-143-2003
		J.M. Huber	LAST	4/28/2003	50 gal	Sorbents	1-142-2003
		J.M. Huber	LAST	4/27/2003	45 gal	Sorbents	1-140-2003
		J.M. Huber	LAST	3/16/2003	30 gal	Excavation	1-76-2003
		J.M. Huber	LAST	3/4/2003	55 gal	Excavation	1-47-2003
		J.M. Huber	LAST	3/3/2003	55 gal	Excavation	1-299-2003

					SPI	LLS/LAST/LUST Information	
Subdivision	Location	Facility	Listed database	Date reported	Spill amount*	Remedial methods	Spill ID
		J.M. Huber	LAST	3/3/2003	55 gal	Excavation	1-73-2003
		J.M. Huber	LAST	2/27/2003	50 gal	Vacuum trucks	1-62-2003
		J.M. Huber	LAST	1/26/2003	250 gal	Sorbents	1-18-2003
		J.M. Huber	LAST	1/19/2003	90 gal BB	Vacuum trucks	1-13-2003
		J.M. Huber	LAST	1/16/2003	25 gal	Sorbents	I-11-2003
		J.M. Huber	LAST	1/12/2003	40 gal	Sorbents	1-9-2003
tota (1. m. of 1. ft.)	- T. L. K.	J.M. Huber	LAST	3/1/2002	500 gal WX	Vacuum trucks	1-43-2002
aston Subdivision	Easton	J.M. Huber	LAST	11/15/2001	35 gal	Sorbents	1-188-2001
		J.M. Huber	LAST	8/13/2001	200 gal	Sorbents/Pumps	1-157-2001
		J.M. Huber	LAST	3/15/2001	60 gal	Sorbents	1-184-2001
		J.M. Huber	LAST	3/9/2001	20 gai	Sorbents	1-53-2001
		J.M. Huber	LAST	7/2/1999	10 gal	Pumps	1-106-1999
		J.M. Huber	LAST	5/9/1997	300 gal	Excavation	1-110-1997
		McCain Foods	NPEDS				
		Vahlsing Warehouse	ALLSITES			Investigation needed	1
		Caribou Generating Station	AST				-1
		Caribou Generating Station	FINDS				
		Caribou Steam & Diesel Station	AST	1			
		Caribou Steam & Diesel Station	UST				
Limestone		Caribou Utilities District	NPDES				
142 C. 175 E. T. 17 11 11 11 11 11 11 11 11 11 11 11 11	Caribou	Caribou Utilities District	NPDES				0.00
Subdivision		L.B. Carter	LAST	5/23/1995	82.5 gai	Excavation	1-45-1995
		Maine Paper Co	RCRA-NonGen, FINDS		2.0		1 1 2 2 2 2 2
1		S.W. Cole Engineering	UST	170 100			
		WPS New England Generation	SPILLS	1/14/2005	1 gal	None	1-20-2005
		WPS New England Generation	NPDES				1.00

Notes

*Amount refers to oil unless otherwise noted

PF = Phenol formaldehyde

BB = Boiler blowdown water

WX = Wax

HALEY & ALDRICH, INC.

g:\projects\37156 - MMA Railway\Report Documents\Tables\2010-0610-HAI-EDR sites summary T2.xls

Database information was provided by Environmental Data Resources (EDR) of Milford, CT in requested reports dated between 21 and 24 May 2010.

DEP-LISTED SPILL SITES ON OR NEAR THE MONTREAL, MAINE & ATLANTIC RAILROAD RIGHT OF WAY MONTREAL, MAINE & ATLANTIC RAILWAY PROJECT

PIN 17643

Subdivision	Location	Facility	Spill event	Date reported	Amount	Remedial method(s)	Database II
	Grindstone	MM&A Railroad	Leaking fuel tank on an MM&AR wrecking crane	4/28/2006	100 gal	Unrecoverable	B-229-2006
	TO2 RO9 WELS	B&A Railroad	Accident - no further explanation	11/11/1999	350 gal	Excavation	8-721-1999
	Oakfield	B&A Railroad B&A Railroad	Unknown Unknown	7/27/1994 5/24/1994	500 gal 100 gal	Excavation Excavation	I-94-1994 I-75-1994
	Masardis	Robinson's Market	AST accident	1/20/1996	538 gal	Excavation	1-6-1996
	Ashland	Antonio Levesque & Sons Great Northern Paper	UST leak UST breakage	4/16/1996 6/2/1988	50 gal 10 gal	Carbon filtration Excavation	I-44-1996 I-73-1988
Main Line	Nashville Pit	Irving Forest Products Pinkham Lumber Pinkham Lumber	Non-hazardous chemical spill – paint UST corrosion UST overfill	6/5/2001 6/16/1998 6/6/1994	400 gal 76 gal 20 gal	Burning Excavation No treatment	I-73-2001 I-132-1998 I-88-1994
	Portage	Maine Woods Co	Pipe corrosion	11/18/2004	30 gal	Sorbents/Burning	1-238-2004
	Wallagrass	B&A Railroad	Accident - no further explanation	4/29/1994	5 gal	No treatment	1-58-1994
	Fort Kent	Daigle Oil Co Dead River Co Daigle Oil Co	AST overfill AST leak - loose fitting UST corrosion	1/23/2008 3/2/2001 5/3/1994	100 gal 10 gal 200 gal	Excavation Excavation Excavation	I-12-2008 I-21-2001 I-67-1994
Houlton	New Limerick	Louisiana Pacific Louisiana Pacific	Valve released - phenol formaldehyde resin Ruptured hydraulic hose	10/21/2004 7/22/1999	1100 gal 35 gal	Sorbents/Burning Burning	J-217-2004 J-163-2000
Subdivision	Houlton	Vernon and Gladys Spooner	AST breakage	3/26/2003	100 gal	Excavation	1-86-2003
		Total Control					1
	Mapleton	Neal Buck	AST breakage	3/26/2001	200 gal	Excavation/sorbents	I-31-2001
Presque Isle Subdivision	Presque Isle	Richard Thompkins McCain Foods Ferris Oil Co	UST leak - loose fitting Hazardous material incedent - utility accident AST overfill	8/20/2003 8/10/1999 1/18/1995	100 gal 50 gal 20 gal	Excavation Excavation Excavation	I-233-2003 I-168-2000 I-4-1995
		J.M. Huber	Ruptured hydraulic hose	6/5/2000	50 gal	Sorbents	1-151-2000
Fort Fairfield Subdivision	Easton	McCain Foods Kana Oil Co Henderson Oil Co	Equipment failure - ammonia release UST corrosion Mechanical piping failure	6/24/1998 9/22/1995 1/6/1995	841 gal 500 gal 500 gal	Released to air Excavation Excavation	I-238-1998 I-90-1995 I-1-1995
Umartana	(Earth Waste Systems	Abandoned UST leakage	9/19/2005	300 gal	Excavation	1-168-2005
Limestone Subdivision	Caribou	Al Cyr L.B. Carter	Transportation accident Unknown	4/16/1994 10/8/1984	55 gal 1250 gal	No treatment Excavation/pump	I-54-1994 I-55-1984

Notes

1. Database information was gathered from the Maine Department of Environmental Protection website at http://www.maine.gov/dep/gis/datamaps/index.htm. Sites were identified using a GIS utility provided by the DEP which displayed the locations of spills on Google Earth. Utilization of this database occurred between 19 and 28 May 2010.

TABLE IV

DEP-LISTED TANK SITES ON OR NEAR THE MONTREAL, MAINE & ATLANTIC RAILROAD RIGHT OF WAY

MONTREAL, MAINE & ATLANTIC RAILWAY PROJECT


PIN 17643

Pag	e	1	of	1
, u _b	•		v.	-

Subdivision	Location	Classification	Facility	Capacity	Status	Tank number
		UST	John Yankee Grocer	10000 gal	Active	18084
		UST	John Yankee Grocer	8000 gal	Active	18084
		UST	Daigle and Houghton	3000 gal	Active	10539
		UST	Northern Main Medical Center	20000 gal	Active	169
		UST	Daigle Oil Bulk Plant	15000 gal	Active	302
Main Line	Fort Kent	UST	MDOT	10000 gal	Active	5087
Main Line	14-13	UST	Voisine Exxon	15000 gal	Active	2513
		UST	Voisine Exxon	15000 gal	Active	2513
		UST	Twins SVC Station	6000 gal	Active	2511
		UST	Twins SVC Station	6000 gal	Active	2511
		UST	Twins SVC Station	6000 gal	Active	2511
	Frenchville	UST	Edwin Pelletier and Sons	12000 gal	Active	9781
		UST	Bradley Citgo	15000 gal	Active	14752
		UST	Buck's Market	6000 gal	Active	13067
Presque Isle	10000000	UST	Buck's Market	6000 gal	Active	13067
Subdivision	Presque Isle	UST	Buck's Market	4000 gal	Active	13067
		UST	Social Security Administration	2500 gal	Active	12112
		UST	Lowe's of Presque Isle	1500 gal	Active	21190

Notes

1. Database information was gathered from the Maine Department of Environmental Protection website at http://www.maine.gov/dep/gis/datamaps/index.htm. Sites were identified using a GIS utility provided by the DEP which displayed the locations of



LEGEND

HOULTON SUBDIVISION

W S

HALEY& ALDRICH

PRELIMINARY ENVIRONMENTAL ASSESSMENT MONTREAL, MAINE AND ATLANTIC RAILWAY PROJECT PENOBSCOT AND AROOSTOOK COUNTIES, MAINE STATE P.I.N. # 17643


HOULTON SUBDIVISION

AS SHOWN JUNE 2010

FIGURE 2


NOTE: AERIAL IMAGE FROM GOOGLE EARTH ©2008

NOTE: AERIAL IMAGE FROM GOOGLE EARTH @2008



AS SHOWN JUNE 2010

FIGURE 3



LEGEND

FORT FAIRFIELD SUBDIVISION



HALEY& ALDRICH


PRELIMINARY ENVIRONMENTAL ASSESSMENT MONTREAL, MAINE AND ATLANTIC RAILWAY PROJECT PENOBSCOT AND AROOSTOOK COUNTIES, MAINE STATE P.I.N. # 17643

FORT FAIRFIELD SUBDIVISION

AS SHOWN JUNE 2010

FIGURE 4

NOTE: AERIAL IMAGE FROM GOOGLE EARTH @2008





LEGEND

LIMESTONE SUBDIVISION

NOTE: AERIAL IMAGE FROM GOOGLE EARTH ©2008



PRELIMINARY ENVIRONMENTAL ASSESSMENT MONTREAL, MAINE AND ATLANTIC RAILWAY PROJECT PENOBSCOT AND AROOSTOOK COUNTIES, MAINE STATE P.I.N. # 17643

LIMESTONE SUBDIVISION

NOT TO SCALE JUNE 2010

FIGURE 5

APPENDIX A

EDR Radius Map Report Executive Summaries

MMA Railway - Sherman Station MMA Railway - Sherman Station Sherman Station, ME 04777

Inquiry Number: 02775704.5r

May 21, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	ES1
Overview Map.	2
Detail Map.	3
Map Findings Summary.	. 4
Map Findings.	. 7
Orphan Summary.	
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary.	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings.	A-8
Physical Setting Source Records Searched.	A-15

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - SHERMAN STATION SHERMAN STATION, ME 04777

COORDINATES

Latitude (North): 45.899200 - 45° 53' 57.1" Longitude (West): 68.429000 - 68° 25' 44.4"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): 544295.4 UTM Y (Meters): 5082788.5

Elevation: 482 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 45068-H4 PATTEN, ME

Most Recent Revision: 1989

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL...... National Priority List

Proposed NPL Proposed National Priority List Sites

NPL LIENS Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list	
CERCLISFEDERAL FACILITY	Comprehensive Environmental Response, Compensation, and Liability Information System Federal Facility Site Information listing
Federal CERCLIS NFRAP s	ite List
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
Federal RCRA CORRACTS	facilities list
CORRACTS	Corrective Action Report
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators l	ist
RCRA-SQG	RCRA - Large Quantity Generators RCRA - Small Quantity Generators RCRA - Conditionally Exempt Small Quantity Generator
Federal institutional contro	ls / engineering controls registries
US ENG CONTROLS US INST CONTROL	Engineering Controls Sites List Sites with Institutional Controls
Federal ERNS list	
ERNS	Emergency Response Notification System
State- and tribal - equivaler	et CERCLIS
SHWS	Remediation Sites List
State and tribal landfill and	or solid waste disposal site lists
SWF/LFLCP.	_ Solid Waste Facility List _ Municipal Landfill Closure Database
State and tribal leaking stor	rage tank lists
LUSTINDIAN LUST	. Hazardous Material and Oil Spill System Database (H.O.S.S.) . Leaking Underground Storage Tanks on Indian Land
State and tribal registered s	storage tank lists
ASTINDIAN UST	_ Underground Storage Tank Database _ Aboveground Storage Tanks _ Underground Storage Tanks on Indian Land _ Underground Storage Tank Listing
State and tribal institutiona	control / engineering control registries

INST CONTROL...... Remediation Sites List

State and tribal voluntary cleanup sites

...... Remediation Sites List

INDIAN VCP.....Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS...... Remediation Sites List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9.......... Torres Martinez Reservation Illegal Dump Site Locations

ODI...... Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

ALLSITES...... Remediation Sites List

DEL SHWS..... Sites Removed from the Uncontrolled Sites List

US HIST CDL...... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS.....Land Use Control Information System

LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

SPILLS...... Hazardous Material and Oil Spill System Database

Other Ascertainable Records

RCRA-NonGen_____RCRA - Non Generators

DOT OPS..... Incident and Accident Data DOD...... Department of Defense Sites FUDS_____ Formerly Used Defense Sites

CONSENT...... Superfund (CERCLA) Consent Decrees

ROD...... Records Of Decision UMTRA...... Uranium Mill Tailings Sites MINES..... Mines Master Index File

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS......Integrated Compliance Information System

RAATS......RCRA Administrative Action Tracking System

UIC...... Underground Injection Control

INDIAN RESERV...... Indian Reservations
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
COAL ASH EPA...... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER....... PCB Transformer Registration Database COAL ASH DOE......... Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

State and tribal leaking storage tank lists

LAST: A listing of leaking aboveground storage tanks.

A review of the LAST list, as provided by EDR, and dated 03/13/2010 has revealed that there is 1 LAST site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROBERT CAITLIN HOME	453 STATION ROAD	NW 1/4 - 1/2 (0.297 mi.)	2	7

ADDITIONAL ENVIRONMENTAL RECORDS

Other Ascertainable Records

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 10/19/2009 has revealed that there is 1 FINDS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SHERMAN LUMBER	HEAD OF MILL STREET	WSW 0 - 1/8 (0.121 mi.)	1	7

NPDES: A listing of wastewater facility locations.


A review of the NPDES list, as provided by EDR, and dated 04/06/2010 has revealed that there is 1 NPDES site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WHEELABRATOR SHERMAN ENERGY		WSW 1/4 - 1/2 (0.300 mi.)	3	10

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
SHERMAN IRVING	UIC
HAYES GROCERY	UIC
SHERMAN LUMBER CO	UIC, LUST, UST
MSAD 25	UIC
DOT SHERMAN	TIER 2
THE LANE CONSTRUCTION CORPORATION	AST, TIER 2
WHEELABRATOR-SHERMAN ENERGY	AST, TIER 2
SHERMAN MILLS JR. HIGH	FTTS, HIST FTTS
RT 11	FTTS, HIST FTTS
STACYVILLE, TOWN OF	UST, LAST
BARBEAU LORRAINE	LAST
MILL ST	SWF/LF
KATAHDIN HIGH SCHOOL	UST
KATAHDIN JUNIOR HIGH SCHOOL	UST
RUSH, MARGUERITE	UST
MCAVOY, JOHN	UST
CUMMINGS, CECIL	UST
SHERMAN TRUCK STOP	UST
CULLENS GULF	UST
KATAHDIN VALLEY MOTEL	UST
HUNTLEY FARM	UST
GOLDEN RIDGE FARMS	UST
PORTER, STEPHEN N	UST
SHERMAN FIRE STATION	UST
SHERMAN MAYTAG LAUNDRY	UST
SHERMAN GYMNASIUM	UST
BOYNTON, LAUREL R	UST
HAYES GROCERY	UST
PERKINS, NORMAN K	UST
BATES FUEL INC	UST
BATES FUEL SHERMAN STATION	AST
BATES FUEL INC	AST
SHERMAN THRIFTWAY	RCRA-NonGen
SHERMAN THRIFTWAY	FINDS
SHERMAN LUMBER CO	FINDS
SHERMAN LUMBER CO	SPILLS
WHEELABRATOR SHERMAN ENERGY CO	SPILLS
WHEELABRATOR SHERMAN ENERGY	ICIS
WHEELABRATOR-SHERMAN ENERGY CO	AIRS

OVERVIEW MAP - 02775704.5r




SITE NAME: MMA Railway - Sherman Station ADDRESS: MMA Railway - Sherman Station Sherman Station ME 04777 LAT/LONG:

45.8992 / 68.4290

CLIENT: Haley & Aldrich, Inc. CONTACT: Andrew Collins INQUIRY #: 02775704.5r

DATE: May 21, 2010 12:27 pm



SITE NAME: MMA Railway - Sherman Station MMA Railway - Sherman Station Sherman Station ME 04777 45.8992 / 68.4290

CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02775704.5r
DATE: May 21, 2010 12:27 pm

MMA Railway - Oakfield Yard MMA Railway - Oakfield Yard Oakfield, ME 04763

Inquiry Number: 02775704.4r

May 21, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	_ ES1
Overview Map	. 2
Detail Map.	. 3
Map Findings Summary	_ 4
Map Findings.	_ 7
Orphan Summary	. 8
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum.	. A-1
Physical Setting Source Summary	. A-2
Physical Setting SSURGO Soil Map	. A-5
Physical Setting Source Map	_ A-13
Physical Setting Source Map Findings.	A-14
Physical Setting Source Records Searched	A-22

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - OAKFIELD YARD OAKFIELD, ME 04763

COORDINATES

Latitude (North): 46.109400 - 46° 6' 33.8" Longitude (West): 68.145500 - 68° 8' 43.8"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): 566037.3 UTM Y (Meters): 5106339.5

Elevation: 565 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 46068-A2 OAKFIELD, ME

Most Recent Revision: 1986

North Map: 46068-B2 SMYRNA MILLS, ME

Most Recent Revision: 1986

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL..... National Priority List

Proposed NPL......Proposed National Priority List Sites

NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list	
CERCLISFEDERAL FACILITY	Comprehensive Environmental Response, Compensation, and Liability Information System Federal Facility Site Information listing
Federal CERCLIS NFRAP si	te List
CERC-NFRAP	. CERCLIS No Further Remedial Action Planned
Federal RCRA CORRACTS	facilities list
CORRACTS	
	·
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators li	st
RCRA-LQG.	. RCRA - Large Quantity Generators
	RCRA - Small Quantity Generators
RCRA-CESQG	RCRA - Conditionally Exempt Small Quantity Generator
Federal institutional control	s / engineering controls registries
US ENG CONTROLS	. Engineering Controls Sites List
US INST CONTROL	Sites with Institutional Controls
Federal ERNS list	
ERNS	Emergency Response Notification System
State- and tribal - equivalent	t CERCLIS
SHWS	Remediation Sites List
State and tribal landfill and	
	or solid waste disposal site lists
SWF/LF	Municipal Landfill Closure Database
	The first control of the control of
State and tribal leaking store	age tank lists
	Hazardous Material and Oil Spill System Database (H.O.S.S.)
LAST	HOSS Database Leaking Underground Storage Tanks on Indian Land
	Estating Should Storage Family on Malan Early
State and tribal registered s	torage tank lists
UST	Underground Storage Tank Database
AST	Aboveground Storage Tanks Underground Storage Tanks on Indian Land
	Underground Storage Tanks on Indian Land Underground Storage Tank Listing
State and tribal institutional	control / engineering control registries

INST CONTROL...... Remediation Sites List

State and tribal volun	ıtary cleanu	p sites
------------------------	--------------	---------

VCP...... Remediation Sites List

INDIAN VCP..... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS..... Remediation Sites List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

ODI...... Open Dump Inventory

INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL...... Clandestine Drug Labs

ALLSITES...... Remediation Sites List

DEL SHWS...... Sites Removed from the Uncontrolled Sites List

US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS_____Land Use Control Information System

LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS...... Hazardous Materials Information Reporting System SPILLS...... Hazardous Material and Oil Spill System Database

Other Ascertainable Records

RCRA-NonGen_____RCRA - Non Generators

CONSENT...... Superfund (CERCLA) Consent Decrees

TRIS...... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

FTTS......FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System

AIRS...... Emissions Inventory Data
TIER 2..... Tier 2 Information Listing
INDIAN RESERV..... Indian Reservations

INDIAN RESERV...... Indian Reservations
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
COAL ASH EPA...... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER....... PCB Transformer Registration Database COAL ASH DOE............ Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants


SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were not identified.

Unmappable (orphan) sites are not considered in the foregoing analysis.

Due to poor or inadequate address information, the following sites were not mapped:


Site Name	Database(s)
OAKFIELD	UIC
IRVING FOREST PRODUCT (WOODLANDS)	UIC
BERNIES TRANSMISSION	UIC
DOT OAKFIELD	TIER 2
OAKFIELD BULK PLANT	AST, TIER 2
DAIGLE OIL OAKFIELD BULK PLANT	AST, TIER 2
DAIGLE OAKFIELD BULK PLANT	AST, TIER 2
BOWATER	LAST
DAIGLE OIL BULK PLANT	LAST
DAIGLE OIL CO	LAST
VERNA BOONE	LAST
OAKFIELD IRVING MAINWAY	LUST
OAKFIELD IRVING MAINWAY	LUST, SPILLS
SEILER, JOHN	UST
OAKFIELD MOBIL & RREDEMPTION	UST
BOUTILIER, DALE	UST
JAMES BROTHERS OIL CO	UST
BERNIES TRANSMISSION	UST
KOLMETSKY, MICHAEL	UST
THOMAS, RONALD	UST
MDOT MAINTENANCE FACILITY	UST
CRANDALL, ROGER	UST
US POST OFFICE	UST
KATAHDIN TRUST CO	UST
236 OAKFIELD SMNYRA RD	RCRA-CESQG, FINDS
MDOT - VEHICLE	SPILLS
OAKFIELD CITGO	MANIFEST



SITE NAME: MMA Railway - Oakfield Yard CLIENT: Haley & Aldrich, Inc.
ADDRESS: MMA Railway - Oakfield Yard CONTACT: Andrew Collins
Oakfield ME 04763 INQUIRY #: 02775704.4r
DATE: May 21, 2010 12:28 pm

Dept. Defense Sites

Copyright © 2010 EDR, Inc. © 2010 Tels Atlas Rel. 07/2007.



State Wetlands

SITE NAME: MMA Railway - Oakfield Yard ADDRESS: MMA Railway - Oakfield Yard Oakfield ME 04763

Sensitive Receptors National Priority List Sites Dept. Defense Sites

Oakfield ME 04763 LAT/LONG: 46.1094 / 68.1455 CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY#: 02775704.4r
DATE: May 21, 2010 12:28 pm

Copyright © 2010 EDR, Inc. © 2010 Tale Atlas Rel. 07/2007.

MMA Railway - Ashland MMA Railway - Ashland Ashland, ME 04732

Inquiry Number: 02775704.3r

May 21, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	. ES1
Overview Map.	2
Detail Map	. 3
Map Findings Summary.	. 4
Map Findings.	₋ 7
Orphan Summary.	. 54
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	, A-1
Physical Setting Source Summary.	. A-2
Physical Setting SSURGO Soil Map	. A-5
Physical Setting Source Map.	_ A-17
Physical Setting Source Map Findings	A-18
Physical Setting Source Records Searched.	A-32

Thank you for your business. Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - ASHLAND ASHLAND, ME 04732

COORDINATES

Latitude (North):

46.630000 - 46* 37' 48.0"

Longitude (West):

68.414780 - 68° 24' 53.2"

Universal Tranverse Mercator: Zone 19 UTM X (Meters):

544799.2

UTM Y (Meters):

5163996.5

Elevation:

564 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:

46068-F4 ASHLAND, ME

Most Recent Revision:

1986

South Map:

46068-E4 SQUA PAN, ME

Most Recent Revision:

1986

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

..... National Priority List

Proposed NPL Proposed National Priority List Sites NPL LIENS Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list	
CERCLISFEDERAL FACILITY	. Comprehensive Environmental Response, Compensation, and Liability Information System . Federal Facility Site Information listing
Federal CERCLIS NFRAP si	te List
CERC-NFRAP	. CERCLIS No Further Remedial Action Planned
Federal RCRA CORRACTS	facilities list
CORRACTS	Corrective Action Report
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators lis	st
RCRA-SQG	RCRA - Large Quantity Generators RCRA - Small Quantity Generators RCRA - Conditionally Exempt Small Quantity Generator
Federal institutional control	s / engineering controls registries
US ENG CONTROLS	Engineering Controls Sites List Sites with Institutional Controls
Federal ERNS list	
ERNS	Emergency Response Notification System
State- and tribal - equivalent	CERCLIS
SHWS	Remediation Sites List
State and tribal landfill and/d	or solid waste disposal site lists
SWF/LFLCP	Solid Waste Facility List Municipal Landfill Closure Database
State and tribal leaking stora	age tank lists
INDIAN LUST	Leaking Underground Storage Tanks on Indian Land
State and tribal registered st	torage tank lists
ASTINDIAN USTFEMA UST	Aboveground Storage Tanks Underground Storage Tanks on Indian Land Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

INST CONTROL...... Remediation Sites List

State and tribal voluntary cleanup sites

..... Remediation Sites List INDIAN VCP...... Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations ODI...... Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs DEL SHWS...... Sites Removed from the Uncontrolled Sites List

US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS.....Land Use Control Information System LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS_____ Hazardous Materials Information Reporting System SPILLS..... Hazardous Material and Oil Spill System Database

Other Ascertainable Records

RCRA-NonGen_____RCRA - Non Generators DOT OPS..... Incident and Accident Data DOD..... Department of Defense Sites FUDS..... Formerly Used Defense Sites

CONSENT..... Superfund (CERCLA) Consent Decrees

ROD....... Records Of Decision UMTRA..... Uranium Mill Tailings Sites MINES Mines Master Index File

Act)/TSCA (Toxic Substances Control Act)

SSTS...... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System

PADS...... PCB Activity Database System MLTS..... Material Licensing Tracking System

FINDSRAATSDRYCLEANERSINDIAN RESERVSCRD DRYCLEANERSCOAL ASH EPA	Emissions Inventory Data Indian Reservations State Coalition for Remediation of Drycleaners Listing Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
COAL ASH DOE	Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Protection's Hazardous Material and Oil Spill System Database (H.O.S.S.).

A review of the LUST list, as provided by EDR, and dated 03/13/2010 has revealed that there are 4 LUST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DOT ASHLAND	25 MASARDIS ROAD	E 1/2 - 1 (0.551 mi.)	4	13
TRANSARK OIL O	57 MAIN ST	E 1/2 - 1 (0.571 mi.)	B8	24
PREU OIL CO	114 MAIN ST	ESE 1/2 - 1 (0.650 mi.)	C11	34
ASHLAND 1 STOP	117 MAIN ST	ESE 1/2 - 1 (0.657 mi.)	C12	36

LAST: A listing of leaking aboveground storage tanks.

A review of the LAST list, as provided by EDR, and dated 03/13/2010 has revealed that there are 2 LAST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARY BEAULIER HOME	93 MAIN STREET	ESE 1/2 - 1 (0.617 mi.)	9	27
LONG PAT & TRACY	118 BRIDGHAM STREET	E 1/2 - 1 (0.808 mi.)	15	42

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 02/01/2010 has revealed that there are 7 UST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FAIRPOINT COMMUNICATIONS	17 SHERIADAN RD	ENE 1/2 - 1 (0.518 mi.)	A2	7
COLLINS, JAMES	54 MAIN ST	E 1/2 - 1 (0.566 mi.)	B5	19
ASHLAND 1 STOP	117 MAIN ST	ESE 1/2 - 1 (0.657 mi.)	C12	36
CHALOU, ALPHONSE	50 EXCHANGE ST	E 1/2 - 1 (0.666 mi.)	13	41
PEOPLES HERITAGE BANK	10 MAIN ST	SE 1/2 - 1 (0.809 mi.)	16	45
DAIGLE OIL CO	57 MAIN	SE 1/2 - 1 (0.926 mi.)	17	46
ASHLAND HIGH SCHOOL	HAYWARD & OAK STS	E 1/2 - 1 (0.933 mi.)	18	52

State and tribal Brownfields sites

BROWNFIELDS: A listing of brownfields site locations.

A review of the BROWNFIELDS list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1 BROWNFIELDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CURTIS GARAGE	6 PORTAGE ROAD	NW 1/4 - 1/2 (0.299 mi.)	1	7

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES: The Sites List Database is the public record of information regarding properties that have been, are now, or are planned to be addressed by the Division of Remediation of the Bureau of Remediation and Waste Management. This database is not intended to be a comprehensive, all-inclusive source of information regarding the properties listed therein.

A review of the ALLSITES list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1

ALLSITES site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CURTIS GARAGE	6 PORTAGE ROAD	NW 1/4 - 1/2 (0.299 mi.)	1	7

Other Ascertainable Records

NPDES: A listing of wastewater facility locations.

A review of the NPDES list, as provided by EDR, and dated 04/06/2010 has revealed that there is 1 NPDES site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ASHLAND WATER AND SEWER DISTRI		N 1/2 - 1 (0.679 mi.)	14	42

UIC: An injection well is any bored, drilled or driven shaft, or dug hole whose depth is greater than its largest surface dimension; an improved sinkhole; or a subsurface distribution system used to discharge fluids underground. These wells range from deep, highly technical, and more frequently monitored wells to shallow on-site drainage systems, such as septic systems, cesspools, and storm water drainage wells.

A review of the UIC list, as provided by EDR, and dated 10/28/2009 has revealed that there are 2 UIC sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OCLAIRS SERVICE STATION	54 MAIN ST	E 1/2 - 1 (0.566 mi.)	B6	24
TRANSARK OIL DIST INC	57 MAIN ST	E 1/2 - 1 (0.571 mi.)	B7	24


TIER 2: A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

A review of the TIER 2 list, as provided by EDR, and dated 12/31/2008 has revealed that there are 3 TIER 2 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VERIZON ASHLAND DIAL OFC (ME71	17 SHERIDAN ST	ENE 1/2 - 1 (0.518 mi.)	A3	9
DOT ASHLAND	25 MASARDIS ROAD	<i>E 1/2 - 1 (0.551 mi.)</i>	4	13
DR PRUE OIL COMPANY	114 MAIN STREET	ESE 1/2 - 1 (0.650 mi.)	C10	30


Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
CAINS	UIC
ASHLAND CENTRAL SCHOOL	FTTS,HIST FTTS INSP
DON GARDNER	LAST
CLARK EARLINE	LAST
DAIGLE OIL CO	LAST
SAVORY GLADYS	LAST
DEAD RIVER BULK PLANT	LAST
IRVING'S PINKHAM SAWMILL	LAST
DAIGLE OIL ASHLAND	AST
GREAT NORTHERN PAPER PINKHAM LUMBE	AST
J PAUL LEVESQUE & SONS INC ASHLAND	AST
DR ASHLAND SERVICE STATION 1001 53	AST
J PAUL LEVESQUE & SONS INC MASARDI	AST
FRASER PAPER	RCRA-SQG,MANIFEST
NEXFOR FRASER PAPERS LEVESQUE OPER	RCRA-SQG
IRVING FOREST PRODUCTS LIMITED	FINDS,RCRA-CESQG,MANIFEST,MANIFEST
J PAUL LEVESQUE & SONS INC - MASAR	FINDS
PRUE OIL CO	ICIS
FRASER TIMBER LIMITED - MASARDIS	AIRS
IRVING FOREST PRODUCTS - PINKHAM M	MANIFEST



SITE NAME: MMA Railway - Ashland ADDRESS: MMA Railway - Ashland Ashland ME 04732 LAT/LONG: 46.6300 / 68.4148 CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02775704.3r
DATE: May 21, 2010 12:28 pm

Copyright © 2010 EDR, Inc. © 2010 Tels Atlas Rel. 07/2007.



SITE NAME: MMA Railway - Ashland MMA Railway - Ashland Ashland ME 04732 ADDRESS: LAT/LONG: 46.6300 / 68.4148

CLIENT: Haley & Aldrich CONTACT: Andrew Collins INQUIRY #: 02775704.3r Haley & Aldrich, Inc. DATE:

May 21, 2010 12:28 pm

	2	

MMA Railway - Portage MMA Railway - Portage Portage, ME 04768

Inquiry Number: 02777161.1r

May 24, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	ES1
Overview Map.	2
Detail Map.	3
Map Findings Summary	4
Map Findings.	7
Orphan Summary.	12
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map.	A-5
Physical Setting Source Map	A-11
Physical Setting Source Map Findings	A-13
Physical Setting Source Records Searched	A-16

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - PORTAGE PORTAGE, ME 04768

COORDINATES

Latitude (North): 46.754700 - 46* 45' 16.9" Longitude (West): 68.489200 - 68* 29' 21.1"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): 539012.4 UTM Y (Meters): 5177813.5

Elevation: 682 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 46068-G4 PORTAGE LAKE EAST, ME

Most Recent Revision: 1986

South Map: 46068-F4 ASHLAND, ME

Most Recent Revision: 1986

Southwest Map: 46068-F5 LITTLE MACHIAS LAKE, ME

Most Recent Revision: 198

West Map: 46068-G5 PORTAGE LAKE WEST, ME

Most Recent Revision: 1986

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Proposed NPL.....Proposed National Priority List Sites NPL LIENS..... Federal Superfund Liens Federal Delisted NPL site list Delisted NPL...... National Priority List Deletions Federal CERCLIS list CERCLIS...... Comprehensive Environmental Response, Compensation, and Liability Information System FEDERAL FACILITY...... Federal Facility Site Information listing Federal CERCLIS NFRAP site List CERC-NFRAP...... CERCLIS No Further Remedial Action Planned Federal RCRA CORRACTS facilities list CORRACTS..... Corrective Action Report Federal RCRA non-CORRACTS TSD facilities list RCRA-TSDF...... RCRA - Treatment, Storage and Disposal Federal RCRA generators list RCRA-LQG_____RCRA - Large Quantity Generators RCRA-SQG..... RCRA - Small Quantity Generators RCRA-CESQG...... RCRA - Conditionally Exempt Small Quantity Generator Federal institutional controls / engineering controls registries US ENG CONTROLS...... Engineering Controls Sites List US INST CONTROL..... Sites with Institutional Controls Federal ERNS list ERNS..... Emergency Response Notification System State- and tribal - equivalent CERCLIS SHWS...... Remediation Sites List State and tribal landfill and/or solid waste disposal site lists SWF/LF..... Solid Waste Facility List LCP..... Municipal Landfill Closure Database State and tribal leaking storage tank lists LUST...... Hazardous Material and Oil Spill System Database (H.O.S.S.) LAST...... HOSS Database INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land State and tribal registered storage tank lists AST..... Aboveground Storage Tanks

FEMA UST..... Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

INST CONTROL...... Remediation Sites List

State and tribal voluntary cleanup sites

VCP...... Remediation Sites List

INDIAN VCP..... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS..... Remediation Sites List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

ODI...... Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES...... Remediation Sites List

DEL SHWS....... Sites Removed from the Uncontrolled Sites List

US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS...... Land Use Control Information System LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System SPILLS..... Hazardous Material and Oil Spill System Database

Other Ascertainable Records

FUDS. Formerly Used Defense Sites

CONSENT..... Superfund (CERCLA) Consent Decrees

MINES..... Mines Master Index File

TRIS...... Toxic Chemical Release Inventory System

TSCA..... Toxic Substances Control Act

FTTS......FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS......FIFRA/TSCA Tracking System Administrative Case Listing

SSTS...... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System

FINDS....... Facility Index System/Facility Registry System RAATS...... RCRA Administrative Action Tracking System

INDIAN RESERV......Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA...... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER....... PCB Transformer Registration Database COAL ASH DOE.......... Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 02/01/2010 has revealed that there is 1 UST


site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
COFFIN GENERAL STORE	24 MAIN ST	ENE 1/2 - 1 (0.739 mi.)	1	7

Due to poor or inadequate address information, the following sites were not mapped:


Site Name	Database(s)
PORTAGE KEY LOCK	AST, TIER 2
DAIGLE PORTAGE KEY LOCK	AST, TIER 2
DAIGLE OIL PORTAGE KEY LOCK	TIER 2
ROBINSONS MARKET	LAST
IRVING'S PINKHAM SAWMILL	LAST
HOLMES ESTATE OF, JAMES	LAST
ST. PETER TED	LAST
ACROSS FROM SAWMILL AT END OF	SWF/LF
RT 11	SWF/LF
PINKHAM LUMBER	LUST, SPILLS
STATION B C	UST
ROBINSON, VINAL	UST
PORTAGE STOREHOUSE	UST
CONDON, WILLIAM	UST
CYR LUMBER INC	UST
CYR, GILMAN	UST
CYR LUMBER	UST
PINKHAM LUMBER	UST
CAMP PORTAGE LAKE LOT 26	UST
THERIAULT, LAUREL	UST
AJ SOUCY & SON	UST
PORTAGE TOWN OF	UST
DANKER, CHERRY	UST
J PAUL LEVESQUE & SONS INC MASARDI	AST
DAIGLE OIL PORTAGE KEYLOCK	AST
RT 11	RCRA-SQG
PORTAGE RD	RCRA-CESQG, FINDS, MANIFEST,
	MANIFEST
J PAUL LEVESQUE & SONS INC - MASAR	FINDS
MPS - POLE #38927	SPILLS
PORTAGE, DAIGLE OIL FACILITY #5	SPILLS
MAINE WOOD CO - LOG YARD	SPILLS
IRVING FOREST PRODUCTS - PINKHAM S	AIRS
FRASER LEVESQUE - MASARDIS	AIRS
MAINE WOODS CO	AIRS

OVERVIEW MAP - 02777161.1r



SITE NAME: MMA Railway - Portage ADDRESS: MMA Railway - Portage Portage ME 04768 LAT/LONG: 46.7547 / 68.4892 CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02777161.1r
DATE: May 24, 2010 1:20 pm





SITE NAME: MMA Railway - Portage ADDRESS: MMA Railway - Portage Portage ME 04768
LAT/LONG: 46.7547 / 68.4892

CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02777161.1r
DATE: May 24, 2010 1:20 pm

MMA Railway - Fort Kent MMA Railway - Fort Kent Fort Kent, ME 04743

Inquiry Number: 02775704.1r

May 21, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	_ ES1
Overview Map.	. 2
Detail Map	_ 3
Map Findings Summary.	_ 4
Map Findings.	_ 7
Orphan Summary.	. 43
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	. A-1
Physical Setting Source Summary	. A-2
Physical Setting SSURGO Soil Map	. A-5
Physical Setting Source Map.	_ A-14
Physical Setting Source Map Findings.	A-15
Physical Setting Source Records Searched	Δ-27

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - FORT KENT FORT KENT, ME 04743

COORDINATES

Latitude (North): 47.270700 - 47* 16' 14.5" Longitude (West): 68.593900 - 68* 35' 38.0"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): 530718.6 UTM Y (Meters): 5235108.0

Elevation: 581 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 47068-C5 FORT KENT NORTH, ME

Most Recent Revision: 1985

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL..... National Priority List

Proposed NPL.......Proposed National Priority List Sites NPL LIENS.....Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list	
CERCLISFEDERAL FACILITY	Comprehensive Environmental Response, Compensation, and Liability Information System Federal Facility Site Information listing
Federal CERCLIS NFRAP s	ite List
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
Federal RCRA CORRACTS	facilities list
CORRACTS	Corrective Action Report
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators li	'st
RCRA-SQG	RCRA - Large Quantity Generators _ RCRA - Small Quantity Generators _ RCRA - Conditionally Exempt Small Quantity Generator
Federal institutional control	ls / engineering controls registries
US ENG CONTROLS	Engineering Controls Sites List Sites with Institutional Controls
Federal ERNS list	
ERNS.	Emergency Response Notification System
State- and tribal - equivalen	t CERCLIS
SHWS	. Remediation Sites List
State and tribal landfill and/	or solid waste disposal site lists
SWF/LF	_ Solid Waste Facility List _ Municipal Landfill Closure Database
State and tribal leaking stor	age tank lists
LUSTINDIAN LUST	. Hazardous Material and Oil Spill System Database (H.O.S.S.) Leaking Underground Storage Tanks on Indian Land
State and tribal registered s	torage tank lists
INDIAN UST	. Aboveground Storage Tanks . Underground Storage Tanks on Indian Land . Underground Storage Tank Listing

State and tribal voluntary cleanup sites

INDIAN VCP......Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations ODI..... Open Dump Inventory INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

DEL SHWS...... Sites Removed from the Uncontrolled Sites List US HIST CDL...... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information LUCIS_____Land Use Control Information System LIENS_____ Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS_____ Hazardous Materials Information Reporting System

Other Ascertainable Records

RCRA-NonGen_____RCRA - Non Generators DOT OPS..... Incident and Accident Data DOD...... Department of Defense Sites FUDS..... Formerly Used Defense Sites

CONSENT...... Superfund (CERCLA) Consent Decrees

ROD...... Records Of Decision UMTRA...... Uranium Mill Tailings Sites MINES..... Mines Master Index File

TRIS...... Toxic Chemical Release Inventory System

TSCA _____ Toxic Substances Control Act FTTS_____ FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS...... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System

PADS...... PCB Activity Database System MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database

RAATS.....RCRA Administrative Action Tracking System

NPDES...... Wastewater Facilities Listing

DRYCLEANERS...... Drycleaner Facilities AIRS..... Emissions Inventory Data INDIAN RESERV.....Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER...... PCB Transformer Registration Database

COAL ASH DOE..... Sleam-Electric Pian Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

State and tribal leaking storage tank lists

LAST: A listing of leaking aboveground storage tanks.

A review of the LAST list, as provided by EDR, and dated 03/13/2010 has revealed that there is 1 LAST site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHRIST CHURCH BUILDING	99 E MAIN ST	SSE 1/2 - 1 (0.857 mi.)	14	29

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 02/01/2010 has revealed that there are 11 UST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ST LOUIS CHURCH	11 EAST MAIN ST	ESE 1/8 - 1/4 (0.183 mi.)	1	7
T & D REAL ESTATE HOLDINGS LLC	15 EAST MAIN ST	SE 1/8 - 1/4 (0.186 mi.)	2	8
VALLEY FUNERAL SVC INC	9 EAST MAIN ST	ESE 1/8 - 1/4 (0.187 mi.)	3	10
THIDOBEAU INSURANCE AGENCY	5 EAST MAIN ST	E 1/8 - 1/4 (0.209 mi.)	4	11
DAIGLE DENTAL BUILDING	BOLDUC AVE	SSE 1/4 - 1/2 (0.405 mi.)	5	12

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GAS N GO FOOD	51 EAST MAIN	SSE 1/4 - 1/2 (0.421 mi.)	A6	13
FOREST MANOR	25 BOLDUC AVE	SSE 1/4 - 1/2 (0.423 mi.)	A7	17
DAIGLE, JOHN A	28 CANNAN ST	SSE 1/2 - 1 (0.705 mi.)	12	27
NADEAU, LEO & JEANINE	96 EAST MAIN ST	SSE 1/2 - 1 (0.830 mi.)	13	28
Lower Elevation	Address	Direction / Distance	Map ID	Page
MCCLAREN MCBREAITY P V ROY CO INC	63 PARK CIRCLE 2 MARKET ST	ENE 1/2 - 1 (0.630 mi.) SSE 1/2 - 1 (0.918 mi.)	11 16	26 37

State and tribal institutional control / engineering control registries

INST CONTROL: Sites with Land Use Restrictions in place.

A review of the INST CONTROL list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1 INST CONTROL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUCY'S ECONOMAT	67 EAST MAIN STREET	SSE 1/2 - 1 (0.567 mi.)	10	22

State and tribal voluntary cleanup sites

VCP: A list of sites where the necessary investigation and/or remedation activities have been completed to the Department's satisfaction and the applicants to the VRAP have been issued final certification documents. The list does not include those sites that are currently participating in the VRAP but have not yet received certification.

A review of the VCP list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1 VCP site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUCY'S ECONOMAT	67 EAST MAIN STREET	SSE 1/2 - 1 (0.567 mi.)	10	22

State and tribal Brownfields sites

BROWNFIELDS: A listing of brownfields site locations.

A review of the BROWNFIELDS list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1 BROWNFIELDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
STEVE'S CYCLE AND MARINE	13 MARKET STREET	SSE 1/2 - 1 (0.964 mi.)	B17	38

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properites addressed by Cooperative Agreement Recipients and Brownfields properties addressed by Targeted Brownfields Assessments

A review of the US BROWNFIELDS list, as provided by EDR, and dated 03/02/2010 has revealed that there is 1 US BROWNFIELDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
STEVE'S CYCLE & MARINE	13 MARKET STREET	SSE 1/2 - 1 (0.964 mi.)	B19	39

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES: The Sites List Database is the public record of information regarding properties that have been, are now, or are planned to be addressed by the Division of Remediation of the Bureau of Remediation and Waste Management. This database is not intended to be a comprehensive, all-inclusive source of information regarding the properties listed therein.

A review of the ALLSITES list, as provided by EDR, and dated 03/01/2010 has revealed that there are 2 ALLSITES sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUCY'S ECONOMAT	67 EAST MAIN STREET	SSE 1/2 - 1 (0.567 ml.)	10	22
Lower Elevation	Address	Direction / Distance	Map ID	Page
STEVE'S CYCLE AND MARINE	13 MARKET STREET	SSE 1/2 - 1 (0.964 mi.)	B17	38

Records of Emergency Release Reports

SPILLS: Department of Environmental Protection's Hazardous Material & Oil Spill Database.

A review of the SPILLS list, as provided by EDR, and dated 03/13/2010 has revealed that there are 2 SPILLS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOUCY'S ECONOMAT	67 EAST MAIN STREET	SSE 1/2 - 1 (0.567 ml.)	10	22
Lower Elevation	Address	Direction / Distance	Map iD	Page
BANGOR & AROOSTOOK RAILYARD	20 DUBE ST	SSE 1/2 - 1 (0.883 mi.)	15	31

Other Ascertainable Records

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 10/19/2009 has revealed that there are 2 FINDS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FOREST HILL MANOR, NORTHERN MA	25 BOLDUC AVE	SSE 1/4 - 1/2 (0.423 mi.)	A9	22
Lower Elevation	Address	Direction / Distance	Map ID	Page
STEVE'S CYCLE & MARINE	13 MARKET STREET	SSE 1/2 - 1 (0.964 mi.)	B18	39

TIER 2: A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.


A review of the TIER 2 list, as provided by EDR, and dated 12/31/2008 has revealed that there is 1 TIER 2 site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NORTHERN MAINE MEDICAL CENTER	25 BOLDUC AVENUE	SSE 1/4 - 1/2 (0.423 mi.)	A8	18

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
DAIGLE OIL FORT KENT BULK PLANT	TIER 2
FORT KENT BULK PLANT	AST, TIER 2
DAIGLE FORT KENT BULK PLANT	AST,TIER 2
ST FRANCIS ELEMENTARY	FTTS,HIST FTTS INSP
DEAD RIVER CO	LAST
OLD BULK PLANT	LAST
FTKT BULK PLANT	LAST
NORTHERN TIMBER	LAST
FORT KENT MAINWAY	LUST,SPILLS
IRVING MAINWAY	LUST
KENT INC	UST
SILVER, DAVID	UST
UNIVERSITY OF MAINE AT FORT KENT	AST
DAIGLE OIL FORT KENT BULK PLANT	AST
NORTHLAND AVIATION INC	FINDS,RCRA-NLR
CIRCLE K #7051	FINDS,RCRA-CESQG
FORT KENT PUBLIC WORKS	FINDS
FORT KENT, TOWN OF	FINDS
MONTREAL, MAINE & ATLANTIC RAILWAY	SPILLS
FORT KENT UTILITY DISTRICT	ICIS


OVERVIEW MAP - 02775704.1r



SITE NAME: MMA Railway - Fort Kent MMA Railway - Fort Kent Fort Kent ME 04743 47.2707 / 68.5939 ADDRESS: LAT/LONG:

CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02775704 1-

May 21, 2010 12:39 pm DATE:



SITE NAME: MMA Railway - Fort Kent CLIENT:
ADDRESS: MMA Railway - Fort Kent CONTACT:
Fort Kent ME 04743 INQUIRY #:
LAT/LONG: 47.2707 / 68.5939 DATE:

CLIENT: Haley & Aldrich, Inc. CONTACT: Andrew Collins INQUIRY#: 02775704.1r

TE: May 21, 2010 12:39 pm

Copyright © 2010 EDR, Inc. © 2010 Tele Atlas Rel. 07/2007.

MMA Railway - Louisiana Pacific Facility MMA Railway - Louisiana Pacific Facility New Limerick, ME 04730

Inquiry Number: 02777161.2r

May 24, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	. ES1
Overview Map	. 2
Detail Map.	. 3
Map Findings Summary.	_ 4
Map Findings.	_ 7
Orphan Summary	. 8
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	. A-1
Physical Setting Source Summary.	. A-2
Physical Setting SSURGO Soil Map	. A-5
Physical Setting Source Map	_ A-13
Physical Setting Source Map Findings.	A-15
Physical Setting Source Records Searched	Δ-18

Thank you for your business. Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates, All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR), The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - LOUISIANA PACIFIC FACILITY **NEW LIMERICK, ME 04730**

COORDINATES

46.109100 - 46° 6' 32.8" Latitude (North): Longitude (West): 67.953900 - 67* 57' 14.0"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): UTM Y (Meters): 580844.9 5106483.0

Elevation: 396 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 46067-A8 LINNEUS, ME

Most Recent Revision: 1984

North Map: 46067-B8 TWIN BROOK, ME

Most Recent Revision:

1984

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

..... National Priority List

Proposed NPL Proposed National Priority List Sites

NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL...... National Priority List Deletions

Federal CERCLIS list	
CERCLISFEDERAL FACILITY	Comprehensive Environmental Response, Compensation, and Liability Information System Federal Facility Site Information listing
Federal CERCLIS NFRAP si	ite List
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
Federal RCRA CORRACTS	facilities list
CORRACTS	. Corrective Action Report
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
Federal RCRA generators li	st
-	RCRA - Large Quantity Generators
RCRA-SQG	RCRA - Small Quantity Generators
RCRA-CESQG.	RCRA - Conditionally Exempt Small Quantity Generator
Federal institutional control	ls / engineering controls registries
	. Engineering Controls Sites List
US INST CONTROL	_ Sites with Institutional Controls
Federal ERNS list	
ERNS	Emergency Response Notification System
State- and tribal - equivalent	t CERCLIS
SHWS	
011110	, Normaldion oftes Elst
State and tribal landfill and/	or solid waste disposal site lists
SWF/LF	
LCP	. Municipal Landfill Closure Database
State and tribal leaking store	age tank lists
LUST	. Hazardous Material and Oil Spill System Database (H.O.S.S.)
LAST	. HOSS Database
INDIAN LUST	Leaking Underground Storage Tanks on Indian Land
State and tribal registered s	torage tank lists
UST	. Underground Storage Tank Database
AST	Aboveground Storage Tanks
INDIAN UST	. Underground Storage Tanks on Indian Land
FEMA UST	Underground Storage Tank Listing
State and tribal institutional	control / engineering control registries
INST CONTROL	Remediation Sites List

State and tribal voluntary cleanup site

VCP..... Remediation Sites List

INDIAN VCP..... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS..... Remediation Sites List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

ODI..... Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

DEL SHWS..... Sites Removed from the Uncontrolled Sites List

US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS...... Land Use Control Information System LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System SPILLS..... Hazardous Material and Oil Spill System Database

Other Ascertainable Records

DOD...... Department of Defense Sites
FUDS...... Formerly Used Defense Sites

CONSENT...... Superfund (CERCLA) Consent Decrees

TRIS...... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS...... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems ICIS...... Integrated Compliance Information System PADS...... PCB Activity Database System MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database FINDS......Facility Index System/Facility Registry System RAATS.......RCRA Administrative Action Tracking System NPDES...... Wastewater Facilities Listing AIRS..... Emissions Inventory Data TIER 2..... Tier 2 Information Listing INDIAN RESERV.....Indian Reservations SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List PCB TRANSFORMER...... PCB Transformer Registration Database COAL ASH DOE...... Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS


Surrounding sites were not identified.

Unmappable (orphan) sites are not considered in the foregoing analysis.

Due to poor or inadequate address information, the following sites were not mapped:


Site Name	Database(s)
LOUISIANA PACIFIC CORP	UIC, LUST
THE LANE CONSTUCTION CORP HOULT	AST, TIER 2
LOUISIANA PACIFIC CORP.	AST, SPILLS, TIER 2
STEVE SPURLING	LAST
WELDON WILLETTE	LAST
WEST RIDGE RD	SWF/LF
VOR, HOULTON	UST
RCAG, HOULTON	UST
QUINT, ANDREW O	UST
MCGILLICUDY, DON	UST
HENDERSON, R KEITH	UST
LE ANDERSON FARMS INC	UST
WRIGHT, DENNIS	UST
A E STANLEY MANUFACTURING CO	UST
LINNEUS TOWN OF	UST
MDOT MAINTENANCE FACILITY	UST
LITTLETON SCHOOL	UST
HUTCHINSON, CLAUDE	UST
GENTLE FARM	UST
CHAREST, DANIEL R	UST
NICKERSON, LOWELL	UST
BAIETTI, DONNA	UST
EMERSON FARMS	UST
LOUISIANA PACIFIC CORP	UST
1 USHY RTE	RCRA-NonGen, FINDS
AROOSTOOK MILLING CO 16 BUFFALO	FINDS
AROOSTOOK MILLING CO 5 HILLVIEW	FINDS
AROOSTOOK MILLING CO 1 PHYLLIS	FINDS
LORING AFB - SEARSPORT PIPELINE	SPILLS
LOUISIANA PACIFIC	SPILLS
LOUISIANA PACIFIC CORP	SPILLS
LOUISIANA PACIFIC	SPILLS
LOUISIANA PACIFIC	SPILLS
STEVEN'S SCRAP YARD	ICIS
LOUISIANA PACIFIC CORP	ICIS
STEELSTONE INDUSTRIES INC - HOULTO	AIRS
LOUISIANA-PACIFIC CORP - NEW LIME	AIRS
LOUISIANA PACIFIC	MANIFEST

OVERVIEW MAP - 02777161.2r



SITE NAME: MMA Railway - Louisiana Pacific Facility ADDRESS: MMA Railway - Louisiana Pacific Facility New Limerick ME 04730

LAT/LONG: 46.1091 / 67.9539 CLIENT: Haley & Aldrich, Inc. CONTACT: Andrew Collins INQUIRY #: 02777161.2r DATE: May 24, 2010 1:21 pm



SITE NAME: MMA Railway - Louisiana Pacific Facility
ADDRESS: MMA Railway - Louisiana Pacific Facility
New Limerica ME 04730

LAT/LONG: 46.1091 / 67.9539 CLIENT: Haley & Aldrich, Inc. CONTACT: Andrew Collins INQUIRY #: 02777161.2r DATE: May 24, 2010 1:21 pm

2					

MMA Railway - Presque Isle MMA Railway - Presque Isle Presque Isle, ME 04769

Inquiry Number: 02777161.5r

May 24, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	ES1
Overview Map.	2
Detail Map	3
Map Findings Summary	. 4
Map Findings.	. 7
Orphan Summary.	549
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-16
Physical Setting Source Map Findings	A-18
Physical Setting Source Records Searched	A-21

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR), The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - PRESQUE ISLE PRESQUE ISLE, ME 04769

COORDINATES

Latitude (North):

46.688900 - 46' 41' 20.0"

Longitude (West):

68.001800 - 68' 0' 6.5"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): UTM Y (Meters):

576330.2 5170859.0

Elevation:

503 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:

46068-F1 PRESQUE ISLE, ME

Most Recent Revision:

1984

East Map:

46067-F8 EASTON, ME

Most Recent Revision:

1984

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

..... National Priority List

Proposed NPL.....Proposed National Priority List Sites

NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

State and tribal voluntary c	leanup sites
	. Underground Storage Tanks on Indian Land . Underground Storage Tank Listing
State and tribal registered s	torage tank lists
INDIAN LUST	Leaking Underground Storage Tanks on Indian Land
State and tribal leaking stor	rage tank lists
SWF/LF	_ Solid Waste Facility List _ Municipal Landfill Closure Database
	or solid waste disposal site lists
SHWS	Remediation Sites List
State- and tribal - equivalen	et CERCLIS
US ENG CONTROLS	. Engineering Controls Sites List . Sites with Institutional Controls
	ls / engineering controls registries
RCRA-LQG	RCRA - Large Quantity Generators
Federal RCRA generators I	ist
	RCRA - Treatment, Storage and Disposal
Federal RCRA non-CORRA	CTS TSD facilities list
CORRACTS	Corrective Action Report
Federal RCRA CORRACTS	facilities list
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
Federal CERCLIS NFRAP s	ite List
Federal CERCLIS list CERCLISFEDERAL FACILITY	Comprehensive Environmental Response, Compensation, and Liability Information System Federal Facility Site Information listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

INDIAN VCP..... Voluntary Cleanup Priority Listing

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

ODI_____ Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

DEL SHWS..... Sites Removed from the Uncontrolled Sites List US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS.....Land Use Control Information System LIENS.____ Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS_____ Hazardous Materials Information Reporting System

Other Ascertainable Records

DOT OPS_____ Incident and Accident Data DOD...... Department of Defense Sites FUDS...... Formerly Used Defense Sites

CONSENT..... Superfund (CERCLA) Consent Decrees

ROD......Records Of Decision UMTRA.....Uranium Mill Tailings Sites

MINES...... Mines Master Index File
TRIS...... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

ICIS...... Integrated Compliance Information System

RADINFO...... Radiation Information Database

RAATS...... RCRA Administrative Action Tracking System

AIRS Emissions Inventory Data INDIAN RESERV Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER...... PCB Transformer Registration Database COAL ASH DOE...... Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/17/2010 has revealed that there are 3 RCRA-SQG sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CITY DRY CLEANERS PRESQUE ISLE VW INC DBA BATES	636 MAIN ST 800 MAIN ST	NNW 1/2 - 1 (0.901 mi.)	S74 BH237	145 437
KMART #4709	830 MAIN STREET	NNW 1/2 - 1 (0.949 mi.)	BL266	494

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 02/17/2010 has revealed that there are 4 RCRA-CESQG sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOWE'S OF PRESQUE ISLE #2209	135 MAYSVILLE ROAD	N 1/4 - 1/2 (0.485 mi.)	K43	70
KELCLAN INC KELLEYS FABRICARE	654 MAIN ST	WNW 1/2 - 1 (0.586 mi.)	X93	175
WAL-MART SUPERCENTER #1924	781 MAIN ST	NNW 1/2 - 1 (0.866 mi.)	BD214	397
CIRCLE K #7059	800 NORTH MAIN STREET	NNW 1/2 - 1 (0.901 mi.)	BH240	451

Federal ERNS list

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/2009 has revealed that there is 1 ERNS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
23 2ND STREET	23 2ND STREET	SW 1/2 - 1 (0.737 mi.)	AM151	284

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Protection's Hazardous Material and Oil Spill System Database (H.O.S.S.).

A review of the LUST list, as provided by EDR, and dated 03/13/2010 has revealed that there are 10 LUST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
THE AROOSTOOK MEDICAL CTR	140 ACADEMY STREET	SSW 1/2 - 1 (0.788 mi.)	AS179	320
MARTIN STEVE	128 HARDY STREET	S 1/2 - 1 (0.890 mi.)	BE224	418
Lower Elevation	Address	Direction / Distance	Map ID	Page
LADNERS EXXON OLD MAINE MUTUAL INSURANCE BUI RH FOSTER KEYBANK STEVENS,ENGLES,BISHOP,& SPRAUG TAYLOR RENTAL CENTER AMES CORP IRVING OIL BULK PLANT	CORNER OF MAIN / NORT	W 1/2 - 1 (0.529 mi.)	P60	110
	555 MAIN STREET	W 1/2 - 1 (0.535 mi.)	Q64	117
	700 MAIN STREET	NW 1/2 - 1 (0.676 mi.)	AH129	238
	187 STATE STREET	SW 1/2 - 1 (0.743 mi.)	AL152	284
	428 MAIN STREET	SW 1/2 - 1 (0.800 mi.)	AU186	328
	16 DYER ST	WSW 1/2 - 1 (0.809 mi.)	BG223	414
	795 MAIN ST	NNW 1/2 - 1 (0.895 mi.)	BH231	425
	800 N MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH238	439

LAST: A listing of leaking aboveground storage tanks.

A review of the LAST list, as provided by EDR, and dated 03/13/2010 has revealed that there are 25 LAST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUTCHINS, JAMES	75 LOMBARD ST	SE 1/8 - 1/4 (0.198 mi.)	7	13
NICKERSON DAROLD	17 OAK STREET	SW 1/2 - 1 (0.570 mi.)	78	156
LEWIS WILLARD	71 HILLSIDE STREET	SSW 1/2 - 1 (0.597 mi.)	101	191
BRADLEY RESIDENCE	64 DUDLEY STREET	SSW 1/2 - 1 (0.606 mi.)	Z105	197
BRINKMAN, GILBERT	50 HARDY ST.	S 1/2 - 1 (0.686 mi.)	137	259
ALISON AND PAT FITZPATRICK	58 BARTON STREET	SSW 1/2 - 1 (0.696 mi.)	139	264
PRESQUE ISLE NURSING HOME	162 ACADEMY ST	SSE 1/2 - 1 (0.988 mi.)	BP281	519
Lower Elevation	Address	Direction / Distance	Map ID	Page
SAUCIER, DIANE	39 WINTER ST	W 1/4 - 1/2 (0.428 mi.)	132	53
PELKEY, DELORES	10 JORDAN ST	W 1/4 - 1/2 (0.465 mi.)	38	60
UNKNOWN RESIDENT	9 SUMMER ST	WSW 1/2 - 1 (0.518 mi.)	N50	83
DEAD RIVER COMPNAY	580 MAIN STREET	W 1/2 - 1 (0.518 mi.)	L53	94
MOSHER, JIM	17 SOUTH STREET	WSW 1/2 - 1 (0.538 mi.)	65	119
DAVIS BILL	16 BLAKE STREET	WSW 1/2 - 1 (0.637 mi.)	117	219
ROY, BONNIE	BOX 290	NW 1/2 - 1 (0.694 mi.)	138	261
Not reported		SW 1/2 - 1 (0.701 mi.)	AK141	267
NICK HANKS	14 VERONNE ST	WNW 1/2 - 1 (0.750 mi.)	156	290
KEVIN SIPE	30 WILSON ST	W 1/2 - 1 (0.762 mi.)	AP162	299
MAINE POTATO GROWERS	50 PARSONS ST	WSW 1/2 - 1 (0.864 mi.)	BC210	380
RHODA BROWN	31 HAYWARD ST	SSW 1/2 - 1 (0.915 mi.)	246	460
WALSH LOUISE	16 CARON STREET	WNW 1/2 - 1 (0.926 mi.)	248	464
MARTHA GRANT	19 PARK ST	W 1/2 - 1 (0.951 mi.)	BK268	497
MILLER STILLMAN JR.	59 STATE STREET	WSW 1/2 - 1 (0.969 mi.)	BM274	507

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUCEY,ROGER	8 EPWORTH STREET	SW 1/2 - 1 (0.978 mi.)	276	511
COWENS, DAVID RAULE MCHATTEN	DEEP COVE SHORES ROAD 42 STATE STREET	SW 1/2 - 1 (0.991 mi.) WSW 1/2 - 1 (0.996 mi.)	287 BQ293	531 540

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 02/01/2010 has revealed that there are 136 UST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRAL AROOSTOOK ARC OFFICES	21 LOMARD ST	SSW 1/8 - 1/4 (0.208 mi.)	12	30
OSBORN, EVERETT	7 HILLSIDE AVE	SSW 1/4 - 1/2 (0.394 mi.)	24	45
MARTIN, DALE & CINDY	9 BARTON ST	SSW 1/4 - 1/2 (0.431 mi.)	34	56
FULL GOSPEL ASSEMBLY OF PI	7 DUDLEY ST	SW 1/4 - 1/2 (0.457 mi.)	36	58
SHAFFER, SIMON PETER SHEILA	45 HILLSIDE ST	SSW 1/2 - 1 (0.530 mi.)	62	115
FREEMAN, GREGORY J	316 STATE ST	S 1/2 - 1 (0.539 mi.)	66	121
WARD, KIRK A	279 STATE ST	SSW 1/2 - 1 (0.571 mi.)	80	161
MARGARET TUCK	35 BARTON ST	SSW 1/2 - 1 (0.576 mi.)	V85	165
BOLDUC, ROBERT J	BELGRADE AVE	SSW 1/2 - 1 (0.581 mi.)	W87	169
LEDGER, FLOYD H	268 STATE ST	SSW 1/2 - 1 (0.582 mi.)	W88	170
CONDONS CANDIES	266 STATE ST	SSW 1/2 - 1 (0.586 mi.)	V89	171
MAISEL, ROBERT	52 DUDLEY ST	SSW 1/2 - 1 (0.586 mi.)	90	172
BOYLE, GERALD & CAROL	41 BARTON ST	SSW 1/2 - 1 (0.601 mi.)	103	195
29 OAK ST ASHLAND HOUSING CORP	29 OAK ST	SW 1/2 - 1 (0.604 mi.)	104	196
TAGGETT, GLENDA M	248 STATE ST	SSW 1/2 - 1 (0.612 mi.)	Z109	209
ANDREWS, ROBERT D	249 STATE ST	SSW 1/2 - 1 (0.612 mi.)	Z110	210
ALBERT, PETER & ANN	242 STATE ST	SSW 1/2 - 1 (0.620 mi.)	Z111	211
TRINITY LODGE 130 A&FM	230 STATE ST	SSW 1/2 - 1 (0.640 mi.)	118	222
RAY LAMOREAU INC	48 THIRD ST	SW 1/2 - 1 (0.727 mi.)	AL146	275
MARGOLIS, JOHN DR	64 BARTON ST	SSW 1/2 - 1 (0.732 mi.)	148	278
MERSEREAU, BETTE N	54 THIRD ST	SW 1/2 - 1 (0.743 mi.)	AL154	288
UNIVERSITY OF ME PRESQUE ISLE	75 HARDY ST	S 1/2 - 1 (0.751 mi.)	AN157	294
VARNUM, NORMAN K	79 HARDY ST	S 1/2 - 1 (0.761 mi.)	AN160	297
LIBBY, MARY E	49 THRID ST	SW 1/2 - 1 (0.764 mi.)	164	303
VARNUM, NORMAN K	166 ACADEMY ST	SSW 1/2 - 1 (0.782 mi.)	AR168	307
BATES, ED	165 ACADEMY ST	SSW 1/2 - 1 (0.782 mi.)	AR169	308
BOUCHARD, BERNARD J	15 COOK ST	SSW 1/2 - 1 (0.786 mi.)	173	312
PARENT, SYLVIA	US RT 1	SSW 1/2 - 1 (0.788 mi.)	AR174	313
VICTORS IRVING	US RT 1	SSW 1/2 - 1 (0.788 mi.)	AR175	314
HIGGINS, GEORGE DR	122 ACADEMY ST	SSW 1/2 - 1 (0.798 mi.)	183	324
LAPLANTE, LARRY E	95 HARDY ST	S 1/2 - 1 (0.799 mi.)	AT184	326
GUS S DAUGHTERS GROC INC	70 ACADEMY ST	SW 1/2 - 1 (0.836 mi.)	193	338
YOUNG, CRAIG & MARCIA	123 HARDY ST	S 1/2 - 1 (0.873 mi.)	BE217	403
MARTIN, STEPHEN	128 HARDY ST	S 1/2 - 1 (0.890 mi.)	BE225	420
THE FAMILY DENTAL HLTH	114 CANTERBURY ST	S 1/2 - 1 (0.936 mi.)	252	473
PRESQUE ISLE NURSING HOME	162 ACADEMY ST	SSE 1/2 - 1 (0.988 mi.)	BP281	519
Lower Elevation	Address	Direction / Distance	Map ID	Page
HITCHCOCK, ALICE A	57 FORT ST	WSW 0 - 1/8 (0.045 mi.)	1	7

Lower Elevation	Address	Direction / Distance	Map ID	Page
ZIPPEL ELEMENTARY SCHOOL	42 FORT ST	SW 0 - 1/8 (0.098 mi.)	2	8
FAIRPOINT COMMUNICATIONS	100 CARMICHAEL ST	NW 1/8 - 1/4 (0.196 mi.)	B5	10
MITCHELL TRUCKING CO INC	75 DAVIS ST	NW 1/8 - 1/4 (0.198 mi.)	B9	27
GEORGES FAMILY RESTURANT	59 DAVIS ST	WNW 1/4 - 1/2 (0.279 mi.)	C15	32
PRESQUE ISLE HOUSING AUTHORITY	58 BIRCH ST	NW 1/4 - 1/2 (0.341 mi.)	16	33
PRESQUE ISLE HIGH SCHOOL	16 FORT ST	SW 1/4 - 1/2 (0.345 mi.)	D19	33 37
BRADLEY CITGO	46 NORTH ST	W 1/4 - 1/2 (0.351 mi.)	E20	40
THE MAD HATTER	5 MARTIN ST	W 1/4 - 1/2 (0.382 mi.)	F23	44
JIMS AUTOMOTIVE	30 NORTH ST	W 1/4 - 1/2 (0.408 mi.)	G26	47
ACADIA HOME CARE	26 NORTH ST	W 1/4 - 1/2 (0.417 mi.)	G27	48
SMYTHES IGA PLUS 480	23 NORTH ST	W 1/4 - 1/2 (0.422 mi.)	G27 G29	49
CONDON, RICKY G	47 ALLEN ST	SW 1/4 - 1/2 (0.422 mi.)	H31	52
UNDERWOOD, EDWARD L	45 ALLEN ST	SW 1/4 - 1/2 (0.432 mi.)	H35	52 57
LIONEL THERIAULT INC	10 DAVIS ST	WNW 1/4 - 1/2 (0.471 mi.)	J40	65
SANBORNS PRESQUE ISLE TERM	5 DAVIS ST	WNW 1/4 - 1/2 (0.492 mi.)	44	74
NORTH PLAZA IGA FOODLINER	5 NORTH ST	W 1/4 - 1/2 (0.499 mi.)	45	7 4 77
HOFFSES AUTO SALES INC	581 MAIN ST	W 1/2 - 1 (0.516 mi.)	L46	77 78
DEMERCHANT TRAILER PARK	7 DEMERCHANT	WNW 1/2 - 1 (0.521 mi.)	55	103
AROOSTOOK BEVERAGE CO	52 RICE ST	NW 1/2 - 1 (0.523 mi.)	O56	
GREAVES, JOHN & BONNIE	22 SOUTH ST	WSW 1/2 - 1 (0.523 mi.)	N58	105 107
CUSHMAN WATCH CLOCK & JEWLRY	619 MAIN ST	WNW 1/2 - 1 (0.526 mi.)	59	
MH PARSON & SONS	560 MAIN ST	W 1/2 - 1 (0.533 mi.)		108
MAINE MUTUAL FIRE INS CO	551 MAIN ST	W 1/2 - 1 (0.539 mi.)	P63 Q67	116 122
CITY DRY CLEANERS	636 MAIN ST	WNW 1/2 - 1 (0.554 mi.)	S74	145
BEVERAGE WAREHOUSE/YOUR VIDEO	640 MAIN ST	WNW 1/2 - 1 (0.561 mi.)	S76	
HARRYS AUTO SALES	641 MAIN ST	WNW 1/2 - 1 (0.568 mi.)	T77	152 154
OASIS PETROLEUM 1102	676 MAINE ST	WNW 1/2 - 1 (0.571 mi.)	T79	159
LUNDSTROM, CHARLES	24 BLAKE ST	SW 1/2 - 1 (0.572 mi.)	U81	162
WRAY, BARBARA S	24 BLAKE ST	SW 1/2 - 1 (0.572 mi.)	U82	163
GALLAGHER, GUY & PATRICIA	22 BLAKE ST	WSW 1/2 - 1 (0.588 mi.)	U96	185
GERVAIS, THERSA M	4 THIRD ST	WSW 1/2 - 1 (0.589 mi.)	U97	186
LADNER CAR WASH	666 MAIN ST	NW 1/2 - 1 (0.610 mi.)	AA106	200
STEEGO AUTO PARTS	6 ALLEN ST	WSW 1/2 - 1 (0.633 mi.)	AC115	218
PERCYS RENTS	690 MAIN ST	NW 1/2 - 1 (0.655 mi.)	AD119	223
NORTHERN LIGHTS MOTEL	692 MAIN ST	NW 1/2 - 1 (0.659 mi.)	AD122	229
GIGGEY, LARRY D	96 DYER ST	WSW 1/2 - 1 (0.661 mi.)	124	233
GRAVES FUNERAL HOME INC	30 CHURCH ST	SW 1/2 - 1 (0.663 mi.)	AG125	234
JP CASH MARKET	694 MAIN ST	NW 1/2 - 1 (0.663 mi.)	AD126	235
ROE, JOSEPH H JR	27 THIRD ST	SW 1/2 - 1 (0.667 mi.)	AG127	236
USAF RECRUITING OFFICE	485 MAIN ST	WSW 1/2 - 1 (0.668 mi.)	AF128	237
PRESQUE ISLE MOBIL	700 MAIN ST	NW 1/2 - 1 (0.676 mi.)	AH131	245
AKELEY, ROBERT V	32 3RD ST	SW 1/2 - 1 (0.696 mi.)	AJ140	266
PRESQUE ISLE CITY HALL	12 SECOND ST	SW 1/2 - 1 (0.701 mi.)	AK142	270
SWEENEY, WILLIAM E	34 3RD ST	SW 1/2 - 1 (0.702 mi.)	AJ143	271
MAURICES BARBER SHOP	4A BLAKE ST	WSW 1/2 - 1 (0.713 mi.)	145	274
US POSTAL SVC	23 SECOND ST	SW 1/2 - 1 (0.728 mi.)	AM147	277
FAIRPOINT COMMUNICATIONS	30 SECOND ST	SW 1/2 - 1 (0.735 mi.)	AM149	279
PUBLIC SAFETY BLDG	11 CHURCH ST	SW 1/2 - 1 (0.736 mi.)	AM150	282
KEY BANK	187 STATE ST	SW 1/2 - 1 (0.743 mi.)	AL153	286
KNIGHT, VAUGHN	62 DYER ST	WSW 1/2 - 1 (0.749 mi.)	155	289
STATE ST OFFICE	STATE & SECOND STS	SW 1/2 - 1 (0.759 mi.)	159	296
OBRIEN, WILLIAM & MARGARET	47 SECOND ST	SW 1/2 - 1 (0.761 mi.)	AO161	298
WARD, RAYMOND	30 WILSON ST	W 1/2 - 1 (0.762 mi.)	AP163	302
MARK TURNER MEMORIAL LIBRARY	39 SECOND ST	SW 1/2 - 1 (0.765 mi.)	AO165	304
SERVICE MERCHANDISE OF PI	435 MAIN ST	SW 1/2 - 1 (0.774 mi.)	AQ166	305
ST JOHN EPISCOPAL CHURCH	52 SECOND ST	SW 1/2 - 1 (0.777 mi.)	167	306

Lower Elevation	Address	Direction / Distance	Map ID	Page
NORTHEASTLAND HOTEL	436 MAIN ST	SW 1/2 - 1 (0.785 mi.)	AQ170	309
SOUCY, ROGER J	15 HALL ST	SW 1/2 - 1 (0.794 mi.)	AU182	323
STEVENS, EUGELS, BESLINGS, SPR	428 MAIN ST	SW 1/2 - 1 (0.800 mi.)	AU185	327
INSPOT REALTY	422 MAIN ST	SW 1/2 - 1 (0.820 mi.)	187	330
PRESQUE ISLE ARMORY	766 MAIN ST	NNW 1/2 - 1 (0.826 mi.)	AV189	333
PRESQUE ISLE NATIONAL GUARD	766 MAIN ST	NNW 1/2 - 1 (0.826 mi.)	AV191	335
WILDERS JEWELRY STORE	407 MAIN ST	SW 1/2 - 1 (0.844 mi.)	AY196	344
BRADEN CINEMA CENTER	408 MAIN ST	SW 1/2 - 1 (0.854 mi.)	AY200	350
MAINE POTATO GROWERS INC	56 PARSONS ST	WSW 1/2 - 1 (0.858 mi.)	BA205	361
DEAD RIVER CONVENIENCE	56 PARSONS ST	WSW 1/2 - 1 (0.858 mi.)	BA206	364
PRESQUE ISLE IRVING	52 ACADEMY ST	SW 1/2 - 1 (0.859 mi.)	BB207	370
DOCS PLACE	782 NORTH MAIN ST	NNW 1/2 - 1 (0.866 mi.)	BD211	383
YOUNG, TERRY D	SCHOOL ST	W 1/2 - 1 (0.868 mi.)	215	401
ERWIN, RUSSELL	36 ACADEMY ST	SW 1/2 - 1 (0.877 mi.)	BF219	409
FREEMAN, ANNE M	21 ACADEMY ST	SW 1/2 - 1 (0.885 mi.)	BF220	410
AROOSTOOK VALLEY RAILROAD	32 PARSONS ST	WSW 1/2 - 1 (0.886 mi.)	221	411
BULL, MERRILL R	17 ACADEMY ST	SW 1/2 - 1 (0.887 mi.)	BF222	413
TAYLOR RENTAL CENTER	16 DYER ST	WSW 1/2 - 1 (0.889 mi.)	BG223	414
VACANT	387 MAIN ST	SW 1/2 - 1 (0.892 mi.)	BI227	421
BURRELLS	387 MAIN ST	SW 1/2 - 1 (0.892 mi.)	BI228	422
RITE AID INC	387 MAIN ST	SW 1/2 - 1 (0.892 mi.)	BI229	423
DW APTS	10 ACADEMY ST	SW 1/2 - 1 (0.895 mi.)	230	424
THOMAS EQUIMPMENT LTD	795 NORTH MAIN ST	NNW 1/2 - 1 (0.895 mi.)	BH232	427
PRESQUE ISLE IRVING MAINWAY	800 NORTH MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH235	432
CITY REALTY INC	12 DYER ST	WSW 1/2 - 1 (0.902 mi.)	BG242	456
FIRST CITIZEN BANK	9 DYER ST	WSW 1/2 - 1 (0.908 mi.)	BJ243	457
FIRST CITIZEN BANK	9 DYER ST	WSW 1/2 - 1 (0.908 mi.)	BJ244	458
GOANS ELECTRICAL SHOP INC	17 PARSONS ST	WSW 1/2 - 1 (0.909 mi.)	245	459
SOCIAL SECURITY ADM	365 MAIN ST	SW 1/2 - 1 (0.922 mi.)	247	463
TONYS MAJOR MUFFLER & REPAIR	109 STATE ST	WSW 1/2 - 1 (0.926 mi.)	249	467
COLLINS, DALE/DBA D & J MARKET	96 STATE ST	WSW 1/2 - 1 (0.936 mi.)	251	472
STATE ST AUTO	87 STATE ST	WSW 1/2 - 1 (0.940 mi.)	253	474
MMP CORP	22 PARK ST	WSW 1/2 - 1 (0.941 mi.)	BK254	476
CAVENDISH AGRI SVCS	825 MAIN ST	NNW 1/2 - 1 (0.943 mi.)	BL257	482
AROOSTOOK CENTRE MALL	830 MAIN ST	NNW 1/2 - 1 (0.949 mi.)	BL265	493
COHEN, RICHARD & ARLA	19 PARK ST	W 1/2 - 1 (0.951 mi.)	BK269	500
GRIFFITHS, DAVID B	350 MAIN ST	SW 1/2 - 1 (0.971 mi.)	BN275	510
TURNER, EMILY	340 MAIN ST	SW 1/2 - 1 (0.984 mi.)	BN279	517
ST MARYS CATHOLIC CHURCH	336 MAIN ST	SW 1/2 - 1 (0.989 mi.)	BN283	525
RIVERSIDE BLDG	36 CHAPMAN ST	SW 1/2 - 1 (0.991 mi.)	BO286	530
RATHBUN LUMBER CO	43 STATE ST	WSW 1/2 - 1 (0.992 mi.)	BQ289	534
SOMERVILLE, GORDON LB CARTER CO	STATE ST HILL	WSW 1/2 - 1 (0.992 mi.)	BQ292	539
LB CARTER CO	45 CHAPMAN ST	SW 1/2 - 1 (0.999 mi.)	296	546

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Protection's Aboveground Storage Tank Database.

A review of the AST list, as provided by EDR, and dated 07/28/2009 has revealed that there are 17 AST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOWE'S OF PRESEQUE ISLE, ME 22 DR 1003 DEAD RIVER PRESQUE ISL	135 MAYSVILLE STREET 580 MAIN ST	N 1/4 - 1/2 (0.485 ml.) W 1/2 - 1 (0.518 mi.)	K42 L54	68 100
MCDONALD'S OF PRESQUE ISLE	656 MAIN STREET	WNW 1/2 - 1 (0.590 mi.)	X98	187

Lower Elevation	Address	Direction / Distance	Map ID	Page
DR 1007 5350 LADNER'S CAR WASH	660 MAIN ST	WNW 1/2 - 1 (0.598 mi.)	X102	193
ADVANTAGE GASES & TOOLS	65 SPRUCE STREET	NNW 1/2 - 1 (0.659 mi.)	AE120	224
ADVANTAGE GASES & TOOLS	65 SPRUCE ST	NNW 1/2 - 1 (0.659 mi.)	AE121	228
RHF PRESQUE ISLE MOBIL	700 MAIN ST	NW 1/2 - 1 (0.676 mi.)	AH130	240
MILITARY BUREAU PRESQUE ISLE	766 MAIN ST	NNW 1/2 - 1 (0.826 mi.)	AV188	331
SAD 1 GOULDVILLE ELEMENTARY SC	44 PARK ST.	WSW 1/2 - 1 (0.848 mi.)	AW197	345
SAD 1 GOULDVILLE ELEMENTARY SC	44 PARK ST	WSW 1/2 - 1 (0.848 mi.)	AW198	346
MAINE POTATO GROWERS INC PRESQ	56 PARSONS ST	WSW 1/2 - 1 (0.858 mi.)	BA204	356
WALMART STORE #1924	781 MAIN STREET	NNW 1/2 - 1 (0.866 mi.)	BD212	390
WALMART 1924 PRESQUE ISLE	781 MAIN ST	NNW 1/2 - 1 (0.866 mi.)	BD213	395
GRAVE'S SHOP N' SAVE	797 MAIN STREET	NNW 1/2 - 1 (0.898 mi.)	BH233	428
CAVENDISH AGRI PRESQUE ISLE	825 MAIN ST	NNW 1/2 - 1 (0.943 mi.)	BL258	484
AMERIGAS PROPANE LP AROOSTOOK	830 MAIN ST	NNW 1/2 - 1 (0.949 mi.)	BL262	491
SAD 1 BUS GARAGE	215 PARSON RD	WNW 1/2 - 1 (0.956 mi.)	271	504

State and tribal institutional control / engineering control registries

INST CONTROL: Sites with Land Use Restrictions in place.

A review of the INST CONTROL list, as provided by EDR, and dated 03/01/2010 has revealed that there are 10 INST CONTROL sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MITCHELL TRUCKING COMPANY	DAVIS / CARMICHAEL ST	NW 1/8 - 1/4 (0.198 mi.)	B11	30
WOODSTOCK MUNICIPAL LANDFILL	ROUTE 232	W 1/4 - 1/2 (0.430 mi.)	133	56
GILS WRECKER SERVICE	11 DAVIS STREET	WNW 1/4 - 1/2 (0.460 mi.)	J37	59
CITY DRY CLEANERS	636 MAIN STREET	WNW 1/2 - 1 (0.554 mi.)	S75	151
NORTHEASTLAND HOTEL	436 MAIN STREET	SW 1/2 - 1 (0.785 mi.)	AQ172	311
PARSONS ST GAS CENTER	86 PARSONS ST	W 1/2 - 1 (0.842 mi.)	AX195	343
AROOSTOOK RR CO. ENGINE HOUSE	25 DYER STREET	WSW 1/2 - 1 (0.857 ml.)	AZ201	351
THOMAS EQUIPMENT LTD.	794 NORTH MAIN STREET	NNW 1/2 - 1 (0.892 mi.)	BH226	421
LOVLEY & DOHERTY	800 NORTH MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH239	451
IFL NUTRITE	825 NORTH MAIN STREET	NNW 1/2 - 1 (0.943 mi.)	BL260	490

State and tribal voluntary cleanup sites

VCP: A list of sites where the necessary investigation and/or remedation activities have been completed to the Department's satisfaction and the applicants to the VRAP have been issued final certification documents. The list does not include those sites that are currently participating in the VRAP but have not yet received certification.

A review of the VCP list, as provided by EDR, and dated 03/01/2010 has revealed that there are 11 VCP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MITCHELL TRUCKING COMPANY	DAVIS / CARMICHAEL ST	NW 1/8 - 1/4 (0.198 mi.)	B11	30
GILS WRECKER SERVICE	11 DAVIS STREET	WNW 1/4 - 1/2 (0.460 mi.)	J37	59
CITY DRY CLEANERS	636 MAIN STREET	WNW 1/2 - 1 (0.554 ml.)	S75	151
NORTHEASTLAND HOTEL	436 MAIN STREET	SW 1/2 - 1 (0.785 ml.)	AQ172	311
PARSONS ST GAS CENTER	86 PARSONS ST	W 1/2 - 1 (0.842 mi.)	AX195	343

Lower Elevation	Address	Direction / Distance	Map ID	Page
AROOSTOOK RR CO. ENGINE HOUSE	25 DYER STREET	WSW 1/2 - 1 (0.857 mi.)	AZ201	351
THOMAS EQUIPMENT LTD.	794 NORTH MAIN STREET	NNW 1/2 - 1 (0.892 mi.)	BH226	421
LOVLEY & DOHERTY	800 NORTH MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH239	451
IFL NUTRITE	825 NORTH MAIN STREET	NNW 1/2 - 1 (0.943 mi.)	BL260	490
28 CHAPMAN STREET	28 CHAPMAN STREET	SW 1/2 - 1 (0.983 mi.)	BO277	513
36 CHAPMAN STREET	36 CHAPMAN STREET	SW 1/2 - 1 (0.991 mi.)	BO284	526

State and tribal Brownfields sites

BROWNFIELDS: A listing of brownfields site locations.

A review of the BROWNFIELDS list, as provided by EDR, and dated 03/01/2010 has revealed that there are 3 BROWNFIELDS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
28 CHAPMAN STREET	28 CHAPMAN STREET	SW 1/2 - 1 (0.983 mi.)	BO277	513
36 CHAPMAN STREET	36 CHAPMAN STREET	SW 1/2 - 1 (0.991 mi.)	BO284	526
42 CHAPMAN STREET	42 CHAPMAN STREET	SW 1/2 - 1 (0.997 mi.)	BO294	543

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properites addressed by Cooperative Agreement Recipients and Brownfields properties addressed by Targeted Brownfields Assessments

A review of the US BROWNFIELDS list, as provided by EDR, and dated 03/02/2010 has revealed that there are 3 US BROWNFIELDS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HAINES MANUFACTURING CO LAVWAY PROPERTY	28 CHAPMAN ROAD 36 CHAPMAN ROAD	SW 1/2 - 1 (0.983 mi.) SW 1/2 - 1 (0.991 mi.)	BO278 BO285	514 527
WEBBER OIL	42 CHAPMAN ROAD	SW 1/2 - 1 (0.997 mi.)	BO295	543

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES: The Sites List Database is the public record of information regarding properties that have been, are now, or are planned to be addressed by the Division of Remediation of the Bureau of Remediation and Waste Management. This database is not intended to be a comprehensive, all-inclusive source of information regarding the properties listed therein.

A review of the ALLSITES list, as provided by EDR, and dated 03/01/2010 has revealed that there are 13 ALLSITES sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MITCHELL TRUCKING COMPANY	DAVIS / CARMICHAEL ST	NW 1/8 - 1/4 (0.198 mi.)	B11	30

Lower Elevation	Address	Direction / Distance	Map ID	Page
WOODSTOCK MUNICIPAL LANDFILL	ROUTE 232	W 1/4 - 1/2 (0.430 mi.)	133	56
GILS WRECKER SERVICE	11 DAVIS STREET	WNW 1/4 - 1/2 (0.460 mi.)	J37	59
CITY DRY CLEANERS	636 MAIN STREET	WNW 1/2 - 1 (0.554 mi.)	S75	151
NORTHEASTLAND HOTEL	436 MAIN STREET	SW 1/2 - 1 (0.785 mi.)	AQ172	311
PARSONS ST GAS CENTER	86 PARSONS ST	W 1/2 - 1 (0.842 mi.)	AX195	343
AROOSTOOK RR CO. ENGINE HOUSE	25 DYER STREET	WSW 1/2 - 1 (0.857 mi.)	AZ201	351
THOMAS EQUIPMENT LTD.	794 NORTH MAIN STREET	NNW 1/2 - 1 (0.892 mi.)	BH226	421
LOVLEY & DOHERTY	800 NORTH MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH239	451
IFL NUTRITE	825 NORTH MAIN STREET	NNW 1/2 - 1 (0.943 mi.)	BL260	490
28 CHAPMAN STREET	28 CHAPMAN STREET	SW 1/2 - 1 (0.983 mi.)	BO277	513
36 CHAPMAN STREET	36 CHAPMAN STREET	SW 1/2 - 1 (0.991 mi.)	BO284	526
42 CHAPMAN STREET	42 CHAPMAN STREET	SW 1/2 - 1 (0.997 ml.)	BO294	543

Records of Emergency Release Reports

SPILLS: Department of Environmental Protection's Hazardous Material & Oil Spill Database.

A review of the SPILLS list, as provided by EDR, and dated 03/13/2010 has revealed that there are 19 SPILLS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREGORY REED	92 CANTERBURY ST	S 1/2 - 1 (0.850 mi.)	199	347
BREWER, PAUL	115 FLEETWOOD STREET	S 1/2 - 1 (0.933 mi.)	250	469
PRESQUE ISLE NURSING HOME	162 ACADEMY STREET	SSE 1/2 - 1 (0.988 mi.)	BP282	523
Lower Elevation	Address	Direction / Distance	Map ID	Page
THERIAULT TIRE & EQUIPMENT	10 DAVIS STREET	WNW 1/4 - 1/2 (0.471 mi.)	J39	62
CLUCKEYS AUTO	611 MAIN STREET	WNW 1/2 - 1 (0.516 mi.)	M48	81
DEAD RIVER CO. (FORMERLY MPG)	580 MAIN STREET	W 1/2 - 1 (0.518 mi.)	L52	88
DEAD RIVER COMPNAY	580 MAIN STREET	W 1/2 - 1 (0.518 mi.)	L53	94
MAIN STREET RECONSTRUCTION	CORNER OF MAIN / NORT	W 1/2 - 1 (0.529 mi.)	P61	112
CITY DRY CLEANERS	636 MAIN ST	WNW 1/2 - 1 (0.554 ml.)	S74	145
LANDER'S CAR WASH	666 MAIN ST.	NW 1/2 - 1 (0.610 mi.)	AA107	206
KINNEY RENTALS	491 MAIN ST	WSW 1/2 - 1 (0.661 mi.)	AF123	230
MAINE PUBLIC SERVICE	209 STATE STREET	SW 1/2 - 1 (0.684 mi.)	AI136	257
TAPLEY, SHIRLEY	1 DOWNING PLACE	W 1/2 - 1 (0.703 mi.)	144	272
BARTLETT, DAVID	47 PARK ST	WSW 1/2 - 1 (0.832 mi.)	AW192	336
MAINE POTATO GROWERS, INC.	50 PARSONS STREET	WSW 1/2 - 1 (0.864 mi.)	BC209	376
MIKE TRAINER	38 ACADAMY ST	SW 1/2 - 1 (0.877 mi.)	BF218	406
PRESQUE ISLE IRVING MAINWAY	800 NO MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH241	454
BILLY MCLEAN	16 HAYWARD ST	SW 1/2 - 1 (0.956 mi.)	270	501
RATHBUN LUMBER CO	43 STATE STREET	WSW 1/2 - 1 (0.992 mi.)	BQ291	536

Other Ascertainable Records

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA)

of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 02/17/2010 has revealed that there are 12 RCRA-NonGen sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
VIKING FREIGHT INC PRESQUE ISL	43 NORTH ST	W 1/4 - 1/2 (0.382 mi.)	F22	43
SMYTHE'S IGA PLUS	23 NORTH STREET	W 1/4 - 1/2 (0.422 mi.)	G30	51
DEAD RIVER CO	580 MAIN ST	W 1/2 - 1 (0.518 mi.)	L51	86
S.W. COLLINS CO.	21 RICE STREET	NW 1/2 - 1 (0.594 mi.)	Y100	189
NEW ENGLAND TELE CO CTL OFFICE	30 SECOND ST	SW 1/2 - 1 (0.753 ml.)	AO158	295
STAR CITY SANITATION INC	218 PARSON RD	WSW 1/2 - 1 (0.870 ml.)	BC216	402
AROOSTOOK VALLEY RAILROAD	32 PARSONS ST	WSW 1/2 - 1 (0.886 mi.)	221	411
GRAVE'S SHOP N' SAVE	797 MAIN STREET	NNW 1/2 - 1 (0.898 mi.)	BH233	428
STAPLES #1563	830 MAIN STREET	NNW 1/2 - 1 (0.949 mi.)	BL264	492
FRIENDS MARKET	60 STATE STREET	WSW 1/2 - 1 (0.969 mi.)	BM272	506
BONVILLE G A & SON	30 CHAPMAN RD	SW 1/2 - 1 (0.985 mi.)	BO280	518
RATHBUN LUMBER CO.	43 STATE STREET	WSW 1/2 - 1 (0.992 mi.)	BQ290	535

FTTS: FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act) over the previous five years. To maintain currency, EDR contacts the Agency on a quarterly basis.

A review of the FTTS list, as provided by EDR, and dated 04/09/2009 has revealed that there are 5 FTTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OPPORTUNITY TRAINING CTR	25 LOMBARD ST	S 1/8 - 1/4 (0.188 ml.)	A4	9
Lower Elevation	Address	Direction / Distance	Map ID	Page
PRESQUE OSLE HIGH SCHOOL	16 FORT ST	SW 1/4 - 1/2 (0.345 mi.)	D17	36
PRESQUE OSLE HIGH SCHOOL	16 FORT ST	SW 1/4 - 1/2 (0.345 mi.)	D18	37
MAINE PUBLIC SERVICE CO	209 STATE ST	SW 1/2 - 1 (0.684 ml.)	AI134	256
MAINE PUBLIC SERVICE CO.	209 STATE ST.	SW 1/2 - 1 (0.684 mi.)	Al135	256

HIST FTTS: A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

A review of the HIST FTTS list, as provided by EDR, and dated 10/19/2006 has revealed that there are 5 HIST FTTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OPPORTUNITY TRAINING CTR	25 LOMBARD ST	S 1/8 - 1/4 (0.188 mi.)	A4	9
Lower Elevation	Address	Direction / Distance	Map ID	Page
PRESQUE OSLE HIGH SCHOOL	16 FORT ST	SW 1/4 - 1/2 (0.345 mi.)	D17	36

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRESQUE OSLE HIGH SCHOOL	16 FORT ST	SW 1/4 - 1/2 (0.345 mi.)	D18	37
MAINE PUBLIC SERVICE CO.	209 STATE ST.	SW 1/2 - 1 (0.684 mi.)	Al132	254
MAINE PUBLIC SERVICE CO	209 STATE ST	SW 1/2 - 1 (0.684 mi.)	Al134	256

SSTS: Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

A review of the SSTS list, as provided by EDR, and dated 12/31/2008 has revealed that there is 1 SSTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NUTRITE CORP.	825 MAIN STREET	NNW 1/2 - 1 (0.943 mi.)	BL256	481

PADS: The PCB Activity Database identifies generators, transporters, commercial storers and/or brokers and disposers of PCBs who are required to notify the United States Environmental Protection Agency of such activities. The source of this database is the U.S. EPA.

A review of the PADS list, as provided by EDR, and dated 09/01/2009 has revealed that there is 1 PADS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MITCHELL TRUCKING	75 DAVIS STREET	NW 1/8 - 1/4 (0.198 mi.)	B10	29

MLTS: The Material Licensing Tracking System is maintained by the Nuclear Regulatory Commission and contains a list fo approximately 8,100 sites which possess or use radioactive materials and are subject to NRC licensing requirements.

A review of the MLTS list, as provided by EDR, and dated 12/24/2009 has revealed that there are 2 MLTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AROOSTOOK MEDICAL CENTER INC	140 ACADEMY ST	SSW 1/2 - 1 (0.788 mi.)	AS177	318
AROOSTOOK MEDICAL CTR.	140 ACADEMY STREET	SSW 1/2 - 1 (0.788 mi.)	AS180	323

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 10/19/2009 has revealed that there are 28

FINDS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OPPORTUNITY TRAINING CENTER	25 LOMBARD STREET	S 1/8 - 1/4 (0.188 mi.)	A3	9
AROOSTOOK MEDICAL CENTER, THE	140 ACADEMY STREET	SSW 1/2 - 1 (0.788 mi.)	AS176	317
Lower Elevation	Address	Direction / Distance	Map ID	Page
H SMITH PACKAGING CORP/SMITH F	55 NORTH STREET, SUITE	WSW 1/8 - 1/4 (0.227 mi.)	13	32
VIKING FREIGHT INC PRESQUE ISL	43 NORTH ST	W 1/4 - 1/2 (0.382 mi.)	F22	43
SMYTHE'S IGA PLUS	23 NORTH STREET	W 1/4 - 1/2 (0.422 mi.)	G28	49
LOWE'S OF PRESQUE ISLE #2209	135 MAYSVILLE ROAD	N 1/4 - 1/2 (0.485 mi.)	K41	67
DEAD RIVER CO	580 MAIN ST	W 1/2 - 1 (0.518 mi.)	L51	86
CITY DRY CLEANERS	636 MAIN ST	WNW 1/2 - 1 (0.554 mi.)	S74	145
KELCLAN INC KELLEYS FABRICARE	654 MAIN ST	WNW 1/2 - 1 (0.586 mi.)	X93	175
S.W. COLLINS CO.	21 RICE STREET	NW 1/2 - 1 (0.594 mi.)	Y99	189
NAME NOT IN AQS	507 MAIN STREET	WSW 1/2 - 1 (0.612 mi.)	108	208
PRESQUE ISLE WASTE WATER TREAT	126 DYER STREET	W 1/2 - 1 (0.633 mi.)	AB113	213
MAINE PUBLIC SERVICE CO	209 STATE ST	SW 1/2 - 1 (0.684 mi.)	AI134	256
NEW ENGLAND TELE CO CTL OFFICE	30 SECOND ST	SW 1/2 - 1 (0.753 ml.)	AO158	295
NORTHEASTLAND HOTEL	436 MAIN ST.	SW 1/2 - 1 (0.785 mi.)	AQ171	311
WAL-MART SUPERCENTER #1924	781 MAIN ST	NNW 1/2 - 1 (0.866 mi.)	BD214	397
STAR CITY SANITATION INC	218 PARSON RD	WSW 1/2 - 1 (0.870 ml.)	BC216	402
AROOSTOOK VALLEY RAILROAD	32 PARSONS ST	WSW 1/2 - 1 (0.886 mi.)	221	411
GRAVE'S SHOP N' SAVE	797 MAIN STREET	NNW 1/2 - 1 (0.898 mi.)	BH234	432
CIRCLE K #7059	800 MAIN STREET	NNW 1/2 - 1 (0.901 mi.)	BH236	436
PRESQUE ISLE VW INC DBA BATES	800 MAIN ST	NNW 1/2 - 1 (0.901 mi.)	BH237	437
NUTRITE CORP	825 MAIN ST.	NNW 1/2 - 1 (0.943 mi.)	BL259	489
CAVENDISH_AGRI SERVICES INC.	825 MAIN ST	NNW 1/2 - 1 (0.943 mi.)	BL261	490
K-MART #4709	830 MAIN STREET	NNW 1/2 - 1 (0.949 mi.)	BL263	492
STAPLES #1563	830 MAIN STREET	NNW 1/2 - 1 (0.949 mi.)	BL267	496
FRIENDS MARKET	60 STATE STREET	WSW 1/2 - 1 (0.969 mi.)	BM273	507
BONVILLE G A & SON	30 CHAPMAN RD	SW 1/2 - 1 (0.985 mi.)	BO280	518
RATHBUN LUMBER CO.	43 STATE STREET	WSW 1/2 - 1 (0.992 mi.)	BQ288	534

NPDES: A listing of wastewater facility locations.

A review of the NPDES list, as provided by EDR, and dated 04/06/2010 has revealed that there is 1 NPDES site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map iD	Page
PRESQUE ISLE W.W.T.F.		WNW 1/2 - 1 (0.631 mi.)	112	212

UIC: An injection well is any bored, drilled or driven shaft, or dug hole whose depth is greater than its largest surface dimension; an improved sinkhole; or a subsurface distribution system used to discharge fluids underground. These wells range from deep, highly technical, and more frequently monitored wells to shallow on-site drainage systems, such as septic systems, cesspools, and storm water drainage wells.

A review of the UIC list, as provided by EDR, and dated 10/28/2009 has revealed that there are 18 UIC sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NELDER, OSCAR	93 HARDY ST	S 1/2 - 1 (0.793 mi.)	AT181	323
Lower Elevation	Address	Direction / Distance	Map ID	Page
BELL ATLANTIC	100 CARMICHAEL ST	NW 1/8 - 1/4 (0.196 mi.)	B6	12

Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTO TECH	59 DAVIS STREET	WNW 1/4 - 1/2 (0.279 mi.)	C14	32
BRADLEYS CAR WASH	46 NORTH ST	W 1/4 - 1/2 (0.351 mi.)	E21	41
JIM'S AUTOMOTIVE	30 NORTH STREET	W 1/4 - 1/2 (0.408 mi.)	G25	46
HOFFSES AUTO SALES	581 MAIN ST	W 1/2 - 1 (0.516 mi.)	L47	80
CLUKEY'S AUTO SUPPLY	611 MAIN ST	WNW 1/2 - 1 (0.516 mi.)	M49	83
AROOSTOOK BEVERAGE	52 RICE STREET	NW 1/2 - 1 (0.523 mi.)	O57	106
MDOT	41 RICE STREET	NW 1/2 - 1 (0.547 mi.)	R68	123
MDOT	41 RICE STREET	NW 1/2 - 1 (0.547 mi.)	R69	124
MDOT	41 RICE STREET	NW 1/2 - 1 (0.547 mi.)	R70	124
COWETT'S AUTOBODY	38 RICE ST	NW 1/2 - 1 (0.553 mi.)	R72	128
HOGAN TIRE INC.	30 RICE STREET	NW 1/2 - 1 (0.573 mi.)	83	164
K.K. MOTOR SPORTS	645 MAIN STREET	WNW 1/2 - 1 (0.575 mi.)	T84	165
KELLYS FABRICARE	654 MAIN ST	WNW 1/2 - 1 (0.586 mi.)	X94	177
HARRY'S HONDA/MITSUBISHI/NISSA	6 ALLEN ST	WSW 1/2 - 1 (0.633 mi.)	AC116	219
T.A. SERVICE CENTER INC.	26 DYER ST	WSW 1/2 - 1 (0.857 mi.)	AZ202	352
STANS IRVING STATION	52 ACADEMY ST	SW 1/2 - 1 (0.859 mi.)	BB208	375

DRYCLEANERS: A listing of drycleaning facilities that use perchloroethylene.

A review of the DRYCLEANERS list, as provided by EDR, and dated 11/01/2009 has revealed that there is 1 DRYCLEANERS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CITY DRY CLEANERS	636 MAIN STREET	WNW 1/2 - 1 (0.554 mi.)	S75	151

TIER 2: A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.


A review of the TIER 2 list, as provided by EDR, and dated 12/31/2008 has revealed that there are 16 TIER 2 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DOT VAN BUREN	271 STATE STREET	SSW 1/2 - 1 (0.580 mi.)	W86	166
THE AROOSTOOK MEDICAL CENTER	140 ACADEMY ST	SSW 1/2 - 1 (0.788 mi.)	AS178	318
Lower Elevation	Address	Direction / Distance	Map ID	Page
LOWE'S OF PRESEQUE ISLE, ME 22	135 MAYSVILLE STREET	N 1/4 - 1/2 (0.485 mi.)	K42	68
DOT PRESQUE ISLE	41 RICE STREET	NW 1/2 - 1 (0.547 mi.)	R71	125
MCDONALD'S OF PRESQUE ISLE	656 MAIN STREET	WNW 1/2 - 1 (0.590 mi.)	X98	187
PRESQUE ISLE WASTEWATER TREATM	126 DYER STREET	W 1/2 - 1 (0.633 mi.)	AB114	213
ADVANTAGE GASES & TOOLS	65 SPRUCE STREET	NNW 1/2 - 1 (0.659 mi.)	AE120	224
RHF PRESQUE ISLE MOBIL	700 MAIN ST	NW 1/2 - 1 (0.676 mi.)	AH130	240
MEARNG PRESQUE ISLE ARMORY	766 MAIN ST.	NNW 1/2 - 1 (0.826 mi.)	AV190	334
DEAD RIVER CONVENIENCE STORE P	86 PARSONS STREET	W 1/2 - 1 (0.842 mi.)	AX194	340
SAD 1 GOULDVILLE ELEMENTARY SC	44 PARK ST.	WSW 1/2 - 1 (0.848 ml.)	AW197	345
MAINE POTATO GROWERS	56 PARSONS ST.	WSW 1/2 - 1 (0.858 mi.)	BA203	352
MAINE POTATO GROWERS, INC.	50 PARSONS STREET	WSW 1/2 - 1 (0.864 mi.)	BC209	376
WALMART STORE #1924	781 MAIN STREET	NNW 1/2 - 1 (0.866 mi.)	BD212	390
GRAVE'S SHOP N' SAVE	797 MAIN STREET	NNW 1/2 - 1 (0.898 mi.)	BH233	428
CAVENDISH AGRI SERVICES INC	825 MAIN ST	NNW 1/2 - 1 (0.943 mi.)	BL255	477

Due to poor or inadequate address information, the following sites were not mapped:


Site Name	Database(s)
PHOTOGRAPHY BY DEBI SMITH	UIC
MDOT SAND SALT STORAGE LOT	LAST
AROOSTOOK STATE FARM PESTICIDE PIT	CERCLIS-NFRAP
COLUMBIA FOREST PRODUCTS	FINDS,LUST
OPPORTUNITY TRAINING CENTER	UST
COLES EXPRESS	UST
UNIVERSITY OF MAINE AT PRESQUE ISL	AST
DR 1003 5300 PRESQUE ISLE BULK STO	AST
MCCAIN FOODS INC TATER MEAL PLT	AST
MAINE POTATO GROWERS SKYWAY PARK	AST
MAINE POTATO GROWERS STATE RD	AST
PRESQUE ISLE FOOTWEAR CO	FINDS,RCRA-NLR
CONVERSE INC	FINDS,RCRA-NLR
PRESQUE ISLE CITY	FINDS
PRESQUE ISLE ME AIRPORT	ICIS
PRESQUE ISLE RECYCLING CENTER	ICIS
MCCAIN FOODS INC. PRESQUE ISLE FAC	ICIS
CAVENDISH_AGRI SERVICES INC.	SSTS
APEX	MANIFEST
MC CAIN FOODS	MANIFEST

OVERVIEW MAP - 02777161.5r



SITE NAME: MMA Railway - Presque Isle ADDRESS: MMA Railway - Presque Isle Presque Isle ME 04769 LAT/LONG: 46.6889 / 68.0018

CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02777161.5r
DATE: May 24, 2010 1:21 pm



SITE NAME: MMA Railway - Presque Isle ADDRESS: MMA Railway - Presque Isle Presque Isle ME 04769 LAT/LONG: 46.6889 / 68.0018 CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02777161.5r
DATE: May 24, 2010 1:21 pm

JM Huber and McCain Foods Facilities JM Huber and McCain Foods Facilities Easton, ME 04740

Inquiry Number: 02777161.6r

May 24, 2010

The EDR Radius Map™ Report with GeoCheck®



440 Wheelers Farms Road Milford, CT 06461 Toll Free: 800.352,0050 www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	ES1
Overview Map	_ 2
Detail Map.	_ 3
Map Findings Summary	4
Map Findings.	7
Orphan Summary.	251
Government Records Searched/Data Currency Tracking.	_ GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-10
Physical Setting Source Map Findings.	_ A-12
Physical Setting Source Records Searched	A-22

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

JM HUBER AND MCCAIN FOODS FACILITIES EASTON, ME 04740

COORDINATES

Latitude (North): 46.664060 - 46* 39' 50.6" Longitude (West): 67.906500 - 67* 54' 23.4"

Universal Tranverse Mercator: Zone 19 UTM X (Meters): 583655.9 UTM Y (Meters): 5168195.5

Elevation: 641 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 46067-F8 EASTON, ME

Most Recent Revision: 1984

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL...... National Priority List

Proposed NPL.....Proposed National Priority List Sites

NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list
CERCLIS
Federal CERCLIS NFRAP site List
CERC-NFRAP CERCLIS No Further Remedial Action Planned
Federal RCRA CORRACTS facilities list
CORRACTSCorrective Action Report
Federal RCRA non-CORRACTS TSD facilities list
RCRA-TSDFRCRA - Treatment, Storage and Disposal
Federal RCRA generators list
RCRA-LQGRCRA - Large Quantity Generators
RCRA-SQG RCRA - Small Quantity Generators
Federal institutional controls / engineering controls registries
US ENG CONTROLS Engineering Controls Sites List
US INST CONTROL Sites with Institutional Controls
Federal ERNS list
ERNS Emergency Response Notification System
State and tribal landfill and/or solid waste disposal site lists
LCP Municipal Landfill Closure Database
State and tribal leaking storage tank lists
LUST
State and tribal registered storage tank lists
INDIAN UST Underground Storage Tanks on Indian Land
FEMA UST Underground Storage Tank Listing
State and tribal institutional control / engineering control registries
INST CONTROL
State and tribal voluntary cleanup sites
INDIAN VCPVoluntary Cleanup Priority Listing
11.5% at 10.
State and tribal Brownfields sites
BROWNFIELDSRemediation Sites List

ADDITIONAL ENVIRONMENTAL RECORDS

Local	ı Bro	wntie	IO I	usts

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

ODI..... Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

DEL SHWS..... Sites Removed from the Uncontrolled Sites List US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS.....Land Use Control Information System LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

Other Ascertainable Records

RCRA-NonGen...... RCRA - Non Generators DOT OPS...... Incident and Accident Data DOD...... Department of Defense Sites FUDS..... Formerly Used Defense Sites

CONSENT..... Superfund (CERCLA) Consent Decrees

ROD...... Records Of Decision UMTRA..... Uranium Mill Tailings Sites MINES..... Mines Master Index File TSCA...... Toxic Substances Control Act

Act)/TSCA (Toxic Substances Control Act)
HIST FTTS......FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems PADS..... PCB Activity Database System MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database

RAATS......RCRA Administrative Action Tracking System

UIC...... Underground Injection Control DRYCLEANERS...... Drycleaner Facilities

INDIAN RESERV.....Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER...... PCB Transformer Registration Database COAL ASH DOE...... Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants.... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 02/17/2010 has revealed that there is 1 RCRA-CESQG site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUBER ENGINEERED WOODS, LLC EA	333 STATION ROAD	SSW 1/2 - 1 (0.960 mi.)	C7	22

State- and tribal - equivalent CERCLIS

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Protection's Uncontrolled Hazardous Substance Sites Program List of Investigations.

A review of the SHWS list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1 SHWS

site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
VAHLSING WAREHOUSE : Investigation Needed	STATION ROAD	ESE 0 - 1/8 (0.072 mi.)	1	7

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Department of Environmental Protection's Solid Waste Facility List.

A review of the SWF/LF list, as provided by EDR, and dated 02/23/2010 has revealed that there is 1 SWF/LF site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C13	240

State and tribal leaking storage tank lists

LAST: A listing of leaking aboveground storage tanks.

A review of the LAST list, as provided by EDR, and dated 03/13/2010 has revealed that there is 1 LAST site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
J M HUBER PLANT	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C12	80

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 02/01/2010 has revealed that there is 1 UST site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FERRIS ONE STOP	378 STATION RD	SSW 1/2 - 1 (0.898 mi.)	B5	20

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Protection's Aboveground Storage Tank Database.

A review of the AST list, as provided by EDR, and dated 07/28/2009 has revealed that there are 2 AST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUBER ENGINEERED WOOD, LLC	333 STATION ROAD	SSW 1/2 - 1 (0.960 mi.)	C9	29
J M HUBER PLANT	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C12	80

State and tribal voluntary cleanup sites

VCP: A list of sites where the necessary investigation and/or remedation activities have been completed to the Department's satisfaction and the applicants to the VRAP have been issued final certification documents. The list does not include those sites that are currently participating in the VRAP but have not yet received certification.

A review of the VCP list, as provided by EDR, and dated 03/01/2010 has revealed that there are 2 VCP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MCLEANS AUTO PARTS	251 / 252 STATION ROA	SSW 1/4 - 1/2 (0.492 mi.)	4	20
MCPHERSON PROPERTY	369 STATION ROAD	SSW 1/2 - 1 (0.909 mi.)	B6	22

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES: The Sites List Database is the public record of information regarding properties that have been, are now, or are planned to be addressed by the Division of Remediation of the Bureau of Remediation and Waste Management. This database is not intended to be a comprehensive, all-inclusive source of information regarding the properties listed therein.

A review of the ALLSITES list, as provided by EDR, and dated 03/01/2010 has revealed that there are 3 ALLSITES sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
VAHLSING WAREHOUSE	STATION ROAD	ESE 0 - 1/8 (0.072 mi.)	1	7
MCLEANS AUTO PARTS	251 / 252 STATION ROA	SSW 1/4 - 1/2 (0.492 mi.)	4	20
MCPHERSON PROPERTY	369 STATION ROAD	SSW 1/2 - 1 (0.909 mi.)	B6	22

Records of Emergency Release Reports

SPILLS: Department of Environmental Protection's Hazardous Material & Oil Spill Database.

A review of the SPILLS list, as provided by EDR, and dated 03/13/2010 has revealed that there are 7 SPILLS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUBER ENGINEERED WOOD, LLC	333 STATION ROAD	SSW 1/2 - 1 (0.960 mi.)	C9	29
J M HUBER	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C10	41
HUBER ENGINEERED WOODS	333 STATION ROAD	SSW 1/2 - 1 (0.960 mi.)	C11	43
J M HUBER PLANT	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C12	80

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C13	240
HUBER ENGINEERED WOODS	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C14	244
J M HUBER	333 STATON RD	SSW 1/2 - 1 (0.960 mi.)	C15	247

Other Ascertainable Records

TRIS: The Toxic Chemical Release Inventory System identifies facilities that release toxic chemicals to the air, water, and land in reportable quantities under SARA Title III, Section 313. The source of this database is the U.S. EPA.

A review of the TRIS list, as provided by EDR, and dated 12/31/2008 has revealed that there is 1 TRIS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUBER ENGINEERED WOODS LLC	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C16	250

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 04/24/2010 has revealed that there is 1 ICIS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
J.M. HUBER CORP.	333 STATION ROAD EAS	SSW 1/2 - 1 (0.960 mi.)	C8	24

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 10/19/2009 has revealed that there is 1 FINDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUBER ENGINEERED WOODS	333 STATION ROAD	SSW 1/2 - 1 (0.960 mi.)	C11	43

NPDES: A listing of wastewater facility locations.

A review of the NPDES list, as provided by EDR, and dated 04/06/2010 has revealed that there are 2 NPDES sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MCCAIN FOODS INC.		SE 1/4 - 1/2 (0.317 mi.)	A2	7
MCCAIN FOODS INC.		SE 1/4 - 1/2 (0.317 mi.)	A3	8

AIRS: Point Source Criteria Pollutant Emissions Inventory data. Criteria air pollutant emissions, expressed in tons, by facility and pollutant.

A review of the AIRS list, as provided by EDR, and dated 12/31/2007 has revealed that there is 1 AIRS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	333 STATION RD	SSW 1/2 - 1 (0.960 mi.)	C13	240


TIER 2: A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

A review of the TIER 2 list, as provided by EDR, and dated 12/31/2008 has revealed that there is 1 TIER 2 site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HUBER ENGINEERED WOOD, LLC	333 STATION ROAD	SSW 1/2 - 1 (0.960 mi.)	C9	29


Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
PHOTOGRAPHY BY DEBI SMITH	UIC
MCCAIN FOOD INC	FTTS,HIST FTTS INSP
TOMPKINS, DEBBIE	LAST
MCCAINS FOODS	SPILLS,LAST
J.M. HUBER	SPILLS,LAST
JM HUBER	SPILLS,LAST
MDOT SAND SALT STORAGE LOT	LAST
MCCAIN FOODS - TATER MEAL	LAST
MAINE POTATO GROWERS	LAST
OLD KEY BANK BUILDING	LAST
MAINE POTATO GROWERS BULK PLANT	LAST
MCCAIN FOODS INC EASTON	AST
UNIVERSITY OF MAINE AT PRESQUE ISL	AST
MCCAIN FOODS INC TATER MEAL PLT	AST
MAINE POTATO GROWERS STATE RD	AST
MCCAIN PROCESSING INC REACH ROAD P	FINDS
MCCAIN FOODS PROPERTY	SPILLS
MCCAIN FOODS INC. PRESQUE ISLE FAC	ICIS
CAVENDISH_AGRI SERVICES INC.	SSTS
MC CAIN FOODS	MANIFEST



SITE NAME: JM Huber and McCain Foods Facilities ADDRESS: JM Huber and McCain Foods Facilities Easton ME 04740

LAT/LONG: 46.6641 / 67.9065 CLIENT: Haley & Aldrich, Inc. CONTACT: Andrew Collins INQUIRY #: 0277161.6r DATE: May 24, 2010 2:56 pm



SITE NAME: JM Huber and McCain Foods Facilities ADDRESS: JM Huber and McCain Foods Facilities Easton ME 04740
LAT/LONG: 46.6641 / 67.9065

Dept. Defense Sites

CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY#: 02777161.6r
DATE: May 24, 2010 2:56 pm

€	15		

MMA Railway - Caribou MMA Railway - Caribou Caribou, ME 04736

Inquiry Number: 02777161.3r

May 24, 2010

The EDR Radius Map™ Report with GeoCheck®



TABLE OF CONTENTS

SECTION	PAGE
Executive Summary.	ES1
Overview Map.	2
Detail Map	3
Map Findings Summary	4
Map Findings.	7
Orphan Summary	337
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum.	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map.	A-5
Physical Setting Source Map	A-1 1
Physical Setting Source Map Findings	A-13
Physical Setting Source Records Searched	A-33

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MMA RAILWAY - CARIBOU CARIBOU, ME 04736

COORDINATES

Latitude (North):

46.858700 - 46" 51' 31.3"

Longitude (West):

67.993100 - 67° 59' 35.2"

Universal Tranverse Mercator: Zone 19 UTM X (Meters):

576753.8 5189736.0

UTM Y (Meters): Elevation:

549 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:

46067-G8 GOODWIN, ME

Most Recent Revision:

1984

North Map:

46067-H8 FORT FAIRFIELD NW, ME

Most Recent Revision:

1978

West Map:

46068-G1 CARIBOU, ME

Most Recent Revision:

1984

Northwest Map:

46068-H1 NEW SWEDEN, ME

Most Recent Revision:

1978

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list NPL...... National Priority List

Proposed NPL Proposed National Priority List Sites NPL LIENS Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY..... Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP...... CERCLIS No Further Remedial Action Planned

Federal RCRA CORRACTS facilities list

CORRACTS..... Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF...... RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-LQG...... RCRA - Large Quantity Generators

Federal institutional controls / engineering controls registries

US ENG CONTROLS...... Engineering Controls Sites List US INST CONTROL...... Sites with Institutional Controls

State- and tribal - equivalent CERCLIS

SHWS______ Remediation Sites List

State and tribal landfill and/or solid waste disposal site lists

SWF/LF..... Solid Waste Facility List

LCP...... Municipal Landfill Closure Database

State and tribal leaking storage tank lists

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

INDIAN UST...... Underground Storage Tanks on Indian Land

FEMA UST...... Underground Storage Tank Listing

State and tribal voluntary cleanup sites

INDIAN VCP...... Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9...... Torres Martinez Reservation Illegal Dump Site Locations

ODI..... Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

DEL SHWS..... Sites Removed from the Uncontrolled Sites List US HIST CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

LUCIS.....Land Use Control Information System LIENS..... Environmental Liens Information Listing

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

Other Ascertainable Records

DOT OPS...... Incident and Accident Data DOD...... Department of Defense Sites FUDS..... Formerly Used Defense Sites

CONSENT..... Superfund (CERCLA) Consent Decrees

ROD......Records Of Decision UMTRA...... Uranium Mill Tailings Sites MINES..... Mines Master Index File

TRIS...... Toxic Chemical Release Inventory System

TSCA..... Toxic Substances Control Act MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database

RAATS......RCRA Administrative Action Tracking System

DRYCLEANERS...... Drycleaner Facilities INDIAN RESERV..... Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

PCB TRANSFORMER...... PCB Transformer Registration Database COAL ASH DOE...... Sleam-Electric Plan Operation Data

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property. Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/17/2010 has revealed that there are 2 RCRA-SQG sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAINE ARMY NATL GUARD OMS 5	20 NORTH ST	NW 1/2 - 1 (0.628 mi.)	C20	43
LEVESQUE OFFICE SUPPLY INC	41 HATCH DR	W 1/2 - 1 (0.972 mi.)	137	287

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 02/17/2010 has revealed that there is 1 RCRA-CESQG site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CIRCLE K #7052	35 BENNETT DRIVE	WNW 1/2 - 1 (0.617 mi.)	B15	31

Federal ERNS list

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/2009 has revealed that there are 3 ERNS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
176 LIMESTONE ST.	176 LIMESTONE ST.	NNW 1/2 - 1 (0.506 mi.)	5	12
27 BIRDSEYE AVE	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R97	210
27 BIRDSEYE AVE	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R99	211

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Protection's Hazardous Material and Oil Spill System Database (H.O.S.S.).

A review of the LUST list, as provided by EDR, and dated 03/13/2010 has revealed that there are 9 LUST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARIBOU MAINWAY - IRVING	35 BENNETT DRIVE	WNW 1/2 - 1 (0.617 mi.)	B16	33
CARIBOU RECREATION & WELLNESS	55 BENNETT DRIVE	WNW 1/2 - 1 (0.667 mi.)	E28	60
HANSON ALLAN	135 HIGH STREET	W 1/2 - 1 (0.684 mi.)	F42	84
CARIBOU FIRE DEPT	121 HIGH ST	W 1/2 - 1 (0.698 mi.)	F47	93
CARIBOU FOOD TREND	89 HIGH ST	W 1/2 - 1 (0.752 mi.)	L67	132
FOOD TREND	89 HIGH ST	W 1/2 - 1 (0.752 mi.)	L68	141
MAINE FROZEN FOODS	27 BIRDSEYE AVENUE	WSW 1/2 - 1 (0.827 mi.)	R95	203
MAINE PACKERS	27 BIRDSEYE AVE.	WSW 1/2 - 1 (0.827 mi.)	R96	208
ROSE ACRES	729 N. MAIN ST.	WNW 1/2 - 1 (0.917 mi.)	132	279

LAST: A listing of leaking aboveground storage tanks.

A review of the LAST list, as provided by EDR, and dated 03/13/2010 has revealed that there are 18 LAST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SOKOLICH, DAVE & FIONA	12 PILGRIM AVE	NW 1/2 - 1 (0.962 mi.)	136	285
Lower Elevation	Address	Direction / Distance	Map ID	Page
L.B. CARTER BULK PLANT	RIVER ROAD	SW 1/4 - 1/2 (0.435 mi.)	1	7
MIKE BOULIER	3 LIBERTY ST	WNW 1/2 - 1 (0.588 mi.)	A10	20
CHRISTOPHER BOYS HOME	18 PLEASANT ST	W 1/2 - 1 (0.595 mi.)	12	24
MADORE, AURORA	20 LOWER LYNDON STREET	WSW 1/2 - 1 (0.596 mi.)	13	26
SLEEPERS STORE	99 LYNDON STREET	W 1/2 - 1 (0.664 mi.)	26	57
JULIANNE BROWN	32 FENDERSON RD	W 1/2 - 1 (0.669 mi.)	31	65
DOUCETTE, BERNADETTE & JOHN	37 GLENDALE ST	NW 1/2 - 1 (0.700 mi.)	H48	97
HODGEDON EDWARD	15 GLENDALE ROAD	NW 1/2 - 1 (0.746 mi.)	65	129
ST.JOHN, LEO	7 LYNDON LANE	W 1/2 - 1 (0.815 mi.)	P86	179
MAINE FROZEN FOODS	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R92	189
HOULTON FARMS DAIRY BAR	98 BENNETT DRIVE	NW 1/2 - 1 (0.830 mi.)	Q101	211
JOHNSON, LUCY C	16 ELMWOOD AVE	WNW 1/2 - 1 (0.852 mi.)	111	226
Not reported	1 WATER STREET	W 1/2 - 1 (0.890 mi.)	125	254
KATZ, ALEX	SLAB CITY ROAD	WNW 1/2 - 1 (0.907 mi.)	Y130	273
CLAUDE BRISSETTE	16 COLLINS ST	WNW 1/2 - 1 (0.974 mi.)	138	289
RYAN, FRANK	49 CROSBY STREET	SW 1/2 - 1 (0.975 mi.)	139	292
FORSMAN SINTERED PRODUCTS	15 ARMCO AVE	SW 1/2 - 1 (0.997 mi.)	146	334

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Protection's Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 02/01/2010 has revealed that there are 50 UST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
S W COLE ENGINEERING INC	161 WATER ST	W 1/4 - 1/2 (0.463 mi.)	3	10
ENGROFF, JOHN	23 BROADWAY ST	W 1/2 - 1 (0.501 mi.)	4	11
FORT ST BEVERAGE & RETURN CTR	34 FORT ST	SW 1/2 - 1 (0.526 mi.)	6	12
SOFT WATER SERVICE INC	20 ELM ST	W 1/2 - 1 (0.530 mi.)	7	14
NEWBEGIN, CLIFFORD R	27 HILLCREST AVE	NW 1/2 - 1 (0.589 mi.)	11	23
CARIBOU MAINWAY	35 BENNETT DR	WNW 1/2 - 1 (0.617 mi.)	B14	28
FIELD MAINT SHOP 5	20 NORTH ST	NW 1/2 - 1 (0.628 mi.)	C17	36
DONNELLY, MAURICE & NANCY	160 HIGH ST	WNW 1/2 - 1 (0.632 mi.)	21	51
CARIBOU GENERATING STATION	LYNDON ST	W 1/2 - 1 (0.641 mi.)	D24	54
CARIBOU RECREATION & WELLNESS	55 BENNETT DR	WNW 1/2 - 1 (0.667 mi.)	E29	63
CARIBOU RECREATION DEPT	59 BENNETT DR	NW 1/2 - 1 (0.672 mi.)	E35	71
CARIBOU ARMORY	59 BENNETT DR	NW 1/2 - 1 (0.672 mi.)	E36	72
OAKHURST DAIRY	HALIFAX STREET	WSW 1/2 - 1 (0.674 mi.)	39	79
CASCO NORTHERN BANK	144 HIGH ST	W 1/2 - 1 (0.677 mi.)	F40	81
ALLAN HANSON	135 HIGH ST	W 1/2 - 1 (0.684 mi.)	F41	82
6 SCHOOL ST	135 HIGH ST	W 1/2 - 1 (0.684 mi.)	F43	86
CARIBOU MIDDLE SCHOOL	21 GLENN ST	WNW 1/2 - 1 (0.694 ml.)	G44	87
CARIBOU FIRE DEPT	121 HIGH ST	W 1/2 - 1 (0.698 mi.)	F47	93
CHASE, STERLING	26 GLENN ST	WNW 1/2 - 1 (0.701 mi.)	G49	100
BUNNELL, WILLIAM	39 PARK ST	WNW 1/2 - 1 (0.731 mi.)	55	107
DISY. ED	33 WATER ST	W 1/2 - 1 (0.732 mi.)	57	107
CARIBOU STEAM & DIESEL STATION	142 LOWER LYNDON ST	SW 1/2 - 1 (0.732 mi.)	K63	126
HOLY ROSARY CHURCH	31 THOMAS AVE	WSW 1/2 - 1 (0.746 mi.)	64	127
MORIN, ROBERT	18 PATTEN ST	SW 1/2 - 1 (0.748 mi.)	66	131
CARIBOU FOOD TREND	89 HIGH ST	W 1/2 - 1 (0.752 mi.)	L67	132
TEAGUE PARK SCHOOL	59 GLEN ST	WNW 1/2 - 1 (0.764 mi.)	M72	151
UNITED BAPTIST CHURCH	74 HIGH ST	W 1/2 - 1 (0.782 mi.)	77	163
HEIGHTS, LYNDON	33 LYNDON ST	W 1/2 - 1 (0.783 mi.)	78	164
BAILEY WHSE	14 EVERGREEN PKWY	NW 1/2 - 1 (0.786 mi.)	N79	165
WAREHOUSE FMR PARKER K BAILEY	14 EVERGREEN PKWY	NW 1/2 - 1 (0.786 mi.)	N80	166
DOCS PLACE	89 BENNETT DR	NW 1/2 - 1 (0.787 mi.)	O81	167
NADEAU, CHARLES DR	92 BENNETT DR	NW 1/2 - 1 (0.796 mi.)	O83	173
CULLINS, ARTHUR	93 BENNETT DR	NW 1/2 - 1 (0.796 mi.)	O84	175
NOYES FLOWERS & PLANT SHOPPE	11 FRANKLIN ST	WNW 1/2 - 1 (0.816 mi.)	87	182
CARIBOU BOWLADROME	97 BENNETT DR	NW 1/2 - 1 (0.819 mi.)	Q88	183
MAINE FROZEN FOODS INC	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R94	199
PLOURDE, LEONEL	13 LAURETTE ST	NW 1/2 - 1 (0.830 mi.)	Q102	214
K P FOODS INC	98 BENNETT DR	NW 1/2 - 1 (0.830 mi.)	Q102 Q104	219
NATIONAL WEATHER SVC	664 NORTH MAIN ST	W 1/2 - 1 (0.832 mi.)	105	220
CARIBOU HIGHWAY GARAGE	83 GLENN ST	NW 1/2 - 1 (0.839 mi.)	S106	221
CARIBOU CHURCH OF CHRIST	104 BENNETT DR	NW 1/2 - 1 (0.842 mi.)	U110	225
CARIBOU LIBRARY	30 HIGH ST	W 1/2 - 1 (0.853 mi.)	V112	229
KATAHDIN TRUST CO	109 BENNETT DR	NW 1/2 - 1 (0.854 mi.)	U115	233
CARIBOU OFFICE BUILDING	25 HIGH ST	W 1/2 - 1 (0.858 mi.)	V116	235
CITY OFFICE BUILDING	25 HIGH ST	W 1/2 - 1 (0.858 mi.)	V116 V117	236
CARIBOU ONE STOP	117 BENNETT DR	NW 1/2 - 1 (0.874 mi.)	120	240
J F HACKETT INC	54 BENNETT DR BOX 1034	NNW 1/2 - 1 (0.926 mi.)	133	2 4 0 281
OT TRONETT INO	ST DENNETT DR BOX 1034	141444 1/2 - 1 (0.320 1111.)	133	201

Lower Elevation	Address	Direction / Distance	Map ID	Page
COMBINED FILE WITH 13658	8 SWEDEN RD	W 1/2 - 1 (0.927 mi.)	134	282
SODERBERG CONSTRUCTION CO	8 SINCOCK ST	WSW 1/2 - 1 (0.950 mi.)	135	283
CONTROL DEVICES INC	60 ACCESS HIGHWAY	N 1/2 - 1 (0.990 mi.)	Z142	325

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Protection's Aboveground Storage Tank Database.

A review of the AST list, as provided by EDR, and dated 07/28/2009 has revealed that there are 10 AST sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WPS CARIBOU GENERATING STATION	276 LYNDON ST	W 1/2 - 1 (0.639 mi.)	D23	53
MILITARY BUREAU CARIBOU	59 BENNETT DR	NW 1/2 - 1 (0.672 mi.)	E33	68
MILITARY BUREAU OMS 5 CARIBOU	59 BENNETT DR	NW 1/2 - 1 (0.672 mi.)	E38	76
CARIBOU GENERATING STATION	142 LOWER LYNDON STREE	TSW 1/2 - 1 (0.732 ml.)	K59	110
CARIBOU STEAM & DIESEL STATION	142 LOWER LYNDON ST	SW 1/2 - 1 (0.732 mi.)	K60	119
MAINE FROZEN FOODS	27 BIRDSEYE AVENUE	WSW 1/2 - 1 (0.827 mi.)	R93	196
MCDONALD'S OF CARIBOU	127 BENNETT DRIVE	NW 1/2 - 1 (0.896 mi.)	126	257
DR CARIBOU BIRDSEYE AVE.	11 BIRDSEYE AVENUE	WSW 1/2 - 1 (0.905 mi.)	X128	260
DR CARIBOU BULK PLANT BIRDSEYE	11 BIRDSEYE AVE	WSW 1/2 - 1 (0.905 mi.)	X129	268
FIRST TECHNOLOGY, INC	60 ACCESS HIGHWAY, RT.	N 1/2 - 1 (0.990 mi.)	Z143	326

State and tribal institutional control / engineering control registries

INST CONTROL: Sites with Land Use Restrictions in place.

A review of the INST CONTROL list, as provided by EDR, and dated 03/01/2010 has revealed that there are 2 INST CONTROL sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NUTRITE CORP.	47 CARROLL STREET	NNW 1/2 - 1 (0.825 ml.)	90	186
PAUL BATES' SUBARU	109 BENNETT ROAD	NW 1/2 - 1 (0.854 mi.)	U114	233

State and tribal voluntary cleanup sites

VCP: A list of sites where the necessary investigation and/or remedation activities have been completed to the Department's satisfaction and the applicants to the VRAP have been issued final certification documents. The list does not include those sites that are currently participating in the VRAP but have not yet received certification.

A review of the VCP list, as provided by EDR, and dated 03/01/2010 has revealed that there are 4 VCP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
L.B. CARTER BULK PLANT	RIVER ROAD	SW 1/4 - 1/2 (0.435 mi.)	1	7
NUTRITE CORP.	47 CARROLL STREET	NNW 1/2 - 1 (0.825 ml.)	90	186
MAINE FROZEN FOODS	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R92	189
PAUL BATES' SUBARU	109 BENNETT ROAD	NW 1/2 - 1 (0.854 mi.)	U114	233

State and tribal Brownfields sites

BROWNFIELDS: A listing of brownfields site locations.

A review of the BROWNFIELDS list, as provided by EDR, and dated 03/01/2010 has revealed that there is 1 BROWNFIELDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHILDREN'S DISCOVERY MUSEUM	82 GLENN STREET	NW 1/2 - 1 (0.839 ml.)	S107	224

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES: The Sites List Database is the public record of information regarding properties that have been, are now, or are planned to be addressed by the Division of Remediation of the Bureau of Remediation and Waste Management. This database is not intended to be a comprehensive, all-inclusive source of information regarding the properties listed therein.

A review of the ALLSITES list, as provided by EDR, and dated 03/01/2010 has revealed that there are 5 ALLSITES sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
L.B. CARTER BULK PLANT	RIVER ROAD	SW 1/4 - 1/2 (0.435 ml.)	1	7
NUTRITE CORP.	47 CARROLL STREET	NNW 1/2 - 1 (0.825 ml.)	90	186
MAINE FROZEN FOODS	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R92	189
CHILDREN'S DISCOVERY MUSEUM	82 GLENN STREET	NW 1/2 - 1 (0.839 mi.)	S107	224
PAUL BATES' SUBARU	109 BENNETT ROAD	NW 1/2 - 1 (0.854 ml.)	U114	233

Records of Emergency Release Reports

SPILLS: Department of Environmental Protection's Hazardous Material & Oil Spill Database.

A review of the SPILLS list, as provided by EDR, and dated 03/13/2010 has revealed that there are 12 SPILLS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CYR NANCY	14 HILLCREST AVE.	NW 1/2 - 1 (0.569 mi.)	8	15
KIM GAHAGAN	15 SO PARK ST	WNW 1/2 - 1 (0.587 mi.)	A9	17
KATHY LAPOINTE	43 GLENDALE STREET	NW 1/2 - 1 (0.697 mi.)	H46	91
WPS NEW ENGLAND GENERATION	142 LOWER LYNDON ST	SW 1/2 - 1 (0.732 mi.)	K61	120
CARIBOU BUS GARAGE	60 GLENN STREET	WNW 1/2 - 1 (0.770 mi.)	M75	155
APARTMENT OWNED BY GAGNON, GAR	4 LYNDON STREET	W 1/2 - 1 (0.821 mi.)	P89	184
IRVING OIL	7 THOMAS AVE.	W 1/2 - 1 (0.826 mi.)	91	187
MAINE FROZEN FOODS	27 BIRDSEYE AVE	WSW 1/2 - 1 (0.827 mi.)	R92	189
MAINE FROZEN FOODS	27 BIRDSEYE AVENUE	WSW 1/2 - 1 (0.827 ml.)	R95	203
CARIBOU LIBRARY	30 HIGH STREET	W 1/2 - 1 (0.853 mi.)	V113	230
PELLETIER CHERISH	7 VAUGHN ST	WSW 1/2 - 1 (0.867 mi.)	W118	237
UNKNOWN	CORNER OF MAIN / COLLIN	WNW 1/2 - 1 (0.907 mi.)	Y131	276

Other Ascertainable Records

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 02/17/2010 has revealed that there are 4 RCRA-NonGen sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ME PAPER CO	50 BROADWAY	W 1/4 - 1/2 (0.455 mi.)	2	9
BOB SANITATION	101 CHURCH ST	WSW 1/2 - 1 (0.660 mi.)	25	56
NEW ENGLAND TELE CO	15 HIGH ST	W 1/2 - 1 (0.875 mi.)	V122	250
FIRST TECHNOLOGY/CONTROL DEVICE	60 ACCESS HIGHWAY	N 1/2 - 1 (0.990 mi.)	Z144	328

FTTS: FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act) over the previous five years. To maintain currency, EDR contacts the Agency on a quarterly basis.

A review of the FTTS list, as provided by EDR, and dated 04/09/2009 has revealed that there are 3 FTTS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HELEN P KNIGHT SCHOOL	75 BENNETT DR	NW 1/2 - 1 (0.730 mi.)	J54	106
TEAGUE PARK SCHOOL	59 GLENN ST	WNW 1/2 - 1 (0.764 mi.)	M70	150
CARIBOU SCHOOL DEPT BUS GARAG	E 60 GLEN STREET	WNW 1/2 - 1 (0.770 mi.)	M74	154

HIST FTTS: A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

A review of the HIST FTTS list, as provided by EDR, and dated 10/19/2006 has revealed that there are 3 HIST FTTS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
HELEN P KNIGHT SCHOOL	75 BENNETT DR	NW 1/2 - 1 (0.730 mi.)	J54	106
TEAGUE PARK SCHOOL	59 GLENN ST	WNW 1/2 - 1 (0.764 mi.)	M70	150
CARIBOU SCHOOL DEPT BUS GARAGE	60 GLEN STREET	WNW 1/2 - 1 (0.770 mi.)	M74	154

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 04/24/2010 has revealed that there are 3 ICIS sites within approximately 1 mile of the target property.

CARIBOU ME PARKS & RECREATION 55 BENNETT ST CARIBO WNW 1/2 - 1 (0.667 mi.) E30 64 CARIBOU ME FIRE DEPT 101 HIGH ST CARIBOU W 1/2 - 1 (0.732 mi.) 158 109	Lower Elevation	Address	Direction / Distance	Map ID	Page
CARIBOU ME FIRE DEPT 101 HIGH ST CARIBOU W 1/2 - 1 (0.732 mi.) 158 100			(,	E30	64
CARIBOU GENERATING STATION 142 LOWER LYNDON STREET SW 1/2 - 1 (0.732 mi.) K62 123		101 HIGH ST CARIBOU	W 1/2 - 1 (0.732 mi.)	158 Kea	109

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 10/19/2009 has revealed that there are 16 FINDS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ME PAPER CO	50 BROADWAY	W 1/4 - 1/2 (0.455 mi.)	2	9
MAINE ARMY NATIONAL GUARD OMS	20 NORTH STREET	NW 1/2 - 1 (0.628 mi.)	C19	43
CARIBOU GENERATING STATION	142 LOWER LYNDON STREET	TSW 1/2 - 1 (0.634 mi.)	22	52
BOB SANITATION	101 CHURCH ST	WSW 1/2 - 1 (0.660 mi.)	25	56
CARIBOU ME PARKS & RECREATION	55 BENNETT ST	WNW 1/2 - 1 (0.667 mi.)	E27	60
CARIBOU MIDDLE SCHOOL	21 GLENN STREET	WNW 1/2 - 1 (0.694 mi.)	G45	90
PARADIS SHOP N' SAVE	114 HIGH STREET	W 1/2 - 1 (0.718 mi.)	I51	105
CARIBOU LEARNING CENTER	75 BENNETT DRIVE	NW 1/2 - 1 (0.730 mi.)	J52	105
HELEN P KNIGHT SCHOOL	75 BENNETT DRIVE	NW 1/2 - 1 (0.730 mi.)	J53	106
CARIBOU ME FIRE DEPT	101 HIGH ST	W 1/2 - 1 (0.731 mi.)	156	108
TEAGUE PARK SCHOOL	59 GLENN STREET	WNW 1/2 - 1 (0.764 mi.)	M71	150
CARIBOU SCHOOL DEPT BUS GARAGE	60 GLEN STREET	WNW 1/2 - 1 (0.770 ml.)	M74	154
MAINE FROZEN FOODS	27 BIRDSEYE AVENUE	WSW 1/2 - 1 (0.827 mi.)	R93	196
NEW ENGLAND TELE CO	15 HIGH ST	W 1/2 - 1 (0.875 mi.)	V122	250
LEVESQUE OFFICE SUPPLY INC	41 HATCH DR	W 1/2 - 1 (0.972 mi.)	137	287
FIRST TECHNOLOGY/CONTROL DEVIC	60 ACCESS HIGHWAY	N 1/2 - 1 (0.990 mi.)	Z144	328

NPDES: A listing of wastewater facility locations.

A review of the NPDES list, as provided by EDR, and dated 04/06/2010 has revealed that there are 3 NPDES sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARIBOU UTILITIES DISTRICT		SSW 1/2 - 1 (0.842 mi.)	T108	224
CARIBOU UTILITIES DISTRICT		SSW 1/2 - 1 (0.842 mi.)	T109	225
WPS NEW ENGLAND GENERATION, IN		SSW 1/2 - 1 (0.877 mi.)	123	251

UIC: An injection well is any bored, drilled or driven shaft, or dug hole whose depth is greater than its largest surface dimension; an improved sinkhole; or a subsurface distribution system used to discharge fluids underground. These wells range from deep, highly technical, and more frequently monitored wells to shallow on-site drainage systems, such as septic systems, cesspools, and storm water drainage wells.

A review of the UIC list, as provided by EDR, and dated 10/28/2009 has revealed that there are 6 UIC sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DAIGLE OIL SERVICE STATION CARIBOU MIDAS COLBY CO-OPERATIVE STARCH CO PAT'S AUTOMOTIVE CENTER PLOURDE AND PLOURDE INC. CARIBOU SCHOOL BUS GARAGE	89 BENNETT DRIVE 93 BENNETT DRIVE 27 BIRDSEYE AVE 669 MAIN STREET 1 LAURETTE ST 628 MAIN STREET	NW 1/2 - 1 (0.787 mi.) NW 1/2 - 1 (0.796 mi.) WSW 1/2 - 1 (0.827 mi.) W 1/2 - 1 (0.829 mi.) NW 1/2 - 1 (0.830 mi.) WSW 1/2 - 1 (0.880 mi.)	O82 O85 R98 100 Q103 W124	173 178 210 211 218 254

AIRS: Point Source Criteria Pollutant Emissions Inventory data. Criteria air pollutant emissions, expressed in tons, by facility and pollutant.

A review of the AIRS list, as provided by EDR, and dated 12/31/2007 has revealed that there is 1 AIRS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARIBOU GENERATING STATION	142 LOWER LYNDON STRE	ETSW 1/2 - 1 (0.732 ml.)	K59	110

TIER 2: A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.


A review of the TIER 2 list, as provided by EDR, and dated 12/31/2008 has revealed that there are 11 TIER 2 sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MEARNG FMS #5 - FEDERAL FACILI	20 NORTH ST.	NW 1/2 - 1 (0.628 mi.)	C18	40
CARIBOU MIDDLE SCHOOL	21 GLENN ST	WNW 1/2 - 1 (0.694 mi.)	G44	87
CARIBOU WATER WORKS, DIV. OF C	122 LOWER LYNDON ST.	SW 1/2 - 1 (0.703 mi.)	50	101
CARIBOU GENERATING STATION	142 LOWER LYNDON STREI		K59	110
DR CARIBOU CONVENIENCE STORE	89 HIGH STREET	W 1/2 - 1 (0.752 mi.)	L69	146
CARIBOU TEAQUE PARK SCHOOL	59 GLEN STREET	WNW 1/2 - 1 (0.764 mi.)	M73	152
DOT CARIBOU	1 EVERGREEN PARKWAY	NW 1/2 - 1 (0.781 mi.)	N76	158
CARIBOU WATER WORKS (DIV. OF C	300 RIVER ROAD	NNE 1/2 - 1 (0.870 mi.)	119	239
VERIZON CARIBOU CO (ME716106)	15 HIGH ST	W 1/2 - 1 (0.875 mi.)	V121	246
MCDONALD'S OF CARIBOU	127 BENNETT DRIVE	NW 1/2 - 1 (0.896 ml.)	126	257
DR CARIBOU BIRDSEYE AVE.	11 BIRDSEYE AVENUE	WSW 1/2 - 1 (0.905 mi.)	X128	260

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
PHILS AUTO REPAIR	UIC
MECON MFG INC	UIC
CARIBOU BULK PLANT	TIER 2
DAIGLE OIL CARIBOU BULK PLANT	TIER 2
DAIGLE CARIBOU BULK PLANT	TIER 2
REED, REGINALD	LAST
JACKSON CINDY	LAST
CARIBOU IGA	UST
KING HENRYS MOTOR INN	UST
MELODY ROLLER RINK	UST
SHERMAN WILLIAMS	UST
NORTHERN PLASTICS ENGINEERING	UST
WILLIAMS, HOWARD G	UST
LORING MOTEL	UST
AGWAY INC	UST
C & J SVC CTR	UST
LAVERDIERS DRUG	UST
HALLMARK STORE	UST
PEOPLES BANK	UST
FLEET BANK	UST
AUTOMOTIVE SUPPLY	UST
MILLERS DISCOUNT	UST
LIQUOR STORE	UST
HARDWARE STORE	UST
COUNTRY LIVING INC	UST
FREDDIES VIDEOS	UST
CALVARY BAPTIST CHURCH	UST
FORMER NIKE LO 85	UST
WOODLAND PLANT	UST
RACK EN BILLARDS	UST
SCOTTWAY OIL	UST
VALLEY VIDEO	UST
WOODLAND LIQUOR STORE	UST
IGA FOODLINER	UST
WOODLAND TOWN GARAGE	UST
AGRICO FARM CENTER	FINDS,RCRA-NLR
SHERWIN WILLIAMS CO THE	FINDS,RCRA-NLR
FIRST TECHNOLOGY,INC. CONTROLE DEV	MANIFEST
FIRST TECHNOLOGY/CONTROL DEVICES	MANIFEST

OVERVIEW MAP - 02777161.3r




SITE NAME: MMA Railway - Caribou ADDRESS: MMA Railway - Caribou Caribou ME 04736 LAT/LONG: 46.8587 / 67.9931

CLIENT: Haley & Aldrich, Inc.
CONTACT: Andrew Collins
INQUIRY #: 02777161.3r
DATE: May 24, 2010 1:21 pm

Copyright © 2010 EDR, Inc. © 2010 Tele Atlas Rel. 07/2007.





SITE NAME: MMA Railway - Caribou ADDRESS: MMA Railway - Caribou MMA Railway - Caribou Caribou ME 04736 46.8587 / 67.9931 LAT/LONG:

CLIENT: Haley & Aldrich, Inc. CONTACT: Andrew Collins INQUIRY#: 02777161.3r DATE: May 24, 2010 1:21 pm

APPENDIX B Maine DEP Spill Reports



DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: B-229-2006

Spill Report Information

Spill Number:

B-229-2006

Report Status:

Final Report

MCD Town:

GRINDSTONE TWP

Local Name:

GRINDSTONE

Primary Responder:

THOMAS W VARNEY

Primary Product:

Diesel {29} - 100.00 ESTIMATE

Subject/Owner:

MONTREAL, MAINE & ATLANTIC RAILWAY - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Land Transportation - Railroad

Cause:

Accident - Transportation

Spili Date/Time

Spill Date/Time:

04/28/2006

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

04/28/2006 00:00

Subject/Spiller (Potential Responsible Party)

Contact:

MONTREAL, MAINE & ATLANTIC RAILWAY

15 IRON RD

HERMON ME 04401 USA

Comment:

Primary Responder and Other Employees

Contact(s):

THOMAS W VARNEY (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Transportation - Rail {RR}

Name:

MONTREAL, MAINE & ATLANTIC RAILWAY

Street Address:

OFF RT 11 - NO OF MEDWAY

MCD Town:

OH KI II NO OF MEDITAL

Local Name.

GRINDSTONE TWP

Local Name:

GRINDSTONE

State/Province:

ME

Spill Point

Spill Point:

UTM North 5064651.63

UTM East 532316.69

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: Undefined

III. CLEANUP

Product Reported: Diesel {29}

Products Found/Amount Spilled: Diesel {29} - 100.00 ESTIMATE (Primary Product)

Material Recovered: Contaminated Soil {CS} - 4.05 tons ACTUAL Other Material {OM} -

0.00 UNKNOWN

Recovery/Treatment Method: Excavation {G} Sorbents {C}

Cleanup DTREE: Stringent

Disposal Information: By Montreal Maine & Atlantic Railroad at Pine Tree Landfill.

IV. NARRATIVE

On Friday, April 28, a southbound train stopped at Oakfield or St. Croix and picked up Montreal Maine & Atlantic Railroad's wreck crane to transport back to Derby. Just prior to crossing the East Branch of the Penobscot, someone on the train noticed that the crane's fuel tank was leaking. It's unknown how long it had been leaking, but the tank was estimated at 100 gallons and there wasn't much left in it when the train was idled on the siding North of the East Branch crossing.

The train crew notified Tom Tardiff, who notified me. He arrived on site and used what sorbents he had to collect product still dripping, then had more brought from Millinocket. By the time I arrived, the fuel was mostly done dripping; there was a sizeable patch of oiled ballast under the crane and a stripe of leaked diesel extending north up the tracks no one knew how far.

The oiled ballast was removed between and along the rails where the crane sat and leaked. The stripe was deemed unrecoverable.

V.ATTACHMENTS

Attachment TypeDescriptionPaper Attach3 PHOTOSElectronic FormCleanup DTREE

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



Copyright © 2005 All rights reserved.



Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: B-721-1999

Spill Report Information

Spill Number:

B-721-1999

Report Status:

Final Report

MCD Town:

T02 R09 WELS

Local Name:

Primary Responder:

DARRYL LUCE

Primary Product:

#2 Fuel Oil {02} - 350.00 ESTIMATE

Subject/Owner:

BANGOR & AROOSTOOK RAILROAD - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Accident - Other

Spill Date/Time

Spill Date/Time:

11/11/1999

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

11/11/1999 00:00

Subject/Spiller

Contact:

BANGOR & AROOSTOOK RAILROAD

RR2 BOX 45

BANGOR ME 04401

Comment:

Primary Responder and Other Employees

Contact(s):

DARRYL LUCE (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Transportation - Rail {RR}

Name:

BANGOR AND AROOSTOOK RAILROAD

Street Address:

SUMMIT SIDING

MCD Town:

T02 R09 WELS

Local Name:

State/Province:

Spill Point

Spill Point:

UTM North 5071078.00

UTM East 537911.00

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

NONE

III. CLEANUP

Product Reported:

#6 Fuel Oil {06}

Products Found/Amount

#2 Fuel Oil {02} - 350.00 ESTIMATE (Primary Product)

Spilled:

Material Recovered:

Unspilled Product {VP} - 25307.00 gals. ACTUAL Contaminated Soil {CS} - 5.00

cu. yds. ESTIMATE Spilled Product {SP} - 350.00 gals. ESTIMATE

Recovery/Treatment

Method:

Excavation {G} Pumps {B} Other {J}

Cleanup DTREE:

Disposal Information:

landspread

IV. NARRATIVE V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-75-1994

Spill Report Information

Spill Number:

I-75-1994

Report Status:

Final Report

MCD Town:

OAKFIELD

Local Name:

Primary Responder:

FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner:

B&A RAILROAD - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Other - Unknown

Spill Date/Time

Spill Date/Time:

Date and Time Unknown

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Other

Reported Date/Time

Reported Date/Time:

05/24/1994 00:00

Subject/Spiller

Contact:

B&A RAILROAD RR 2 BOX 45

BANGOR ME

Comment:

Primary Responder and Other Employees

Contact(s):

FRANKLIN S WEZNER JR (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Commercial {CM}

Name:

B&A RAILROAD OAKFIELD FACILITY

Street Address:

MCD Town:

OAKFIELD

Local Name:

State/Province:

Spill Point

Spill Point:

UTM North 5106437.00

UTM East 565839.00

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 1 Well At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported: Waste Oil/Used Motor Oil {81}

Products Found/Amount Spilled: Waste Oil/Used Motor Oil {81} - 100.00 ESTIMATE

Material Recovered: Mixed Liquid Media {MM} - 80.99 gals. ACTUAL

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information: IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF Bureau of Re

DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-94-1994

Spill Report Information

Spill Number:

I-94-1994

Report Status:

Final Report

MCD Town:

OAKFIELD

Local Name:

Primary Responder:

FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner:

- GORDAN DUNCAN -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Other - Unknown

Spill Date/Time

Spill Date/Time:

Date and Time Unknown

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

07/27/1994 00:00

Subject/Spiller

Contact:

GORDAN DUNCAN-B&A RAILROAD

OAKFIELD ME

Comment:

Primary Responder and Other Employees

Contact(s):

FRANKLIN S WEZNER JR (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Commercial {CM}

Name:

B&A RAILROAD

Street Address:

MCD Town:

OAKFIELD

Local Name:

State/Province:

Spill Point

Spill Point:

UTM North 5106468.00

UTM East 565839.00

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 1 Well At Risk

Media Affected: Groundwater {G}

Inland Surface Water {I}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported: Waste Oil/Used Motor Oil {81}

Products Found/Amount Spilled: Waste Oil/Used Motor Oil {81} - 500.00 ESTIMATE

Material Recovered: Mixed Liquid Media {MM} - 400.00 gals. ESTIMATE

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-6-1996

Spill Report Information

Spill Number:

I-6-1996

Report Status:

Final Report

MCD Town:

MASARDIS

Local Name:

MASARDIS CARL ALLEN

Primary Responder: Primary Product:

Unleaded Gasoline {23} - 538.00 ACTUAL

Subject/Owner:

- ELIZABETH ROBINSON -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Storage Unit - Aboveground Storage Tank

Cause:

Accident - Other

Spill Date/Time

Spill Date/Time:

01/02/1996

Reporter Type/Detection Method

Type:

Contractor/Consultant {6}

Method:

AST Tank Anomaly

Reported Date/Time

Reported Date/Time:

01/20/1996 00:00

Subject/Spiller (Potential Responsible Party)

Contact:

ELIZABETH ROBINSON-

PO BOX 8

MASARDIS ME 04759

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Terminal - Service Station (SS)

Name:

ROBINSONS MARKET

Street Address:

RT 11

MCD Town:

MASARDIS

Local Name:

MASARDIS

State/Province:

ME

Spill Point

Spill Point:

UTM North 5150171.64

UTM East 549008.61

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 3 Wells At Risk

Media Affected: Groundwater {G}
Land {L}

Atmosphere {A}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported: Unleaded Gasoline {23}

Products Found/Amount Spilled: Unleaded Gasoline {23} - 538.00 ACTUAL (Primary Product)

Material Recovered: Contaminated Soil {CS} - 12.00 cu. yds. ESTIMATE

Recovery/Treatment Method: Excavation {G} Treatment in Place {I}

Cleanup DTREE: Stringent

Disposal Information: SVE system in place

IV. NARRATIVE

See attached narrative

V.ATTACHMENTS

Attachment TypeDescriptionElectronic FormCleanup DTREE

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-44-1996

Spill Report Information

Spill Number: I-44-1996
Report Status: Final Report
MCD Town: ASHLAND

Local Name:

Primary Responder: FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner: ANTONIO LEVESQUE AND SONS - -

I. EVENT

Spill Info

Type: Oil Incident

Source:

Cause: Other - Unknown

Spill Date/Time

Spill Date/Time: Date and Time Unknown

Reporter Type/Detection Method

Type: Contractor/Consultant {6}

Method: Site Assessment

Reported Date/Time

Reported Date/Time: 04/16/1996 00:00

Subject/Spiller

Contact: ANTONIO LEVESQUE AND SONS

P.O. BOX V ASHLAND ME

Comment:

Primary Responder and Other Employees

Contact(s): FRANKLIN S WEZNER JR (Primary Responder)

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Business - Commercial {CM}

Name: ANTONIO LEVESQUE AND SONS

Street Address: P.O. BOX V
MCD Town: ASHLAND

Local Name:
State/Province:
Spill Point

Spill Point: UTM North 5163247.71

UTM East 544925.23

Wells and Media Affected

Wells Affected: 1 Well Impacted/ 1 Well At Risk

Media Affected: Groundwater {G}

Tanks Involved

Tanks Involved: Underground Tank(s) Involved-0 0

III. CLEANUP

Product Reported: Diesel {29}

Products Found/Amount Spilled: Diesel {29} - 50.00 ESTIMATE

Material Recovered: Mixed Liquid Media {MM} - 0.00 gals. ACTUAL

Recovery/Treatment Method: NONE

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

On 4-16-96, County Environmental conducted a site assessment for the removal of a waste oil tank at the Levesque mill in Ashland. At the time of removal no contamination was observed. Later lab analysis of the drinking water well located about 150' away did however indicate a groundwater problem. The system has been placed on a carbon filter and quarterly monitoring.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

I-73-1988

ASHLAND

06/02/1988

Subject/Spiller {2}

06/02/1988 00:00

ENVIRON. AFFAIRS MILLINOCKET ME

Final Report

FRANKLIN S WEZNER JR

GREAT NORTHERN PAPER CO. - -

Non-Oil, Non-Hazardous Incident

Accident - Physical Breakage

Tank and/or Piping Removal

GREAT NORTHERN PAPER CO.

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-73-1988

Spill Report Information

Spill Number:

Report Status:

MCD Town:

Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type:

Method:

Reported Date/Time

Reported Date/Time:

Subject/Spiller

Contact:

Comment:

Primary Responder and Other Employees

Contact(s):

FRANKLIN S WEZNER JR (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Industrial {ID}

Name:

Street Address:

MCD Town:

ASHLAND

Local Name: State/Province:

Spill Point

Spill Point:

UTM North 5171883.29

UTM East 539704.79

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Groundwater {G}

Tanks Involved

Tanks Involved: Underground Tank(s) Involved-11913 0

Underground Tank(s) Involved-11913 0 Underground Tank(s) Involved-11913 0

III. CLEANUP

Product Reported: Leaded Gasoline {22}

Products Found/Amount Spilled: Leaded Gasoline {22} - 10.00 ESTIMATE

Material Recovered: NONE

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information: LANDSPREAD ACCORDING TO GUIDELINES

IV. NARRATIVE V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-73-2001

Spill Report Information

Spill Number:

I-73-2001

Report Status:

Final Report

MCD Town:

NASHVILLE PLT

Local Name:

Primary Responder:

CARL ALLEN

Primary Product:

Non-Hazardous Chemical - Specified in report {92} - 400.00

ESTIMATE

Subject/Owner:

IRVING FOREST PRODUCTS INC - PINKHAM SAWMILL - -

I. EVENT

Spill Info

Type:

Hazardous Material Incident

Source:

Cause:

Accident - Human Error

Spill Date/Time

Spill Date/Time:

06/04/2001

Reporter Type/Detection Method

Type:

Anonymous {5}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

06/05/2001 00:00

Subject/Spiller

Contact:

IRVING FOREST PRODUCTS INC - PINKHAM SAWMILL

PO BOX 389

ASHLAND ME 04732

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Industrial {ID}

Name:

IRVING FOREST PRODUCTS INC PINKHAM SAWMILL

Street Address: MCD Town:

PINKHAM RD

NASHVILLE PLT

Local Name:

State/Province:

ME

Spill Point

Spill Point: UTM North 5172106.00

UTM East 539446.00

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported: Non-Hazardous Chemical - Specified in report {92}

Products Found/Amount Spilled: Non-Hazardous Chemical - Specified in report {92} - 400.00

ESTIMATE (Primary Product)

Material Recovered: Other Material {OM} - 0.00 UNKNOWN

Recovery/Treatment Method: Other {J}

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

A complaintant stated that 500 to 600 gallons of waste paint had been dumped onto the bark pile and this mixture was to be burned in the mills boiler. The complaintant also stated that another 800 gal. was to be dumped on 6/6/01. (I found no evidence of this additional volume).

I meet Kathy Hoppe on site since she is familiar with the site. We went to the steam plant bark pile where complaintant stated the drums had been dumped and found them still laying over on their sides with a large amount of colored bark on the ground.

We then made contact with Ralph Dwyer, who presented an e-mail explaining to Jim Gramlich what Irving was going to do with this waste paint.

The Waste Paint came from a painting contractor who painted the entire facility last year. The contractor left many smaller containers of brush cleanings and left over paints. Ralph had his crews consolidate these materials into 8 open top 55 gal. drums.

I stopped the burning and explained we may have a problem with Hazardous Waste issues concerning the material.

The procedure that was to follow was to dump the liquids onto a 4 foot thick pile of bark & wood waste, then burn it in the boiler.

The material was piled up and covered with poly. Sampling is being done for parameters requested by Lou Pizzuti in Solid Waste unit and Mary Corr in Haz. Waste unit.

Sampling will be done by S.W. Cole.

Response case closed.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report Selected Report: I-132-1998

Spill Report Information

Spill Number: Report Status:

MCD Town:

Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type: Method:

Reported Date/Time

Reported Date/Time:

Subject/Spiller

Contact:

Comment:

Primary Responder and Other Employees

Contact(s): Comment:

II. SITE Location

Location Type:

Name: Street Address:

Local Name: State/Province:

Spill Point

MCD Town:

Spill Point:

I-132-1998

Final Report PORTAGE LAKE

FRANKLIN S WEZNER JR

PINKHAM LUMBER (BOWATER) - -

Oil Incident

Corrosion - Tank

Date and Time Unknown

Subject/Spiller {2}

Visual Product

06/16/1998 00:00

PINKHAM LUMBER (BOWATER)

PORTAGE LAKE ME

FRANKLIN S WEZNER JR (Primary Responder)

No Further Response Action Expected

Business - Commercial {CM}

PINKHAM LUMBER **NASHVILLE MILL**

PORTAGE LAKE

UTM North 5171883.29 UTM East 539704.79

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Underground Tank(s) Involved-11913 0

III. CLEANUP

Product Reported:

Diesel {29}

Products Found/Amount Spilled:

Diesel {29} - 75.99 ACTUAL

Material Recovered:

Mixed Liquid Media {MM} - 65.99 gals. ACTUAL

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Disposal Information:

Landspread according to guidelines

IV. NARRATIVE

On 6-16-98, a spill of diesel fuel at the Pinkham Lumber mill in Portage was reported to this office. About 75 gallons had been lost from an abandoned UST stored in their scrap yard that was thought to be empty. A stain on the ground beneath and around the tank revealed the problem. About 40 yards of soil was removed and landspread at a appropriate area on site. No further action was seen as necessary.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-88-1994

Spill Report Information

Spill Number: I-88-1994
Report Status: Final Report
MCD Town: NASHVILLE PLT

Local Name:

Primary Responder: FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner: PINKHAM LUMBER CO. - -

I. EVENT
Spill Info

Type: Non-Oil, Non-Hazardous Incident

Source:

Cause: Overfill

Spill Date/Time

Spill Date/Time: Date and Time Unknown

Reporter Type/Detection Method

Type: Subject/Spiller {2} Method: Monitoring Well

Reported Date/Time

Reported Date/Time: 06/06/1994 00:00

Subject/Spiller

Contact: PINKHAM LUMBER CO.

RT. 11

NASHVILLE PLT ME

Comment:

Primary Responder and Other Employees

Contact(s): FRANKLIN S WEZNER JR (Primary Responder)

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Business - Industrial {ID}

Name: PINKHAM LUMBER

Street Address:

MCD Town: NASHVILLE PLT

Local Name: State/Province: **Spill Point**

Spill Point: UTM North 5171883.29

UTM East 539704.79

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 1 Well At Risk

Media Affected: Groundwater {G}

Tanks Involved

Tanks Involved: Underground Tank(s) Involved-11913 0

III. CLEANUP

Product Reported: Unleaded Gasoline {23}

Products Found/Amount Spilled: Unleaded Gasoline {23} - 20.00 ESTIMATE

Material Recovered: NONE Recovery/Treatment Method: NONE

Cleanup DTREE:

Disposal Information: IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-238-2004

Spill Report Information

Spill Number: Report Status:

Final Report PORTAGE LAKE

Local Name: Primary Responder:

MCD Town:

PORTAGE CARL ALLEN

I-238-2004

Primary Product:

Hydraulic Oil {86} - 30.00 ESTIMATE

Subject/Owner:

MAINE WOODS CO - -

I. EVENT

Spill Info

Type:

Oil Incident

Source: Cause:

Equipment - Heavy Equipment Mechanical Failure - Piping/Hose

Spill Date/Time

Spill Date/Time:

11/18/2004 00:00

Reporter Type/Detection Method

Type: Method: Subject/Spiller {2}
Visual Product

Reported Date/Time

Reported Date/Time:

11/18/2004 00:00

Subject/Spiller (Potential Responsible Party)

Contact:

MAINE WOODS CO PO BOX 111

PORTAGE ME 04768 USA

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Industrial {ID}

Name:

MAINE WOOD CO - LOG YARD

Street Address:

ROCKY BROOK RD

MCD Town:

PORTAGE LAKE

Local Name:

PORTAGE

State/Province:

ME

Spill Point

Spill Point:

UTM North 5177176.00

UTM East 538015.63

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Undefined

III. CLEANUP

Product Reported:

Hydraulic Oil {86}

Products Found/Amount Spilled:

Hydraulic Oil {86} - 30.00 ESTIMATE (Primary Product)

Material Recovered:

Other Material {OM} - 0.00 UNKNOWN

Recovery/Treatment Method:

Sorbents {C}

Cleanup DTREE:

Disposal Information:

Disposed of in on-site boiler

IV. NARRATIVE

11/18/04, a spill was reported after a broken hydraulic line was found on a company crane.

The spill was cleaned up with sawdust and sorbents which were burned in the mill boiler.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-58-1994

Spill Report Information

Spill Number:

I-58-1994

Report Status:

Final Report

MCD Town:

WALLAGRASS

Local Name:

WALLAGRASS PLT

Primary Responder:

CARL ALLEN

Primary Product:

Subject/Owner:

BANGOR & AROOSTOOK RAILROAD - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Accident - Transportation

Spill Date/Time

Spill Date/Time:

04/29/1994 00:00

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Other

Reported Date/Time

Reported Date/Time:

04/29/1994 00:00

Subject/Spiller

Contact:

BANGOR & AROOSTOOK RAILROAD

NORTHERN MAINE JCT

BANGOR ME

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Transportation - Rail {RR}

Name:

BANGOR & AROOSTOOK RAILROAD

Street Address:

SLY BROOK ROAD

MCD Town:

WALLAGRASS

Local Name:

WALLAGRASS PLT

State/Province:

ME

Spill Point

Spill Point:

UTM North 5222568.00

UTM East 532069.00

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

NONE

III. CLEANUP

Product Reported:

#6 Fuel Oil {06}

Products Found/Amount Spilled:

#6 Fuel Oil {06} - 5.00 ESTIMATE

Material Recovered:

Mixed Liquid Media {MM} - 5.00 gals. ESTIMATE

Recovery/Treatment Method:

NONE

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-12-2008

Spill Report Information

Spill Number: I-12-2008
Report Status: Final Report
MCD Town: FORT KENT
Local Name: FORT KENT

Primary Responder: FRANKLIN S WEZNER JR

Primary Product: Diesel {29} - 100.00 ESTIMATE

Subject/Owner: DAIGLE OIL COMPANY - -

I. EVENT

Spill Info

Type: Oil Incident

Source: Storage Unit - Aboveground Storage Tank

Cause: Overfill

Spill Date/Time

Spill Date/Time: Date and Time Unknown

Reporter Type/Detection Method

Type: Subject/Spiller {2}
Method: Visual Product

Reported Date/Time

Reported Date/Time: 01/23/2008 00:00

Subject/Spiller (Potential Responsible Party)

Contact: DAIGLE OIL COMPANY

155 MAIN STREET

FORT KENT ME 04743 USA

Comment:

Primary Responder and Other Employees

Contact(s): FRANKLIN S WEZNER JR (Primary Responder)

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Terminal - Bulk Plant {BP}
Name: DAIGLE OIL BULK PLANT

Street Address: FRENCHVILLE ROAD

MCD Town: FORT KENT Local Name: FORT KENT

State/Province: ME

Spill Point

Spill Point: UTM North 5236434.76

UTM East 531804.90

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported:

#2 Fuel Oil {02}

Products Found/Amount Spilled:

Diesel {29} - 100.00 ESTIMATE (Primary Product)

Material Recovered:

Mixed Liquid Media {MM} - 0.00 UNKNOWN

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Disposal Information:

Tri Community Landfill

IV. NARRATIVE

On 1-23-08, Bert Levesque of Daigle Oil reported that due to an overfill, about 100 gallons of diesel fuel had been spilled at their bulk plant in Fort Kent. Apparently the driver had miscalculated the amount necessary to fill the tank. Several Daigle employees were dispatched to remove contaminated snow in the diked area. I met with Bert at the facility that day. They were hand shoveling, as no heavy equipment could be brought into the dike.

V.ATTACHMENTS

Attachment Type

Description

Electronic Form

Spill Debris

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



*

DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-21-2001

Spill Report Information

Spill Number:

I-21-2001

Report Status:

Final Report

MCD Town:

FORT KENT

Local Name:

BULK PLANT NEXT TO RR TRACKS

Primary Responder:

CARL ALLEN

Primary Product:

Subject/Owner:

DEAD RIVER CO - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Mechanical Failure - Loose Fitting

Spill Date/Time

Spill Date/Time:

03/02/2001

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

03/02/2001 00:00

Subject/Spiller

Contact:

DEAD RIVER CO 86 WEST MAIN ST

FORT KENT ME 04743

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Terminal - Bulk Plant {BP}

Name:

DEAD RIVER CO

Street Address:

RT 161

MCD Town:

FORT KENT

Local Name:

BULK PLANT NEXT TO RR TRACKS

State/Province:

Spill Point

Spill Point:

UTM North 5233556.00

UTM East 531611.00

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported:

#2 Fuel Oil {02}

Products Found/Amount Spilled:

#2 Fuel Oil {02} - 10.00 ESTIMATE

Material Recovered:

Mixed Liquid Media {MM} - 5.00 gals. ESTIMATE

Recovery/Treatment Method:

Excavation {G} Sorbents {C}

Cleanup DTREE:

Disposal Information:

Tricommunity Landfill - contaminated snow

IV. NARRATIVE

One of Dead River's drivers noticed a discoloration of the snow under one of their pumps at the Fort Kent Bulk Plant. Further investigation revealed that a seal was leaking.

A pickup load of contaminated snow was excavated and hauled to the landfill by Dead River staff.

The seal was wrapped with sorbants & poly to keep the plant operational until the seal could be replaced.

The site will continue to be monitored through the spring melt and will receive further clean-up as needed.

Case closed.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

UNLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-67-1994

Spill Report Information

Spill Number:

Report Status:

I-67-1994 Final Report

MCD Town:

FORT KENT

Local Name:

Primary Responder:

CARL ALLEN

Primary Product:

Subject/Owner:

DAIGLE OIL CO - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Corrosion - Tank

Spill Date/Time

Spill Date/Time:

Date and Time Unknown

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

UST Tank Anomaly

Reported Date/Time

Reported Date/Time:

05/03/1994 00:00

Subject/Spiller

Contact:

DAIGLE OIL CO

44W MAIN ST. P.O.BOX 328

FORT KENT ME 04743

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Terminal - Bulk Plant {BP}

Name:

DAIGLE OIL CO

Street Address:

44W MAIN ST. P.O.BOX 328

MCD Town:

FORT KENT

Local Name:

State/Province:

Spill PointSpill Point:

UTM North 5235713.00

UTM East 530948.00

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Groundwater {G}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported:

Products Found/Amount Spilled: #1 Fuel Oil - Kerosene {01} - 200.00 ESTIMATE

Material Recovered: NONE

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information: IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security

inform[3

DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-217-2004

Spill Report Information

Spill Number:

I-217-2004

Report Status:

Final Report

MCD Town:

NEW LIMERICK NEW LIMERICK

Local Name:

Primary Responder: **Primary Product:**

CARL ALLEN

Hazardous Chemical - Specified in report {79} - 1100.00 ESTIMATE

Subject/Owner:

LOUISIANA PACIFIC CORP - -

I. EVENT

Spill Info

Type: Source: Hazardous Material Incident

Equipment - Industrial Machinery

Cause:

Process Failure - Other

Spill Date/Time

Spill Date/Time:

10/21/2004 00:00

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

10/21/2004 00:00

Subject/Spiller (Potential Responsible Party)

Contact:

LOUISIANA PACIFIC CORP

PO BOX 396

HOULTON ME 04730 USA

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Industrial {ID}

Name:

LOUISIANA PACIFIC CORP

Street Address:

240 STATION RD

MCD Town:

NEW LIMERICK

Local Name:

NEW LIMERICK

State/Province:

ME

Spill Point

Spill Point:

UTM North 5106703.19

UTM East 580842.91

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Interior Surface {S}

Tanks Involved

Tanks Involved:

Undefined

III. CLEANUP

Product Reported:

Hazardous Chemical - Specified in report {79}

Products Found/Amount Spilled:

Hazardous Chemical - Specified in report {79} - 1100.00 ESTIMATE Additional Product Description - phenol formaldehyde resin (Primary

Product)

Material Recovered:

Other Material {OM} - 100.00 cu. yds. ESTIMATE

Recovery/Treatment Method:

Sorbents {C}

Cleanup DTREE:

Disposal Information:

material collected on wood chips and burned in Hog Boiler

IV. NARRATIVE

A spill of Phenol Formaldehyde resin, resulted from a "PLC Control Problem". An air operated valve opened when it shouldn't have.

The spill was contained inside the building and cleaned up with wood chips, then burned on site in the boilers.

Response Case Closed.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-163-2000

Spill Report Information

Spill Number: Report Status:

MCD Town: Local Name:

Primary Responder:

Primary Product:

Subject/Owner: I. EVENT

Spill Info

Type:

Source:

Cause: Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type: Method:

Reported Date/Time

Reported Date/Time: Subject/Spiller

Contact:

Comment: **Primary Responder and Other Employees**

Contact(s):

Comment:

II. SITE Location

Location Type: Name:

MCD Town: Local Name: State/Province:

Street Address:

Spill Point

Spill Point:

I-163-2000

Final Report HOULTON

HOULTON CARL ALLEN

Hydraulic Oil {86} - 35.00 ESTIMATE

LOUISIANA PACIFIC CORP. - -

Oil Incident

Equipment - Industrial Machinery

Mechanical Failure - Piping/Hose

07/21/1999

Subject/Spiller {2}

07/22/1999 00:00

Visual Product

LOUISIANA PACIFIC CORP. PO BOX 396

HOULTON ME 04730

CARL ALLEN (Primary Responder) No Further Response Action Expected

Business - Industrial {ID}

LOUISIANA PACIFIC PLANT

HOULTON

HOULTON

ME

UTM North 5106542.42

UTM East 586509.66

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Undefined

III. CLEANUP

Product Reported:

Hydraulic Oil {86}

Products Found/Amount Spilled:

Hydraulic Oil {86} - 35.00 ESTIMATE (Primary Product)

Material Recovered:

Mixed Liquid Media {MM} - 35.00 gals. ESTIMATE

Recovery/Treatment Method:

Burning {H}

Cleanup DTREE:

Disposal Information:

Thermally degrade onsite under air lic # A-327-72-D-A/R

IV. NARRATIVE

Hydraulic hose ruptured causing 35 gallons of hydraulic fluid to be lost inside the main production building, on concrete floor near the press area. It was cleaned up and put into thermal oil heater per air license.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report
Selected Report: 1-86-2003

Spill Report Information

Spill Number: I-86-2003
Report Status: Final Report

MCD Town: HOULTON
Local Name: HOULTON
Primary Responder: CARL ALLEN

Primary Product: #1 Fuel Oil - Kerosene {01} - 100.00 ESTIMATE

Subject/Owner: - VERNON & GLADYS SPOONER -

I. EVENT

Spill Info

Type: Oil Incident

Source: Storage Unit - Aboveground Storage Tank

Cause: Accident - Physical Breakage

Spill Date/Time

Spill Date/Time: Date and Time Unknown

Reporter Type/Detection Method

Type: Subject/Spiller {2}
Method: Odor/Vapor/Mist

Reported Date/Time

Reported Date/Time: 03/26/2003 00:00

Other Contact

Contact: MICHAEL TIDD-

B RD ME USA

Comment:

Subject/Spiller (Potential Responsible Party)

Contact: VERNON & GLADYS SPOONER-

110 B RD

HOULTON ME 04730 USA

Comment:

Primary Responder and Other Employees

Contact(s): CARL ALLEN (Primary Responder)

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Residential - Single Family {SF}

Name: VERNON SPOONER

Street Address: 110 B RD

MCD Town: HOULTON
Local Name: HOULTON

State/Province: ME

Spill Point

Spill Point: UTM North 5111150.09
UTM East 588805.09

Wells and Media Affected

Wells Affected: 1 Well Impacted/ 1 Well At Risk

Media Affected: Groundwater {G}

Land {L}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported: #1 Fuel Oil - Kerosene {01}

Products Found/Amount Spilled: #1 Fuel Oil - Kerosene {01} - 100.00 ESTIMATE (Primary Product)

Material Recovered: Contaminated Soil {CS} - 9.56 tons ESTIMATE

Recovery/Treatment Method: Excavation {G} Filter {F}

Cleanup DTREE: Stringent

Disposal Information: Tricommunity landfill

IV. NARRATIVE

AST spill at filter. Brass nipple broke when ice fell on copper line.

Filter was protected by a piece of wood.

Contaminated soil was removed to bedrock, which was about 5 feet below grade. Contaminated wood was removed and replaced and the hole was back filled.

Oil did reach the bedrock.

Aroostook Water Care has been contacted to supply a filter, because I could smell oil in the water.

Case has been turned over to Paul Higgins.

V.ATTACHMENTS

Attachment Type Description

Paper Attach Tri Community Generator Form

Paper Attach Oil Spill Debris Form

Paper Attach Clean up Actions Agreement

Electronic Form QMP Request
Electronic Form Expense Tracking
Electronic Form Cleanup DTREE

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security

infor_u[3

DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-31-2001

Spill Report Information

Spill Number:

Report Status:

MCD Town:

Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type: Method:

Reported Date/Time

Reported Date/Time:

Subject/Spiller

Contact:

Primary Responder and Other Employees

Comment:

Contact(s):

Comment:

II. SITE Location

Name:

Location Type:

Street Address:

MCD Town: Local Name:

State/Province: **Spill Point**

Spill Point:

I-31-2001

Final Report

CHAPMAN

CHAPMAN

FRANKLIN S WEZNER JR

- NEAL BUCK -

Oil Incident

Accident - Physical Breakage

03/26/2001

Subject/Spiller {2}

Visual Product

03/26/2001 00:00

NEAL BUCK-

PO BOX 286

MAPLETON ME 04757

FRANKLIN S WEZNER JR (Primary Responder)

No Further Response Action Expected

Residential - Single Family {SF}

BUCK, NEAL

WEST CHAPMAN ROAD

CHAPMAN CHAPMAN

ME

UTM North 5169569.38

UTM East 563990.13

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 1 Well At Risk

Media Affected: Groundwater {G}

Land {L}

Tanks Involved

Tanks Involved: Above Ground Tank(s) Involved-Tank Outside

III. CLEANUP

Product Reported: #1 Fuel Oil - Kerosene {01}

Products Found/Amount Spilled: #1 Fuel Oil - Kerosene {01} - 200.00 ESTIMATE

Material Recovered: Mixed Liquid Media {MM} - 185.00 gals. ESTIMATE

Recovery/Treatment Method: Excavation {G} Sorbents {C} Other {J}

Cleanup DTREE:

Disposal Information: Tri Community Landfill

IV. NARRATIVE

On 3-26-01, Neal Buck called to report a spill at his home on the West Chapman Road in Mapleton. He had just returned home after being away for two weeks and discovered the tank to be empty. A contractor was hired that day to perform the cleanup. Oil was found beneath the snow to have run down his front yard to a road ditch, and down the ditch about 800 feet. Contaminated soil near the source was removed and a series of collection sumps were placed and maintained in the road ditch.

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-233-2003

Spill Report Information

Spill Number:

Report Status:

MCD Town: Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time Spill Date/Time:

Reporter Type/Detection Method

Type: Method:

Reported Date/Time Reported Date/Time:

Subject/Spiller (Potential Responsible Party)

Contact:

Comment:

Contact(s): Comment:

Location

II. SITE

Location Type:

Name: Street Address:

Local Name: State/Province:

Spill Point Spill Point:

MCD Town:

I-233-2003

Final Report PRESQUE ISLE

PRESQUE ISLE

FRANKLIN S WEZNER JR

Gasoline Unspecified {20} - 100.00 ESTIMATE

- RICHARD THOMPKINS -

Oil Incident

Storage Unit - Underground Storage Tank

Mechanical Failure - Loose Fitting

Date and Time Unknown

Contractor/Consultant {6}

Tank and/or Piping Removal

08/20/2003 00:00

RICHARD THOMPKINS-

24 INDUSTRIAL ST PRESQUE ISLE ME 04769 USA

Primary Responder and Other Employees

FRANKLIN S WEZNER JR (Primary Responder)

No Further Response Action Expected

Terminal - Service Station (SS)

BUCKS MARKET

INDUSTRIAL STREET

PRESQUE ISLE PRESQUE ISLE

ME

UTM North 5169790.46

UTM East 574066.99

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Groundwater {G}

Land {L}

Tanks Involved

Tanks Involved:

Underground Tank(s) Involved-13067 0

III. CLEANUP

Product Reported:

Gasoline Unspecified {20}

Products Found/Amount Spilled:

Gasoline Unspecified {20} - 100.00 ESTIMATE (Primary Product)

Material Recovered:

Contaminated Soil {CS} - 350.00 cu. yds. ESTIMATE

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Intermediate

Disposal Information:

IV. NARRATIVE

On 8-20-03, this office was notified of soil contamination that was encountered while UST's were being replaced at Buck's Market. There was contamination found beneath the area of the old pump island and one of the piping sumps during the course of the site assessment. I met with Chad Mc Pherson of SW Cole on site the same day. An intermediate cleanup standard was set and all soil encountered was removed to that standard. About 300 yards was removed and taken to the Presque Isle Landfill.

On 9-9-03, while excavating for the new water line to the building, more contamination was found. I recommended removal of all that was encountered during the excavation.

V.ATTACHMENTS

Attachment Type

Description

Electronic Form

Expense Tracking

Electronic Form

Cleanup DTREE

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMENT OF ENVIRONMENTAL PROTECTION Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVIC

SEARCH: Results: Full Report

Selected Report: I-168-2000

Spill Report Information

Spill Number:

Report Status:

MCD Town:

Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type:

Method:

Reported Date/Time

Reported Date/Time:

Subject/Spiller

Contact:

Primary Responder and Other Employees

Contact(s):

Comment:

Comment:

II. SITE Location

Location Type:

Name:

Street Address: MCD Town:

Local Name:

State/Province:

Spill Point Spill Point:

I-168-2000

Final Report

PRESQUE ISLE PRESQUE ISLE

CARL ALLEN

PCB Oil {71} - 50.00 ESTIMATE

MCCAIN FOODS - -

Hazardous Material Incident

Utility - Electrical Transformer

Accident - Transportation

08/10/1999 00:00

Subject/Spiller {2}

Visual Product

08/10/1999 00:00

MCCAIN FOODS

REACH ROAD

PRESQUE ISLE ME 04769

No Further Response Action Expected

CARL ALLEN (Primary Responder)

Business - Industrial {ID}

MCCAIN FOODS

REACH ROAD

PRESQUE ISLE PRESQUE ISLE

ME

UTM North 5172087.17

UTM East 577428.02

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: Undefined

III. CLEANUP

Product Reported: PCB Oil {71}

Products Found/Amount Spilled: PCB Oil {71} - 50.00 ESTIMATE (Primary Product)

Material Recovered: Mixed Liquid Media {MM} - 50.00 gals. ESTIMATE

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information: Clean Harbour, New York

IV. NARRATIVE

Contractor struck buried pole stabilization cable, breaking pole with 3 phase 167 KVA transformer, spilling 40-50 gallons onto roadway. All chemical was recovered by excavation and sent to Clean Harbor, New York.

Response case closed

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-4-1995

Spill Report Information

Spill Number: I-4-1995
Report Status: Final Report
MCD Town: PRESQUE ISLE

Local Name:

Primary Responder: FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner: FERRIS OIL COMPANY - -

I. EVENT
Spill Info

Type: Oil Incident

Source:

Cause: Overfill

Spill Date/Time

Spill Date/Time: 01/18/1995

Reporter Type/Detection Method

Type: Subject/Spiller {2}

Method: Other

Reported Date/Time

Reported Date/Time: 01/18/1995 00:00

Subject/Spiller

Contact: FERRIS OIL COMPANY

RT. 10

PRESQUE ISLE ME

Comment:

Primary Responder and Other Employees

Contact(s): FRANKLIN S WEZNER JR (Primary Responder)

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Terminal - Bulk Plant {BP}
Name: FERRIS OIL COMPANY

Street Address: RT. 10

MCD Town: PRESQUE ISLE

Local Name: State/Province: **Spill Point**

Spill Point: UTM North 5170167.00

UTM East 575181.00

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Land {L}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported: Diesel {29}

Products Found/Amount Spilled: Diesel {29} - 20.00 ESTIMATE

Material Recovered: Mixed Liquid Media {MM} - 15.00 gals. ESTIMATE

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-151-2000

Spill Report Information

Spill Number:

I-151-2000

Report Status:

Final Report

MCD Town:

EASTON

Local Name:

EASTON

Primary Responder:

CARL ALLEN

Primary Product:

Hydraulic Oil {86} - 50.00 ESTIMATE

Subject/Owner:

J.M. HUBER - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Equipment - Heavy Equipment

Cause:

Mechanical Failure - Piping/Hose

Spill Date/Time

Spill Date/Time:

06/05/2000 00:00

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Visual Product

Reported Date/Time

Reported Date/Time:

06/05/2000 00:00

Subject/Spiller

Contact:

J.M. HUBER

PO BOX 69

EASTON ME 04740

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Transportation - Other Off-Road {OTP}

Name:

JM HUBER RAILYARD

Street Address:

MCD Town:

EASTON

Local Name:

EASTON

State/Province:

ME

Spill Point

Spill Point:

UTM North 5168462.23

UTM East 583758.74

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

Undefined

III. CLEANUP

Product Reported:

Hydraulic Oil {86}

Products Found/Amount Spilled:

Hydraulic Oil {86} - 50.00 ESTIMATE (Primary Product)

Material Recovered:

Other Material {OM} - 50.00 gals. ESTIMATE

Recovery/Treatment Method:

Sorbents {C}

Cleanup DTREE:

Disposal Information:

PUT IN BOILER

IV. NARRATIVE

A hydraulic hose broke on a log loader. Sawdust fines were spread over the spill and the clean up debris was burned in the onsite boiler.

Response case clsoed

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-238-1998

Spill Report Information

Spill Number:

I-238-1998

Report Status:

Final Report

MCD Town:

EASTON

Local Name:

EASTON

Primary Responder:

CARL ALLEN

Primary Product: Subject/Owner:

MCCAIN FOODS, INC. - -

I. EVENT

Spill Info

Type:

Hazardous Material Incident

Source:

Equipment - Industrial Machinery

Ammonia {76} - 841.00 ACTUAL

Cause:

Mechanical Failure - Valve

Spill Date/Time

Spill Date/Time:

06/24/1998 00:00

Reporter Type/Detection Method

Type:

Subject/Spiller {2}

Method:

Odor/Vapor/Mist

Reported Date/Time

Reported Date/Time:

06/24/1998 00:00

Subject/Spiller

Contact:

MCCAIN FOODS, INC. RICHARDSON ROAD

EASTON ME 04740

Comment:

Primary Responder and Other Employees

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Business - Industrial {ID}

Name:

MCCAIN FOODS USA

Street Address:

319 RICHARDSON ROAD

MCD Town:

EASTON

Local Name:

EASTON

State/Province:

ME

Spill PointSpill Point:

UTM North 5168232.40

UTM East 584019.72

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 0 Wells At Risk

Media Affected: Atmosphere {A}

Tanks Involved

Tanks Involved: NONE

III. CLEANUP

Product Reported: Ammonia {76}

Products Found/Amount Spilled: Ammonia {76} - 841.00 ACTUAL (Primary Product)

Material Recovered: None {NO} - 0.00 gals. ACTUAL

Recovery/Treatment Method: None {K}

Cleanup DTREE:

Disposal Information: RELEASED TO AIR

IV. NARRATIVE

EMPLOYEE WAS REMOVING BROKEN VACUUM GAUGE, SHUT OFF L/4" VALVE WHICH DID NOT HOLD.

RELEASED 841 LBS. AMMONIA INTO AIR

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



DEPARTMEN Bureau o

DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-90-1995

Spill Report Information

Spill Number: Report Status:

Final Report EASTON

I-90-1995

MCD Town: Local Name:

Primary Responder:

FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner:

KANA OIL COMPANY - -

I. EVENT

Spill Info

Type:

Oil Incident

Source:

Cause:

Corrosion - Tank

Spill Date/Time

Spill Date/Time:

Date and Time Unknown

Reporter Type/Detection Method

Type:

Contractor/Consultant {6}
Tank and/or Piping Removal

Method:

Reported Date/Time

Reported Date/Time:

09/22/1995 00:00

Subject/Spiller

Contact:

KANA OIL COMPANY STATION ROAD

EASTON ME

Comment:

Primary Responder and Other Employees

Contact(s):

FRANKLIN S WEZNER JR (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Terminal - Service Station (SS)

Name:

KANA OIL COMPANY

Street Address:

STATION ROAD

MCD Town:

EASTON

Local Name:

State/Province:

Spill Point

Spill Point:

UTM North 5167958.00

UTM East 583328.00

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 2 Wells At Risk

Media Affected:

 $Groundwater~\{G\}$

Land {L}

Tanks Involved

Tanks Involved:

Underground Tank(s) Involved-0 0

III. CLEANUP

Product Reported:

Unleaded Gasoline {23}

Products Found/Amount Spilled:

Unleaded Gasoline {23} - 500.00 ESTIMATE

Material Recovered:

Mixed Liquid Media $\{MM\}$ - 400.00 gals. ESTIMATE

Recovery/Treatment Method:

Excavation $\{G\}$

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



- t

DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-1-1995

Spill Report Information

Spill Number: Report Status:

MCD Town: EASTON

Local Name:

Primary Responder: FRANKLIN S WEZNER JR

Primary Product:

Subject/Owner: HENDERSON OIL COMPANY - -

I-1-1995

Final Report

I. EVENT
Spill Info

Type: Oil Incident

Source:

Cause: Mechanical Failure - Piping/Hose

Spill Date/Time

Spill Date/Time: 01/06/1995

Reporter Type/Detection Method

Type: Subject/Spiller {2}

Method: Other

Reported Date/Time

Reported Date/Time: 01/06/1995 00:00

Subject/Spiller

Contact: HENDERSON OIL COMPANY

STATION ROAD EASTON ME

Comment:

Primary Responder and Other Employees

Contact(s): FRANKLIN S WEZNER JR (Primary Responder)

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Terminal - Bulk Plant {BP}

Name: HENDERSON OIL COMPANY

Street Address: STATION ROAD

MCD Town: EASTON

Local Name: State/Province:

Spill Point

Spill Point: UTM North 5167893.00

UTM East 583095.00

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

NONE

III. CLEANUP

Product Reported:

Unleaded Gasoline {23}

Products Found/Amount Spilled:

Unleaded Gasoline {23} - 500.00 ESTIMATE

Material Recovered:

Mixed Liquid Media {MM} - 400.00 gals. ESTIMATE

Recovery/Treatment Method:

Excavation {G}

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security



Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-168-2005

Spill Report Information

Spill Number:

Report Status:

MCD Town:

Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type:

Method: Reported Date/Time

Reported Date/Time:

Subject/Spiller (Potential Responsible Party)

Contact:

Comment:

Primary Responder and Other Employees

Contact(s): Comment:

II. SITE Location

Location Type:

Name: Street Address:

MCD Town: Local Name:

State/Province:

Spill Point

Spill Point:

I-168-2005

Final Report

CARIBOU CARIBOU

FRANKLIN S WEZNER JR

Diesel {29} - 300.00 ESTIMATE

EARTH WASTE SYSTEMS - KEVIN ELNICKI -

Oil Incident

Storage Unit - Underground Storage Tank

Other - Unknown

Date and Time Unknown

Public Official {4}

Visual Product

09/19/2005 00:00

KEVIN ELNICKI-EARTH WASTE SYSTEMS

PO BOX 120

PITTSFORD VT 05763 USA

FRANKLIN S WEZNER JR (Primary Responder)

No Further Response Action Expected

Business - Commercial {CM}

KEVIN ELNICKI

LIMESTONE STREET **CARIBOU**

CARIBOU

ME

UTM North 5190617.33

UTM East 576364.82

Wells and Media Affected

Wells Affected: 0 Wells Impacted/ 1 Well At Risk

Media Affected: Groundwater {G}

Land {L}

Tanks Involved

Tanks Involved: Underground Tank(s) Involved-10448 0

III. CLEANUP

Product Reported: Gasoline Unspecified {20}

Products Found/Amount Spilled: Diesel {29} - 300.00 ESTIMATE (Primary Product)

Material Recovered: Contaminated Soil {CS} - 1797.46 tons ACTUAL

Recovery/Treatment Method: Excavation {G}

Cleanup DTREE: Stringent

Disposal Information: Soil disposed of at Tri Community Landfill..

IV. NARRATIVE

On 9-19-05, Al Hitchcock, of the Caribou Utilities District called to report that while excavating to replace a water line on Limestone Street two abandoned underground tanks were discovered. I met with him there that day. It looked like the tanks were on the property of Earth Waste Systems. I told Al to allow the contractor to remove the tanks and have a site assessment and tank installer present. The tanks were removed that day. A considerable amount of contaminated soil was present and the soil in the city's right of way was removed. Contaminated soil on the tank owner's property will need to be addressed and this has been referred to technical services for future action. No further action will be completed by Response Services since the site has been referred.

V.ATTACHMENTS

Attachment Type Description

Paper Attach UST Site Assessment - 10/24/2005

Electronic Form Referral to PAUL S BLOOD

Electronic Form Cleanup DTREE
Electronic Form Expense Tracking

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-54-1994

Spill Report Information

Spill Number: I-54-1994
Report Status: Final Report
MCD Town: CARIBOU

Local Name:

Primary Responder: CARL ALLEN

Primary Product:

Subject/Owner: - AL CYR -

I. EVENT
Spill Info

Type: Oil Incident

Source:

Cause: Accident - Transportation

Spill Date/Time

Spill Date/Time: 04/16/1994

Reporter Type/Detection Method

Type: Citizen Complaint {3}

Method: Other

Reported Date/Time

Reported Date/Time: 04/16/1994 00:00

Subject/Spiller

Contact: AL CYR-

22 PROSPECT STREET

CARIBOU ME

Comment:

Primary Responder and Other Employees

Contact(s): CARL ALLEN (Primary Responder)

WEZNER JR, FRANKLIN

Comment: No Further Response Action Expected

II. SITE Location

Location Type: Business - Other {OB}

Name: CYR, AL RESOURCE RECOVERY INC

Street Address: 22 PROSPECT STREET

MCD Town: CARIBOU

Local Name:
State/Province:
Spill Point

Spill Point:

UTM North 5189780.00 UTM East 575995.00

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Inland Surface Water {I}

Tanks Involved

Tanks Involved:

NONE

III. CLEANUP

Product Reported:

Products Found/Amount Spilled:

Diesel {29} - 55.00 ACTUAL

Material Recovered:

NONE

Recovery/Treatment Method:

NONE

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security





Bureau of Remediation & Waste Management

I-55-1984

CARIBOU

Final Report

CARL ALLEN

Oil Incident

L B CARTER INC - -

Accident - Human Error

Date and Time Unknown

Subject/Spiller {2}

10/08/1984 00:00

L B CARTER INC CARIBOU ME

Other

Hazardous & Oil Spill System

ONLINE REPORT SERVICE

SEARCH: Results: Full Report

Selected Report: I-55-1984

Spill Report Information

Spill Number:

Report Status:

MCD Town: Local Name:

Primary Responder:

Primary Product:

Subject/Owner:

I. EVENT

Spill Info

Type:

Source:

Cause:

Spill Date/Time

Spill Date/Time:

Reporter Type/Detection Method

Type:

Method:

Reported Date/Time

Reported Date/Time:

Subject/Spiller

Contact:

Comment: **Primary Responder and Other Employees**

Contact(s):

CARL ALLEN (Primary Responder)

Comment:

No Further Response Action Expected

II. SITE

Location

Location Type:

Terminal - Bulk Plant {BP}

Name:

Street Address:

MCD Town:

CARIBOU

Local Name:

State/Province:

Spill Point

Spill Point:

UTM North 5189506.01

UTM East 576212.96

Wells and Media Affected

Wells Affected:

0 Wells Impacted/ 0 Wells At Risk

Media Affected:

Land {L}

Tanks Involved

Tanks Involved:

NONE

III. CLEANUP

Product Reported:

#2 Fuel Oil {02}

Products Found/Amount Spilled:

#2 Fuel Oil {02} - 1250.00 ACTUAL

Material Recovered:

Mixed Liquid Media {MM} - 800.00 gals. ACTUAL

Recovery/Treatment Method:

Excavation {G} Pumps {B}

Cleanup DTREE:

Disposal Information:

IV. NARRATIVE

V.ATTACHMENTS

None

New Search

Questions about this Service? Contact the Bureau at: (207) 287-2651 or Email: deprwm@maine.gov

Technical Assistance | Bureau Home | Maine.gov | Privacy | Security

