

## Andover

This report shows the 2017-2019 Work Plan entries for Andover. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Andover in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2018/19

**Municipalities(s):** Andover

**Asset(s):** Route 120

**Description:** Merrill Bridge (No.3215) over the West Branch Ellis River. Located 0.02 of a mile west of Blakie Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021658.00	Bridge Replacement	4	\$1,350,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Albany Twp, Andover, Bethel, Grafton Twp, Mexico, Newry, Roxbury, Rumford, Upton

**Asset(s):** Route 26, Route 5, Route 120

**Description:** Bethel Area 2018 LCP.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022104.00	Light Capital Paving	Varies	\$2,130,800

### Local Road Assistance – Fiscal Year 2016

\$28,640

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 15.2 Shoulder Miles of Sweeping
- 40.0 Sq Feet of Bridge Wearing Surface Repaired
- 26.1 Miles of Striping Applied
- 10.0 Bridge(s) Washed
- 19.0 Minor Sign(s) Installed or Maintained
- 60.0 Linear Feet of Shoulder Rebuilt
- 3,012.5 Linear Feet of Guardrail or Fence Maintained
- 8.0 Mile(s) of Shoulder Graded
- 3.0 Linear Feet of Bridge Rail Repaired or Replaced
- 1.0 Bridge(s) Sealed
- 1.0 Ton(s) of Cold Patch Applied
- 27.5 Shoulder Miles of Herbicide Applied
- 36.0 Linear Feet of Bridge Joints Repaired or Replaced
- 220.7 Center Lane Mile(s) Patrolling and Inspecting
  - 1.0 Underwater Inspection(s) Performed
  - 3.0 Bridge Inspection(s) Performed