

Chesterville

This report shows the 2017-2019 Work Plan entries for Chesterville. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Chesterville in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Chesterville, Farmington

Asset(s): Route 41

Description: Farmington Falls Bridge (No.2273) over the Sandy River. Located on the Chesterville-Farmington Falls town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022296.00	Bridge Improvement-PE Only	3	\$300,000

Work Plan Year: 2017

Municipalities(s): Chesterville, Vienna

Asset(s): Mace Road

Description: 71304 WP 17 George Washington Bridge (No.0561)

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32032	Maintenance		\$20,000

Work Plan Year: 2018/19

Municipalities(s): Chesterville

Asset(s): Dutch Gap Road

Description: Dutch Gap Bridge (No.3951) over Little Norridgewock Stream. Located 1.19 miles north of Zions Hill Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021688.00	Bridge Culvert Replacement	5	\$600,000

Local Road Assistance – Fiscal Year 2016

\$42,300

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 6.0 Emergency Event Responses
- 35.4 Shoulder Miles of Herbicide Applied
- 156.0 Linear Feet of Bridge Rail Repaired or Replaced
- 17.0 Minor Sign(s) Installed or Maintained
- 2,300.0 Linear Feet of Brush Removed
- 1,020.0 Sq Feet of Bridge Pier Repairs
- 585.4 Center Lane Mile(s) Patrolling and Inspecting
- 25.0 Sq Feet of Bridge Wearing Surface Repaired
- 2.0 Underwater Inspection(s) Performed
- 5.0 Bridge(s) Washed
- 29.8 Miles of Striping Applied
- 50.0 Linear Feet of Shoulder Rebuilt
- 221.0 Linear Feet of Bridge Joints Repaired or Replaced
- 1.0 Bridge Inspection(s) Performed
- 3.0 Mile(s) of Shoulder Graded
- 0.8 Ton(s) of Cold Patch Applied

25.0 Linear Feet of Guardrail or Fence Maintained

11.1 Shoulder Miles of Sweeping

13.6 Shoulder Miles of Mowing
