

Dixfield

This report shows the 2017-2019 Work Plan entries for Dixfield. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Dixfield in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Canton, Dixfield, Hartford, Peru

Asset(s): Route 140, Route 2, Route 108

Description: 71302 - WP 17 Drainage Repairs

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32897	Maintenance	Corridor 1, Corridor 2, Corridor 4	\$12,000

Work Plan Year: 2017

Municipalities(s): Dixfield

Asset(s): Route 2

Description: Beginning at Hall Hill Road and extending east 2.77 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
019169.00	Reconstruction	1	\$8,150,000

Work Plan Year: 2017

Municipalities(s): Dixfield

Asset(s): Route 2

Description: Located at the intersection of Route 2 and Route 142.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
018860.00	Traffic Signals	1	\$161,500

Work Plan Year: 2018/19

Municipalities(s): Dixfield

Asset(s): Common Road

Description: Durrells Mill Bridge (No.0658) over Norton Road. Located 0.04 of a mile northwest of Main Street.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022234.00	Bridge Culvert Replacement	6	\$700,000

Local Road Assistance – Fiscal Year 2016

\$24,328

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 48.2 Shoulder Miles of Sweeping
- 16,404.0 Linear Feet of Brush Removed
- 65.0 Shoulder Miles of Herbicide Applied
- 13.0 Minor Sign(s) Installed or Maintained
- 4.0 Mile(s) of Shoulder Graded
- 455.0 Linear Feet of Guardrail or Fence Maintained
- 78.1 Miles of Striping Applied
- 5,212.0 Linear Feet of Grader Ditching
- 3.0 Ton(s) of Cold Patch Applied
- 9.0 Emergency Event Responses
- 17,512.0 Linear Feet of Backhoe Ditching

- 99.0 Trees Removed
 - 225.0 Linear Feet of Shoulder Rebuilt
 - 913.2 Center Lane Mile(s) Patrolling and Inspecting
 - 4.0 Bridge(s) Washed
 - 35.0 Drainage Structures Cleaned
-