

## Greenwood

This report shows the 2017-2019 Work Plan entries for Greenwood. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Greenwood in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** Bethel, Greenwood

**Asset(s):** Route 26

**Description:** Beginning 0.17 of a mile west of Bird Hill Road and extending northwesterly 1.59 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021990.00	3/4" Overlay	2	\$361,200

**Work Plan Year:** 2017

**Municipalities(s):** Greenwood

**Asset(s):** Route 219

**Description:** 71301 WP 17 Repairing Little Androscoggin River Br

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32282	Maintenance	Corridor 5	\$63,000

**Work Plan Year:** 2017

**Municipalities(s):** Greenwood, Turner, West Paris

**Asset(s):** Route 219

**Description:** 71301 - WP 17 Grader Ditching

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32320	Maintenance	Corridor 3, Corridor 5	\$55,000

### Local Road Assistance – Fiscal Year 2016

\$41,344

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 3.0 Shoulder Miles of Sweeping
- 24.4 Shoulder Miles of Herbicide Applied
- 6.0 Bridge(s) Washed
- 2.0 Bridge Inspection(s) Performed
- 9,330.0 Linear Feet of Brush Removed
- 24.2 Miles of Striping Applied
- 1.0 Trees Removed
- 500.0 Linear Feet of Backhoe Ditching
- 16.0 Minor Sign(s) Installed or Maintained
- 8.6 Ton(s) of Cold Patch Applied
- 2.0 Emergency Event Responses
- 1,589.7 Center Lane Mile(s) Patrolling and Inspecting