

Livermore Falls

This report shows the 2017-2019 Work Plan entries for Livermore Falls. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Livermore Falls in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Livermore Falls

Asset(s): Route 17

Description: Beginning at the intersection of Route 133 and 17 and extending north 1.10 miles to Route 4.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022643.00	Highway Improvement-PE Only	3	\$215,000

Work Plan Year: 2018/19

Municipalities(s): Livermore Falls

Asset(s): Route 4

Description: Androscoggin River Bridge (No.2018) over Androscoggin River. Located at Livermore - Livermore Falls town line.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021735.00	Bridge Painting	1	\$800,000

Local Road Assistance – Fiscal Year 2016

\$31,268

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 6.0 Drainage Structures Installed or Replaced
- 18.6 Shoulder Miles of Herbicide Applied
- 2.0 Linear Feet of Bridge Rail Repaired or Replaced
- 6.0 Drainage Structures Repaired
- 1.0 Bridge Inspection(s) Performed
- 2.0 Bridge(s) Washed
- 69.0 Minor Sign(s) Installed or Maintained
- 10.0 Emergency Event Responses
- 230.9 Center Lane Mile(s) Patrolling and Inspecting
- 0.0 Mile(s) of Shoulder Graded
- 3.2 Sq Feet of Bridge Curb Repaired or Replaced
- 26.6 Miles of Striping Applied
- 209.1 Ton(s) of Cold Patch Applied
- 3.0 Bridge Electrical Maintenance Action(s)
- 9.0 Ton(s) of Cold Patch Applied
- 6,999.0 Linear Feet of Backhoe Ditching
- 24.0 Linear Feet of Guardrail or Fence Maintained
- 25.3 Shoulder Miles of Sweeping

Completed Capital Projects – 2016

019411.00 LIVERMORE FALLS, ROUTE 17 Beginning at Foundry Road and extending northerly for approximately 0.26 of a mile to an existing sidewalk.