

Sumner

This report shows the 2017-2019 Work Plan entries for Sumner. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to Sumner in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

Planned Capital and Maintenance Work 2017-2019

Work Plan Year: 2017

Municipalities(s): Peru, Sumner

Asset(s): Greenwood Road

Description: 71302 - WP 17 Ditching on Greenwood Road

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
WR 33428	Maintenance	Corridor 5		\$54,000

Work Plan Year: 2018/19

Municipalities(s): Sumner

Asset(s): Redding Road

Description: Heald Bridge (No.0673) over West Branch of Nezinscot River. Located 0.45 of a mile west of Black Mountain Road.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
021704.00	Bridge Replacement	6		\$700,000

Work Plan Year: 2018/19

Municipalities(s): Hartford, Sumner

Asset(s): Gammon Road

Description: Fields Bridge (No.0690) over the East Branch Nezinscot River. Located at the Sumner - Hartford town line.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
021705.00	Bridge Replacement	6		\$800,000

Work Plan Year: 2018/19

Municipalities(s): Sumner

Asset(s): Main Street

Description: West Sumner Meadow Bridge (No.5843) over the West Branch Nezinscot River. Located 0.25 of a mile northeast of Front Street.

ID	Scope of Work	Highway Corridor	Priority	Estimated Funding
022360.00	Bridge Substructure Rehabilitation	3		\$200,000

Local Road Assistance – Fiscal Year 2016

\$44,124

Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 3.1 Ton(s) of Cold Patch Applied
- 450.0 Linear Feet of Backhoe Ditching
- 3.0 Bridge(s) Washed
- 283.0 Linear Feet of Grader Ditching
- 467.8 Center Lane Mile(s) Patrolling and Inspecting
- 6.0 Emergency Event Responses
- 20.0 Shoulder Miles of Herbicide Applied
- 1.0 Bridge Inspection(s) Performed
- 15.9 Miles of Striping Applied

- 60.0 Linear Feet of Bridge Rail Repaired or Replaced
 - 22.3 Shoulder Miles of Sweeping
 - 25.0 Minor Sign(s) Installed or Maintained
 - 220.0 Linear Feet of Brush Removed
-