

## West Paris

This report shows the 2017-2019 Work Plan entries for West Paris. The costs listed are the total cost of these projects – some of which may extend into neighboring towns. It also shows a listing of maintenance work specifically recorded to West Paris in 2016, as well as any 2016 Local Road Assistance payments. Activities that are managed on a larger scale, such as snow & ice control, and maintenance work done by contract are not listed. The maintenance accomplishments may also extend into neighboring towns, but are listed in the first town where the work was reported. Finally, any capital projects that were completed in 2016 are also listed.

### Planned Capital and Maintenance Work 2017-2019

**Work Plan Year:** 2017

**Municipalities(s):** West Paris

**Asset(s):** Route 219

**Description:** Penley Avenue Bridge (No.3460) over the Little Androscoggin River. Located 1.03 miles south of the Lower River Road.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
021758.00	Bridge Wearing Surface Replacement	5	\$75,000

**Work Plan Year:** 2017

**Municipalities(s):** Greenwood, Turner, West Paris

**Asset(s):** Route 219

**Description:** 71301 - WP 17 Grader Ditching

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
WR 32320	Maintenance	Corridor 3, Corridor 5	\$55,000

**Work Plan Year:** 2018/19

**Municipalities(s):** Paris, West Paris

**Asset(s):** Route 26

**Description:** Beginning 0.02 of a mile south of Porter Street and extending northerly 8.79 miles.

ID	Scope of Work	Highway Corridor Priority	Estimated Funding
022448.00	Hot In Place Recycled	2	\$2,379,300

### Local Road Assistance – Fiscal Year 2016

\$31,336

### Maintenance Accomplishments – 2016

Activities managed on a larger scale, such as snow & ice control, and work done by contract are not listed. *The maintenance accomplishments may extend into neighboring towns, but are listed in the first town where the work was reported.*

- 37.5 Shoulder Miles of Sweeping
- 3,700.0 Linear Feet of Brush Removed
- 3,150.0 Linear Feet of Backhoe Ditching
- 6.0 Emergency Event Responses
- 1.0 Channel(s) Maintained
- 3.0 Mile(s) of Shoulder Graded
- 14.0 Minor Sign(s) Installed or Maintained
- 311.5 Center Lane Mile(s) Patrolling and Inspecting
- 6.0 Bridge(s) Washed
- 1.0 Drainage Structures Cleaned
- 2.0 Drainage Structures Repaired
- 5.0 Trees Removed
- 13.3 Ton(s) of Cold Patch Applied
- 75.0 Linear Feet of Shoulder Rebuilt
- 2.0 Drainage Structures Installed or Replaced
- 24.2 Shoulder Miles of Herbicide Applied

3.0 Bridge Inspection(s) Performed  
11.9 Miles of Striping Applied

---