

Structures in the Municipality of Dallas Plt

CONDITION RATINGS

| | | |
|---|-------------------------------------|---|
| TOWN1: Dallas Plt | TOWN2: No town 2 | SUBSTRUCTURE CONDITION: N Not Applicable |
| BRIDGE NO.: 5913 | BRIDGE REGION: Western | SUPERSTRUCTURE CONDITION: N Not Applicable |
| LOCATION: .3 MI S TOWNLINE | YEAR BUILT: 1962 | DECK CONDITION: N Not Applicable |
| BRDGNAME: QUILL POND STREAM | SPAN MATERIAL: 1 Steel | CHANNEL CONDITION: 5 Fair |
| OWNER: 1 State DOT | SPAN TYPE: 4 Culvert | CULVERT CONDITION: 6 Satisfactory |
| MAINTAINER: 1 State DOT | NUMBER OF MAIN SPANS: 1 | APPROACH CONDITION: 5 Fair |
| FEATURE ON: #16 | STRUCTURE LENGTH IN FEET: 11 | DATE OF INSPECTION: 11/17/2011 |
| FEATURE UNDER: QUILL POND STREAM | POSTING STATUS: 1 Open | FEDERAL SUFFICIENCY RATING: 96.5 |
| ROAD INV NO: 000000016X | POSTING TYPE: 0 None needed | |
| ROUTE NO: 00016 | | |
| ROAD WIDTH: 0 FEET | FEDERAL BRIDGE INDICATOR: N | |
| CLASS: MINOR SPAN ON STATE HIGHWAY | | |

Structures in the Municipality of Dallas Plt

CONDITION RATINGS

| | | |
|---|-------------------------------------|--|
| TOWN1: Dallas Plt | TOWN2: No town 2 | SUBSTRUCTURE CONDITION: 7 Good |
| BRIDGE NO.: 3261 | BRIDGE REGION: Western | SUPERSTRUCTURE CONDITION: 7 Good |
| LOCATION: 3.9 MI NE OF RANGELEY | YEAR BUILT: 1958 | DECK CONDITION: 6 Satisfactory |
| BRDGNAME: DEAD RIVER | SPAN MATERIAL: 2 Concrete | CHANNEL CONDITION: 6 Satisfactory |
| OWNER: 1 State DOT | SPAN TYPE: 1 Girder | CULVERT CONDITION: N Not Applicable |
| MAINTAINER: 1 State DOT | NUMBER OF MAIN SPANS: 1 | APPROACH CONDITION: 6 Satisfactory |
| FEATURE ON: ROUTE 16 | STRUCTURE LENGTH IN FEET: 48 | DATE OF INSPECTION: 10/18/2011 |
| FEATURE UNDER: S BRANCH DEAD RIVER | POSTING STATUS: 1 Open | FEDERAL SUFFICIENCY RATING: 89.8 |
| ROAD INV NO: 000000016X | POSTING TYPE: 0 None needed | |
| ROUTE NO: 00016 | | |
| ROAD WIDTH: 29 FEET | FEDERAL BRIDGE INDICATOR: Y | |
| CLASS: BRIDGE ON STATE HIGHWAY | | |

Structures in the Municipality of Dallas Plt

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: Dallas Plt | TOWN2: No town 2 | SUBSTRUCTURE CONDITION: N Not Applicable |
| BRIDGE NO.: 3260 | BRIDGE REGION: Western | SUPERSTRUCTURE CONDITION: N Not Applicable |
| LOCATION: .8 MI E TOWNLINE | YEAR BUILT: 2011 | DECK CONDITION: N Not Applicable |
| BRDGNAME: GULL POND | SPAN MATERIAL: 7 Precast Concrete | CHANNEL CONDITION: 8 Very Good |
| OWNER: 1 State DOT | SPAN TYPE: 4 Culvert | CULVERT CONDITION: 9 Excellent |
| MAINTAINER: 1 State DOT | NUMBER OF MAIN SPANS: 1 | APPROACH CONDITION: 3 Serious |
| FEATURE ON: #16 | STRUCTURE LENGTH IN FEET: 13 | DATE OF INSPECTION: 2/1/2012 |
| FEATURE UNDER: GULL POND STREAM | POSTING STATUS: 1 Open | FEDERAL SUFFICIENCY RATING: 85 |
| ROAD INV NO: 000000016X | POSTING TYPE: 0 None needed | |
| ROUTE NO: 00016 | | |
| ROAD WIDTH: 33 FEET | FEDERAL BRIDGE INDICATOR: N | |
| CLASS: MINOR SPAN ON STATE HIGHWAY | | |