

Structures in the Municipality of Detroit

CONDITION RATINGS

TOWN1: <input type="text" value="Detroit"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="5125"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value=".8*MI*W*TOWNLINe"/>	YEAR BUILT: <input type="text" value="1927"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: <input type="text" value="POND"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="RTE 69"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="18"/>	DATE OF INSPECTION: <input type="text" value="12/22/2011"/>
FEATURE UNDER: <input type="text" value="BRACKETT BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="71.1"/>
ROAD INV NO: <input type="text" value="000000069X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00069"/>		
ROAD WIDTH: <input type="text" value="25"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Detroit

CONDITION RATINGS

TOWN1: <input type="text" value="Detroit"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="3627"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.2 MI S TOWNLIN"/>	YEAR BUILT: <input type="text" value="1939"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="DETROIT OVER HEAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="6 Railroad"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="ROUTE 220"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="130"/>	DATE OF INSPECTION: <input type="text" value="6/18/2012"/>
FEATURE UNDER: <input type="text" value="MCRR SPRINGFIELD TER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="82.7"/>
ROAD INV NO: <input type="text" value="000000220X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00220"/>		
ROAD WIDTH: <input type="text" value="27"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="RAILROAD BRIDGE"/>		

Structures in the Municipality of Detroit

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Detroit"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="3309"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
LOCATION: <input style="width: 130px;" type="text" value="ADJ TO W JCT RTE 69 & 220"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1936"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRDGNAME: <input style="width: 100px;" type="text" value="VILLAGE"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
OWNER: <input style="width: 90px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="5 Truss"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 90px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
FEATURE ON: <input style="width: 110px;" type="text" value="ROUTES 69 & 220"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="94"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="4/26/2012"/>
FEATURE UNDER: <input style="width: 110px;" type="text" value="E BRANCH SEBASTICOO"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="36.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000069X"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00069"/>		
ROAD WIDTH: <input style="width: 60px;" type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Detroit

CONDITION RATINGS

TOWN1: <input type="text" value="Detroit"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="1016"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value=".7 MI N RT 100"/>	YEAR BUILT: <input type="text" value="1984"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="CEMETERY"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="RT 220"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="13"/>	DATE OF INSPECTION: <input type="text" value="1/3/2012"/>
FEATURE UNDER: <input type="text" value="BRACKETT BK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="97.9"/>
ROAD INV NO: <input type="text" value="000000220X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00220"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Pittsfield

CONDITION RATINGS

TOWN1: <input type="text" value="Pittsfield"/>	TOWN2: <input type="text" value="Detroit"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="3435"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="3.0 MI SE OF RTE 11 & 100"/>	YEAR BUILT: <input type="text" value="1961"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: PELTOMA	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="4"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="PELTOMA AVE(PITTS)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="271"/>	DATE OF INSPECTION: <input type="text" value="10/1/2012"/>
FEATURE UNDER: <input type="text" value="SEBASTICOOK RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="79.9"/>
ROAD INV NO: <input type="text" value="0002500483"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="24"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		