

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="0358"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="0.1 MI E RT 100"/> | YEAR BUILT: <input type="text" value="1960"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="MILL ROAD"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="4 Municipal"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="4 Municipal"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| FEATURE ON: <input type="text" value="MILL ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="39"/> | DATE OF INSPECTION: <input type="text" value="11/15/2011"/> |
| FEATURE UNDER: <input type="text" value="PISCATAQUA RIVER"/> | POSTING STATUS: <input type="text" value="3 Posted"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="27.2"/> |
| ROAD INV NO: <input type="text" value="0000540308"/> | POSTING TYPE: <input type="text" value="1 Weight Limit"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="16"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="0206"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.070 mi W of I-95"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="HURRICANE RD / PISCATAQU"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="HURRICANE ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="122"/> | DATE OF INSPECTION: <input type="text" value="5/2/2012"/> |
| FEATURE UNDER: <input type="text" value="PISCATAQUA RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="66.6"/> |
| ROAD INV NO: <input type="text" value="0000500396"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="23"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="1505"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="1.0 MI N OF PORTLAND TL"/> | YEAR BUILT: <input type="text" value="1960"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="I295 SB / PRESUMPCOT RIVE"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="I-295 SOUTHBOUND"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="285"/> | DATE OF INSPECTION: <input type="text" value="1/10/2013"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="79"/> |
| ROAD INV NO: <input type="text" value="000000295S"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00295"/> | | |
| ROAD WIDTH: <input type="text" value="30"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="Portland"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="1489"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.107 mi W of Blackstrap"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="PRESUMPCOT RIVER SB"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-95(SB)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="160"/> | DATE OF INSPECTION: <input type="text" value="4/27/2012"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="98.8"/> |
| ROAD INV NO: <input type="text" value="000000095S"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="54"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="1468"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="0.491 mi W of Falmouth Rd"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="PRESUMSCOT RIVER WB"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="1-495 (EB)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="360"/> | DATE OF INSPECTION: <input type="text" value="5/22/2012"/> |
| FEATURE UNDER: <input type="text" value="PRESUMSCOT RIVER / F"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="61"/> |
| ROAD INV NO: <input type="text" value="000000495W"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00495"/> | | |
| ROAD WIDTH: <input type="text" value="30"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | | |
|--|---|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> | |
| BRIDGE NO.: <input type="text" value="1467"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> | |
| LOCATION: <input type="text" value="0.157 mi N of Lambert St"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> | |
| BRDGNAME: <input type="text" value="MCRR WB"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> | |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> | |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> | |
| FEATURE ON: <input type="text" value="I-495 (WB)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="177"/> | DATE OF INSPECTION: <input type="text" value="5/1/2012"/> | |
| FEATURE UNDER: <input type="text" value="MCRR"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="49.7"/> | |
| ROAD INV NO: <input type="text" value="000000495W"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | | |
| ROUTE NO: <input type="text" value="00495"/> | | | |
| ROAD WIDTH: <input type="text" value="34"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="0365"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="0.420 mi E of Blackstrap"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="AUBURN ST"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text"/> <input type="text"/> |
| FEATURE ON: <input type="text" value="AUBURN ST"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="211"/> | DATE OF INSPECTION: <input type="text" value="5/1/2012"/> |
| FEATURE UNDER: <input type="text" value="I-495"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="73.4"/> |
| ROAD INV NO: <input type="text" value="000000026X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00026"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="0364"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.146 mi N of Lambert St"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="MCRREB"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-495"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="177"/> | DATE OF INSPECTION: <input type="text" value="5/1/2012"/> |
| FEATURE UNDER: <input type="text" value="MCRREB"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="29.5"/> |
| ROAD INV NO: <input type="text" value="000000495X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00495"/> | | |
| ROAD WIDTH: <input type="text" value="34"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="0363"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.195 mi N of Davis Farm"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="BLACKSTRAP RD"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-495"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="113"/> | DATE OF INSPECTION: <input type="text" value="5/1/2012"/> |
| FEATURE UNDER: <input type="text" value="LAMBERT ST/FALMOUT"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="76.7"/> |
| ROAD INV NO: <input type="text" value="000000495X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00495"/> | | |
| ROAD WIDTH: <input type="text" value="83"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="2457"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.4 MI N JCT FALMOUTH RD"/> | YEAR BUILT: <input type="text" value="1939"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="LIBBY"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="ROUTES 26 & 100"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="39"/> | DATE OF INSPECTION: <input type="text" value="6/29/2012"/> |
| FEATURE UNDER: <input type="text" value="PISCATAQUA RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="76.2"/> |
| ROAD INV NO: <input type="text" value="000000026X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00026"/> | | |
| ROAD WIDTH: <input type="text" value="34"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="0361"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.259 mi W of SR 100&26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: LEIGHTONRD | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text"/> <input type="text"/> |
| FEATURE ON: <input type="text" value="LEIGHTON RD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="248"/> | DATE OF INSPECTION: <input type="text" value="2/20/2013"/> |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="57.3"/> |
| ROAD INV NO: <input type="text" value="0000540306"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="24"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="2560"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="1.3 MI N JCT US 1"/> | YEAR BUILT: <input type="text" value="1894"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="MILL CREEK"/> | SPAN MATERIAL: <input type="text" value="4 Stone"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="6 Arch"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="88"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="16"/> | DATE OF INSPECTION: <input type="text" value="6/28/2012"/> |
| FEATURE UNDER: <input type="text" value="MILL CREEK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="76.9"/> |
| ROAD INV NO: <input type="text" value="00000088X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00088"/> | | |
| ROAD WIDTH: <input type="text" value="35"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="0284"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="0.567 mi W of SR 100&26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRDGNAME: <input type="text" value="PISCATAQUA RIVER #28"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="43"/> | DATE OF INSPECTION: <input type="text" value="5/2/2012"/> |
| FEATURE UNDER: <input type="text" value="PISCATAQUA RIVER STR#"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="77.5"/> |
| ROAD INV NO: <input type="text" value="000000095X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="72"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="0283"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.458 mi W of SR 100&26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="LAMBERT STREET"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="BLACKSTRAP RD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="322"/> | DATE OF INSPECTION: <input type="text" value="5/3/2012"/> |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="3 Posted"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="62.8"/> |
| ROAD INV NO: <input type="text" value="0000540030"/> | POSTING TYPE: <input type="text" value="3 Underclearance Limit"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="0281"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.505 mi W of Falmouth Rd"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="PRESUMSCOT RIVER EB"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-495 (WB)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="360"/> | DATE OF INSPECTION: <input type="text" value="2/20/2013"/> |
| FEATURE UNDER: <input type="text" value="PRESUMSCOT RIV/FALM"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="61.1"/> |
| ROAD INV NO: <input type="text" value="000000495X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00495"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRIDGE NO.: <input type="text" value="0280"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.487 mi W of SR 100&26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="HURRICANE RD/MTPK"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="HURRICANE ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="210"/> | DATE OF INSPECTION: <input type="text" value="5/2/2012"/> |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="38.3"/> |
| ROAD INV NO: <input type="text" value="0000500396"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="22"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="0279"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="0.095 mi NE of Hurricane"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRDGNAME: <input type="text" value="PISCATAQUA RIVER #31"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="32"/> | DATE OF INSPECTION: <input type="text" value="5/3/2012"/> |
| FEATURE UNDER: <input type="text" value="PISCATIQUA RIVER STR"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="73.4"/> |
| ROAD INV NO: <input type="text" value="000000095X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="64"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="0278"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.304 mi W of SR 100&26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: WEST FALMOUTH INTERCHA | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="W. FALMOUTH/CUMBER"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="220"/> | DATE OF INSPECTION: <input type="text" value="2/20/2013"/> |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="66.1"/> |
| ROAD INV NO: <input type="text" value="00005A0500"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="46"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="Portland"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="0277"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.095 mi W of Blackstrap"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="PRESUMPCOT RIVER NB"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-95 (NB)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="160"/> | DATE OF INSPECTION: <input type="text" value="4/27/2012"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="96.9"/> |
| ROAD INV NO: <input type="text" value="000000095X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="65"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="0214"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="0.2 MI E OF JCT RTE 100"/> | YEAR BUILT: <input type="text" value="1957"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="UNDERWITTED ROAD"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| FEATURE ON: <input type="text" value="LEIGHTON ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="34"/> | DATE OF INSPECTION: <input type="text" value="10/4/2011"/> |
| FEATURE UNDER: <input type="text" value="PISCATAQUA RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="97.6"/> |
| ROAD INV NO: <input type="text" value="0000500718"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="0213"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="1.0 MI S OF JCT WINN RD"/> | YEAR BUILT: <input type="text" value="1999"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="FIELD"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="FIELD ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="24"/> | DATE OF INSPECTION: <input type="text" value="5/8/2012"/> |
| FEATURE UNDER: <input type="text" value="EAST BRANCH PISCATIQU"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="91.9"/> |
| ROAD INV NO: <input type="text" value="0000540448"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="0362"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.231 mi W of SR 100&26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="MOUNTAIN RD"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="MOUNTAIN RD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="207"/> | DATE OF INSPECTION: <input type="text" value="2/20/2013"/> |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="67.6"/> |
| ROAD INV NO: <input type="text" value="0000540309"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="5553"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| LOCATION: <input type="text" value="1.8 MI N OF JCT RTE 26"/> | YEAR BUILT: <input type="text" value="1961"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="LAMBERT STREET"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| FEATURE ON: <input type="text" value="LAMBERT ST (SA6)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="169"/> | DATE OF INSPECTION: <input type="text" value="11/27/2012"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="62.9"/> |
| ROAD INV NO: <input type="text" value="0000540030"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="28"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="6020"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.111 mi S of Woods Rd"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="RTE 9"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="SR 9 (MIDDLE ROAD)"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="153"/> | DATE OF INSPECTION: <input type="text" value="5/11/2012"/> |
| FEATURE UNDER: <input type="text" value="I-495"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="80.9"/> |
| ROAD INV NO: <input type="text" value="000000009X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00009"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="6019"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="2.9MI N TOWNLINE"/> | YEAR BUILT: <input type="text" value="1961"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="STATION 251"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="I295"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="13"/> | DATE OF INSPECTION: <input type="text" value="1/10/2012"/> |
| FEATURE UNDER: <input type="text" value="CHENERY BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="97.3"/> |
| ROAD INV NO: <input type="text" value="000000295X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00295"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="5922"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.1 MI W OF I95 OVER I295"/> | YEAR BUILT: <input type="text" value="1990"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="SPUR/CNRR"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="7 Rigid Frame"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="I95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="29"/> | DATE OF INSPECTION: <input type="text" value="11/7/2012"/> |
| FEATURE UNDER: <input type="text" value="CNRR"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="94.7"/> |
| ROAD INV NO: <input type="text" value="000000495X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00495"/> | | |
| ROAD WIDTH: <input type="text" value="72"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="5921"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="I95 SPUR INTERCHANGE"/> | YEAR BUILT: <input type="text" value="1955"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="I-95 SPUR / US RTE 1"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="FALMOUTH I-95 SPUR"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="186"/> | DATE OF INSPECTION: <input type="text" value="12/21/2012"/> |
| FEATURE UNDER: <input type="text" value="ROUTE US 1"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="94"/> |
| ROAD INV NO: <input type="text" value="00005A5036"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input style="width: 150px;" type="text" value="Falmouth"/> | TOWN2: <input style="width: 100px;" type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input style="width: 60px;" type="text" value="5831"/> | BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/> |
| LOCATION: <input style="width: 130px;" type="text" value="EXIT 15"/> | YEAR BUILT: <input style="width: 50px;" type="text" value="1960"/> | DECK CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/> |
| BRDGNAME: <input style="width: 100px;" type="text" value="FALMOUTH SPUR"/> | SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/> | CHANNEL CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/> |
| OWNER: <input style="width: 90px;" type="text" value="1 State DOT"/> | SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/> | CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/> |
| MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="4"/> | APPROACH CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/> |
| FEATURE ON: <input style="width: 110px;" type="text" value="I95"/> | STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="231"/> | DATE OF INSPECTION: <input style="width: 60px;" type="text" value="1/9/2013"/> |
| FEATURE UNDER: <input style="width: 110px;" type="text" value="I295"/> | POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="93.7"/> |
| ROAD INV NO: <input style="width: 60px;" type="text" value="000000495X"/> | POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/> | |
| ROUTE NO: <input style="width: 60px;" type="text" value="00495"/> | | |
| ROAD WIDTH: <input style="width: 60px;" type="text" value="76"/> FEET | FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/> | |
| CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="5830"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.3 MI W'LY OF JCT US1"/> | YEAR BUILT: <input type="text" value="1960"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="BUCKNAM RD OVER I295"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="BUCKNAM RD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="231"/> | DATE OF INSPECTION: <input type="text" value="10/25/2012"/> |
| FEATURE UNDER: <input type="text" value="I295"/> | POSTING STATUS: <input type="text" value="3 Posted"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="75.4"/> |
| ROAD INV NO: <input type="text" value="0000540146"/> | POSTING TYPE: <input type="text" value="3 Underclearance Limit"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="5829"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.1 MIE OF JCT RTE 9"/> | YEAR BUILT: <input type="text" value="1960"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="LUNT ROAD / I295"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="LUNT ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="222"/> | DATE OF INSPECTION: <input type="text" value="1/10/2012"/> |
| FEATURE UNDER: <input type="text" value="INTERSTATE 295"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="60.4"/> |
| ROAD INV NO: <input type="text" value="0000540204"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="5828"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="1.0 MI N OF PORTLAND TL"/> | YEAR BUILT: <input type="text" value="1960"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="I295 NB / PRESUMPCOT RIVE"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="I-295 NORTHBOUND"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="285"/> | DATE OF INSPECTION: <input type="text" value="1/10/2013"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="78.9"/> |
| ROAD INV NO: <input type="text" value="000000295X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00295"/> | | |
| ROAD WIDTH: <input type="text" value="30"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="5792"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.2 MI W OF JCT RTE US 1"/> | YEAR BUILT: <input type="text" value="1957"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="JOHNSON ROAD / I295"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="JOHNSON ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="227"/> | DATE OF INSPECTION: <input type="text" value="10/1/2012"/> |
| FEATURE UNDER: <input type="text" value="INTERSTATE 295"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="64.3"/> |
| ROAD INV NO: <input type="text" value="0000500430"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRIDGE NO.: <input type="text" value="5600"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| LOCATION: <input type="text" value=".2 MI E JCT US 1"/> | YEAR BUILT: <input type="text" value="1955"/> | DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRDGNAME: <input type="text" value="MACKWORTH ISLAND BR"/> | SPAN MATERIAL: <input type="text" value="3 Wood"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="2 Other state agency"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="2 Other state agency"/> | NUMBER OF MAIN SPANS: <input type="text" value="5"/> | APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| FEATURE ON: <input type="text" value="ANDREWS AVE"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="102"/> | DATE OF INSPECTION: <input type="text" value="1/9/2012"/> |
| FEATURE UNDER: <input type="text" value="CASCO BAY"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="44"/> |
| ROAD INV NO: <input type="text" value="0000540002"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="24"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="OTHER BRIDGE"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="6448"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="Mile marker 55.6"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="PISCATAQUA RIVER TRIBUT"/> | SPAN MATERIAL: <input type="text"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text"/> <input type="text"/> |
| FEATURE ON: <input type="text" value="I-95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="25"/> | DATE OF INSPECTION: <input type="text" value="5/2/2012"/> |
| FEATURE UNDER: <input type="text" value="Piscataqua Tributary"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="55.5"/> |
| ROAD INV NO: <input type="text" value="-1"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="I-95"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="5462"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="1.3 MI N OF JCT WOODS RD"/> | YEAR BUILT: <input type="text" value="1952"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="DUNHAM ROAD"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="WOODSVILLE ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="31"/> | DATE OF INSPECTION: <input type="text" value="6/29/2012"/> |
| FEATURE UNDER: <input type="text" value="EAST BR PISCATAQUA R"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="69.8"/> |
| ROAD INV NO: <input type="text" value="0000540446"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="5278"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="1 MI N TOWNLINE"/> | YEAR BUILT: <input type="text" value="1951"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: STAPLES POINT | SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="ROUTE 9"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="239"/> | DATE OF INSPECTION: <input type="text" value="9/26/2011"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="95.2"/> |
| ROAD INV NO: <input type="text" value="000000009X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00009"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="5237"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="3.2MI*N*TOWNLIN"/> | YEAR BUILT: <input type="text" value="1942"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="MILL CREEK NO. 2"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="7 Rigid Frame"/> | CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| FEATURE ON: <input type="text" value="US 1"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="17"/> | DATE OF INSPECTION: <input type="text" value="12/15/2011"/> |
| FEATURE UNDER: <input type="text" value="MILL CREEK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="65.4"/> |
| ROAD INV NO: <input type="text" value="000000001X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00001"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="3686"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="0.941 mi E of SR 26"/> | YEAR BUILT: <input type="text" value="1956"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="W FALMOUTH RD"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="FALMOUTH RD/FAL SP"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="198"/> | DATE OF INSPECTION: <input type="text" value="5/1/2012"/> |
| FEATURE UNDER: <input type="text" value="I-495"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="87.2"/> |
| ROAD INV NO: <input type="text" value="0000540203"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="36"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="3563"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.2 MI E OF RTES 26 & 100"/> | YEAR BUILT: <input type="text" value="2008"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: MERRILLS | SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="FALMOUTH ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="34"/> | DATE OF INSPECTION: <input type="text" value="8/2/2011"/> |
| FEATURE UNDER: <input type="text" value="PISCATAQUA RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="97.8"/> |
| ROAD INV NO: <input type="text" value="0000540203"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="34"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="3143"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.8 MI N OF I95 UNDER"/> | YEAR BUILT: <input type="text" value="1998"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: ALLENS | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="FALMOUTH ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="92"/> | DATE OF INSPECTION: <input type="text" value="10/4/2011"/> |
| FEATURE UNDER: <input type="text" value="EAST BR PISCATAQUA R"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="78.3"/> |
| ROAD INV NO: <input type="text" value="0000540203"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="30"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|--|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRIDGE NO.: <input type="text" value="2782"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| LOCATION: <input type="text" value=".1 MI S TOWNLINE"/> | YEAR BUILT: <input type="text" value="1922"/> | DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRDGNAME: <input type="text" value="SOULE"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="26 & 100"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="15"/> | DATE OF INSPECTION: <input type="text" value="1/30/2012"/> |
| FEATURE UNDER: <input type="text" value="HOBBS BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="54.3"/> |
| ROAD INV NO: <input type="text" value="000000026X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00026"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="2702"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.1 MI S OF TPKE INTERCH"/> | YEAR BUILT: <input type="text" value="2011"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="RAILROAD CROSSING"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="4"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="ROUTES 26 & 100"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="722"/> | DATE OF INSPECTION: <input type="text" value="11/27/2012"/> |
| FEATURE UNDER: <input type="text" value="MCRR & PRESUMPCOT"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="84"/> |
| ROAD INV NO: <input type="text" value="000000026X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00026"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Falmouth

CONDITION RATINGS

| | | |
|---|---|--|
| TOWN1: <input type="text" value="Falmouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="5669"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.7 MI N OF PORTLAND"/> | YEAR BUILT: <input type="text" value="1995"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="PRESUMPCOT FALLS"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="6 Arch"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="ALLEN AVE EXTENSIO"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="368"/> | DATE OF INSPECTION: <input type="text" value="10/22/2012"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="97"/> |
| ROAD INV NO: <input type="text" value="0000540001"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="34"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Portland

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Portland"/> | TOWN2: <input type="text" value="Falmouth"/> | SUBSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRIDGE NO.: <input type="text" value="2515"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| LOCATION: <input type="text" value="FALMOUTH-PORTLAND TL"/> | YEAR BUILT: <input type="text" value="1943"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="MARTIN POINT"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="RTE 1"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="1403"/> | DATE OF INSPECTION: <input type="text" value="1/10/2013"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOT*RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="17.1"/> |
| ROAD INV NO: <input type="text" value="00000001X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00001"/> | | |
| ROAD WIDTH: <input type="text" value="44"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Portland

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Portland"/> | TOWN2: <input type="text" value="Falmouth"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="0371"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="TOWNLINE"/> | YEAR BUILT: <input type="text" value="1969"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: BRIDGE AT STA. 98&88 | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="295 NB&SB"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="14"/> | DATE OF INSPECTION: <input type="text" value="1/24/2001"/> |
| FEATURE UNDER: <input type="text" value="PRESUMPCOTT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="49.4"/> |
| ROAD INV NO: <input type="text" value="000000295X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00295"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text"/> | | |