

Structures in the Municipality of Chesterville

CONDITION RATINGS

TOWN1: <input type="text" value="Chesterville"/>	TOWN2: <input type="text" value="Farmington"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="3181"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value="0.5 MI SW OF JCT RTE 41"/>	YEAR BUILT: <input type="text" value="1937"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: <input type="text" value="WILLIAMS #2"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="5 Truss"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="2"/> <input type="text" value="Critical"/>
FEATURE ON: <input type="text" value="ROUTE 156"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="176"/>	DATE OF INSPECTION: <input type="text" value="8/7/2012"/>
FEATURE UNDER: <input type="text" value="WILSON STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="45.7"/>
ROAD INV NO: <input type="text" value="000000156X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00156"/>		
ROAD WIDTH: <input type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Chesterville

CONDITION RATINGS

TOWN1: <input type="text" value="Chesterville"/>	TOWN2: <input type="text" value="Farmington"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="2273"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value="IMMEDIATELY N JCT RTE 156"/>	YEAR BUILT: <input type="text" value="1931"/>	DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
BRDGNAME: <input type="text" value="FARMINGTON FALLS"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="4"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="ROUTE 41"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="215"/>	DATE OF INSPECTION: <input type="text" value="8/8/2012"/>
FEATURE UNDER: <input type="text" value="SANDY RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="60.9"/>
ROAD INV NO: <input type="text" value="000000041X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00041"/>		
ROAD WIDTH: <input type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 2623	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 1.1 MI E TOWNLIN	YEAR BUILT: 1930	DECK CONDITION: 6 Satisfactory
BRDGRNAME: NORTH TWIN	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: RTE 43	STRUCTURE LENGTH IN FEET: 49	DATE OF INSPECTION: 8/16/2012
FEATURE UNDER: TEMPLE STR	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 82.9
ROAD INV NO: 000000043X	POSTING TYPE: 0 None needed	
ROUTE NO: 00043		
ROAD WIDTH: 26 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0374"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1.1 MI E TOWNLINE"/>	YEAR BUILT: <input type="text" value="1999"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="TWIN NO 2"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="RTE 43"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="14"/>	DATE OF INSPECTION: <input type="text" value="10/20/2011"/>
FEATURE UNDER: <input type="text" value="TEMPLE STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="98.9"/>
ROAD INV NO: <input type="text" value="000000043X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00043"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 0416	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 0.6 M S KNOWLTN CORNER R	YEAR BUILT: 1950	DECK CONDITION: 8 Very Good
BRDGNAME: WEBSTER	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 4 Poor
FEATURE ON: WEBSTER ROAD	STRUCTURE LENGTH IN FEET: 75	DATE OF INSPECTION: 8/13/2012
FEATURE UNDER: WILSON STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 81.5
ROAD INV NO: 0000700459	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 20 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 2004	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 3.5 MI NO TOWNLINE	YEAR BUILT: 1958	DECK CONDITION: N Not Applicable
BRDGNAME: ABBOT	SPAN MATERIAL: 9 Other	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 8 Very Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 2	APPROACH CONDITION: 8 Very Good
FEATURE ON: 4/27/1943	STRUCTURE LENGTH IN FEET: 12	DATE OF INSPECTION: 5/29/2012
FEATURE UNDER: ABBOT BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 83.9
ROAD INV NO: 000000002X	POSTING TYPE: 0 None needed	
ROUTE NO: 00002		
ROAD WIDTH: 48 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE HIGHWAY		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="2146"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="0.1 W OF JCT RTE 27"/>	YEAR BUILT: <input type="text" value="1991"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="CENTER"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="RTES US2, 4, & 43"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="375"/>	DATE OF INSPECTION: <input type="text" value="9/25/2012"/>
FEATURE UNDER: <input type="text" value="SANDY RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="68"/>
ROAD INV NO: <input type="text" value="000000002X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00002"/>		
ROAD WIDTH: <input type="text" value="52"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="2271"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="0.2 MI W OF JCT RTE 149"/>	YEAR BUILT: <input type="text" value="1988"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: FAIRBANKS	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="ROUTE 4"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="342"/>	DATE OF INSPECTION: <input type="text" value="9/25/2012"/>
FEATURE UNDER: <input type="text" value="SANDY RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="96.5"/>
ROAD INV NO: <input type="text" value="000000004X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00004"/>		
ROAD WIDTH: <input type="text" value="40"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="2311"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1 MI E INT 4"/>	YEAR BUILT: <input type="text" value="1958"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="GILBERT BROOK"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="#2 & 27"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="14"/>	DATE OF INSPECTION: <input type="text" value="10/18/2011"/>
FEATURE UNDER: <input type="text" value="CASCADE BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="93.6"/>
ROAD INV NO: <input type="text" value="000000002X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00002"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="0067"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
LOCATION: <input type="text" value="0.2 MI N JCT OF RTE 43"/>	YEAR BUILT: <input type="text" value="1967"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="RUSSELL MILLS"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/>
FEATURE ON: <input type="text" value="RUSSELL MILLS ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="60"/>	DATE OF INSPECTION: <input type="text" value="9/25/2012"/>
FEATURE UNDER: <input type="text" value="TEMPLE STREAM"/>	POSTING STATUS: <input type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="50.4"/>
ROAD INV NO: <input type="text" value="0000700691"/>	POSTING TYPE: <input type="text" value="1 Weight Limit"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="18"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 2563	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 0.1 SLY JCT RTES 4 & 27	YEAR BUILT: 1960	DECK CONDITION: N Not Applicable
BRDGNAME: MILL POND	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 8 Very Good
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: 7 Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTES 4 & 27	STRUCTURE LENGTH IN FEET: 29	DATE OF INSPECTION: 7/24/2012
FEATURE UNDER: BARKER STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 96.6
ROAD INV NO: 000000004X	POSTING TYPE: 0 None needed	
ROUTE NO: 00004		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="2705"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="0.3 MI S JCT OF RTE 43"/>	YEAR BUILT: <input type="text" value="1929"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="RED"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="ROUTES US2 & 4"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="87"/>	DATE OF INSPECTION: <input type="text" value="12/11/2012"/>
FEATURE UNDER: <input type="text" value="TEMPLE STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="57.2"/>
ROAD INV NO: <input type="text" value="000000002X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00002"/>		
ROAD WIDTH: <input type="text" value="50"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="2980"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.1 MI EAST TOWNLINE"/>	YEAR BUILT: <input type="text" value="1954"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="WILLIAMS # 1"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="6 Arch"/>	CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="ROUTE 156"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="20"/>	DATE OF INSPECTION: <input type="text" value="8/13/2012"/>
FEATURE UNDER: <input type="text" value="BR OF WILLIAMS BROO"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="71.7"/>
ROAD INV NO: <input type="text" value="000000156X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00156"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: Chesterville	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 3066	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: ON TOWNLINE	YEAR BUILT: 1933	DECK CONDITION: 5 Fair
BRDGNAME: NORTH CHESTERVILLE	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 2	APPROACH CONDITION: 5 Fair
FEATURE ON: ROUTE 156	STRUCTURE LENGTH IN FEET: 98	DATE OF INSPECTION: 8/13/2012
FEATURE UNDER: WILSON STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 55
ROAD INV NO: 000000156X	POSTING TYPE: 0 None needed	
ROUTE NO: 00156		
ROAD WIDTH: 21 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 3286	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 0.4 MI N OF WILTON	YEAR BUILT: 1938	DECK CONDITION: 6 Satisfactory
BRDGNAME: HAMLIN	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE 133	STRUCTURE LENGTH IN FEET: 66	DATE OF INSPECTION: 8/13/2012
FEATURE UNDER: WILSON STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 68.3
ROAD INV NO: 000000133X	POSTING TYPE: 0 None needed	
ROUTE NO: 00133		
ROAD WIDTH: 24 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: Farmington	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 3982	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 0.1 MI S OF JCT RTE 43	YEAR BUILT: 1948	DECK CONDITION: 6 Satisfactory
BRDGNAME: WALTON MILL	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: MORRISON HILL ROAD	STRUCTURE LENGTH IN FEET: 127	DATE OF INSPECTION: 8/16/2012
FEATURE UNDER: TEMPLE STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 67.2
ROAD INV NO: 0000700438	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 22 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="5358"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="NEAR NEW VINYARD TL"/>	YEAR BUILT: <input type="text" value="1954"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="BARKER STREAM"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="#27"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="16"/>	DATE OF INSPECTION: <input type="text" value="8/27/2012"/>
FEATURE UNDER: <input type="text" value="BARKER STR"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="90.7"/>
ROAD INV NO: <input type="text" value="000000027X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00027"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

Structures in the Municipality of Farmington

CONDITION RATINGS

TOWN1: <input type="text" value="Farmington"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="2324"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="2.5 MI W TOWNLIN"/>	YEAR BUILT: <input type="text" value="1958"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="GOWER FARM"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="#2-27"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="15"/>	DATE OF INSPECTION: <input type="text" value="8/27/2012"/>
FEATURE UNDER: <input type="text" value="BEALES BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="82.6"/>
ROAD INV NO: <input type="text" value="000000002X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00002"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

Structures in the Municipality of Wilton

CONDITION RATINGS

TOWN1: <input type="text" value="Wilton"/>	TOWN2: <input type="text" value="Farmington"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="6398"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="TOWN LINE"/>	YEAR BUILT: <input type="text" value="1999"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="RT 43"/>	SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="RTE 43"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="14"/>	DATE OF INSPECTION: <input type="text" value="8/17/2012"/>
FEATURE UNDER: <input type="text" value="R TRIB"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="97"/>
ROAD INV NO: <input type="text" value="000000043X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00043"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		