

Structures in the Municipality of Freedom

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Freedom"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="5150"/> | BRIDGE REGION: <input type="text" value="Mid-Coast"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.2 MI S OF JCT RTE 137"/> | YEAR BUILT: <input type="text" value="1927"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="UPPER"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="PLEASANT STREET"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="28"/> | DATE OF INSPECTION: <input type="text" value="12/8/2011"/> |
| FEATURE UNDER: <input type="text" value="SANDY STREAM"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="80.9"/> |
| ROAD INV NO: <input type="text" value="0002700369"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="20"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Freedom

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Freedom"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="5148"/> | BRIDGE REGION: <input type="text" value="Mid-Coast"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| LOCATION: <input type="text" value=".7 MI SE JCT 137"/> | YEAR BUILT: <input type="text" value="1927"/> | DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRDGNAME: <input type="text" value="HUSTUS BROOK"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="4 Municipal"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="4 Municipal"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| FEATURE ON: <input type="text" value="MITCHEL RD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="15"/> | DATE OF INSPECTION: <input type="text" value="1/15/2013"/> |
| FEATURE UNDER: <input type="text" value="WILLOW CREEK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="50.8"/> |
| ROAD INV NO: <input type="text" value="0002701292"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="20"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/> | | |

Structures in the Municipality of Freedom

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Freedom"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="5145"/> | BRIDGE REGION: <input type="text" value="Mid-Coast"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="1.3 MI S JCT 137"/> | YEAR BUILT: <input type="text" value="1928"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="BARLOW BROOK"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| FEATURE ON: <input type="text" value="SA 1A"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="15"/> | DATE OF INSPECTION: <input type="text" value="1/15/2013"/> |
| FEATURE UNDER: <input type="text" value="BARLOW BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="65.5"/> |
| ROAD INV NO: <input type="text" value="0002700391"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="20"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/> | | |

Structures in the Municipality of Freedom

CONDITION RATINGS

| | | |
|--|--|--|
| TOWN1: <input type="text" value="Freedom"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="2485"/> | BRIDGE REGION: <input type="text" value="Mid-Coast"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value=".2 MI W TOWNLINE"/> | YEAR BUILT: <input type="text" value="1927"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="LOWER VILLAGE"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="137"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="17"/> | DATE OF INSPECTION: <input type="text" value="1/15/2013"/> |
| FEATURE UNDER: <input type="text" value="SANDY STREAM"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="67.3"/> |
| ROAD INV NO: <input type="text" value="000000137X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00137"/> | | |
| ROAD WIDTH: <input type="text" value="23"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |