

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="5020"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI NW OF BOG BK RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1921"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="FISH STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="PATTEN ST (OLD RTE)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="97"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="FISH STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="80.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000301043"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1401"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="1.1 MI SW DYER BROOK TL"/>	<b>YEAR BUILT:</b> <input type="text" value="1979"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="I95 NB / W BR MATTAWAM RI"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="I-95 NORTHBOUND"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="147"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/6/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="W BR MATTAWAMKEAG"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="97.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000095X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input type="text" value="42"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1402"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value=".5 MI N 159"/>	<b>YEAR BUILT:</b> <input type="text" value="1979"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="I95 NB / FISH STR &amp; BOG BK R"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="I-95 NB"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="337"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="FISH STREAM &amp; BOG BK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="93.7"/>
<b>ROAD INV NO:</b> <input type="text" value="000000095X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input type="text" value="41"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Island Falls"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="1403"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.5 MI NLY OF RTE 159"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1979"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input style="width: 130px;" type="text" value="I95NB / B&amp;ARR &amp; PATTEN RD"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="I95 NORTHBOUND"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="180"/>	<b>DATE OF INSPECTION:</b> <input style="width: 50px;" type="text" value="8/22/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="PATTEN ROAD &amp; RR"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="96.4"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000095X"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="41"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="2163"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI NE TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1929"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="COLD BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="US RTE 2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="23"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/6/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="90.9"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Island Falls"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="2243"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.4 MI E OF JCT RTE 159"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1929"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="DYER BROOK"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="US RTE 2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="33"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="11/6/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="DYER BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="96.8"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="35"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="0154"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".8MI N OUTER PATTEN ST"/>	<b>YEAR BUILT:</b> <input type="text" value="1977"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="ALDER BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="JACOB SHUR RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="14"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/2/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="ALOER BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="71"/>
<b>ROAD INV NO:</b> <input type="text" value="0000301447"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="2703"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.3 MI N OF JCT RTE 159"/>	<b>YEAR BUILT:</b> <input type="text" value="1931"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="RANDALL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="OLD PATTEN ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="58"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="W BR MATTAWAMKEAG"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="56.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000302048"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="21"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Island Falls"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="6178"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="1.1 MI SW DYER BROOK TL"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1967"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>BRDGNAME:</b> <input style="width: 130px;" type="text" value="I95 SB / W BR MATTAWAMKE"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>OWNER:</b> <input style="width: 90px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 90px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 110px;" type="text" value="I95 SOUTHBOUND"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="146"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="11/6/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 110px;" type="text" value="W BR MATTAWAMKEAG"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="97.7"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000095S"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input style="width: 60px;" type="text" value="43"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="6162"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.7 MI S OF JCT RTE 159"/>	<b>YEAR BUILT:</b> <input type="text" value="1967"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="SLY BROOK - NEW"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="US RTE 2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="26"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="SLY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98.6"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="6163"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.4 MI E OF OVER I-95"/>	<b>YEAR BUILT:</b> <input type="text" value="1967"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="RTE 159 / W BR MATTAWAMK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 159"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="224"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/29/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="W BR MATTAWAMKEAG"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="86.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000159X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00159"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Island Falls"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="6174"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 120px;" type="text" value="0.6 MI NW OF JCT RTE 2"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1967"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRDGNAME:</b> <input style="width: 120px;" type="text" value="BELVEDERE ROAD / I-95"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="6"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="BELVEDERE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="462"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="5/29/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="INTERSTATE 95"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 40px;" type="text" value="91"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0000301449"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="6175"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="INTERCHANGE 276"/>	<b>YEAR BUILT:</b> <input type="text" value="1967"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="ROUTE 159 / I-95"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="6"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 159"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="412"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/5/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="INTERSTATE 95"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="83.6"/>
<b>ROAD INV NO:</b> <input type="text" value="000000159X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00159"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="6176"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.5 MI N'LY OF RTE 159"/>	<b>YEAR BUILT:</b> <input type="text" value="1967"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="I95SB/B&amp;ARR &amp; PATTEN RD"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="I95 SOUTHBOUND"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="198"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/22/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="PATTEN ROAD"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="95.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000095S"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input type="text" value="43"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="6177"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value=".5 MI N 159"/>	<b>YEAR BUILT:</b> <input type="text" value="1967"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="I95SB/FISH STR&amp;BOG BRK RD"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="I-95 SOUTHBOUND"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="326"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="FISH STREAM &amp; BOG BK"/>	<b>POSTING STATUS:</b> <input type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="93.4"/>
<b>ROAD INV NO:</b> <input type="text" value="00000095S"/>	<b>POSTING TYPE:</b> <input type="text" value="3 Underclearance Limit"/>	
<b>ROUTE NO:</b> <input type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input type="text" value="43"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Island Falls

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Island Falls"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>BRIDGE NO.:</b> <input type="text" value="2403"/>	<b>BRIDGE REGION:</b> <input type="text" value="Northern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>LOCATION:</b> <input type="text" value="300 FT S OF JCT RTE 159"/>	<b>YEAR BUILT:</b> <input type="text" value="2010"/>	<b>DECK CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>BRDGNAME:</b> <input type="text" value="IRON"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE US 2"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="222"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="W BR MATTAWAMKEAG"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="83.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000002X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00002"/>		
<b>ROAD WIDTH:</b> <input type="text" value="25"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		