

## Structures in the Municipality of Lee

### CONDITION RATINGS

<b>TOWN1:</b> Lee	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 5 Fair
<b>BRIDGE NO.:</b> 5417	<b>BRIDGE REGION:</b> Northern	<b>SUPERSTRUCTURE CONDITION:</b> 5 Fair
<b>LOCATION:</b> 3*2*MI*W*TOWNLIN	<b>YEAR BUILT:</b> 1952	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> MILL STREAM	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 7 Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 7 Good
<b>FEATURE ON:</b> RTE 6	<b>STRUCTURE LENGTH IN FEET:</b> 15	<b>DATE OF INSPECTION:</b> 1/30/2012
<b>FEATURE UNDER:</b> MILL STREAM	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 59.5
<b>ROAD INV NO:</b> 000000006X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00006		
<b>ROAD WIDTH:</b> 34 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		

## Structures in the Municipality of Lee

### CONDITION RATINGS

<b>TOWN1:</b> Lee	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 5 Fair
<b>BRIDGE NO.:</b> 3177	<b>BRIDGE REGION:</b> Northern	<b>SUPERSTRUCTURE CONDITION:</b> 5 Fair
<b>LOCATION:</b> .2 MI S RTE 6	<b>YEAR BUILT:</b> 1934	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> POND	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 5 Fair
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 4 Poor
<b>FEATURE ON:</b> ARAB RD	<b>STRUCTURE LENGTH IN FEET:</b> 21	<b>DATE OF INSPECTION:</b> 9/10/2012
<b>FEATURE UNDER:</b> MATTAKE STREAM	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 57.1
<b>ROAD INV NO:</b> 0001900718	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 20 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		

## Structures in the Municipality of Lee

### CONDITION RATINGS

<b>TOWN1:</b> Lee	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 0871	<b>BRIDGE REGION:</b> Northern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> .3 MI N RTE 6	<b>YEAR BUILT:</b> 2003	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> MERRILL	<b>SPAN MATERIAL:</b> 7 Precast Concrete	<b>CHANNEL CONDITION:</b> 8 Very Good
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 4 Culvert	<b>CULVERT CONDITION:</b> 8 Very Good
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 3	<b>APPROACH CONDITION:</b> 5 Fair
<b>FEATURE ON:</b> MALLETS MILL RD	<b>STRUCTURE LENGTH IN FEET:</b> 18	<b>DATE OF INSPECTION:</b> 9/10/2012
<b>FEATURE UNDER:</b> MATTAKE STREAM	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 89.3
<b>ROAD INV NO:</b> 0001900708	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		