

Structures in the Municipality of Auburn

CONDITION RATINGS

TOWN1: Auburn	TOWN2: Lewiston	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 3076	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 8 Very Good
LOCATION: LEWISTON-AUBURN TL	YEAR BUILT: 1983	DECK CONDITION: 6 Satisfactory
BRDGNAME: JAMES B. LONGLEY MEMORI	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 7	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE US 202, 100	STRUCTURE LENGTH IN FEET: 600	DATE OF INSPECTION: 12/17/2012
FEATURE UNDER: ANDROSCOGGIN RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 82
ROAD INV NO: 000000202X	POSTING TYPE: 0 None needed	
ROUTE NO: 00202		
ROAD WIDTH: 64 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Auburn

CONDITION RATINGS

TOWN1: Auburn	TOWN2: Lewiston	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 6260	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 0.5 MI W JCT OF US 202	YEAR BUILT: 1973	DECK CONDITION: 6 Satisfactory
BRDGNAME: VIET NAM MEMORIAL, WEST	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 5 Fair
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 7 Good
FEATURE ON: VIETNAM VET CONNEC	STRUCTURE LENGTH IN FEET: 505	DATE OF INSPECTION: 7/19/2012
FEATURE UNDER: W CHAN ANDRO R & RIV	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 96.2
ROAD INV NO: 0000110484	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 72 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Auburn

CONDITION RATINGS

TOWN1: Auburn	TOWN2: Lewiston	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 0086	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: 0.163 mi E of Vickery Rd	YEAR BUILT: 1956	DECK CONDITION: 7 Good
BRDGNAME: MTPK(NB)/ANDROSCOGGIN R	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 8 ME TPK	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 8 ME TPK	NUMBER OF MAIN SPANS: 6	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: I-95 (NB)	STRUCTURE LENGTH IN FEET: 846	DATE OF INSPECTION: 7/26/2012
FEATURE UNDER: ANDROSCOGGIN RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 97.3
ROAD INV NO: 000000095X	POSTING TYPE: 0 None needed	
ROUTE NO: 00095		
ROAD WIDTH: 38 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: MAINE TURNPIKE AUTHORITY		

Structures in the Municipality of Auburn

CONDITION RATINGS

TOWN1: Auburn	TOWN2: Lewiston	SUBSTRUCTURE CONDITION: 4 Poor
BRIDGE NO.: 3330	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 4 Poor
LOCATION: TOWNLINE	YEAR BUILT: 1936	DECK CONDITION: 7 Good
BRDGNAME: BERNARD LOWN PEACE	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 5 Truss	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: CEDAR STREET	STRUCTURE LENGTH IN FEET: 723	DATE OF INSPECTION: 6/4/2012
FEATURE UNDER: ANDROSCOGGIN RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 47.5
ROAD INV NO: 0000110047	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 41 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0101"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
LOCATION: <input style="width: 130px;" type="text" value="0.036 mi N of Gould Rd"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1956"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="4"/> <input style="width: 100px;" type="text" value="Poor"/>
BRDGNAME: LISBON ROAD/MTPK	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
OWNER: <input style="width: 80px;" type="text" value="8 ME TPK"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 80px;" type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="4"/>	APPROACH CONDITION: <input style="width: 30px;" type="text"/> <input style="width: 100px;" type="text"/>
FEATURE ON: <input style="width: 100px;" type="text" value="OLD LISBON RD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="276"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="5/17/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="METPK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="59.6"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120320"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="0100"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.197 mi N of N Lisbon Rd"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="MTPK(NB)/RTE 196 & MCRR"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="6"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95 (NB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="440"/>	DATE OF INSPECTION: <input type="text" value="5/17/2012"/>
FEATURE UNDER: <input type="text" value="LISBON ST/RTE 196 & MC"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="93.5"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="38"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0099"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.330 mi W of SR 196"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MTPK/FERRY & COTTAGE RO"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text"/> <input type="text"/>
FEATURE ON: <input type="text" value="I-95 (NB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="50"/>	DATE OF INSPECTION: <input type="text" value="2/20/2013"/>
FEATURE UNDER: <input type="text" value="FERRY ROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.5"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="38"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0098"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
LOCATION: <input style="width: 130px;" type="text" value="0.380 mi W of Pleasant St"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1956"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRDGNAME: LEWISTON INTERCHANGE (N)	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
OWNER: <input style="width: 80px;" type="text" value="8 ME TPK"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 80px;" type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="3"/>	APPROACH CONDITION: <input style="width: 30px;" type="text"/> <input style="width: 80px;" type="text"/>
FEATURE ON: <input style="width: 100px;" type="text" value="I-95 (NB)"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="151"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="5/16/2012"/>
FEATURE UNDER: LEWISTON INTERCHANG	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="80.4"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000095X"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00095"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="43"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0097"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="0.172 mi E of River Rd"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MTPK(NB)/GOODARD ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95 (NB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="109"/>	DATE OF INSPECTION: <input type="text" value="5/16/2012"/>
FEATURE UNDER: <input type="text" value="GOODARD ROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.3"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="42"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0096"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="0.452 mi E of SR 136"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MTPK(NB)/RIVER ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95 (NB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="162"/>	DATE OF INSPECTION: <input type="text" value="5/17/2012"/>
FEATURE UNDER: <input type="text" value="RIVER ROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.3"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="39"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0095"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.1MI NE RTE 196"/>	YEAR BUILT: <input type="text" value="1994"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="FOSS ROAD"/>	SPAN MATERIAL: <input type="text" value="5 Aluminum"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="4"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="FOSS ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="44"/>	DATE OF INSPECTION: <input type="text" value="7/29/2011"/>
FEATURE UNDER: <input type="text" value="NO NAME BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="93.1"/>
ROAD INV NO: <input type="text" value="0000120137"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0094"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.1 MI E COLLEGE RD"/>	YEAR BUILT: <input type="text" value="1975"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="STETSON ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="6 Arch"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="STETSON ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="11"/>	DATE OF INSPECTION: <input type="text" value="8/25/2011"/>
FEATURE UNDER: <input type="text" value="STETSON BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="98.8"/>
ROAD INV NO: <input type="text" value="0000120406"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0093"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.1 MI N ME TURNPIKE"/>	YEAR BUILT: <input type="text" value="1986"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: HART'S RIVER ROAD	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="RIVER ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="14"/>	DATE OF INSPECTION: <input type="text" value="2/4/2013"/>
FEATURE UNDER: <input type="text" value="HARTS BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="98.9"/>
ROAD INV NO: <input type="text" value="0000120366"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0092"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.3 MI. SE OF COLLEGE RD."/>	YEAR BUILT: <input type="text" value="2005"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="HAMEL ROAD"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="OLD FARM ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="19"/>	DATE OF INSPECTION: <input type="text" value="8/25/2011"/>
FEATURE UNDER: <input type="text" value="STETSON BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="92.4"/>
ROAD INV NO: <input type="text" value="0000120172"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0091"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="200 FT FROM GREENE T L"/>	YEAR BUILT: <input type="text" value="1998"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="STETSON BROOK"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="COLLEGE STREET"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="18"/>	DATE OF INSPECTION: <input type="text" value="8/22/2011"/>
FEATURE UNDER: <input type="text" value="STETSON BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="99.8"/>
ROAD INV NO: <input type="text" value="0000120081"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0102"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
LOCATION: <input style="width: 150px;" type="text" value="0.081 mi NW of Crowley"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1956"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
BRDGNAME: <input style="width: 150px;" type="text" value="WEBSTER ROAD/MTPK"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
OWNER: <input style="width: 100px;" type="text" value="8 ME TPK"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="4"/>	APPROACH CONDITION: <input style="width: 30px;" type="text"/> <input style="width: 80px;" type="text"/>
FEATURE ON: <input style="width: 100px;" type="text" value="WEBSTER ROAD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="94"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="5/17/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="I-95"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="80.2"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120556"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="25"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0089"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
LOCATION: <input style="width: 130px;" type="text" value="0.9 MI E POND RD."/>	YEAR BUILT: <input style="width: 50px;" type="text" value="2011"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
BRDGNAME: <input style="width: 100px;" type="text" value="RANDALL (SCRIBNER)"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="5 Aluminum"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
OWNER: <input style="width: 80px;" type="text" value="4 Municipal"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="4 Culvert"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="9"/> <input style="width: 80px;" type="text" value="Excellent"/>
MAINTAINER: <input style="width: 100px;" type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="RANDALL ROAD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="22"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="3/16/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="NO NAME BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="100"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120355"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0105"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.165 mi W of Crowley Rd"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="NO NAME BROOK CULVERT"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text"/> <input type="text"/>
FEATURE ON: <input type="text" value="I-95"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="40"/>	DATE OF INSPECTION: <input type="text" value="5/17/2012"/>
FEATURE UNDER: <input type="text" value="NO NAME BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="71.3"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="0088"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value=".1MI SE RT196(DS FROM FOS)"/>	YEAR BUILT: <input type="text" value="1966"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="JORDAN ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
FEATURE ON: <input type="text" value="JORDAN RD (TOWN FA)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="35"/>	DATE OF INSPECTION: <input type="text" value="8/25/2011"/>
FEATURE UNDER: <input type="text" value="NO NAME BROOK"/>	POSTING STATUS: <input type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="76.1"/>
ROAD INV NO: <input type="text" value="0000120215"/>	POSTING TYPE: <input type="text" value="1 Weight Limit"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="24"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="0087"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="1.0 MI W TOWN LINE"/>	YEAR BUILT: <input type="text" value="2002"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="CROWLEY ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="CROWLEY ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="61"/>	DATE OF INSPECTION: <input type="text" value="11/7/2012"/>
FEATURE UNDER: <input type="text" value="NO NAME BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="91.2"/>
ROAD INV NO: <input type="text" value="0000120092"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0061"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.4 MI S OF RTE 126"/>	YEAR BUILT: <input type="text" value="1970"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="POND ROAD (REYNOLDS)"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="POND ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="13"/>	DATE OF INSPECTION: <input type="text" value="8/22/2011"/>
FEATURE UNDER: <input type="text" value="NO NAME BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="92.3"/>
ROAD INV NO: <input type="text" value="0000120345"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0060"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="077.70 MILE POINT"/>	YEAR BUILT: <input type="text" value="1955"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="INTERCHANGE / RTE 196"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="LEWISTON INTERCHAN"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="200"/>	DATE OF INSPECTION: <input type="text" value="12/17/2011"/>
FEATURE UNDER: <input type="text" value="RTE 196"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="81"/>
ROAD INV NO: <input type="text" value="0000120620"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="30"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0059"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="77.72 MILE POINT"/>	YEAR BUILT: <input type="text" value="1955"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="MTPK EXIT 13 / MCRR"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="MTPK EXIT 13"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="98"/>	DATE OF INSPECTION: <input type="text" value="12/17/2011"/>
FEATURE UNDER: <input type="text" value="M C RR"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="89"/>
ROAD INV NO: <input type="text" value="0000120620"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="32"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0054"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
LOCATION: <input style="width: 130px;" type="text" value="IMI E OF TOWNLINE"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="2006"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
BRDGNAME: RIVERSIDE STREET	SPAN MATERIAL: <input style="width: 100px;" type="text" value="7 Precast Concrete"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
OWNER: <input style="width: 80px;" type="text" value="4 Municipal"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="3 Slab"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="RIVERSIDE ST"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="54"/>	DATE OF INSPECTION: <input style="width: 80px;" type="text" value="10/20/2011"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="M C RR"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="81.9"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120369"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="24"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
BRIDGE NO.: <input type="text" value="0053"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.2 MI N OF 202 & MAIN ST"/>	YEAR BUILT: <input type="text" value="1994"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGRNAME: <input type="text" value="BRIDGE STREET"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="BRIDGE STREET"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="71"/>	DATE OF INSPECTION: <input type="text" value="10/20/2011"/>
FEATURE UNDER: <input type="text" value="MAINE CENTRAL RR"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="59.7"/>
ROAD INV NO: <input type="text" value="0000120050"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="26"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="0050"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="8"/> <input style="width: 60px;" type="text" value="Very Good"/>
LOCATION: <input style="width: 130px;" type="text" value="0.1 MIL W LINCOLN ST"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1996"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="8"/> <input style="width: 60px;" type="text" value="Very Good"/>
BRDGNAME: <input style="width: 100px;" type="text" value="OXFORD STREET"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="3 Slab"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="OXFORD STREET"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="32"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="8/28/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="CROSS CANAN #2"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="88.5"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120326"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0048"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="0.4 MIL 5 US 202"/>	YEAR BUILT: <input type="text" value="1927"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="LINCOLN STREET #2"/>	SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="LINCOLN STREET"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="29"/>	DATE OF INSPECTION: <input type="text" value="1/30/2012"/>
FEATURE UNDER: <input type="text" value="CROSS CANAL #2"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="94.6"/>
ROAD INV NO: <input type="text" value="0000120241"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="48"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="0090"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.1 MI W SABATTUS TL"/>	YEAR BUILT: <input type="text" value="2011"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="GROVE STREET"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="GROVE ST"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="22"/>	DATE OF INSPECTION: <input type="text" value="9/2/2011"/>
FEATURE UNDER: <input type="text" value="SALMON BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="90.7"/>
ROAD INV NO: <input type="text" value="0000120165"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="2229"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
LOCATION: <input style="width: 140px;" type="text" value="5 MI E TOWNLINE"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1955"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
BRDGNAME: <input style="width: 100px;" type="text" value="DILL"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
OWNER: <input style="width: 90px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="4 Culvert"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
FEATURE ON: <input style="width: 110px;" type="text" value="RTE 196 & MTA ON R"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="16"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="12/22/2011"/>
FEATURE UNDER: <input style="width: 110px;" type="text" value="DILL BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="65.6"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000196X"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00196"/>		
ROAD WIDTH: <input style="width: 60px;" type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="6378"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1.0 M W LISBON T.L."/>	YEAR BUILT: <input type="text" value="1998"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="COTTON ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="COTTON ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="14"/>	DATE OF INSPECTION: <input type="text" value="7/29/2011"/>
FEATURE UNDER: <input type="text" value="SALMON BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="99.8"/>
ROAD INV NO: <input type="text" value="0000120089"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="6331"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
LOCATION: <input style="width: 130px;" type="text" value="0.4 MI W OF JCT US 202"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1973"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
BRDGNAME: <input style="width: 130px;" type="text" value="VIET NAM MEMORIAL, EAST"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
OWNER: <input style="width: 90px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 90px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="3"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="VIET VET'S CONNECT"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="450"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="10/25/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="ANDROSCOGGIN RIVER"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="96.5"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120510"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 60px;" type="text" value="72"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="6214"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="IMMED. W'LY OF ROUTE 196"/>	YEAR BUILT: <input type="text" value="1987"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="CEDAR STREET WESTBOUND"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="CEDAR ST"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="94"/>	DATE OF INSPECTION: <input type="text" value="1/25/2012"/>
FEATURE UNDER: <input type="text" value="MAIN CANAL"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="80.9"/>
ROAD INV NO: <input type="text" value="0000120069"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="27"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="6189"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1.8 MI W TOWNLIN"/>	YEAR BUILT: <input type="text" value="1969"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="WEBSTER ROAD BRIDGE"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="WEBSTER RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="12"/>	DATE OF INSPECTION: <input type="text" value="9/2/2011"/>
FEATURE UNDER: <input type="text" value="NO NAME PD BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="73"/>
ROAD INV NO: <input type="text" value="0000120556"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="6117"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="6 MI EAST TOWNLINE"/>	YEAR BUILT: <input type="text" value="1967"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: HART BROOK	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="6 Arch"/>	CULVERT CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="PLEASANT ST"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="13"/>	DATE OF INSPECTION: <input type="text" value="12/22/2011"/>
FEATURE UNDER: <input type="text" value="DILL BRK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="55.4"/>
ROAD INV NO: <input type="text" value="0000120344"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="40"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="5689"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="1 MI S'LY OF JCT 202"/>	YEAR BUILT: <input type="text" value="1958"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="LINCOLN ST. ANDROS MILL"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="LINCOLN ST"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="89"/>	DATE OF INSPECTION: <input type="text" value="1/30/2012"/>
FEATURE UNDER: <input type="text" value="MAIN CANAL"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="94.9"/>
ROAD INV NO: <input type="text" value="0000120241"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="34"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="5643"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
LOCATION: <input style="width: 150px;" type="text" value="2 MI N JCT 126"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1955"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRDGNAME: COLLEGE STREET BRIDGE	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="3"/> <input style="width: 100px;" type="text" value="Serious"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="3 Slab"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 80px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="COLLEGE STREET"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="22"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="8/22/2011"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="STETSON BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="67.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120081"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="5003"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
LOCATION: <input style="width: 130px;" type="text" value="400 FT W RTE #196"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1927"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
BRDGNAME: <input style="width: 100px;" type="text" value="CHESTNUT STREET"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="6 Arch"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
FEATURE ON: <input style="width: 100px;" type="text" value="CHESTNUT ST."/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="74"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="8/28/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="MAIN CANAL"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="28.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000120076"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="3 Underclearance Limit"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="24"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="3900"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="0.1 MI S RTE 202"/>	YEAR BUILT: <input type="text" value="1930"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="LINCOLN STREET"/>	SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="LINCOLN STREET"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="47"/>	DATE OF INSPECTION: <input type="text" value="1/30/2012"/>
FEATURE UNDER: <input type="text" value="CROSS CANAL #1"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="98.9"/>
ROAD INV NO: <input type="text" value="0000120241"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="48"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="3201"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="2MI N OF RT126 OVER RT202"/>	YEAR BUILT: <input type="text" value="1936"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="FAIRGROUNDS CROSSING"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="6 Railroad"/>	SPAN TYPE: <input type="text" value="2 Girder - floor beam"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="6 Railroad"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
FEATURE ON: <input type="text" value="MAINE CENTRAL RAIL"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="129"/>	DATE OF INSPECTION: <input type="text" value="8/28/2012"/>
FEATURE UNDER: <input type="text" value="STATE ROUTE 202"/>	POSTING STATUS: <input type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="-1"/>
ROAD INV NO: <input type="text"/>	POSTING TYPE: <input type="text" value="3 Underclearance Limit"/>	
ROUTE NO: <input type="text"/>		
ROAD WIDTH: <input type="text"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0103"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="79.56 MILE POINT"/>	YEAR BUILT: <input type="text" value="1955"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="MTPK/DILL BROOK"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text"/> <input type="text"/>
FEATURE ON: <input type="text" value="I-95"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="10"/>	DATE OF INSPECTION: <input type="text" value="5/9/2012"/>
FEATURE UNDER: <input type="text" value="HART BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="81"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
BRIDGE NO.: <input type="text" value="2803"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value="2.2 MI SW GREENE TL"/>	YEAR BUILT: <input type="text" value="1927"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: <input type="text" value="STETSON BRIDGE"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="MAIN ST US #202"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="15"/>	DATE OF INSPECTION: <input type="text" value="8/30/2011"/>
FEATURE UNDER: <input type="text" value="STETSON BK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="62.1"/>
ROAD INV NO: <input type="text" value="000000202X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00202"/>		
ROAD WIDTH: <input type="text" value="40"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0047"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="IMMED. SW'LY OF ROUTE 196"/>	YEAR BUILT: <input type="text" value="1975"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="LOCUST STREET"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="LOCUST STREET"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="90"/>	DATE OF INSPECTION: <input type="text" value="1/25/2012"/>
FEATURE UNDER: <input type="text" value="MAIN CANAL"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.2"/>
ROAD INV NO: <input type="text" value="0000120245"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="30"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="1531"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="IMMED. W'LY OF ROUTE 196"/>	YEAR BUILT: <input type="text" value="1973"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="CEDAR STREET, NEW"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="CEDAR STREET E B"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="107"/>	DATE OF INSPECTION: <input type="text" value="1/25/2012"/>
FEATURE UNDER: <input type="text" value="MAIN CANAL"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="80.8"/>
ROAD INV NO: <input type="text" value="0003201031"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="28"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="1498"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.209 mi N of N Lisbon Rd"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="MTPK(SB) / RTE 196 & MCRR"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="6"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95(SB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="440"/>	DATE OF INSPECTION: <input type="text" value="5/17/2012"/>
FEATURE UNDER: <input type="text" value="LISBON ST/RTE 196 & MC"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="67.3"/>
ROAD INV NO: <input type="text" value="000000095S"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="38"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="1497"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value="0.378 mi W of Pleasant St"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: LEWISTON INTERCHANGE (S)	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text"/> <input type="text"/>
FEATURE ON: <input type="text" value="I-95(SB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="151"/>	DATE OF INSPECTION: <input type="text" value="5/16/2012"/>
FEATURE UNDER: <input type="text" value="ALFRED PLOURDE PKW"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="69.5"/>
ROAD INV NO: <input type="text" value="000000095S"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="31"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="1496"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="0.163 mi E of River Rd"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MTPK(SB)/GOODARD ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95(SB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="109"/>	DATE OF INSPECTION: <input type="text" value="5/16/2012"/>
FEATURE UNDER: <input type="text" value="GOODARD ROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="97.3"/>
ROAD INV NO: <input type="text" value="000000095S"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="42"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="1495"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value="0.450 mi E of SR 136"/>	YEAR BUILT: <input type="text" value="1956"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: <input type="text" value="MTPK(SB)/RIVER ROAD"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95(SB)"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="162"/>	DATE OF INSPECTION: <input type="text" value="5/17/2012"/>
FEATURE UNDER: <input type="text" value="RIVER ROAD"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="97.3"/>
ROAD INV NO: <input type="text" value="000000095S"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="39"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="Auburn"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="1494"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
LOCATION: <input style="width: 130px;" type="text" value="0.151 mi E of Vickery Rd"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1995"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
BRDGNAME: <input style="width: 130px;" type="text" value="MTPK(SB)/ANDROSCOGGIN R"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
OWNER: <input style="width: 80px;" type="text" value="8 ME TPK"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 80px;" type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="6"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="8"/> <input style="width: 100px;" type="text" value="Very Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="I-95(SB)"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="846"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="7/26/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="ANDROSCOGGIN RIVER"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="95.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="00000095S"/>	POSTING TYPE: <input style="width: 80px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 50px;" type="text" value="00095"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="38"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="1371"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
LOCATION: <input style="width: 130px;" type="text" value=".2 MI E TOWNLINE"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1973"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRDGNAME: <input style="width: 100px;" type="text" value="RAMP D / MCRR"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="3"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
FEATURE ON: <input style="width: 100px;" type="text" value="VIETNAM VET WB"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="183"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="10/11/2011"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="M C RR"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="80.6"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0003200174"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="29"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Lewiston"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="1370"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
LOCATION: <input style="width: 130px;" type="text" value=".2 MI E TOWNLINE"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1973"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRDGNAME: <input style="width: 100px;" type="text" value="RAMP A / MCRR"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="3"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
FEATURE ON: <input style="width: 100px;" type="text" value="VIETNAM VET EB"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="188"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="10/11/2011"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="M C RR"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="79.7"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0003200178"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="29"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="6383"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="Rt 202 & Russell Street"/>	YEAR BUILT: <input type="text" value="2005"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: <input type="text" value="Main Street Overpass"/>	SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/>	CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="Russell Street"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="131"/>	DATE OF INSPECTION: <input type="text" value="12/17/2012"/>
FEATURE UNDER: <input type="text" value="Main Street"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="80.8"/>
ROAD INV NO: <input type="text" value="0000120510"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="26"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="0104"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="79.64 MILE POINT"/>	YEAR BUILT: <input type="text" value="1955"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="CITY FARM CULVERT"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="8 ME TPK"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="8 ME TPK"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/>
FEATURE ON: <input type="text" value="I-95"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="10"/>	DATE OF INSPECTION: <input type="text" value="5/9/2012"/>
FEATURE UNDER: <input type="text" value="HART BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="79"/>
ROAD INV NO: <input type="text" value="000000095X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00095"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

Structures in the Municipality of Lewiston

CONDITION RATINGS

TOWN1: <input type="text" value="Lewiston"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="3083"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value=".1 MI W 196"/>	YEAR BUILT: <input type="text" value="1991"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="MAIN STREET"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="3"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="RTE 1100-US202"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="91"/>	DATE OF INSPECTION: <input type="text" value="8/28/2012"/>
FEATURE UNDER: <input type="text" value="MAIN CANAL"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="68"/>
ROAD INV NO: <input type="text" value="000000202X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00202"/>		
ROAD WIDTH: <input type="text" value="54"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		