

## Structures in the Municipality of Bar Harbor

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Bar Harbor"/>	<b>TOWN2:</b> <input type="text" value="Mt Desert"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3161"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1935"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <b>KITTREDGE BRIDGE</b>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="102 &amp; 198"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="15"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/19/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MEADOW BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="69.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000102X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00102"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="0479"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value=".4MI N RT3(.9TO NPS RTE12"/>	<b>YEAR BUILT:</b> <input type="text" value="1928"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="BRIDGE (NPS # 030P)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="7 Rigid Frame"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="STANLEY RD (NPS RT"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="17"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/7/1991"/>
<b>FEATURE UNDER:</b> <input type="text" value="STANLEY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="66.6"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900839"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="0465"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value=".1 MI W RT 102"/>	<b>YEAR BUILT:</b> <input type="text" value="1950"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="SOMES POND"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="TW (CEMETERY ACCES"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="18"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="9/12/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="SOMES POND OUTLET"/>	<b>POSTING STATUS:</b> <input type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="53.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900522"/>	<b>POSTING TYPE:</b> <input type="text" value="1 Weight Limit"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="16"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0466"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.37 MI N ROUTE 3"/>	<b>YEAR BUILT:</b> <input type="text" value="1928"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <b>BRIDGE 1</b>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="7 Rigid Frame"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="STANLEY RD (NPS RT)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="16"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/7/1991"/>
<b>FEATURE UNDER:</b> <input type="text" value="STANLEY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="77.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900839"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0467"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.35MI N RT3(1.0TONPSRT12)"/>	<b>YEAR BUILT:</b> <input type="text" value="1928"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="BRIDGE (NPS # 031P)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="7 Rigid Frame"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="STANLEY RD (NPS RT)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="16"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/7/1991"/>
<b>FEATURE UNDER:</b> <input type="text" value="STANLEY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="77.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900839"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0468"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.3MI N RT3(,3 TO ME RTE3"/>	<b>YEAR BUILT:</b> <input type="text" value="1928"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="BRIDGE (NPS # 032P)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="7 Rigid Frame"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="STANLEY RD (NPS RT"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="26"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/7/1991"/>
<b>FEATURE UNDER:</b> <input type="text" value="STANLEY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="77.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900839"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="Bar Harbor"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="0475"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="6.3MI S ME RTE OR BR#5380"/>	<b>YEAR BUILT:</b> <input type="text" value="1938"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="OTTER CREEK (NPS # 019P)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="4 Stone"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="PARK LOOP RD (NPS)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="70"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/1/1992"/>
<b>FEATURE UNDER:</b> <input type="text" value="OTTER CREEK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="70.3"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900538"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="27"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="0476"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="1.8MI E STNLY RD(NPS RT14"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="HUNTER BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="PARK LOOP RD (INN"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="23"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/20/1991"/>
<b>FEATURE UNDER:</b> <input type="text" value="HUNTERS BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="89.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900538"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0459"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="1 MI N RT 3"/>	<b>YEAR BUILT:</b> <input type="text" value="1932"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="JORDAN POND ROAD"/>	<b>SPAN MATERIAL:</b> <input type="text" value="4 Stone"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="JORDAN POND RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="26"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/15/1998"/>
<b>FEATURE UNDER:</b> <input type="text" value="CARRIAGE ROAD"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="84.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900852"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="29"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0478"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.3E STNLY RD (.3TO NPS14"/>	<b>YEAR BUILT:</b> <input type="text" value="1952"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="CARRIAGE RD BR (NPS#004P)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="PARK LOOP RD (NPS)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="29"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/1/1992"/>
<b>FEATURE UNDER:</b> <input type="text" value="ABANDONNED CARRIAG"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="77.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900538"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5570"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="2.7 MI E 198"/>	<b>YEAR BUILT:</b> <input type="text" value="2011"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="STANLEY BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>FEATURE ON:</b> <input type="text" value="3"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="30"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="1/31/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="STANLEY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="96.3"/>
<b>ROAD INV NO:</b> <input type="text" value="000000003X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00003"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="0559"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="IMI N RT3(0.2 TO NPS RT)"/>	<b>YEAR BUILT:</b> <input type="text" value="1933"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="OVERPASS(NPS#0265)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="4 Stone"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="CARRIAGE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="77"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/1/1992"/>
<b>FEATURE UNDER:</b> <input type="text" value="STANLEY BROOK&amp;ROA"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="77.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900839"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5042"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".5 MI S JCT 233"/>	<b>YEAR BUILT:</b> <input type="text" value="1953"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="RICHARDSON BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="3 &amp; 198"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="13"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/20/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="RICHARDSON BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="49.1"/>
<b>ROAD INV NO:</b> <input type="text" value="000000003X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00003"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="5244"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value=".5 MI S TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1949"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="BABSONS"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="198"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="21"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/20/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MEADOW BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="47"/>
<b>ROAD INV NO:</b> <input type="text" value="000000003X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00003"/>		
<b>ROAD WIDTH:</b> <input type="text" value="25"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="5377"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="1.5 MI S JCT 198"/>	<b>YEAR BUILT:</b> <input type="text" value="1978"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> HARBOR BROOK BRIDGE	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="3"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="28"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="LITTLE HARBOR BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="91.1"/>
<b>ROAD INV NO:</b> <input type="text" value="000000003X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00003"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="5383"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="1.5MI SW T.L.(1.9TO NPS14)"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="RT #3 OVERPASS (NPS 003P)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="MAINE RTE #3"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="42"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/1/1992"/>
<b>FEATURE UNDER:</b> <input type="text" value="PARK LOOP RD (ONE WA)"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="74.3"/>
<b>ROAD INV NO:</b> <input type="text" value="000000003X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00003"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text"/>		

## Structures in the Municipality of Mt Desert

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Mt Desert"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0477"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.8 MI E NPS RT114 STNLY"/>	<b>YEAR BUILT:</b> <input type="text" value="1941"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="OVERPASS(NPS #0055)"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="5 Federal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="5 Federal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="CARRIAGE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="42"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/1/1992"/>
<b>FEATURE UNDER:</b> <input type="text" value="NPS RTE 300(PARK LOOP)"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="73.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900538"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="14"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text"/>		