

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="3759"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value=".7 MI S JCT 9"/> | YEAR BUILT: <input type="text" value="1942"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: WEARS | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="SHORE RD SA 15"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="18"/> | DATE OF INSPECTION: <input type="text" value="4/7/2011"/> |
| FEATURE UNDER: <input type="text" value="JOSIAS RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="94.3"/> |
| ROAD INV NO: <input type="text" value="0003100747"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/> | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|---|---|--|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="3492"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value=".3 MI E JCT RTE US1"/> | YEAR BUILT: <input type="text" value="2003"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="OGUNQUIT BEACH"/> | SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/> | CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="BEACH STREET"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="214"/> | DATE OF INSPECTION: <input type="text" value="6/20/2011"/> |
| FEATURE UNDER: <input type="text" value="OGUNQUIT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="63"/> |
| ROAD INV NO: <input type="text" value="0003101030"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="30"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|--|--|--|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="2663"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| LOCATION: <input type="text" value=".5 MI NO TOWNLINE"/> | YEAR BUILT: <input type="text" value="1928"/> | DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRDGNAME: <input type="text" value="PHILLIPS"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="RTE #1"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="20"/> | DATE OF INSPECTION: <input type="text" value="6/1/2011"/> |
| FEATURE UNDER: <input type="text" value="JOSIAS*RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="63.2"/> |
| ROAD INV NO: <input type="text" value="00000001X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00001"/> | | |
| ROAD WIDTH: <input type="text" value="36"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|--|--|--|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="Wells"/> | SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NO.: <input type="text" value="2239"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="2.3 MI N TOWNLIN E"/> | YEAR BUILT: <input type="text" value="1931"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="DONNELLS"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/> |
| FEATURE ON: <input type="text" value="US1"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="24"/> | DATE OF INSPECTION: <input type="text" value="6/1/2011"/> |
| FEATURE UNDER: <input type="text" value="OGUNQUIT R."/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="75.7"/> |
| ROAD INV NO: <input type="text" value="000000001X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00001"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="Wells"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="1317"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="0.264 mi E Capt Thomas Rd"/> | YEAR BUILT: <input type="text" value="1947"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="OGUNQUIT RIVER BRIDGE"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="6 Arch"/> | CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> |
| FEATURE ON: <input type="text" value="I-95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="40"/> | DATE OF INSPECTION: <input type="text" value="5/12/2012"/> |
| FEATURE UNDER: <input type="text" value="OGUNQUIT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="77.1"/> |
| ROAD INV NO: <input type="text" value="000000095X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | | |
|--|---|--|--|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> | |
| BRIDGE NO.: <input type="text" value="1316"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> | |
| LOCATION: <input type="text" value="0.080 mi E Village Green"/> | YEAR BUILT: <input type="text" value="2000"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> | |
| BRDGNAME: CAPTAIN THOMAS ROAD | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> | |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> | |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text" value=""/> <input type="text" value=""/> | |
| FEATURE ON: <input type="text" value="CAPTAIN THOMAS ROA"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="192"/> | DATE OF INSPECTION: <input type="text" value="5/11/2012"/> | |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="99"/> | |
| ROAD INV NO: <input type="text" value="0003100734"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | | |
| ROUTE NO: <input type="text" value="00000"/> | | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="1315"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.554 mi E of N. Village"/> | YEAR BUILT: <input type="text" value="1994"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: NORTH BURWICK ROAD | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="8 ME TPK"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="8 ME TPK"/> | NUMBER OF MAIN SPANS: <input type="text" value="2"/> | APPROACH CONDITION: <input type="text"/> <input type="text"/> |
| FEATURE ON: <input type="text" value="OGUNQUIT/BERWICK"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="184"/> | DATE OF INSPECTION: <input type="text" value="5/11/2012"/> |
| FEATURE UNDER: <input type="text" value="I-95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="96.9"/> |
| ROAD INV NO: <input type="text" value="0003100648"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="32"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="MAINE TURNPIKE AUTHORITY"/> | | |

Structures in the Municipality of Ogunquit

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Ogunquit"/> | TOWN2: <input type="text" value="Wells"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="1252"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value=".4 MI SW TATNIC RD"/> | YEAR BUILT: <input type="text" value="1955"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="DICKENS HILL"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="NORTH VILLAGE ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="31"/> | DATE OF INSPECTION: <input type="text" value="11/27/2012"/> |
| FEATURE UNDER: <input type="text" value="OGUNQUIT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="81.8"/> |
| ROAD INV NO: <input type="text" value="0003100749"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="25"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Wells

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Wells"/> | TOWN2: <input type="text" value="Ogunquit"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="6122"/> | BRIDGE REGION: <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="1.7 MI W JCT US1"/> | YEAR BUILT: <input type="text" value="2007"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="SHERBURNE"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="CAPTAIN THOMAS RD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="40"/> | DATE OF INSPECTION: <input type="text" value="4/13/2011"/> |
| FEATURE UNDER: <input type="text" value="OGUNQUIT RIVER"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="99"/> |
| ROAD INV NO: <input type="text" value="0003100734"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="28"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |