

## Structures in the Municipality of Orrington

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Orrington"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5300"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="2 MI W TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1951"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="E. ORRINGTON"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="TW"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="13"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="2/6/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="SEDGEED"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="67.3"/>
<b>ROAD INV NO:</b> <input type="text" value="0001900636"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Orrington

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Orrington"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5285"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="3 MI E TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1951"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="SWETTS POND"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="TW"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="12"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="2/6/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="OUTLET - SWETTS POND"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="75.1"/>
<b>ROAD INV NO:</b> <input type="text" value="0001900658"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Orrington

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Orrington"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="3613"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI N OF LONG HILL RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1939"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="RED"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="BREWER LAKE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="25"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/5/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="SEDGEED STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="76.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0001900683"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Orrington

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Orrington"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3361"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value=".2MI W OF RTE15 ON INV689"/>	<b>YEAR BUILT:</b> <input type="text" value="1982"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="MILL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="MILL CREEK ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="55"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/31/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MILL STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="74.3"/>
<b>ROAD INV NO:</b> <input type="text" value="0001900689"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="19"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Orrington

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Orrington"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="2108"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="1.3 MI.N. TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1931"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="BER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 15"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="24"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/31/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MILL CREEK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000015X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00015"/>		
<b>ROAD WIDTH:</b> <input type="text" value="40"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Orrington

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Orrington"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="0862"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="8"/> <input style="width: 60px;" type="text" value="Very Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="1.2 MI N RT 15"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1972"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="8"/> <input style="width: 60px;" type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="MILL CREEK #2"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="4"/> <input style="width: 60px;" type="text" value="Poor"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="JOHNSON MILL ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="18"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="2/6/2013"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="MILL BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="93.8"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0001900636"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="30"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		