

Structures in the Municipality of Harrison

CONDITION RATINGS

TOWN1: Harrison	TOWN2: Otisfield	SUBSTRUCTURE CONDITION: 3 Serious
BRIDGE NO.: 3345	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: 1.5 MI E MAPLE RDGE RD	YEAR BUILT: 1936	DECK CONDITION: 5 Fair
BRDGNAME: SCRIBNER'S BRIDGE	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 8 Very Good
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 5 Fair
FEATURE ON: SCRIBNERS MILL RD	STRUCTURE LENGTH IN FEET: 112	DATE OF INSPECTION: 7/14/2011
FEATURE UNDER: CROOKED RIVER	POSTING STATUS: 3 Posted	FEDERAL SUFFICIENCY RATING: 18.6
ROAD INV NO: 0001703619	POSTING TYPE: 1 Weight Limit	
ROUTE NO: 00000		
ROAD WIDTH: 11 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Harrison

CONDITION RATINGS

TOWN1: Harrison	TOWN2: Otisfield	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 3036	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 8 Very Good
LOCATION: HARRISON-OTISFIELD T.L.	YEAR BUILT: 1986	DECK CONDITION: 7 Good
BRDGNAME: WEST TWIN	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: ROUTE 117	STRUCTURE LENGTH IN FEET: 64	DATE OF INSPECTION: 10/19/2011
FEATURE UNDER: CROOKED RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 92.5
ROAD INV NO: 000000117X	POSTING TYPE: 0 None needed	
ROUTE NO: 00117		
ROAD WIDTH: 33 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Harrison

CONDITION RATINGS

TOWN1: Harrison	TOWN2: Otisfield	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 0238	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 0.4 MI E OF JCT UPTON RD	YEAR BUILT: 1912	DECK CONDITION: 7 Good
BRDGNAME: RYEFIELD	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 5 Truss	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: RYEFIELD BRIDGE RD	STRUCTURE LENGTH IN FEET: 98	DATE OF INSPECTION: 8/11/2012
FEATURE UNDER: CROOKED RIVER	POSTING STATUS: 3 Posted	FEDERAL SUFFICIENCY RATING: 73.5
ROAD INV NO: 0000500770	POSTING TYPE: 5 Weight & Underclearance Limit	
ROUTE NO: 00000		
ROAD WIDTH: 17 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Otisfield

CONDITION RATINGS

TOWN1: <input type="text" value="Otisfield"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="5049"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="1.5 MI SW'LY OF OXFORD TL"/>	YEAR BUILT: <input type="text" value="1925"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="EAST OTISFIELD"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="2"/>	APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
FEATURE ON: <input type="text" value="RTE 121"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="25"/>	DATE OF INSPECTION: <input type="text" value="6/6/2011"/>
FEATURE UNDER: <input type="text" value="SUCKER BK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.9"/>
ROAD INV NO: <input type="text" value="000000121X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00121"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Otisfield

CONDITION RATINGS

TOWN1: <input type="text" value="Otisfield"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="3475"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
LOCATION: <input type="text" value=".5 MI N JCT 121"/>	YEAR BUILT: <input type="text" value="1937"/>	DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRDGNAME: COLLEGE SWAMP	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="BOLSTERS MILLS RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="23"/>	DATE OF INSPECTION: <input type="text" value="1/24/2013"/>
FEATURE UNDER: <input type="text" value="COLLEGE SWAMP"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="67.9"/>
ROAD INV NO: <input type="text" value="0001703616"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Otisfield

CONDITION RATINGS

TOWN1: <input type="text" value="Otisfield"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRIDGE NO.: <input type="text" value="0237"/>	BRIDGE REGION: <input type="text" value="Southern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="0.7 MI E OF GORE RD"/>	YEAR BUILT: <input type="text" value="1997"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: YEATON	SPAN MATERIAL: <input type="text" value="3 Wood"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON: <input type="text" value="BONNEY HILL ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="37"/>	DATE OF INSPECTION: <input type="text" value="6/6/2011"/>
FEATURE UNDER: <input type="text" value="GREELY BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="78.9"/>
ROAD INV NO: <input type="text" value="0001700646"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="20"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		