

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="6118"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.4 MI N RTE 121"/>	<b>YEAR BUILT:</b> <input type="text" value="2001"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="MEADOW BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="SCHOOL HOUSE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="12"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MEADOW BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="100"/>
<b>ROAD INV NO:</b> <input type="text" value="0001700635"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="5761"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="3 MI NO TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1959"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="STATION ROAD"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="7 Rigid Frame"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="STATION RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="14"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MEADOW BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="87.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0001701473"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5639"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1.5 MI NW RTE 121"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="RICHFIELD"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>FEATURE ON:</b> <input type="text" value="GORE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="31"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREELY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="48"/>
<b>ROAD INV NO:</b> <input type="text" value="0001700643"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="5552"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI S OF JCT RTE 121"/>	<b>YEAR BUILT:</b> <input type="text" value="1954"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="KING STREET"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="KING STREET"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="33"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="THOMPSON LAKE OUTL"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="72.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0001700657"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="5256"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value=".1 MI E'LY OF RTE 121"/>	<b>YEAR BUILT:</b> <input type="text" value="1949"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="RALPH E. EDWARDS"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="MAIN ST (ABANDONED)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="56"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="THOMPSON LAKE OUTL"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="80.3"/>
<b>ROAD INV NO:</b> <input type="text" value="0001700884"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3903"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="2.7 MI W'LY OF JCT RTE 26"/>	<b>YEAR BUILT:</b> <input type="text" value="1946"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="WARDWELL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 121"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="54"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREELEY STR./THOMPS"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="67.1"/>
<b>ROAD INV NO:</b> <input type="text" value="000000121X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00121"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="3738"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="1.1 MI W N'LY JCT RTE 27"/>	<b>YEAR BUILT:</b> <input type="text" value="1940"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="COVERED"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 121"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="177"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="9/28/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="LITTLE ANDROSCOGGIN"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="37.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000121X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00121"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="2921"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value=".1 MI S #121"/>	<b>YEAR BUILT:</b> <input type="text" value="1932"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="WELCHVILLE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="#26"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="88"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="9/28/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="LITTLE ANDROSCOGGIN"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="97.7"/>
<b>ROAD INV NO:</b> <input type="text" value="000000026X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00026"/>		
<b>ROAD WIDTH:</b> <input type="text" value="40"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2574"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="1.6 MI N TOWNLIN E"/>	<b>YEAR BUILT:</b> <input type="text" value="1931"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="MINISTER BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="#121"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="18"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="1/29/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="MINISTER BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="74.3"/>
<b>ROAD INV NO:</b> <input type="text" value="000000121X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00121"/>		
<b>ROAD WIDTH:</b> <input type="text" value="29"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Oxford"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="2461"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.7 MI S'LY OF NORWAY TL"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1997"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input style="width: 120px;" type="text" value="LITTLE ANDROSGOGGIN"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>OWNER:</b> <input style="width: 90px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input style="width: 110px;" type="text" value="ROUTE 26"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="187"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="9/20/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 110px;" type="text" value="LITTLE ANDROSCOG RIV"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="79"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000026X"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00026"/>		
<b>ROAD WIDTH:</b> <input style="width: 60px;" type="text" value="40"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2037"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="1.9 MI N TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1931"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="BAKER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="#121"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="18"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="1/29/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="MINISTER BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="95.4"/>
<b>ROAD INV NO:</b> <input type="text" value="000000121X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00121"/>		
<b>ROAD WIDTH:</b> <input type="text" value="74"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Oxford

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Oxford"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="0744"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.2 MI S GORE RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1984"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="GEORGE YEATON"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="TOWN WAY"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="33"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/4/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREELEY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="56.4"/>
<b>ROAD INV NO:</b> <input type="text" value="0001700896"/>	<b>POSTING TYPE:</b> <input type="text" value="1 Weight Limit"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="16"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		