

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|--|---|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="5960"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="I-95 INTERCHANGE # 161"/> | YEAR BUILT: <input type="text" value="1962"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="ROUTE 7 / I-95"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="6"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="ROUTE 7"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="549"/> | DATE OF INSPECTION: <input type="text" value="11/13/2012"/> |
| FEATURE UNDER: <input type="text" value="INTERSTATE 95"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="75.7"/> |
| ROAD INV NO: <input type="text" value="000000007X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00007"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="5959"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value=".8 MI SO TOWNLINE"/> | YEAR BUILT: <input type="text" value="1962"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="MCINTYR BROOK NB"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| FEATURE ON: <input type="text" value="I-95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="17"/> | DATE OF INSPECTION: <input type="text" value="1/20/2012"/> |
| FEATURE UNDER: <input type="text" value="MCINTYRE BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="97.2"/> |
| ROAD INV NO: <input type="text" value="000000095X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="5854"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="2.2 MI SE OF JCT RTE 7"/> | YEAR BUILT: <input type="text" value="1961"/> | DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRDGNAME: <input type="text" value="KNIGHTS"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="4 Municipal"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="4 Municipal"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="LOUD ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="38"/> | DATE OF INSPECTION: <input type="text" value="10/30/2012"/> |
| FEATURE UNDER: <input type="text" value="DIXMONT (MARTIN) STR"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="89.5"/> |
| ROAD INV NO: <input type="text" value="0001900520"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="26"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|---|--|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="5732"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: <input type="text" value="200 FT SW OF RTE 7 & 69"/> | YEAR BUILT: <input type="text" value="1958"/> | DECK CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRDGNAME: <input type="text" value="PLYMOUTH-TROY"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="CLARK ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="42"/> | DATE OF INSPECTION: <input type="text" value="6/18/2012"/> |
| FEATURE UNDER: <input type="text" value="PLYMOUTH POND"/> | POSTING STATUS: <input type="text" value="3 Posted"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="96.3"/> |
| ROAD INV NO: <input type="text" value="0001900472"/> | POSTING TYPE: <input type="text" value="1 Weight Limit"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="29"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|---|--|--|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="Newport"/> | SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| BRIDGE NO.: <input type="text" value="3605"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| LOCATION: <input type="text" value="0.9 MI S OF US RTE 2"/> | YEAR BUILT: <input type="text" value="1959"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: BOULIER | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| FEATURE ON: <input type="text" value="RIDGE ROAD"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="85"/> | DATE OF INSPECTION: <input type="text" value="12/23/2011"/> |
| FEATURE UNDER: <input type="text" value="MARTIN STREAM"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="75.3"/> |
| ROAD INV NO: <input type="text" value="0001900453"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00000"/> | | |
| ROAD WIDTH: <input type="text" value="24"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="3126"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value="0.3 MI S OF NEWPORT"/> | YEAR BUILT: <input type="text" value="1999"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="MCINTYRE"/> | SPAN MATERIAL: <input type="text" value="5 Aluminum"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="ROUTE 7"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="20"/> | DATE OF INSPECTION: <input type="text" value="10/16/2012"/> |
| FEATURE UNDER: <input type="text" value="MCINTYRE BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="99.2"/> |
| ROAD INV NO: <input type="text" value="00000007X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00007"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|---|---|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRIDGE NO.: <input type="text" value="2982"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| LOCATION: <input type="text" value="0.2 MI NW JCT RTE 7"/> | YEAR BUILT: <input type="text" value="1933"/> | DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| BRDGNAME: <input type="text" value="TANNERY"/> | SPAN MATERIAL: <input type="text" value="1 Steel"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="1 Girder"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="3"/> | APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/> |
| FEATURE ON: <input type="text" value="ROUTE 69"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="121"/> | DATE OF INSPECTION: <input type="text" value="12/23/2011"/> |
| FEATURE UNDER: <input type="text" value="MARTIN STREAM"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="51.8"/> |
| ROAD INV NO: <input type="text" value="000000069X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00069"/> | | |
| ROAD WIDTH: <input type="text" value="22"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|--|---|--|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRIDGE NO.: <input type="text" value="2287"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| LOCATION: <input type="text" value="0.5MI S JCT RTE#69"/> | YEAR BUILT: <input type="text" value="1989"/> | DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| BRDGNAME: <input type="text" value="FLOATING"/> | SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="3 Slab"/> | CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="ROUTE 7"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="48"/> | DATE OF INSPECTION: <input type="text" value="10/16/2012"/> |
| FEATURE UNDER: <input type="text" value="PLYMOUTH POND"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="97.9"/> |
| ROAD INV NO: <input type="text" value="000000007X"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00007"/> | | |
| ROAD WIDTH: <input type="text" value="33"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/> | |
| CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/> | | |

Structures in the Municipality of Plymouth

CONDITION RATINGS

| | | |
|--|--|---|
| TOWN1: <input type="text" value="Plymouth"/> | TOWN2: <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRIDGE NO.: <input type="text" value="1439"/> | BRIDGE REGION: <input type="text" value="Eastern"/> | SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| LOCATION: <input type="text" value=".8 MI SO TOWNLINE"/> | YEAR BUILT: <input type="text" value="1962"/> | DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| BRDGNAME: <input type="text" value="I95 SB / MCINTYRE BROOK"/> | SPAN MATERIAL: <input type="text" value="2 Concrete"/> | CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| OWNER: <input type="text" value="1 State DOT"/> | SPAN TYPE: <input type="text" value="4 Culvert"/> | CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/> |
| MAINTAINER: <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: <input type="text" value="1"/> | APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/> |
| FEATURE ON: <input type="text" value="I-95"/> | STRUCTURE LENGTH IN FEET: <input type="text" value="17"/> | DATE OF INSPECTION: <input type="text" value="1/19/2012"/> |
| FEATURE UNDER: <input type="text" value="MCINTYRE BROOK"/> | POSTING STATUS: <input type="text" value="1 Open"/> | FEDERAL SUFFICIENCY RATING: <input type="text" value="96.2"/> |
| ROAD INV NO: <input type="text" value="000000095S"/> | POSTING TYPE: <input type="text" value="0 None needed"/> | |
| ROUTE NO: <input type="text" value="00095"/> | | |
| ROAD WIDTH: <input type="text" value="0"/> FEET | FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/> | |
| CLASS: <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/> | | |