

## Structures in the Municipality of Rangeley

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Rangeley"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3544"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="1.3 MI NW OF JCT RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1980"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="KENNEBAGO"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 16"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="120"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/13/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="KENNEBAGO RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="90.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000016X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00016"/>		
<b>ROAD WIDTH:</b> <input type="text" value="29"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Rangeley

### CONDITION RATINGS

<b>TOWN1:</b> Rangeley	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 2669	<b>BRIDGE REGION:</b> Western	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> .8 MI W TL (RANGELY PLT)	<b>YEAR BUILT:</b> 1954	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> NILE BROOK	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 7 Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> 6 Satisfactory
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 7 Good
<b>FEATURE ON:</b> #4	<b>STRUCTURE LENGTH IN FEET:</b> 19	<b>DATE OF INSPECTION:</b> 11/21/2011
<b>FEATURE UNDER:</b> NILE BROOK	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 92.7
<b>ROAD INV NO:</b> 000000004X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00004		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		

## Structures in the Municipality of Rangeley

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Rangeley"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="2631"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.2 MI E OF JCT RTE 17"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1951"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="OQUOSSOC"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="ROUTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="81"/>	<b>DATE OF INSPECTION:</b> <input style="width: 50px;" type="text" value="11/13/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="RANGELEY RIVER"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="56.3"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Rangeley

### CONDITION RATINGS

<b>TOWN1:</b> Rangeley	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 3 Serious
<b>BRIDGE NO.:</b> 2384	<b>BRIDGE REGION:</b> Western	<b>SUPERSTRUCTURE CONDITION:</b> 5 Fair
<b>LOCATION:</b> 1.3 MI W OF JCT RTE 4	<b>YEAR BUILT:</b> 1940	<b>DECK CONDITION:</b> 5 Fair
<b>BRDGNAME:</b> HUNTER COVE	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 5 Fair
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 1 Girder	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 5 Fair
<b>FEATURE ON:</b> MINGO LOOP ROAD	<b>STRUCTURE LENGTH IN FEET:</b> 71	<b>DATE OF INSPECTION:</b> 11/13/2012
<b>FEATURE UNDER:</b> HUNTER COVE	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 72
<b>ROAD INV NO:</b> 0000700538	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 24 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> Y	
<b>CLASS:</b> BRIDGE ON TOWN WAY OR STATE AID ROAD		

## Structures in the Municipality of Rangeley

### CONDITION RATINGS

<b>TOWN1:</b> Rangeley	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>BRIDGE NO.:</b> 2231	<b>BRIDGE REGION:</b> Western	<b>SUPERSTRUCTURE CONDITION:</b> 6 Satisfactory
<b>LOCATION:</b> 5.8 MI W TOWNLIN	<b>YEAR BUILT:</b> 1925	<b>DECK CONDITION:</b> 6 Satisfactory
<b>BRDGNAME:</b> DODGE POND	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 8 Very Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 7 Good
<b>FEATURE ON:</b> #4	<b>STRUCTURE LENGTH IN FEET:</b> 22	<b>DATE OF INSPECTION:</b> 11/17/2011
<b>FEATURE UNDER:</b> DODGE POND OUTLET	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 94.2
<b>ROAD INV NO:</b> 000000004X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00004		
<b>ROAD WIDTH:</b> 35 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		