

Structures in the Municipality of Rome

CONDITION RATINGS

TOWN1: <input type="text" value="Rome"/>	TOWN2: <input type="text" value="Smithfield"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="5221"/>	BRIDGE REGION: <input type="text" value="Mid-Coast"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.4 MI W OF ROUTES 8&137"/>	YEAR BUILT: <input type="text" value="2006"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="UPPER"/>	SPAN MATERIAL: <input type="text" value="5 Aluminum"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="N PD / PINE TRE RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="23"/>	DATE OF INSPECTION: <input type="text" value="4/5/2012"/>
FEATURE UNDER: <input type="text" value="GREAT MEADOW STREA"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="100"/>
ROAD INV NO: <input type="text" value="0001100329"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Rome

CONDITION RATINGS

TOWN1: Rome	TOWN2: Smithfield	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 5071	BRIDGE REGION: Mid-Coast	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: 0.7 MI W OF ROUTES 8&137	YEAR BUILT: 1930	DECK CONDITION: 6 Satisfactory
BRDGNAME: MEADOW STREAM	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE 225	STRUCTURE LENGTH IN FEET: 28	DATE OF INSPECTION: 4/5/2012
FEATURE UNDER: GREAT MEADOW STREA	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 78.3
ROAD INV NO: 000000225X	POSTING TYPE: 0 None needed	
ROUTE NO: 00225		
ROAD WIDTH: 24 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Smithfield

CONDITION RATINGS

TOWN1: <input type="text" value="Smithfield"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="3466"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
LOCATION: <input type="text" value="200' S OF N'LY JCT8 & 137"/>	YEAR BUILT: <input type="text" value="1937"/>	DECK CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRDGNAME: <input type="text" value="MILL STREAM"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="ROUTES 8 & 137"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="25"/>	DATE OF INSPECTION: <input type="text" value="7/21/2011"/>
FEATURE UNDER: <input type="text" value="MILL STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="72.2"/>
ROAD INV NO: <input type="text" value="000000008X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00008"/>		
ROAD WIDTH: <input type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		