

## Structures in the Municipality of Starks

---

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="5842"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 140px;" type="text" value="1.5 MI E JCT 134"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1962"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>BRDGNAME:</b> WILLIAMSON	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="4"/> <input style="width: 80px;" type="text" value="Poor"/>
<b>OWNER:</b> <input style="width: 90px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 110px;" type="text" value="RIVER RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="75"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="7/13/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 110px;" type="text" value="LEMON STR"/>	<b>POSTING STATUS:</b> <input style="width: 90px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 60px;" type="text" value="90.8"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0002500650"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 60px;" type="text" value="24"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 40px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="3758"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.6 MI N JCT RTE 134"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1941"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="VILLAGE"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 90px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 110px;" type="text" value="ROUTE 43"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="77"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="10/25/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 110px;" type="text" value="LEMON STREAM"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="71.8"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000043X"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00043"/>		
<b>ROAD WIDTH:</b> <input style="width: 60px;" type="text" value="24"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="3688"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="1.3 MI S TOWNLIN"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1964"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="HILTON BROOK"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="7 Rigid Frame"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>MAINTAINER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="4"/> <input style="width: 100px;" type="text" value="Poor"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="ROUTE 43"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="23"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="7/10/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="HILTON BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 40px;" type="text" value="99"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000043X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 50px;" type="text" value="00043"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="3571"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value=".5 MI E TOWNLINE"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1938"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="CURTIS"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="#43"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="21"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="1/11/2013"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="CURTIS BRK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="89.3"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000043X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00043"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="27"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="3054"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="1.3 MI NO TOWNLINE"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1934"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="JOSHUA BROOK"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="#134"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="21"/>	<b>DATE OF INSPECTION:</b> <input style="width: 50px;" type="text" value="1/14/2013"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="JOSHUA BRK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="84.3"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000134X"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00134"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="22"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Starks"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="1054"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="1.4 MI S RT 43"/>	<b>YEAR BUILT:</b> <input type="text" value="1920"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="LEEMAN"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="BRANN MILL RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="22"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/13/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="CURTIS BRK"/>	<b>POSTING STATUS:</b> <input type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="32.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0002500652"/>	<b>POSTING TYPE:</b> <input type="text" value="1 Weight Limit"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="17"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="1053"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value=".5 MI WEST RT 134"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1988"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="BRANN"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="BRANN MILLS ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="16"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="7/13/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="JOSHUA BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="100"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0002500652"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Starks"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>BRIDGE NO.:</b> <input type="text" value="1052"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>LOCATION:</b> <input type="text" value=".3 MI E RT 148"/>	<b>YEAR BUILT:</b> <input type="text" value="1989"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="LEMON STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="2"/> <input type="text" value="Critical"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="WEST MILLS RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="21"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/12/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="LEMON STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="26.6"/>
<b>ROAD INV NO:</b> <input type="text" value="0002500665"/>	<b>POSTING TYPE:</b> <input type="text" value="1 Weight Limit"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="15"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Starks

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Starks"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="3"/> <input style="width: 70px;" type="text" value="Serious"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="1051"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="4"/> <input style="width: 70px;" type="text" value="Poor"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="1 MI S RT 148"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1907"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 70px;" type="text" value="Fair"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="PELTON BROOK"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="4"/> <input style="width: 70px;" type="text" value="Poor"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 70px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 70px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="TW (MAYEW RD ?)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="24"/>	<b>DATE OF INSPECTION:</b> <input style="width: 50px;" type="text" value="7/12/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="PELTON BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="26.3"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0002500642"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="1 Weight Limit"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="17"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		