

Structures in the Municipality of Stonington

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Stonington"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="4"/> <input style="width: 60px;" type="text" value="Poor"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="3696"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="4"/> <input style="width: 60px;" type="text" value="Poor"/>
LOCATION: <input style="width: 130px;" type="text" value="1.3 MI E JCT RTE 15"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1940"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
BRDGNAME: <input style="width: 100px;" type="text" value="OCEANVILLE"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
FEATURE ON: <input style="width: 100px;" type="text" value="OCEANVILLE ROAD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="42"/>	DATE OF INSPECTION: <input style="width: 50px;" type="text" value="4/30/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="OCEANVILLE THOROUGH"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="40.4"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0000900478"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Stonington

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Stonington"/>	TOWN2: <input style="width: 100px;" type="text" value="Deer Isle"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="3063"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
LOCATION: <input style="width: 130px;" type="text" value="DEERISLE-STONINGTON T.L."/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1939"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="4"/> <input style="width: 100px;" type="text" value="Poor"/>
BRDGNAME: <input style="width: 100px;" type="text" value="MILL HILL"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
FEATURE ON: <input style="width: 100px;" type="text" value="ROUTE 15"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="43"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="4/30/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="MILL POND OUTLET"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="63.8"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000015X"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00015"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		