

Structures in the Municipality of Hancock

CONDITION RATINGS

TOWN1: <input type="text" value="Hancock"/>	TOWN2: <input type="text" value="Sullivan"/>	SUBSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRIDGE NO.: <input type="text" value="2973"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION: <input type="text" value="4.5 MI E JCT 182 ON 1"/>	YEAR BUILT: <input type="text" value="1999"/>	DECK CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
BRDGNAME: HANCOCK SULLIVAN	SPAN MATERIAL: <input type="text" value="7 Precast Concrete"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="8"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="US 1"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="1023"/>	DATE OF INSPECTION: <input type="text" value="10/31/2012"/>
FEATURE UNDER: <input type="text" value="TAUNTON RIVER"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="95.7"/>
ROAD INV NO: <input type="text" value="000000001X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00001"/>		
ROAD WIDTH: <input type="text" value="34"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

Structures in the Municipality of Sullivan

CONDITION RATINGS

TOWN1: Sullivan	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5896	BRIDGE REGION: Eastern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 1.5 MI W RT 200	YEAR BUILT: 1950	DECK CONDITION: N Not Applicable
BRDGNAME: VILLAGE	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 7 Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 9 Excellent
FEATURE ON: US 1	STRUCTURE LENGTH IN FEET: 16	DATE OF INSPECTION: 6/13/2011
FEATURE UNDER: HIGGINS STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 66.1
ROAD INV NO: 000000001X	POSTING TYPE: 0 None needed	
ROUTE NO: 00001		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE HIGHWAY		

Structures in the Municipality of Sullivan

CONDITION RATINGS

TOWN1: Sullivan	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5668	BRIDGE REGION: Eastern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: .3 MI W TOWNLINE	YEAR BUILT: 1955	DECK CONDITION: N Not Applicable
BRDGNAME: MORANCY PD OUTLET	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 8 Very Good
OWNER: 1 State DOT	SPAN TYPE: 6 Arch	CULVERT CONDITION: 7 Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: US 1	STRUCTURE LENGTH IN FEET: 14	DATE OF INSPECTION: 6/10/2011
FEATURE UNDER: MORANCY PD OUTLET	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 84.8
ROAD INV NO: 000000001X	POSTING TYPE: 0 None needed	
ROUTE NO: 00001		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE HIGHWAY		

Structures in the Municipality of Sullivan

CONDITION RATINGS

TOWN1: <input type="text" value="Sullivan"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="5184"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="4 MI N JCT US 1"/>	YEAR BUILT: <input type="text" value="2012"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="BEAN"/>	SPAN MATERIAL: <input type="text" value="5 Aluminum"/>	CHANNEL CONDITION: <input type="text" value="9"/> <input type="text" value="Excellent"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="4 Culvert"/>	CULVERT CONDITION: <input type="text" value="9"/> <input type="text" value="Excellent"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="9"/> <input type="text" value="Excellent"/>
FEATURE ON: <input type="text" value="THORNE RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="0"/>	DATE OF INSPECTION: <input type="text" value="10/19/2012"/>
FEATURE UNDER: <input type="text" value="FLANDERS STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="33.6"/>
ROAD INV NO: <input type="text" value="0000900511"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Sullivan

CONDITION RATINGS

TOWN1: <input type="text" value="Sullivan"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="2984"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value=".2 MI NE RTE 1"/>	YEAR BUILT: <input type="text" value="1935"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: SMITH MILL	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="OLD RTE 1(TO ASHVI"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="14"/>	DATE OF INSPECTION: <input type="text" value="10/19/2012"/>
FEATURE UNDER: <input type="text" value="MORANCEY STR."/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="92.8"/>
ROAD INV NO: <input type="text" value="0000901819"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Sullivan

CONDITION RATINGS

TOWN1: <input type="text" value="Sullivan"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRIDGE NO.: <input type="text" value="2285"/>	BRIDGE REGION: <input type="text" value="Eastern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
LOCATION: <input type="text" value="0.2 MI W JCT RTE 183"/>	YEAR BUILT: <input type="text" value="1927"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
BRDGNAME: <input type="text" value="FLANDERS STREAM"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="ROUTE US 1"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="23"/>	DATE OF INSPECTION: <input type="text" value="4/7/2011"/>
FEATURE UNDER: <input type="text" value="FLANDERS STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="83.8"/>
ROAD INV NO: <input type="text" value="000000001X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00001"/>		
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		