

## Structures in the Municipality of Taunton and Raynham Grant

### CONDITION RATINGS

<b>TOWN1:</b>	Taunton and Raynham Grant	<b>TOWN2:</b>	No town 2	<b>SUBSTRUCTURE CONDITION</b>	8	Very Good
<b>BRIDGE NO.:</b>	3113	<b>BRIDGE REGION:</b>	Western	<b>SUPERSTRUCTURE CONDITION</b>	8	Very Good
<b>LOCATION:</b>	1.3 MI S OF ROCKWOOD TL	<b>YEAR BUILT</b>	2000	<b>DECK CONDITION</b>	8	Very Good
<b>BRDGNAME:</b>	WEST OUTLET	<b>SPAN MATERIAL</b>	1 Steel	<b>CHANNEL CONDITION:</b>	7	Good
<b>OWNER:</b>	1 State DOT	<b>SPAN TYPE:</b>	1 Girder	<b>CULVERT CONDITION:</b>	N	Not Applicable
<b>MAINTAINER</b>	1 State DOT	<b>NUMBER OF MAIN SPANS:</b>	2	<b>APPROACH CONDITION:</b>	7	Good
<b>FEATURE ON:</b>	ROUTES 6 & 15	<b>STRUCTURE LENGTH IN FEET</b>	153	<b>DATE OF INSPECTION:</b>	5/14/2012	
<b>FEATURE UNDER</b>	W OUTLET KENNEBEC R	<b>POSTING STATUS:</b>	1 Open	<b>FEDERAL SUFFICIENCY RATING</b>	88.7	
<b>ROAD INV NO:</b>	00000006X	<b>POSTING TYPE:</b>	0 None needed			
<b>ROUTE NO:</b>	00006					
<b>ROAD WIDTH</b>	29	<b>FEDERAL BRIDGE INDICATOR:</b>	Y			
<b>CLASS:</b>	BRIDGE ON STATE HIGHWAY					