

## Structures in the Municipality of Greene

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Greene"/>	<b>TOWN2:</b> <input type="text" value="Turner"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="3426"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="2.2 MI ELY RTE 117"/>	<b>YEAR BUILT:</b> <input type="text" value="1937"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="TURNER CENTER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="5 Truss"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="CENTER BRIDGE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="456"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="ANDROSCOGGIN RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="47"/>
<b>ROAD INV NO:</b> <input type="text" value="0000100460"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="2619"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="2.5 MI NELY JCT RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1941"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="NORTH PARISH"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="N. PARISH RD RTE"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="210"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="NEZINSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="58.6"/>
<b>ROAD INV NO:</b> <input type="text" value="000000117X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00117"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="0007"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI E RT 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1972"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="TRIPPS"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="TIDSWELL RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="15"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/31/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="53.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000100366"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="0019"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>LOCATION:</b> <input type="text" value="0.4 MI NW JCT RTE 117"/>	<b>YEAR BUILT:</b> <input type="text" value="1938"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <b>RICKERS</b>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>FEATURE ON:</b> <input type="text" value="RICKER HILL ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="37"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/29/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="15.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0000100443"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="16"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1037"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI S RTE 117"/>	<b>YEAR BUILT:</b> <input type="text" value="1988"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="TURNER NEW"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="136"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="NEZINSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="95"/>
<b>ROAD INV NO:</b> <input type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input type="text" value="39"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="Leeds"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1474"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="AT JCT ROUTE 108"/>	<b>YEAR BUILT:</b> <input type="text" value="2008"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="NORTH TURNER, WEST"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 219"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="360"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/14/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="WEST CHANN ANDROSC"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="74.9"/>
<b>ROAD INV NO:</b> <input type="text" value="000000219X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00219"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2152"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="2.0 MI W'LY OF ROUTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1938"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="CHASES MILL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 117"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="60"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/29/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="76.9"/>
<b>ROAD INV NO:</b> <input type="text" value="000000117X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00117"/>		
<b>ROAD WIDTH:</b> <input type="text" value="29"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="0006"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.5 MI SE RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1997"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="MEADOW"/>	<b>SPAN MATERIAL:</b> <input type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="SCHOOL HOUSE HILL"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="20"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/3/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MEADOW BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="81.4"/>
<b>ROAD INV NO:</b> <input type="text" value="0000100360"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="2537"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="3 MI NO TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1985"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="MEADOW BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="14"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/19/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MEADOW BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="100"/>
<b>ROAD INV NO:</b> <input type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="6234"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.2 MI S JCT 117"/>	<b>YEAR BUILT:</b> <input type="text" value="1972"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="RUSSELL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="EAST HEBRON ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="115"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/29/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="NEZINSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0000100455"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="2622"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.4 MI N JCT RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1930"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="NORTH TURNER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="MILL HILL ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="58"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/14/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="66.7"/>
<b>ROAD INV NO:</b> <input type="text" value="0000100721"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2874"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="50 FT S OF JCT RTE 117"/>	<b>YEAR BUILT:</b> <input type="text" value="1999"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="TURNER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="MAIN STREET"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="151"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="NEZINSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="83"/>
<b>ROAD INV NO:</b> <input type="text" value="0000101271"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="3480"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI S OF JCT RTE 219"/>	<b>YEAR BUILT:</b> <input type="text" value="1970"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="NORTH TURNER NO. 2"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="33"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/18/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="86.6"/>
<b>ROAD INV NO:</b> <input type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3886"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="1.8 MI NELY JCT RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1947"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="TURNER CENTER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 117"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="185"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/16/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="NEZINSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="64"/>
<b>ROAD INV NO:</b> <input type="text" value="000000117X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00117"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5441"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.1 MI W OF JCT RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="1952"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="TEAGUE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 219"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="33"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/18/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="88.4"/>
<b>ROAD INV NO:</b> <input type="text" value="000000219X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00219"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Turner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Turner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2518"/>	<b>BRIDGE REGION:</b> <input type="text" value="Western"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="2.5 MI N OF JCT RTE 117"/>	<b>YEAR BUILT:</b> <input type="text" value="1991"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="MARTIN STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="3 Slab"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="83"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="9/28/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="MARTIN STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="97.4"/>
<b>ROAD INV NO:</b> <input type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input type="text" value="45"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		