

Structures in the Municipality of Twp 01 R 05 Wels

CONDITION RATINGS

TOWN1:	Twp 01 R 05 Wels	TOWN2:	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.:	5909	BRIDGE REGION:	Northern	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION:	2.8 MI N OF MOLUS TL	YEAR BUILT	1962	DECK CONDITION	N	Not Applicable
BRDGNAME:	MOLUS STREAM (LITTLE)	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	5	Fair
OWNER:	1 State DOT	SPAN TYPE:	6 Arch	CULVERT CONDITION:	6	Satisfactory
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS:	1	APPROACH CONDITION:	5	Fair
FEATURE ON:	AROOSTOOK ROAD	STRUCTURE LENGTH IN FEET	23	DATE OF INSPECTION:	7/22/2011	
FEATURE UNDER	LITTLE MOLUS STREAM	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	98.9	
ROAD INV NO:	0000301433	POSTING TYPE:	0 None needed			
ROUTE NO:	00000					
ROAD WIDTH	0	FEDERAL BRIDGE INDICATOR:	Y			
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD					

Structures in the Municipality of Twp 01 R 05 Wels

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 01 R 05 Wels"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
BRIDGE NO.: <input type="text" value="2338"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
LOCATION: <input type="text" value="0.9 MI NW OF T1R4 TL"/>	YEAR BUILT: <input type="text" value="1930"/>	DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
BRDGNAME: <input type="text" value="GULLIVER BROOK"/>	SPAN MATERIAL: <input type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="3 Slab"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
FEATURE ON: <input type="text" value="US ROUTE 2"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="23"/>	DATE OF INSPECTION: <input type="text" value="11/26/2012"/>
FEATURE UNDER: <input type="text" value="GULLIVER BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="63.5"/>
ROAD INV NO: <input type="text" value="000000002X"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00002"/>		
ROAD WIDTH: <input type="text" value="27"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		