

Structures in the Municipality of Twp 06 R 07 Wels

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 06 R 07 Wels"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NO.: <input type="text" value="6044"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>
LOCATION: <input type="text" value="3.8 MI W TOWNLINe"/>	YEAR BUILT: <input type="text" value="1966"/>	DECK CONDITION: <input type="text" value="7"/> <input type="text" value="Good"/>
BRDGNAME: SEBOEIS	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
OWNER: <input type="text" value="1 State DOT"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
FEATURE ON: <input type="text" value="GRAND LAKE ROAD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="93"/>	DATE OF INSPECTION: <input type="text" value="9/19/2012"/>
FEATURE UNDER: <input type="text" value="SEBOEIS STREAM"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="79.1"/>
ROAD INV NO: <input type="text" value="0001900787"/>	POSTING TYPE: <input type="text" value="0 None needed"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="26"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>	
CLASS: <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Twp 06 R 07 Wels

CONDITION RATINGS

TOWN1: <input type="text" value="Twp 06 R 07 Wels"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
BRIDGE NO.: <input type="text" value="0879"/>	BRIDGE REGION: <input type="text" value="Northern"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
LOCATION: <input type="text" value="1.6 MI N GRAND LAKE RD"/>	YEAR BUILT: <input type="text" value="1997"/>	DECK CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
BRDGNAME: SAWTELL	SPAN MATERIAL: <input type="text" value="5 Aluminum"/>	CHANNEL CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="7 Rigid Frame"/>	CULVERT CONDITION: <input type="text" value="8"/> <input type="text" value="Very Good"/>	
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="5"/> <input type="text" value="Fair"/>	
FEATURE ON: <input type="text" value="THREAD RD (SCRAGGL"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="25"/>	DATE OF INSPECTION: <input type="text" value="8/23/2012"/>	
FEATURE UNDER: <input type="text" value="SAWTELLE BROOK"/>	POSTING STATUS: <input type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="92.8"/>	
ROAD INV NO: <input type="text" value="0001900774"/>	POSTING TYPE: <input type="text" value="0 None needed"/>		
ROUTE NO: <input type="text" value="00000"/>			
ROAD WIDTH: <input type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="Y"/>		
CLASS: <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>			