

## Structures in the Municipality of Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Gardiner"/>	<b>TOWN2:</b> <input type="text" value="West Gardiner"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="6319"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="GARDNER/W GARDINER"/>	<b>YEAR BUILT:</b> <input type="text" value="1974"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="I95 NB/ COBBOSSEE STR."/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="I-95 NB"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="205"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="1/18/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSECONTEE STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="93.3"/>
<b>ROAD INV NO:</b> <input type="text" value="000000295X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00295"/>		
<b>ROAD WIDTH:</b> <input type="text" value="41"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Litchfield

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Litchfield"/>	<b>TOWN2:</b> <input type="text" value="West Gardiner"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="3"/> <input type="text" value="Serious"/>
<b>BRIDGE NO.:</b> <input type="text" value="3329"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.1 MIE OF BOG HILL RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1936"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="WHARF"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="INDIANA &amp; DENNIS R"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="100"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSEE STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="52"/>
<b>ROAD INV NO:</b> <input type="text" value="0001100316"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="23"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Litchfield

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Litchfield"/>	<b>TOWN2:</b> <input type="text" value="West Gardiner"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="2029"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="LITCHFLD-W.GARDINER TL"/>	<b>YEAR BUILT:</b> <input type="text" value="1931"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <b>BABCOCK</b>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 126"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="53"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/11/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSECONTEE STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="64.8"/>
<b>ROAD INV NO:</b> <input type="text" value="000000009X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00009"/>		
<b>ROAD WIDTH:</b> <input type="text" value="24"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Litchfield

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Litchfield"/>	<b>TOWN2:</b> <input type="text" value="West Gardiner"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0547"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="0.240 mi W of Plains Rd"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="COBBOSSECONTEE STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value=""/> <input type="text" value=""/>
<b>FEATURE ON:</b> <input type="text" value="I-95 (NB)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="210"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/21/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSECONTEE STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="73.2"/>
<b>ROAD INV NO:</b> <input type="text" value="000000095X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="Litchfield"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="2834"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="LITCHFIELD-W GARD TL"/>	<b>YEAR BUILT:</b> <input type="text" value="1964"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="TAPPAN"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="HALLOWELL LITCHFIE"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="163"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/3/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSEE STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="85"/>
<b>ROAD INV NO:</b> <input type="text" value="0001100353"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="28"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0548"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.394 mi W of I-295"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="ROUTE 126"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value=""/> <input type="text" value=""/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE126"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="278"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/23/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="I-95"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="72.7"/>
<b>ROAD INV NO:</b> <input type="text" value="000000009X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00009"/>		
<b>ROAD WIDTH:</b> <input type="text" value="31"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0549"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="0.271 mi W of I-295"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="GARDINER INTERCHANGE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="5"/>	<b>APPROACH CONDITION:</b> <input type="text"/> <input type="text"/>
<b>FEATURE ON:</b> <input type="text" value="GARDINER/LITCHFIEL"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="233"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="2/20/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="I-95"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="74.6"/>
<b>ROAD INV NO:</b> <input type="text" value="00011G1355"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="0550"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="0.085 mi W of Fire Rd 204"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="HIGH STREET"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value=""/> <input type="text" value=""/>
<b>FEATURE ON:</b> <input type="text" value="HIGH STREET"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="240"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/21/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="I-95"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="67.4"/>
<b>ROAD INV NO:</b> <input type="text" value="0003209730"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="25"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="Litchfield"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1500"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.249 mi W of Plains Rd"/>	<b>YEAR BUILT:</b> <input type="text" value="1956"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="COBBOSSECONTEE STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text"/> <input type="text"/>
<b>FEATURE ON:</b> <input type="text" value="I-95(SB)"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="210"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/21/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSECONTEE STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="75.2"/>
<b>ROAD INV NO:</b> <input type="text" value="000000095S"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00095"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="Gardiner"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="1534"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1974"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="I295 SB / COBBOSSEE STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="I-295 SOUTHBOUND"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="205"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="7/20/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSECONTEE STR"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="93.5"/>
<b>ROAD INV NO:</b> <input type="text" value="000000295S"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00295"/>		
<b>ROAD WIDTH:</b> <input type="text" value="41"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="Litchfield"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRIDGE NO.:</b> <input type="text" value="2112"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value="LITCHFIELD-W GARD TL"/>	<b>YEAR BUILT:</b> <input type="text" value="1936"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="BURNHAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="PLAINS ROAD-POND R"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="98"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/8/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBBOSSEE STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="57.6"/>
<b>ROAD INV NO:</b> <input type="text" value="0001100304"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="2321"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="2.0*MI*W*TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1959"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="GOSLINE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="6 Arch"/>	<b>CULVERT CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="HIGH ST"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="17"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/25/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="73"/>
<b>ROAD INV NO:</b> <input type="text" value="0003209730"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="6323"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.433 mi W of Stoneham Dr"/>	<b>YEAR BUILT:</b> <input type="text" value="1972"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="I-295 SB OVER MTA"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="5"/>	<b>APPROACH CONDITION:</b> <input type="text"/> <input type="text"/>
<b>FEATURE ON:</b> <input type="text" value="I-295 SB UNDERPASS"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="233"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/23/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="I-95"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="91.6"/>
<b>ROAD INV NO:</b> <input type="text" value="000000295S"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00295"/>		
<b>ROAD WIDTH:</b> <input type="text" value="39"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3331"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.7 MI N OF LITCHFIELD RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1961"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> COLLINS	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="3"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="COLLINS MILL ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="121"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="9/20/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COBOSSEE STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="71.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0001102243"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5200"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1.8 MI W TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1997"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="CURTIS BROOK"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="HIGHLAND AVE"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="10"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="11/20/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="CURTIS BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98.3"/>
<b>ROAD INV NO:</b> <input type="text" value="0003209730"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="6320"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="2.1MI NE OF LITCHFIELD"/>	<b>YEAR BUILT:</b> <input type="text" value="1973"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="POND ROAD / I 295"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="POND ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="227"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/21/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="INTERSTATE 295"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="89.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0001100304"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="6321"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="2.0 MI N GARDINER T.L."/>	<b>YEAR BUILT:</b> <input type="text" value="1973"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="ROUTE 126 / I-295"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTES 9 &amp; 126"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="176"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="12/3/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="INTERSTATE 295"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="98"/>
<b>ROAD INV NO:</b> <input type="text" value="000000009X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00009"/>		
<b>ROAD WIDTH:</b> <input type="text" value="43"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="6322"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="0.224 mi E of I-95"/>	<b>YEAR BUILT:</b> <input type="text" value="1977"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="RAMP E OVER I-95"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="8 ME TPK"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="8 ME TPK"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="5"/>	<b>APPROACH CONDITION:</b> <input type="text"/> <input type="text"/>
<b>FEATURE ON:</b> <input type="text" value="RAMP E/1295 TPLAZA"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="198"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/21/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="I-95"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="78"/>
<b>ROAD INV NO:</b> <input type="text" value="-1"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MAINE TURNPIKE AUTHORITY"/>		

## Structures in the Municipality of West Gardiner

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="West Gardiner"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="2165"/>	<b>BRIDGE REGION:</b> <input type="text" value="Mid-Coast"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value=".5 MI W I-95 ON 126"/>	<b>YEAR BUILT:</b> <input type="text" value="1931"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="COLD STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="RTE 9 + 126"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="39"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/7/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="97.4"/>
<b>ROAD INV NO:</b> <input type="text" value="000000009X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00009"/>		
<b>ROAD WIDTH:</b> <input type="text" value="33"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		